Chw # 19312

PETROLEUM RELEASE FORM Please Check All That Apply

OKMET 383KL	INCIDENT INFORMATION——	
LOG NBR: (Dept. use only) 03-05-0461	RECEIVED BY: (Dept. use only)	REGULATED UST
	DATE REPORTED: (today's date) 3	이 있는 사람들은 사람들은 가는 그렇게 보고 있었다. 그리고 있는 것은 사람들은 사람들은 사람들은 사람들은 사람들은 사람들은 사람들은 사람들
UST FAC NBR: (Dept. use only) 6024		☐ HEATING OIL TANK
SITE NAME: Molalla KMK GOS	Thurt be west with 1	117 17010
SITE ADDRESS: 307 5 Main	(Main - mill	FUNDING: (Dept. use only)
SITE ADDRESS:	1038	UST HSRAF HOT (heating oil tank)
Circly Monal	UPDATES	: (Dept. use only)
	MAIL CONTACTS——PESPONSIBLE PAR	TY (person responsible for remedial action)
REPORTED BY (person reporting this release to the Dept.)	Let	Powell JR
NAME: Wanda Peltz		DWELL DISTRIBUTION
COMPANY: SME INC	COMPANY:	PO 1904 17160
ADDRESS:	ADDRESS:	1and ZIP: 97217
ZIP:	CITY:	PHONE: 503 299 5558
STATE:PHONE: 1 800 550 15		
INVOICE CONTACT (required, may be same as responsible	e party), , OTHER CONTACT	
	NAME:	•
NAME:	COMPANY:	
COMPANY:	ADDRESS.	
ADDRESS:	CITY:	ZIP:
CITY:ZIP:		PHONE:
STATE:PHONE:	- LONGGATAIT	
3/15/	DATE TANK IS	EMPTY:/
DATE DISCOVERED: 3 / 15 /		CAUSE
CONFIRMATION:	VERY: RM) ROUTINE MONITORING	TL) TANK LEAK
☐ SI) STAFF ☐ LD) LAB: DEQ	DC) DECOMMISSIONING CP) COMPLAINT	OF) OVERFILL
□ I.R) LAB: RP	TIC) INVENTORY CONTROL	SS) SURFACE SPILL PV) PUMP/VALVE LEAK
LO) LAB: OTHER RR) RP REPORT	SA) SITE ASSESSMENT	OT) OTHER
CN) CONTRACTOR	TT) TANK TEST	UN) MKNOMN
OT) OTHER	OT) OTHER CONTAMINANTS	
	COLVIII	OP) OTHER PET. DIST
r GASOL DIE	☐ WO) WASTE OIL	CH) CHEMICAL
UG) UNLEADED GASOLINE	HO) HEATING OIL	OT OTHER
GMG) MISC. GASOLINE	LB) LUBRICANT	☐ ∩W) ∩WKNOMN
DS) DIESEL (motor fuel)	SV) SOLVENTIMPACTS	
	Y) SURFACE WATER DW) DRINKIN	
1 131, 33.2) FACILITY OR BUILDING (FREE PRODUC	T. USE ONLY)
SITE-MAN	JAGEMENT (THIS SECTION DE	T. USE ONLY)————————————————————————————————————
RELEASE STOPPED:/	FINAL REQUEST INVOICE	DATE
CLEANUP STARTED:/		ПОМ:
NOTES/COMMENTS:		
MOTES/COMMITTION.		1

From:

HOOD Robert

Sent:

Monday, April 22, 2013 10:13 AM

To:

'John Day'

Subject:

RE: Molalla Kwik Gas 03-05-0461

Ok. Thanks John. Look forward to seeing the reports. -Rob

From: John Day [mailto:jday@dayenv.com]
Sent: Thursday, April 18, 2013 1:51 PM

To: HOOD Robert

Subject: RE: Molalla Kwik Gas 03-05-0461

Rob, I am not sure why I didn't see the first two emails. I apologize for the delay.

The two additional monitoring wells were installed in April 2011. Quarterly groundwater monitoring has been conducted since.

We were holding off completing the Risk-based CAP until the summer when groundwater elevations would be lower, so the soil gas survey could be included. However, The ball was dropped on all reporting. You may recall that when we initially attempted the survey, depth to shallow groundwater was within 2 feet of ground surface.

I am working on a preliminary RBCAP (without a soil gas survey), which began in 2011. I project that it will be submitted to you within three weeks (by May 9). Individual groundwater monitoring report for each quarter will be submitted after that time-frame. A soil gas survey WILL be completed this summer in hopes of eliminating the vapor intrusion into buildings exposure pathway from the CSM.

Again, I apologize for not getting back to you sooner and for not submitting reports in a timely manner.

Thanks for your patience, John Day

John M. Day, RG, LHg Principal Geologist Environmental Compliance Northwest (503) 936-4818 – Phone (503) 213-9980 - Fax

From: HOOD Robert [mailto:HOOD.Robert@deq.state.or.us]

Sent: Wednesday, April 17, 2013 9:19 AM **To:** HOOD Robert; 'jday@dayenv.com' **Subject:** RE: Molalla Kwik Gas 03-05-0461

Importance: High

John: Can you let me know the status? -Rob

From: HOOD Robert

Sent: Wednesday, March 13, 2013 4:37 PM

To: 'jday@dayenv.com'

Subject: RE: Molalla Kwik Gas 03-05-0461

Hi John: Wanted to follow-up on my email from November. Can you provide the status of the work that I approved in my letter dated 11 February 2011 (some monitoring wells and soil gas points)? Also, has sampling occurred. Thanks. - Rob

From: HOOD Robert

Sent: Thursday, November 08, 2012 11:08 AM

To: 'jday@dayenv.com'

Subject: Molalla Kwik Gas 03-05-0461

Hi John. Can you provide me an update of this site? I think some soil gas sampling was to be completed.

Thanks. -Rob

Rob

Rob Hood

Project Manager, UST Cleanup Program

Oregon Dept. of Environmental Quality

2020 SW 4th Ave., Ste. 400

Portland, OR 97201-4987

Ph: (503) 229-5617

Fax: (503) 229-6945

email: hood.robert@deq.state.or.us

From:

HOOD Robert

Sent:

Wednesday, April 17, 2013 9:19 AM

To: Subject:

HOOD Robert; 'jday@dayenv.com' RE: Molalla Kwik Gas 03-05-0461

Importance:

High

John: Can you let me know the status? -Rob

From: HOOD Robert

Sent: Wednesday, March 13, 2013 4:37 PM

To: 'jday@dayenv.com'

Subject: RE: Molalla Kwik Gas 03-05-0461

Hi John: Wanted to follow-up on my email from November. Can you provide the status of the work that I approved in my letter dated 11 February 2011 (some monitoring wells and soil gas points)? Also, has sampling occurred. Thanks. - Rob

From: HOOD Robert

Sent: Thursday, November 08, 2012 11:08 AM

To: 'jday@dayenv.com'

Subject: Molalla Kwik Gas 03-05-0461

Hi John. Can you provide me an update of this site? I think some soil gas sampling was to be completed.

Thanks. -Rob

Rob

Rob Hood

Project Manager, UST Cleanup Program

Oregon Dept. of Environmental Quality

2020 SW 4th Ave., Ste. 400

Portland, OR 97201-4987

Ph: (503) 229-5617

Fax: (503) 229-6945

email: hood.robert@deq.state.or.us

From:

HOOD Robert

Sent:

Wednesday, March 13, 2013 4:37 PM

To:

'jday@dayenv.com'

Subject:

RE: Molalla Kwik Gas 03-05-0461

Hi John: Wanted to follow-up on my email from November. Can you provide the status of the work that I approved in my letter dated 11 February 2011 (some monitoring wells and soil gas points)? Also, has sampling occurred. Thanks. - Rob

From: HOOD Robert

Sent: Thursday, November 08, 2012 11:08 AM

To: 'jday@dayenv.com'

Subject: Molalla Kwik Gas 03-05-0461

Hi John. Can you provide me an update of this site? I think some soil gas sampling was to be completed.

Thanks. -Rob

Rob

Rob Hood

Project Manager, UST Cleanup Program

Oregon Dept. of Environmental Quality

2020 SW 4th Ave., Ste. 400

Portland, OR 97201-4987

Ph: (503) 229-5617

Fax: (503) 229-6945

email: hood.robert@deq.state.or.us

From:

HOOD Robert

Sent:

Thursday, November 08, 2012 11:08 AM

To:

Subject:

'jday@dayenv.com' Molalla Kwik Gas 03-05-0461

Hi John. Can you provide me an update of this site? I think some soil gas sampling was to be completed.

Thanks. -Rob

Rob

Rob Hood

Project Manager, UST Cleanup Program

Oregon Dept. of Environmental Quality

2020 SW 4th Ave., Ste. 400

Portland, OR 97201-4987

Ph: (503) 229-5617

Fax: (503) 229-6945

email: hood.robert@deq.state.or.us



ENVIRONMENTAL COMPLIANCE NORTHWEST

PO BOX 230163 PORTLAND, OR 97281 (503) 372-9760 Phone (503) 213-9980 Fax

TRANSMITTAL

Date: May 26, 2011

File: 05-106

TO:

Mr. Rob Hood Oregon DEQ-NW Region 2020 SW Fourth Avenue, Suite 400 Portland, OR 97201

Subject

First Quarter 2011 Groundwater Monitoring Report Former Kwik Gas Service Station 305 West Main Street Molalla, Oregon

DEQ LUST File No.: 03-05-491

0461

We are sending the following:

One copy of the above-referenced report.

Remarks:

If you have any questions, please contact our office at (503) 372-9760. Thank you.

By:

John M. Day, RG Principal Geologist

President

DEPT OF ENVIRONMENTAL QUALITY RECEIVED

JUN 6 2011

NORTHWEST REGION



ENVIRONMENTAL COMPLIANCE NORTHWEST PO BOX 230163

PORTLAND, OR 97281

(503) 213-9980 Fax

DEPT OF ENVIRONMENTAL QUALITY RECEIVED

NORTHWEST REGION

TRANSMITTAL

Date: February 18, 2011

File: 05-106

TO:

Mr. Rob Hood Oregon DEQ, NW Region 2020 SW Fourth Avenue, Suite 400 Portland, OR 97201

Subject

Fourth Quarter 2010 Groundwater Monitoring Report Former Molalla Kwik Gas 305 West Main Street Molalla, Oregon

DEQ LUST File No.: 03-05-461

We are sending the following:

One copy of the above-referenced report.

Remarks:

If you have any questions, please contact our office at (503) 372-9760. Thank you.

John M. Day, R.G. Principal Geologist

President



file

Department of Environmental Quality

Nortwest Region Portland Office 2020 SW 4th Avenue, Suite 400 Portland, OR 97201-4987 (503) 229-5263

Fax: (503) 229-6945 TTY: (800) 736-2900

11 February 2011

JASON POWELL POWELL DISTRIBUTING PO BOX 17160 PORTLAND OR 97217

Re:

Molalla Kwik Gas File No. 03-05-0461

Dear Mr. Powell:

The Department of Environmental Quality (DEQ) has reviewed the nine submitted groundwater monitoring reports and the work plan dated 10 December 2010, regarding the underground storage tank (UST) cleanup at 305 West Main Street in Molalla, Oregon. From review and per discussion between your consultant, Mr. John Day {Environmental Compliance Northwest (ECN)} and me on 8 February 2011, DEQ has the following comments:

Groundwater Monitoring Reports:

- -Please provide the purge water disposal receipts from the groundwater monitoring events.
- -Please provide a topographic vicinity map as Figure 1 in future reports.
- -The groundwater gradient at the site appears to be unusually steep. It was agreed that gradient will be further evaluated after measurements are collected from the newly added wells.

Work Plan:

-ECN proposes two additional monitoring wells. Based on discussion, the southern monitoring well location is acceptable. The northern location will be moved approximately 30 feet southwest of the proposed location (see attached Figure 1 for general location). For 2011, DEQ requests that two groundwater monitoring events be completed this year from the new wells and from monitoring wells MW-1 and MW-4 (near the time of installation and in approximately August or September 2011). At this time, there is no need to collect additional data from monitoring wells MW-2 and MW-3.

Molalla Kwik Gas File No: 03-05-0461 11 February 2011 Page 2 of 2

For analytical methods, please complete the following:

MW-1: NWTPH-Gx only (for first event only) MW-4: NWTPH-Gx and Dx only (both events)

New wells (for both events): for the upgradient well, NWTPH-Gx and Dx only. For the downgradient or southern well, NWTPH-Gx and Dx and RBDM VOCs.

(Note, water level measurements should be collected from all wells)

-Based on soil and groundwater results, concentrations at the site exceed screening levels for the vapor intrusion into buildings exposure pathway. As a result, DEQ requests that two temporary soil gas points and one temporary sub-slab point be installed for the collection of subsurface vapor. Approximate locations are shown on the enclosed Figure 1 (noted as SG for soil gas locations and SS for the sub-slab location). However, you will want to verify conditions and propose any changes prior to the investigation. Soil gas and sub-slab procedures from DEQ's 2010 vapor intrusion guidance should be followed. Analyses should be completed using the EPA TO-15 Method (Gx and RBDM VOCs).

DEQ requests that the investigation be completed by **15 April 2011**. If you have any questions, please call me at (503) 229-5617.

Respectfully,

Robert A. Hood, Jr. UST Cleanup Specialist

enclosure: Figure 1

cc: John Day


Environmental Compliance

Northwest

PO Box 230163

Portland, OR 97281

(rah:RAH)



From:

HOOD Robert

Sent:

Friday, February 11, 2011 9:53 AM

To:

'John Day'

Subject:

Molalla Qwik Gas Work Plan 03-05-0461

John: I was relooking a the data and it looks like an additional soil gas point may be necessary (if physically feasible). I put that in the letter, which is going out I hope today, but made some other reductions to groundwater analyticals to balance out the work. Have a look and let's reconnect after you review my letter. Thanks.

Rob

Rob Hood Project Manager, UST Cleanup Program Oregon Dept. of Environmental Quality 2020 SW 4th Ave., Ste. 400 Portland, OR 97201-4987 Ph: (503) 229-5617

Fax: (503) 229-6945

email: hood.robert@deq.state.or.us
website: www.oregon.gov/deq

Portland, OR 97201-4987

Ph: (503) 229-5617

Fax: (503) 229-6945

email: hood.robert@deq.state.or.us

From:

HOOD Robert

Sent:

Tuesday, February 08, 2011 2:10 PM

To:

'John Day'

Subject:

RE: Molalla Kwik Gas, 03-05-0461, Work Plan

Thanks for the discussion today. Attached is the link for the VI guidance. Note, the sampling techniques are more advanced than in the past (like the use of tracer compounds is required now). Some people contract that out if they don't have the experience. Also, I my goal is to get my reply out this week. If not, early next week.

http://www.deq.state.or.us/lq/pubs/docs/cu/VaporIntrusionGuidance.pdf

Rob

From: John Day [mailto:jday@dayenv.com] **Sent:** Monday, February 07, 2011 4:16 PM

To: HOOD Robert

Subject: RE: Molalla Kwik Gas, 03-05-0461, Work Plan

Rob,

1:30 tomorrow works for me. I will call you then.

Thanks, John

From: HOOD Robert [mailto:HOOD.Robert@deq.state.or.us]

Sent: Monday, February 07, 2011 3:35 PM

To: John Day

Subject: Molalla Kwik Gas, 03-05-0461, Work Plan

John:

I was wondering if you had a couple of minutes for a phone call sometime this week to go over your work plan and regarding the groundwater monitoring reports. I could be available tomorrow at \sim 1:30, and I am around both Wednesday and Thursday. Thanks.

Rob

Rob Hood

Project Manager, UST Cleanup Program

Oregon Dept. of Environmental Quality

2020 SW 4th Ave., Ste. 400



ENVIRONMENTAL COMPLIANCE NORTHWEST

PO BOX 230163 PORTLAND, OR 97281 (503) 372-9760 Phone (503) 213-9980 Fax

TRANSMITTAL

Date: December 15, 2010

File: 05-106

<u>TO:</u>

Mr. Rob Hood Oregon DEQ, NW Region 2020 SW Fourth Avenue, Suite 400 Portland, OR 97201

Subject

Groundwater Monitoring Reports And Work Plan Former Molalla Kwik Gas 305 West Main Street Molalla, Oregon

DEQ LUST File No.: 03-05-461



We are sending the following:

One copy each of the 1st Quarter 2008 through 3rd Quarter 2010 Groundwater Monitoring Reports, and Work Plan for additional monitoring well installation and Risk-Based Corrective Action Plan preparation.

Remarks:

If you have any questions, please contact our office at (503) 372-9760. Thank you.

By:

John M. Day, R.G. Principal Geologist

President



Project No. 05-106

PO BOX 230163 PORTLAND, OR 97281 (503) 372-9760 Phone (503) 213-9980 Fax

Environmental Compliance Northwest

Mr. Rob Hood Oregon Department of Environmental Quality Northwest Region 2020 SW Fourth Avenue, Suite 400 Portland, Oregon 97201

Subject:

Work Plan

Additional Monitoring Well Installation

Risk-Based Corrective Action Plan Preparation

Former Molalla Kwik Gas 305 West Main Street Molalla, Oregon

DEQ File No. 03-05-0461

Dear Mr. Hood:

Environmental Compliance Northwest, Inc., (ECN) has prepared this work plan to conduct additional site assessment activities and prepare a risk-based corrective action plan (RBCAP) for the subject site. This work plan addresses the Oregon Department of Environmental Quality's (DEQ's) request for further site activities addressed in letter dated 25-October-2010. Following is a brief description of site activities previously conducted and the proposed scope of services to meet the project objectives.

BACKGROUND

The following background information was obtained from DEQ files, verbal discussions with Powell Distributing Company (Powell) personnel, and activities observed and conducted by ECN. The facility operated since at least 1977 until 2005 and consisted of a retail fueling and automotive repair facility. The former UST system consisted of three gasoline USTs and one diesel UST, located in the northwest corner of the site and one fuel dispenser island, located in the southern portion of the site (Figure 1). In April 2005, an apparent leak was detected in the underground product piping. A portion of the piping was uncovered and several small holes were observed in the piping.

In March 2005, ECN conducted initial site assessment activities consisting of drilling two hand auger borings adjacent to the fuel product piping. Subsurface soil sampling indicated the

presence of petroleum hydrocarbon impact to soil in to the maximum explored depth of 8.5 feet below ground surface (bgs).

Also in March 2005, ECN conducted site assessment activities, including drilling a total of nine soil borings. Seven borings were completed adjacent and in the vanity of the underground product piping trench. Two of the borings were completed adjacent to the former fuel island. Petroleum hydrocarbons were detected in soil samples collected from each boring, with the exception of the boring completed located near the northwest corner of the former service station building. Grab groundwater samples were collected from four of the borings. Petroleum hydrocarbons were detected in each grab groundwater sample collected.

Between September and October 2006, the UST system (consisting of four USTs and underground product piping) were decommissioned by removal. Two soil samples were collected from beneath each UST. In addition, one soil sample was collected from the south sidewall of the UST cavity and from beneath each of the three former fuel dispensers.

Petroleum hydrocarbons were not detected the soil samples collected from beneath the former USTs, with the exception of the southeastern portion of the former UST cavity, near the location where the product piping entered the cavity. Gasoline- and diesel-range hydrocarbons were detected in the soil samples collected from the former fuel dispensers.

A total of four monitoring wells (MW-1 through MW-4) were installed and two soil borings (B-101 and B-102) were completed in May 2007. The locations of the monitoring wells are shown on Figures 2 and 3. Borings B-101 and B-102 were drilled north and east of the existing building, respectively, to further define soil and groundwater impacts. Laboratory results indicated that the highest petroleum hydrocarbons were detected in the samples collected from MW-4, located adjacent to the former underground product piping. Lower petroleum hydrocarbon concentrations were detected in the other three monitoring wells, as well as in boring B-102.

Ongoing groundwater monitoring has been conducted at the site since the monitoring wells were installed. Petroleum hydrocarbons have not been detected in either MW-1 or MW-2 since at least the second quarter 2009 monitoring event.

PROPOSED SCOPE OF WORK

Based on the results of the site assessment activities in 2005 and 2007, as well as groundwater monitoring activities, and the above-referenced DEQ letter dated 25-October-2010, we propose

additional assessment activities consisting of installation of two additional groundwater monitoring wells at the site and preparation of an RBCAP.

Shallow groundwater flow at the site varies between west-southwest and southwest. Based on previous site assessment activities conducted onsite, the shallow water-bearing zone is anticipated to be encountered at depths ranging from approximately 8 to 13 feet bgs.

One monitoring well is proposed in the hydraulically up-gradient direction, north of the existing building, near the northern property boundary. The other monitoring well is proposed to be installed near the southern property boundary, southwest of the former fuel dispenser island. The proposed monitoring well locations are shown on Figure 1.

DRILLING AND SOIL SAMPLING

Prior to intrusive field activities, the Utility Notification Center will be contacted to locate underground utilities adjacent to the subject site.

Based on the anticipated drilling conditions, drilling will be conducted using hollow-stem auger drilling technology. Each well bore will be logged in the field by an Oregon-Registered Geologist. Soil will be sampled from a maximum of five-foot intervals during drilling. Olfactory and visual indications of impact will be observed and noted. The sample with the highest indication of impact from each boring will be submitted for laboratory analysis. If evidence of impact is not observed, the soil sample collected from approximately the soil/shallow groundwater interface will be analyzed. The soil samples will be placed in laboratory-supplied containers, labeled, stored in an ice-filled cooler, and transported to an analytical laboratory following chain-of-custody protocols.

The wells will be constructed of 2-inch diameter PVC and completed to a depth of approximately 20 to 25 feet below the ground surface (bgs), and screened from approximately 5 to the total depth the boring. Following installation, each well will be developed until relatively sediment-free.

The top of casing elevations of the newly installed monitoring wells will be surveyed relative to the existing monitoring well elevations.

GROUNDWATER MONITORING

Groundwater samples will be collected from each of the monitoring wells. Before sampling, water level measurements will be recorded, and the presence of light non-aqueous phase liquid (LNAPL) will be assessed. Each well will then be purged of groundwater to obtain a water sample that is representative of the groundwater in the shallow water-bearing zone. The monitoring wells will be purged using a bailer or a pump to avoid agitating the water or exposing it to air. Purging will continue until a minimum of three well casing volumes have been evacuated. The samples will be placed in an iced cooler and transported to an analytical laboratory following chain-of-custody protocols.

ANALYTICAL PROGRAM

Based on previously completed work at the site, soil samples will be analyzed for gasoline- and diesel-range hydrocarbons. Soil samples with detectable concentrations of gasoline will be analyzed for the DEQ RBDM volatile organic compounds (VOCs) contained in the September 2003 and 2009 RBDM guidance documents. The soil sample with the highest concentration of diesel will be additionally analyzed for polynuclear aromatic hydrocarbons (PAHs).

In accordance with DEQ requirements, each groundwater sample will be analyzed for gasolineand diesel-range hydrocarbons, as well as, DEQ RBDM VOCS. Samples with diesel concentrations of at least 500 micrograms per liter will also be analyzed for PAHs. Select samples will also be analyzed for dissolved lead.

INVESTIGATION DERIVED WASTE MANAGEMENT

Soil, decontamination rinsate, and purge water generated during investigation activities will be stored in drums onsite pending laboratory results. If analytical results indicate the presence of petroleum hydrocarbons, soil will be transported to an appropriate landfill for disposal. Purged water from sampling and decontamination rinsate will be transported to an approved facility for treatment and disposal.

RISK-BASED CORRECTIVE ACTION PLAN

Following receipt of the analytical results, ECN will prepare a report presenting a discussion and findings of the additional monitoring well installation activities. The report will also include an RBCAP, consisting of previous site activities, beneficial land and water use surveys, utility

evaluation, conceptual site model, and proposed corrective action measures. Soil and groundwater contaminant plume maps will also be included in the RBCAP.

SCHEDULE

We are prepared to commence work as soon as practical after receiving the notice to proceed and consensus with DEQ regarding our technical approach.

CLOSING

We appreciate your assistance on this project. Should you require additional information or have questions regarding this project, please contact us at (503) 372-9760.

Sincerely,

Environmental Compliance Northwest, Inc.


John M. Day, R.G.

Principal Geologist

President

Attachment: Figure 1 – Groundwater Analytical Results, 3rd Quarter 2010 and Proposed Monitoring Well Locations

cc: Jason Powell-Powell Distributing



Molalla Kwik Gas File No: 03-05-0461 25 October 2010 Page 2 of 2

Please provide a work plan for additional investigation by **22 November 2010**. If you have any questions, please call me at (503) 229-5617.

Respectfully,

Robert A. Hood, Jr.

UST Cleanup Specialist

cc: John Day

Environmental Compliance

Northwest

PO Box 230163

Portland, OR 97281

(rah:RAH)





Department of Environmental Quality

Northwest Region Portland Office 2020 SW 4th Avenue, Suite 400 Portland, OR 97201-4987 (503) 229-5263

Fax: (503) 229-6945 TTY: (503) 229-5471

25 October 2010

JASON POWELL POWELL DISTRIBUTING PO BOX 17160 PORTLAND OR 97217

Re:

Molalla Kwik Gas File No. 03-05-0461

Dear Mr. Powell:

The Department of Environmental Quality (DEQ) has completed review of the report submitted by Environmental Compliance Northwest (ECN), dated 14 October 2010, regarding the underground storage tank cleanup at 307 South Main Street in Molalla, Oregon. In the report ENC provides two conclusions, which are as follows: 1) the extent of petroleum contamination has been determined and 2) discuss possible passive remediation in the vicinity of monitoring well MW-4.

On item 1), groundwater results appear to show that while petroleum concentrations at the northwest, west, and south boundaries are not significantly elevated, the full extent has not been determined. With that, please provide soil and groundwater plume maps and provide a work plan for additional investigation to complete delineation.

On item 2), DEQ requests that a more complete risk evaluation of data collected thus far be completed prior to determining the need for remediation. This evaluation should include beneficial land and water use determinations (including actual zoning documentation for the land use evaluation).

Other: As discussed with ECN, the quarterly reports from groundwater monitoring have not been submitted and are overdue. Please submit these reports **as soon as possible**. Some of the missing information, particularly groundwater flow direction trends, will need to be evaluated in determining additional boring locations (which DEQ should have that information for work plan evaluation).



ENVIRONMENTAL COMPLIANCE NORTHWEST PO BOX 230163 (503) 273 0700 Pi

PORTLAND, OR 97281

(503) 213-9980 Fax

TRANSMITTAL

Date: October 14, 2010

File: 05-106

TO:

Mr. Rob Hood Oregon DEQ, NW Region 2020 SW Fourth Avenue, Suite 400 Portland, OR 97201

Subject

Additional Site Assessment and Monitoring Well Installation Report Former Molalla Kwik Gas 305 West Main Street Molalla, Oregon

DEQ LUST File No.: 03-05-461

We are sending the following:

One copy of the above-referenced report and summary of groundwater analytical results.

Remarks:

If you have any questions, please contact our office at (503) 372-9760. Thank you.

By:

John M. Day, R.G. Principal Geologist

President

DEPT OF ENVIRONMENTAL QUALITY RECEIVED

NORTHWEST REGION

TABLE 1 Groundwater Analytical Results - TPH-Dx, TPH-G, RBDM VOCs, and Dissolved Lead Former Kwik Gas Station 305 West Main Street Molalla, Oregon ECN Project No. 05-106



Well I.D.	Date of Sampling	Casing Elevation (Feet)	Depth to Water (Feet)	Groundwater Elevation (Feet)	Change in Elevation (Feet)	TPH- Diesel	Dx [1] Lube Oil	TPH-G [2]	B [3]	T [3]	E [3]	X [3]	1,2,4-TMB [3]	EDB [3]	EDC [3]	1,3,5-TMB [3]	IPB [3]	MTBE [3]	NPB [3]	Naph- thalene [3]	Dissolved Lead [4]	LAB
MVV-1	6/5/2007	94.77		80.95		247	440	604	40.5	7.40	54.0			ND 4 65							-	
1010 0-1	3/30/2008	94.77	13.82 8.06	86.71	5.76	247 ND<245	116 ND<491	624 ND<100	40.5 ND<0.300	7.16 ND<1.00	51.2 ND<1.00	67.4 ND<1.00	9.34 ND<1.00	ND<1.00 ND<1.00	ND<1.00 ND<1.00	5.98	2.95	ND<1.00	5.04	ND<1.00		SA
	9/28/2008	94.77	17.41	77.36	-9.35	ND<243	ND<487	ND<100	ND<0.300		ND<0.500	ND<1.00	ND~1.00	ND<1.00	ND<1.00	ND<1.00	ND<1.00	ND<1.00	ND<1.00	ND<1.00		SA
	3/26/2009	94.77	9.54	85.23	7.87	ND<238	ND<476	ND<100	ND<0.300		ND<0.500	ND<1.50										SA SA
	6/30/2009	94.77	14.43	80.34	-4.89	ND<86.3	ND<216		0.910	ND<1.00		ND<3.00	ND<1.00	ND<1.00	ND<1.00	ND<1.00	ND<1.00	ND<1.00	ND<1.00	ND<1.00		SA
	9/29/2009	94.77	20.13	74.64	-5.7	ND<249	ND<498	ND<100			ND<0.500	ND<1.50		1415-1.00	142-1.00	140<1.00	140<1.00	ND<1.00	145-1.00	1415<1.00		SA
	12/26/2009	94.77	10.54	84.23	9.59	ND<243	ND<487	ND<100	ND<0.300		ND<0.500	ND<1.50										SA
	3/30/2010	94.77	8.74	86.03	1.8	ND<77.1	ND<193	ND<100	ND<0.300	ND<1.00		ND<3.00	ND<1.00	ND<1.00	ND<1.00	ND<1.00	ND<1.00	ND<1.00	ND<1.00	ND<1.00		SA
	6/30/2010	94.77	12.83	81.94	-4.09	ND<76.1	ND<190	ND<100			ND<0.500	ND<1.50										SA
	9/28/2010	94.77	16.38	78.39	-3.55	ND<82.6	ND<210	ND<100			ND<0.500	ND<1.50										SA
MW-2	6/5/2007	93.73	9.36	84.37		237	ND<100	ND<100	ND<0.300	ND<0.500	ND<0.500	ND<1.50										SA
	3/30/2008	93.73	3.35	90.38	6.01	ND<248	ND<495	ND<100	ND<0.300	ND<1.00	ND<1.00	ND<1.00	ND<1.00	ND<1.00	ND<1.00	ND<1.00	ND<1.00	ND<1.00	ND<1.00	ND<1.00		SA
	9/28/2008	93.73	11.10	82.63	-7.75	ND<242	ND<483	ND<100	ND<0.300	ND<0.500	ND<0.500	ND<1.50						***				SA
	3/26/2009	93.73	3.50	90.23	7.6	ND<236	ND<473	ND<100			ND<0.500	ND<1.50							***		*****	SA
	6/30/2009	93.73	9.36	84.37	-5.86	ND<82.5	ND<206		ND<0.300		ND<1.00	ND<3.00	ND<1.00	ND<1.00	ND<1.00	ND<1.00	ND<1.00	ND<1.00	ND<1.00	ND<1.00		SA
	9/29/2009	93.73	14.09	79.64	-4.73	ND<485	ND<971	ND<100	ND<0.300	ND<0.500	ND<0.500	ND<1.50										SA
	12/26/2009	93.73	4.03	89.70	10.06	ND<275	ND<552	ND<100	ND<0.300	ND<0.500	ND<0.500	ND<1.50										SA
	3/30/2010	93.73	3.42	90.31	0.61	ND<77.8	ND<195	ND<100	ND<0.300	ND<1.00		ND<3.00	ND<1.00	ND<1.00	ND<1.00	ND<1.00	ND<1.00	ND<1.00	ND<1.00	ND<1.00	***	SA
	6/30/2010	93.73	8.12	85.61	-4.7	ND<76.6	ND<192	ND<100			ND<0.500	ND<1.50										SA
	9/28/2010	93.73	9.23	84.50	-1.11	ND<78.7	ND<197	ND<100	ND<0.300	ND<0.500	ND<0.500	ND<1.50										SA
MW-3	6/5/2007	93.44	6.65	86.79		ND<49.9	ND<49.9	363	ND<0.300	0.84	2.04	ND<1.50										SA
	3/30/2008	93.44	4.31	89.13	2.34	269	ND<485	589	ND<0.300	ND<1.00	ND<1.00	ND<3.00	ND<1.00	ND<1.00	ND<1.00	ND<1.00	ND<1.00	ND<1.00	ND<1.00	ND<1.00		SA
	9/28/2008	93.44	6.46	86.98	-2.15	350	ND<541	787	ND<0.300	ND<1.00	ND<1.00	ND<3.00	ND<1.00	ND<1.00	ND<1.00	ND<1.00	1.00	ND<1.00	ND<1.00	ND<1.00	0.65	SA
	3/26/2009	93.44	4.62	88.82	1.84	0.277	ND<478	429	ND<0.300	ND<1.00	ND<1.00	ND<3.00	ND<1.00	ND<1.00	ND<1.00	ND<1.00	ND<1.00	ND<1.00	ND<1.00	ND<1.00	1.1	SA
	6/30/2009	93.44	6.79	86.65	-2.17	194	ND<203		ND<0.300	ND<1.00	ND<1.00	ND<3.00	ND<1.00	ND<1.00	ND<1.00	ND<1.00	1.21	ND<1.00	ND<1.00	ND<1.00	1.1	SA
	9/29/2009	93.44	8.96	84.48	-2.17	275	ND<482	631	ND<0.300	ND<1.00	ND<1.00	ND<3.00	ND<1.00	ND<1.00	ND<1.00	ND<1.00	1.26	ND<1.00	ND<1.00	ND<1.00	1.8	SA
	12/26/2009	93.44	4.39	89.05	4.57	336	ND<513	245	ND<0.300	ND<1.00	ND<1.00	ND<3.00	ND<1.00	ND<1.00	ND<1.00	ND<1.00	1.26	ND<1.00	ND<1.00	ND<1.00	0.96	SA
	3/30/2010	93.44	4.09	89.35	0.3	216	235	477	ND<0.300	ND<1.00	ND<1.00	ND<3.00	ND<1.00	ND<1.00	ND<1.00	ND<1.00	2.58	ND<1.00	ND<1.00	1.48		SA
	6/30/2010 9/28/2010	93.44 93.44	6.31 5.71	87.13 87.73	-2.22 0.6	291 257	215 ND<193	749 338	1.26 ND<0.300	ND<1.00 ND<1.00	1.70 ND<1.00	ND<3.00 ND<3.00	ND<1.00 ND<1.00	ND<1.00 ND<1.00	ND<1.00 ND<1.00	ND<1.00 ND<1.00	ND<1.00 1.01	ND<1.00 ND<1.00	ND<1.00 ND<1.00	ND<1.00 ND<1.00		SA SA
MW-4	6/5/2007	94.10	7 19	96.04		2.000	2 500	7 270	200	E 07												
101 A A	3/30/2008	94.10	7.16 4.29	86.94	2.07	2,060	3,500	7,370	326	5.97	216	336.2	239	ND<1.00	ND<1.00	55	34.4	6.92	66.2	55.6	14	SA
	9/28/2008	94.10	7.69	89.81 86.41	2.87	2,050	ND<489	15,900	985	8.93	397	343.0	386	ND<1.00	ND<1.00	43.4	92.2	11.3	261	150	2.5	SA
	3/26/2009	94.10	4.54	89.56	-3.4 3.15	2,070	665	14,000	979	9.74	743	167.8	332	ND<1.00	ND<1.00	88.3	125	ND<1.00	460	766	0.34	SA
	6/30/2009	94.10	7.65	86.45		1,700	0.893	8,010	480	4.49	356	91.4	125	ND<1.00	ND<1.00	23.7	87.6	1.80	185	119	0.82 DE	SA
	9/29/2009	94.10	12.75	81.35	-3.11 -5.1	1,460 2,760	310 805	13 300	682 925	7.28	769	248.2	594	ND<1.00	ND<1.00	76.7	133	2.62	438	347	1.4	SAN
	12/26/2009	94.10	4.36	89.74	8.39	2,780	1,020	13,300	397	7.07 4.84	889 435	30.00	30.4	ND<1.00	ND<1.00	34.3	115	7.16	395	540	1.5	SA SA
	3/30/2010	94.10	4.55	89.55	-0.19	1,094	532	21,100 12,200	594	5.31	435 634	361.2 330.9	451		ND<1.00	25.5	114	1.43	245	509	ND 0.10	
	6/30/2010	94.10	6.49	87.61	-1.94	2,350	585	11,600	705	5.27	419	396.2	530	ND<1.00	ND<1.00	60.4	128	ND<1.00	515	274	1.8	DEAT !
	9/28/2010	94.10	7.12	86.98	-0.63	1,410	244	18,100	470	7.34	776	432.2	115 65.0		ND<1.00 ND<1.00	35.6 665	117 153	2.17 2.80	368 554	136 756	2.4	SA]
k-Based Concen	ntrations [5]																					
olatilization to Ou						>\$	NE	>\$	14,000	>\$	41,000	>\$	>8	960	9,500	6,800	>8	1,000,000	NE	16,000	NV N	ORTHWE
cipational) apor Intrusion Int	nto Buildings					>S	NE	>\$	2,800	>8	7,400	>\$	>8	690	3,800	41,000	>\$	590,000	NE	10,000	NV	
cupational) froundwater in ar	n Eveavation																					
	in Excavation Excavation Worker	r)				>\$	NE	13,000	1,700	210,000	4,400	23,000	1,700	28	630	1,400	>S	62,000	NE	500	>\$	

ABBREVIATIONS: B: Benzene

T: Toluene E: Ethylbenzene

X: Total Xylenes

MTBE: Metyl tertiary-butyl ether
ND: Not detected at or above the indicated laboratory reporting limit
NE: Not established by DEQ

>S: The groundwater RBC exceeds the solubility limit.

NV: This chemical is considered "nonvolatile" for purposes of the exposure calculations

Results are in micrograms per liter (µg/L) (1) Nortwest Method NWTPH-Dx

Northwest Method NWTPH-Gx

EPA Method 8021B 0r 8260B

(1) (2) (3) (4) (5) SA EPA Method 6011

Oregon Department of Environmental Quality (DEQ) Generic Risk Based Concentrations (RBCs)

Specialty Analytical

Exceeds the RBC





Polynuclear Aromatic [1		Acenaphthene	Acenapthylene	Anthracene	Benz(a)anthracene	Benzo(a)pyrene	nzo(b)fluoranthene	Benzo(g,h,l)perylene	nzo(k)fluoranthene	Chrysene	enz(a,h)anthraœne	Fluoroanthene	Fluorene	no(1,2,3-cd)pyrene	Naphthalene	Phenanthrene	Pyrene	LAB
Sample Identification	Sample Date				ă		Bei	Be	Ber		Dibe			Indeno(1,				
MW-1	6/5/2007	ND<0.0503	ND<0.0503	ND<0.0503	ND<0.0503	ND<0.0503	ND<0.0503	ND<0.0503	ND<0.0503	ND<0.0503	ND<0.0503	ND<0.0503	ND<0.0503	ND<0.0503	2.81	ND<0.0503	ND<0.0503	SA
MW-2	6/5/2007	ND<0.0498	ND<0.0498	ND<0.0498	ND<0.0498	ND<0.0498	ND<0.0498	ND<0.0498	ND<0.0498	ND<0.0498	ND<0.0498	ND<0.0498	ND<0.0498	ND<0.0498	ND<0.0498	ND<0.0498	ND<0.0498	SA
,MW-3	6/5/2007	ND<0.0495	ND<0.0495	ND<0.0495	ND<0.0495	ND<0.0495	ND<0.0495	ND<0.0495	ND<0.0495	ND<0.0495	ND<0.0495	ND<0.0495	0.0792	ND<0.0495	0.287	ND<0.0495	ND<0.0495	SA
	3/26/2009	ND<0.0479	ND<0.0479	ND<0.0479	ND<0.0479	ND<0.0479	ND<0.0479	ND<0.0479	ND<0.0479	ND<0.0479	ND<0.0479	ND<0.0479	ND<0.0479	ND<0.0479	0.211	ND<0.0479	ND<0.0479	SA
	6/30/2009	0.0572	ND<0.0477	ND<0.0477	ND<0.0477	ND<0.0477	ND<0.0477	ND<0.0477	ND<0.0477	ND<0.0477	ND<0.0477	ND<0.0477	0.124	ND<0.0477	0.734	ND<0.0477	ND<0.0477	SA
	6/30/2010	0.0576	ND<0.0480	ND<0.0480	ND<0.0480	ND<0.0480	ND<0.0480	ND<0.0480	ND<0.0480	ND<0.0480	ND<0.0480	ND<0.0480	0.182	ND<0.0480	0.480	ND<0.0480	ND<0.0480	SA
MW-4	6/5/2007	0.115	ND<0.0525	ND<0.0525	ND<0.0525	ND<0.0525	ND<0.0525	ND<0.0525	ND<0.0525	ND<0.0525	ND<0.0525	ND<0.0525	0.136	ND<0.0525	83.4	0.0630	ND<0.0525	SA
	3/30/2008	0.231	ND<0.0482	ND<0.0482	ND<0.0482	ND<0.0482	ND<0.0482	ND<0.0482	ND<0.0482	ND<0.0482	ND<0.0482	0.0868	0.482	ND<0.0482	115	0.415	0.0868	SA
	9/28/2008	0.203	0.0676	ND< 0.0483	ND< 0.0483	ND< 0.0483	ND< 0.0483	ND< 0.0483	ND< 0.0483	ND< 0.0483	ND< 0.0483	0.126	0.261	ND< 0.0483	94.7	0.300	0.126	SA
	3/26/2009	0.138	ND<0.0429	ND<0.0429	ND<0.0429	ND<0.0429	ND<0.0429	ND<0.0429	ND<0.0429	ND<0.0429	ND<0.0429	0.138	ND<0.0429	ND<0.0429	56.9	0.0984	0.0591	SA
	6/30/2009	0.191	0.0765	ND<0.0478	ND<0.0478	ND<0.0478	ND<0.0478	ND<0.0478	ND<0.0478	ND<0.0478	ND<0.0478	ND<0.0478	0.229	ND<0.0478	179	0.143	0.0478	SA
	9/29/2009	0.172	0.0858	ND<0.0477	ND<0.0477	ND<0.0477	ND<0.0477	ND<0.0477	ND<0.0477	ND<0.0477	ND<0.0477	ND<0.0477	0.210	ND<0.0477	145	0.0953	ND<0.0477	SA
	12/26/2009	0.282	0.126	ND<0.0523	ND<0.0523	ND<0.0523	ND<0.0523	ND<0.0523	ND<0.0523	ND<0.0523	ND<0.0523	ND<0.0523	0.366	ND<0.0523	200	0.209	ND<0.0523	SA
	3/30/2010	0.209	0.112	ND<0.0500	ND<0.0500	ND<0.0500	ND<0.0500	ND<0.0500	ND<0.0500	ND<0.0500	ND<0.0500	ND<0.0500	0.316	ND<0.0500	150	0.179	ND<0.0500	SA
	6/30/2010	0.165	0.0778	ND<0.0486	ND<0.0486	ND<0.0486	ND<0.0486	ND<0.0486	ND<0.0486	ND<0.0486	ND<0.0486	ND<0.0486	0.223	ND<0.0486	30.9	0.0973	ND<0.0486	SA
	9/28/2010	0.265	0.128	ND<0.0491	ND<0.0491	ND<0.0491	ND<0.0491	ND<0.0491	ND<0.0491	ND<0.0491	ND<0.0491	ND<0.0491	0.402	ND<0.0491	244	0.275	ND<0.0491	SA
isk-Based Concentration Occ. Volatilization to Cocc. Vapor Intrusion In Groundwater in an Exc Construction and Exce	Outdoor Air nto buidlings cavation	>S >S >S	NE NE NE	>S >S >S	NV NV 9.1	NV NV 0.53	NV NV >S	NE NE NE	NV NV >S	NV NV >S	NV NV 0.21	NV NV >S	>S >S >S	NV NV >S	16,000 10,000 500	NE NE NE	NV NV >S	

ND not detected at or above the indicated laboratory reporting limit SA Specialty Analytical

μg/L Micrograms per Liter

Oregon Department of Environmental Quality (DEQ) Generic Risk Based Concentrations (RBCs) (DEQ, 2009).

NE NV >S

A Risk-Based Concentration has not been determined for this constituent

This chemical is considered "nonvolatile" for purposes of the exposure calculation

This groundwater RBC exceeds the solubility limit. Groundwater concentrations in excess of S indicate that free product may be present. If solubility is not listed, data was not listed in Appendix D of the DEQ RBDM guidance document (DEQ, 2009).

From:

HOOD Robert

Sent:

Wednesday, October 13, 2010 10:17 AM

To:

'John Day'

Subject:

Molalla Kwik Gas, 03-05-0461

Importance:

High

John:

As noted yesterday, these reports are well overdue from when you promised even just last month (approximately 5 weeks ago). I am not sure why I am not receiving any communication back (unless for some reason you are incapacitated with things other than business-related). As I've noted, these reports should have been completed and submitted some time ago (2007 for the investigation report and all the quarterly reports since). As mentioned in my voice message yesterday, they should be submitted by today.

Respectfully,

Rob

Rob Hood Project Manager, UST Cleanup Program Oregon Dept. of Environmental Quality 2020 SW 4th Ave., Ste. 400 Portland, OR 97201-4987

Ph: (503) 229-5617 Fax: (503) 229-6945

email: hood.robert@deq.state.or.us
website: www.oregon.gov/deq

UST CLEANUP TELEPHONE USE REPORT

CALL FROM/TO:	John Day	DATE: 10/12/2010
WITH:	Consultant	TIME: 900
TELEPHONE NO:	(503) 372 - 9760	
REGARDING:	Molalla Quik Ger	
FILE NO:	03-05-0467	
SUMMARY OF CAL	<u>T</u>	
Left Vorce	nessage. Aill der	nd have reports.
Town it	Appears No Work	has been
amplete	A. Reports ned to	1 0 1
today or to	worrow or I will	Call discus
GNANTEN	WI Affect Him I'm	Color
	And the second s	
	. 0	
	Staff Si	Consture Constant



Department of Environmental Quality

Northwest Region Portland Office 2020 SW 4th Avenue, Suite 400 Portland, OR 97201-4987

(503) 229-5263

Fax: (503) 229-6945 TTY: (503) 229-5471

17 August 2010

JASON POWELL POWELL DISTRIBUTING PO BOX 17160 PORTLAND OR 97217

Re:

Molalla Kwik Gas

File No. 03-05-0461

Dear Mr. Powell:

Please refer to the attached message to your consultant John Day regarding completion of investigation work at the underground storage tank (UST) cleanup at 307 South Main Street in Molalla, Oregon. As noted, all reports should be submitted by **27 August 2010**. If you have any questions, please call me at (503) 229-5617.

Respectfully,

Robert A. Hood, Jr.

UST Cleanup Specialist

enclosure: 16 August 2010 electronic message to John Day.

cc:

John Day

Environmental Compliance

Northwest

PO Box 230163

Portland, OR 97281

(rah:RAH)

From:

HOOD Robert

Sent:

Monday, August 16, 2010 3:45 PM

To:

John Day

Subject:

Molalla Kwik Gas, File 03-05-0461

John:

I received your voice message last week that you are out until the 18th. Not only will I need the investigation report from a few years ago (2007), I need separate monitoring reports for each quarterly event since then. Please submit all reports by **27 August 2010**. This notice is being sent to Mr. Powell to ensure as the responsible party he has been notified.

Rob

Rob Hood Project Manager, UST Cleanup Program Oregon Dept. of Environmental Quality 2020 SW 4th Ave., Ste. 400 Portland, OR 97201-4987 Ph: (503) 229-5617

Ph: (503) 229-5617 Fax: (503) 229-6945

email: hood.robert@deq.state.or.us
website: www.oregon.gov/deq

UST CLEANUP TELEPHONE USE REPORT

CALL FROM/TO:	John Day	DATE: 10/30/09
WITH:	Consultant	TIME: New
TELEPHONE NO:	()	
REGARDING:	Regard Ribmidel	
FILE NO:	C3 -OT -046]	
SUMMARY OF CAL	<u>T</u>	
The motous	it field work was comple	ted (per our Just
	ns) that some Figures /ch	
	He Sharted Report, thin	
	. Nonefleless se regrest	
Er Report	Filmshol to 30 Nove	mber Granted.
	cuted 4 MWs were mo	
	had been completed :	
	I also that separate G	
and begin	red Sevesich event a.	Not high our in
	iswe Report. (2 juis un)	
	ul our repenabely with	
www inch	ell Report.	()
	Autor Staff Si	gnature





Department of Environmental Quality

Northwest Region Portland Office 2020 SW 4th Avenue, Suite 400 Portland, OR 97201-4987 (503) 229-5263

Fax: (503) 229-6945 TTY: (503) 229-5471

21 October 2009

LEE POWELL JR POWELL DISTRIBUTING PO BOX 17160 PORTLAND OR 97217

Re:

Molalla Kwik Gas

File No. 03-05-0461

Dear Mr. Powell:

The Department of Environmental Quality (DEQ) has not received any information regarding completion of investigation work at the underground storage tank (UST) cleanup at 305 West Main Street in Molalla, Oregon. In March 2008, your consultant, John Day indicated that a report from investigation activities was in draft. Please submit the report by **30 October 2009**. If you have any questions, please call me at (503) 229-5617.

Respectfully,

Robert A. Hood, Jr.

UST Cleanup Specialist

cc:

John Day

Environmental Compliance

Northwest

PO Box 230163

Portland, OR 97281

Jason Powell

Powell Distribution Company

9125 N. Burrage

Portland, OR 97217

(rah:RAH)

UST CLEANUP TELEPHONE USE REPORT

CALL FROM TO:	John Day DATE: 24 March 2008
WITH:	Consider for Powell TIME: 1545
TELEPHONE NO:	15031 <u>272 - 9760</u>
REGARDING:	Reporting
FILE NO:	03 -05 -046)
SUMMARY OF CAL	<u></u>
John med	report to Had someone else worky on the
Report de 1	este lest so signified ver delayed.
	responder it can be completed in mid-April
so we of	red on the week of the 14th.
	Staff Signature

From:

HOOD Robert

Sent:

Tuesday, May 22, 2007 9:56 AM

To:

'John Day'

Subject:

Molalla Kwik Gas Discussion, 03-05-0461

John:

From this morning and the follow-up voice message I left you.

I mapped the locations on a clean site plan, will fax over. One adjustment I could see is moving PB-1 to a location between PB-1 and the MW (high concentration). It seems that would tighten it up better.

From the temporary borings collect both soil and grab groundwater samples. For the soil samples, probably analyze a sample with the highest PID reading or at the soil/water interface (Gx, Dx, and RBDM VOCs./PAHs, if necessary). The water samples should be for Gx, Dx, appropriate RBDM VOCs, and PAHs if Dx is greater than 88 ppb). Since groundwater use has not been ruled out yet, please make sure detection or method reporting limits meet ingestion and inhalation from tap water risk-based screening levels.

Let me know if you have comments/questions. Thanks.

Rob

Robert A. Hood, Jr. Natural Resource Specialist 4 DEQ, Northwest Region 2020 SW 4th Ave, Ste. 400 Portland, OR 97201-4987

Phone: 503.229.5617 Fax: 503.229.6945

FAX COVER SHEET


TO: John Day
OFFICE
PHONE:
FAX: 503 213 9980
DATE:

FROM: Rob Hood
OFFICE:
PHONE: 229 5617
RETURN FAX: (503) 229-6945
Number of pages (including this cover sheet):
Comments: Also, see my email to you.
Also, see my email to you.



State of Oregon Department of Environmental Quality

Northwest Region Office 2020 SW 4th Avenue Suite 400 Portland, OR 97201 Phone: 503 229-5263



FAX COVER SHEET

TO: John Day	
OFFICE	State Depa
PHONE:	Envir Quali
FAX: 503 213 9980	North Office
DATE: 21 May 2007	2020 S Suite 4
	Portlan Phone:

FROM: Rob Hod2	



OFFICE:

PHONE: Z29 56 17

RETURN FAX: (503) 229-6945

Number of pages (including this cover sheet): 3

Number of pages (including this cover sheet): 3

Comments:

Per my voice message let's discuss the intended approach of the additional burns of monitoring well locations.

Rob.

X Berry MW COMMERCIAL BUSINESS UST CAVITY -MW (sowed COMMERCIAL BUSINESS Borry. STATION BUILDING APPROXIMATE PROPERTY LINE DISPENSER ISLA SIDEWALK MAIN STREET

Malalla Kuik Gar LEGEND UST Underground Storage Tank Former Underground Storage Tank Former Underground Product Piping Trench Borny (mottempt to) FORMER -SERVICE In attempt to define extent WW (10' 20' 40' 1"=20" Scale in Feet SITE PLAN **E**NVIRONMENTAL COMPLIANCE KWIK GAS 305 WEST MAIN STREET NORTHWEST, INC. MOLALLA, OREGON

Project No. 05-106

FIGURE 2

Environmental Compliance Northwest

May 16, 2007 Project No. 05-106

Mr. Rob Hood Oregon Department of Environmental Quality Northwest Region 2020 SW Fourth Avenue, Suite 400 Portland, Oregon 97201

Subject:

Work Plan

Additional Site Assessment and Monitoring Well Installation Former Molalla Kwik Gas 305 West Main Street Molalla, Oregon

DEO File No. 03-05-0461

DEPT OF ENVIRONMENTAL QUALITY RECEIVED

MAY 1 7 2007

NORTHWEST REGION

Dear Mr. Hood:

Environmental Compliance Northwest, Inc., (ECNW) has prepared this work plan to conduct additional site assessment and groundwater monitoring well installation activities at the subject site. This work plan addresses the Oregon Department of Environmental Quality's (DEQ's) request to further characterize impacts to soil and groundwater at the site associated with a historic petroleum hydrocarbon release (letter dated May 1, 2007). Following is a brief description of site activities previously conducted and the proposed scope of services to meet the project objectives.

BACKGROUND

The following background information was obtained from DEQ files, verbal discussions with Powell Distributing Company (Powell) personnel, and previous site activities. The facility has operated since at least 1977 and consisted of a retail fueling and automotive repair facility. The UST system consisted of four USTs (three gasoline and one diesel), located in the northwest corner of the site and one fuel dispenser island, located in the southern portion of the site (Figure 2).

In April 2005, an apparent leak was detected in the underground product piping. A portion of the piping was uncovered and several small holes were observed in the piping.

ECNW conducted site assessment activities between March and April 2005. Initial activities included drilling soil borings adjacent to underground product piping using hand auger

equipment. Based on results of the initial sampling, the apparent most highly impacted soil associated with the product piping leak was excavated and additional soil samples were analyzed. Laboratory results indicated that residual gasoline- and diesel-range hydrocarbons remain beneath the site.

In April 2005, a total of nine soil borings were drilled to further assess petroleum hydrocarbon impact beneath the site. Seven borings were advanced in the vicinity of the underground product piping trench and two borings were advanced in the southern portion of the site, near the fuel dispenser island. Soil samples from each boring and grab groundwater samples from four borings were collected and analyzed for petroleum hydrocarbons. Analytical results of several soil and grab groundwater samples indicated that residual gasoline- and diesel-range hydrocarbons are present beneath the site, exceeding one or more preliminary DEQ risk-based decision making (RBDM) cleanup levels for the exposure pathways considered to be potentially complete at the site (ECNW, 2007).

In October 2006, the four USTs at the site were decommissioned by removal. A limited quantity of apparent petroleum hydrocarbon-impacted backfill material was encountered and excavated during decommissioning activities. Analytical results of soil samples collected from the excavation bottom, in the southeastern portion of the tank cavity, indicated relatively low concentrations of gasoline- and diesel-range hydrocarbons. Soil samples were also collected during UST decommissioning activities from beneath the three former fuel dispensers. Elevated diesel-range and relatively low gasoline-range hydrocarbons were detected in the soil samples collected from beneath the former fuel dispensers.

PROPOSED SCOPE OF WORK

Based on the results of the site assessment activities in 2005, UST decommissioning conducted in October 2006, and the above-referenced DEQ letter dated May 1, 2007, we propose additional assessment activities consisting of installation of a total of four groundwater monitoring wells at the site.

Based on information from DEQ files from an adjacent property (Buckaroo Ford), shallow groundwater in the site vicinity flows toward the west-northwest. In addition, based on previous site assessment activities conducted onsite, the shallow water-bearing zone is anticipated to be encountered at depths ranging from approximately 8 to 13 feet bgs.

One monitoring well is proposed in the southern portion of the site, near the east end of the former fuel dispenser island (hydraulically up-gradient). The remaining three monitoring wells

are proposed in the west and northwest portions of the site, hydraulically down-gradient and cross-gradient of the former onsite source(s). The proposed monitoring well locations are shown on Figure 2.

DRILLING AND SOIL SAMPLING

Prior to intrusive field activities, the Utility Notification Center will be contacted to locate underground utilities adjacent to the subject site.

Based on the anticipated drilling conditions, drilling will be conducted using hollow-stem auger drilling technology. Each well bore will be logged in the field by an Oregon-Registered Geologist. Soil will be continuously sampled during drilling. Olfactory and visual indications of impact will be observed and noted. The sample with the highest indication of impact from each boring will be submitted for laboratory analysis. If evidence of impact is not observed, the soil sample collected from approximately the soil/shallow groundwater interface will be analyzed. The soil samples will be placed in laboratory-supplied containers, labeled, stored in an ice-filled cooler, and transported to an analytical laboratory following chain-of-custody protocols.

The wells will be constructed of 2-inch diameter PVC and completed to a depth of approximately 20 feet below the ground surface (bgs), and screened from approximately 5 to 20 feet bgs. Following installation, each well will be developed until relatively sediment-free.

If drilling refusal is encountered, field activities will be stopped and use of alternative drilling technologies will be considered. The top of casing elevations of the newly installed monitoring wells will be surveyed relative to an arbitrary benchmark.

GROUNDWATER MONITORING

Groundwater samples will be collected from each of the monitoring wells. Before sampling, water level measurements will be recorded, and the presence of light non-aqueous phase liquid (LNAPL) will be assessed. If LNAPL is not present, each well will then be purged of groundwater to obtain a water sample that is representative of the groundwater in the shallow water-bearing zone. The monitoring wells will be purged using a bailer or a pump to avoid agitating the water or exposing it to air. Purging will continue until a minimum of three well casing volumes have been evacuated. The samples will be placed in an iced cooler and transported to an analytical laboratory following chain-of-custody protocols.

ANALYTICAL PROGRAM

Based on previously completed work at the site, soil samples will be analyzed for gasoline- and diesel-range hydrocarbons. Soil samples with detectable concentrations of gasoline will be analyzed for the DEQ RBDM volatile organic compounds (VOCs) contained in the September 2003 RDBM guidance document. The soil sample with the highest concentration of diesel will be additionally analyzed for polynuclear aromatic hydrocarbons (PAHs).

In accordance with DEQ requirements, each groundwater sample will be analyzed for gasolineand diesel-range hydrocarbons and as well as benzene, toluene, ethlybenzene, and total xylenes (BTEX). The groundwater sample with the highest BTEX concentrations will be analyzed for DEQ RBDM VOCS. Samples with diesel concentrations of at least 500 micrograms per liter will also be analyzed for PAHs.

INVESTIGATION DERIVED WASTE MANAGEMENT

Soil, decontamination rinsate, and purge water generated during investigation activities will be stored in drums onsite pending laboratory results. If analytical results indicate the presence of petroleum hydrocarbons, soil will be transported to an appropriate landfill for disposal. Purged water from sampling and decontamination rinsate will be transported to an approved facility for treatment and disposal.

ADDITIONAL SITE ASSESSMENT REPORT

Following receipt of the analytical results, ECNW will prepare a report presenting the finding and conclusions of the additional site assessment. The report will include tabulated analytical results, site plan showing well locations, groundwater gradient and contaminant data maps, and boring logs with well construction details. The report will also include a preliminary risk-based evaluation of potentially complete exposure pathways. The report will be submitted within four weeks of receipt of the laboratory report.

SCHEDULE

We are prepared to commence work as soon as practical after receiving the notice to proceed. The field work has tentatively been scheduled for the last week of May 2007.

CLOSING

We appreciate your assistance on this project. Should you require additional information or have questions regarding this project, please contact us at (503) 372-9760.

Sincerely,

ENVIRONMENTAL COMPLIANCE NORTHWEST, INC.


John M. Day, R.G.

Senior Geologist/President

Attachments: Figure 1 – Vicinity Map

Figure 2 – Site Plan and Proposed Monitoring Well Locations

cc: Jason Powell-Powell Distributing




© 2007 MapQuest, Inc ; © 2007 Tele Atlas

VICINITY MAP

MOLALLA KWIK GAS 305 WEST MAIN STREET MOLALLA, OREGON

ECNW PROJ. No. 05-106

FIGURE 1





Department of Environmental Quality Northwest Region Portland Office

2020 SW 4th Avenue, Suite 400 Portland, OR 97201-4987

> (503) 229-5263 FAX (503) 229-6945 TTY (503) 229-5471

1 May 2007

LEE POWELL JR POWELL DISTRIBUTING PO BOX 17160 PORTLAND OR 97217

Re:

Molalla Kwik Gas

File No. 03-05-0461

Dear Mr. Powell:

The Department of Environmental Quality (DEQ) has reviewed the report entitled, *Site Assessment and UST Decommissioning Report*, dated 17 April 2007, regarding the underground storage tank (UST) cleanup at 305 West Main Street in Molalla, Oregon. DEQ has the following comments:

- -Please submit a work plan for proposed additional borings and monitoring wells and include work timelines. Please coordinate with me so I may consider a site visit.
- -Please show the excavation limits at the piping area.
- -Please identify which samples remain in-place compared to over-excavated soil.
- -Note the following on tabulation and figures:

S1-8.5', xylenes should be 113 parts per million (ppm).

T2-S-13.5', ethylbenzene should be 0.189 ppm, xylenes 0.0503 ppm PL-1-5', toluene should be 664 ppm (Figure 3 only).

Molalla Kwik Gas File No: 03-05-0461 1 May 2007 Page 2 of 2

Please provide the above-requested information by **25 May 2007**. If you have any questions, please call me at (503) 229-5617.

Respectfully,

Robert A. Hood, Jr.

UST Cleanup Specialist

cc: John Day

Environmental Compliance

Northwest

PO Box 230163

Portland, OR 97281

Jason Powell

Powell Distribution Company

9125 N. Burrage

Portland, OR 97217

(rah:RAH)

Environmental Compliance Northwest

TRANSMITTAL

Date: April 17, 2007

File: 05-106

TO:

Mr. Rob Hood Oregon DEQ, NW Region 2020 SW Fourth Avenue, Suite 400 Portland, OR 97201

Subject

Site Assessment and UST Decommissioning Report Molalla Kwik Gas 305 West Main Street Molalla, Oregon

DEQ LUST File No.: 03-05-461

We are sending the following:

One copy of the above-referenced report.

Remarks:

If you have any questions, please contact our office at (503) 372-9760. Thank you.

By:

John M. Day, R.G. Senior Geologist

President

DEPT OF ENVIRONMENTAL QUALITY

APR 2 0 2007

NORTHWEST REGION

HOOD Robert

From:

John Day [jday@dayenv.com]

Sent:

Monday, February 26, 2007 10:54 AM

To:

HOOD Robert

Subject:

RE: Molalla Qwik Gas, Leaking UST No: 03-05-0461

Rob, thanks for the email. I apologize for the delay. I am actually working on the report today. The finalized report will be to you within two weeks (no later than March 12, 2007), likely sooner.

Please call or email me if you have more questions.

Thanks, John Day

----Original Message----

From: HOOD Robert [mailto:HOOD.Robert@deq.state.or.us]

Sent: Monday, February 26, 2007 10:43 AM

To: Jday@dayenv.com

Subject: Molalla Qwik Gas, Leaking UST No: 03-05-0461

John: I have not received a report that was due 13 November 2006. What's your status?

Thanks.

Rob



From:

HOOD Robert

Sent:

Wednesday, October 11, 2006 3:47 PM

To:

'jday@dayenv.com'

Subject:

Molalla Kwik Gas Report Extension 03-05-0461

John: This is to confirm our conversation today. You indicated that site assessment work was completed prior to the decommissioning work, which occurred in the last couple of weeks. The decommissioning paper work will be submitted shortly (after receiving analytical results). Also, a more formal report will be submitted regarding the earlier site assessment work and decommissioning activities due by Monday 13 November 2006. Please inform Mr. Powell of the new timeline. If you have any questions or comments, let me know.

Rob

Robert A. Hood, Jr.
Natural Resource Specialist 4
DEQ, Northwest Region
2020 SW 4th Ave, Ste. 400
Portland, OR 97201-4987
Phone: 503.229.5617

Fax: 503.229.6945

FAX COVER SHEET

	- PC B ex 23016 Pertland 97781	
TO: John Day	jdy@dayenv. Co	n
OFFICE		
PHONE:		
FAX: 503 213 9980		
DATE: 10/11/06		
	· · · · · · · · · · · · · · · · · · ·	
***	•	
FROM: Reb Hood		
OFFICE:		
PHONE: 503 229 5617		
RETURN FAX: (503) 229-6945		
Number of pages (including this cover sheet): 2	• •	
Comments:		

Modalla kwik Gas.



2020 SW 4th Avenue Suite 400 Portland, OR 97201 Phone: 503 229-5263

U.S. Postal Service CERTIFIED MAIL RECEIPT

mestic Mail Only; No Insurance Coverage Pro



Article Sent To:

2 5975

F 0 F

П

FU E

6

Postage

Certified Fee

Return Receipt Fee (Endorsement Required

Restricted Delivery Fee (Endorsement Requirec Total Postage & Fees

POWELL DISTRIBUTING
P. O. BOX 17160

PORTLAND, OREGON 97217

E S

Name (Please Print Clearly) (To be completed by mailer)

Street, Apt. No.; or PO Box No.

City, State, ZIP+ 4

PS Form 3800, July 1999

See Reverse for Instructions

Certified Mail Provides:

- A mailing receipt
- A unique identifier for your mailpiece
- A signature upon delivery
- A record of delivery kept by the Postal Service for two years

Important Reminders:

- Certified Mail may ONLY be combined with First-Class Mail or Priority Mail.
- Certified Mail is not available for any class of international mail.
- NO INSURANCE COVERAGE IS PROVIDED with Certified Mail. For valuables, please consider Insured or Registered Mail.
- For an additional fee, a Return Receipt may be requested to provide proof of delivery. To obtain Return Receipt service, please complete and attach a Return Receipt (PS Form 3811) to the article and add applicable postage to cover the fee. Endorse mailpiece "Return Receipt Requested". To receive a fee waiver for a duplicate return receipt, a USPS postmark on your Certified Mail receipt is required.
- For an additional fee, delivery may be restricted to the addressee or addressee's authorized agent. Advise the clerk or mark the mailpiece with the endorsement "Restricted Delivery".
- If a postmark on the Certified Mail receipt is desired, please present the article at the post office for postmarking. If a postmark on the Certified Mail receipt is not needed, detach and affix label with postage and mail.

IMI

NT: Save this receipt and present it when making an



Department of Environmental Quality
Northwest Region Portland Office

2020 SW 4th Avenue, Suite 400

Portland, OR 97201-4987 (503) 229-5263

FAX (503) 229-6945 TTY (503) 229-5471

Certified Mail Return Receipt Requested 7099 3220 0000 9092 5975

2 October 2006

LEE POWELL JR POWELL DISTRIBUTING PO BOX 17160 PORTLAND OR 97217

Re:

Molalla Kwik Gas

File No. 03-05-0461

Dear Mr. Powell:

To date, your site assessment report has not been submitted to the Department of Environmental Quality as requested in a letter dated 24 January 2006. Please submit the report(s) by 11 October 2006. If you have any questions, please call me at (503) 229-5617.

Respectfully,

Robert A. Hood, Jr.

UST Cleanup Specialist

cc:

Kleinfelder, Inc.

15050 SW Koll Pkwy.

Beaverton, OR 97006-6028

(rah:RAH)



Department of Environmental Quality

Northwest Region Portland Office 2020 SW 4th Avenue, Suite 400 Portland, OR 97201-4987 (503) 229-5263 FAX (503) 229-6945 TTY (503) 229-5471

24 January 2006

LEE POWELL JR POWELL DISTRIBUTING PO BOX 17160 PORTLAND OR 97217

Re:

Molalla Kwik Gas

File No. 03-05-0461

Dear Mr. Powell:

I have been assigned project manager for your underground storage tank (UST) cleanup at 307 South Main in Molalla, Oregon. To date, a site assessment report has not been submitted to the Department of Environmental Quality. Please submit the report(s) by 3 February 2006.

If you have any questions, please call me at (503) 229-5617.

Respectfully,

Robert A. Hood, Jr.

UST Cleanup Specialist

cc:

John Day

Kleinfelder, Inc.

15050 SW Koll Pkwy.

Beaverton, OR 97006-6028

(rah:RAH)

03-05-0410

09/14/2005 14:40

50373

SEP 14 2005 15:17

5032155380

PAGE 01

Oregon Department of Environmental Quality GENERAL PERMIT REGISTORATION FORM AND

30-DAY NOTICE OF INTENT TO DECOMMISSION USTI OR COMPLETE A CHANGE-IN-SERVICE 1. FACILITY (Location of Tunks) (Please Print) 2. PERMITTEE (Please Print) Un knile GAS Now forell Distribution PENTLAND, 5R 97217 Address: 47038 Phose: NIA Phone: DEQ General Permit Operating Certificate Number: Work To Be Performed By: A STORE LINE Service Provider)

(Permittee, Tank Owner, Property Owner or Licensed Service Provider) License #

Phone: 503- 705-2926 THIS FORM MUST BE SUBMITTED BY UST PERMITTEE 30 DAYS REFORE START OF WORK YOU MUST CONTACT YOUR LOCAL DEQ REGICAL OFFICE 3-DAYS BEFORE STARTING ANY DECOMMISSIONING WORK. (Flore numbers are listed on Page 2)

Will tank removal or potential cleanup affect adjacent property or Removed Way property? Yes ______ No _______

Mobile Phone:

Date decommissioning is scheduled to begin: TAN I DEE CLOSURE OR CHANGE-IN-SERVICE? PRODUCT: GASOLIT. Z. DIRSEL, USED OU NO CHANGE OTRER? CLOSURE TANK IN TANK SIZE REMOVAL DEQ-UST SER VICE DN GALLONS PERMIT * TANK D

- If decommissioned tank(s) are to be replaced by next derground storage tanks you must submit a General Prints Registration Form to Install and Operate USTs for the new tenks 30 days before installing them.
- Submit a soil sampling plan to the DEQ regional office and raive plan approved prior to starting work if (1) to it is to be decommissioned in-place, (2) tank contents are the option of the plane approved prior to starting work if (1) to it is to be decommissioned in-place, (2) tank contents are the option of the plane approved prior to starting work if (1) to it is to substance other than petroleum, or (4) tank is changed so an unaegulated use.

36.751		
AS	ower _	
Permittee:	(Pil)sie Print)	Date: 9/14/05
Durantinas / Say	Covar_	Date:
Permittee:	(Signature)	

Tame 2005

PARECEIVED

DEQ-05-LQ-0120

SEP 14 2005

DEQ - SALEM OFFICE

6029

PO Box 230163 Portland, OR 97281 (503) 372-9760 - Phone (503) 213-9980 - Fax ENVIRONMENTAL
COMPLIANCE
NORTHWEST, INC.



To:	Duty Officer	From: John Da	ay	
Company:	Oregon DEQ-Western Region	Pages: 2	4	, and the same of
Fax:	503-373-7944	Date: 0/15/	105	
Re:	30-Day Notice	CC:		10 mg
		ž.		
☐ Urgent	☑ For Review ☐ Please Con	nent 🗆 Pleaso	e Reply	eke (%)
USTs is su	nts: On behalf of Powell Distributing, to bmitted for your review. Please contactional information.	following 30-Day John Day at 503-3	Notice of Intent to Decom 372-9760 if you have ques	n ssion ins or
John M. Da Geologist/				Commence of the commence of th

SEP I 9 2005

DEPT OF ENVIRONMENTAL QUALITY

NOR HAVE SERVICED.

UST CLEANUP TELEPHONE USE REPORT

John Day	DATE: 4/13/05			
	* TIME: 8:10 tm			
(603) 372 - 9760				
GW impacts				
03-05-0461				
rountered at 6.5' ba	s and obviously			
ted: Shew and odor	. GW Samples			
yet been collected.				
norm proma will be kep	Placed. A complete			
ment MI be unducte	d perope to diagrama.			
	1 00 0			
county has address	as 305 W Main in			
Molalla and MK Rewas Show the address to be				
307 S Main in Morbila. Also John believes the				
VST Sizes are 5000 gallons Not 10,000 gallons.				
look into these descre	puncies and contact			
0				
Staff &	ignature			
	(503) 372-9760 GW impacts 03-05-0461 rountered at 6.5' bog ted; Sheen and odor yet been collected. mum piping will be rep ment will be unducte county has address a our rewals Show ain in Molalla. Also			



Department of Environmental Quality


Northwest Region Portland Office 2020 SW 4th Avenue, Suite 400

> Portland, OR 97201-4987 (503) 229-5263 FAX (503) 229-6945

TTY (503) 229-5471

March 17, 2005

LEE POWELL JR POWELL DISTRIBUTING CO INC PO BOX 17160 PORTLAND OR 97217



UST piping failure Facility ID No.: 6024

Dear Mr. Powell:

On March 15, 2005, the Oregon Department of Environmental Quality (DEQ) performed a piping inspection of the underground storage tank (UST) system at your facility located at 307 S MAIN in Molalla, Oregon.

During the inspection, pressurized product piping was found that exhibited visible corrosion, several holes, and severe pitting. The piping failure was caused by corrosion and resulted in a confirmed release of gasoline.

Following a release of petroleum from a UST system, responsible parties are required by Oregon Administrative Rules 340-122-201 through 340-122-360 to perform initial response, initial abatement measures, initial site characterization, and investigation for the magnitude and extent of contamination, to be followed by remediation. The DEQ has found that often the guickest, safest, and most cost efficient way to achieve cleanup is to act quickly.

Therefore, the DEQ requests that Powell Distributing take action at once by contacting and hiring a qualified contractor or consultant to assist you in evaluating and cleaning up the site now while the piping trench is still open. A DEQ project manager (Rob Hood) has been assigned to assist you in reaching remediation goals and achieving site closure. If you have questions concerning the cleanup, Mr. Hood can be reached at 503-229-5617.

The product piping at this facility is single wall steel and according to DEQ records, was installed without corrosion protection in 1977. The piping was retrofitted with an impressed currant cathodic protection system in December of 1998. In 2002 following an inspection by the DEQ and subsequent testing, the cathodic protection system was documented as being insufficient in protecting the UST system including the piping.

The ability of the cathodic protection system to protect as well as the remaining service life of the single wall product piping is in question, and both must be extensively examined. Please contact a licensed and NACE certified cathodic protection expert, and determine why the cathodic protection system allowed the piping to corrode and to fail.

Demonstrating compliance with all related UST requirements in rule, standard, manufacturer's specifications, and codes that apply to the cathodic protection system and the failing piping at this facility will be an expensive and time consuming undertaking, and the DEQ does not believe that the existing piping will hold up to such rigorous examination.

After briefly speaking with Mr. Jason Powell today, I understand that Powell Distributing would like to continue to keep the site open as an operating fueling station.

The DEQ requests that Powell Distributing take the following steps to address the issues surrounding the failed piping and to bring the UST system safely back into operation.

- Cease dispensing product at once and contact this office about placing the UST systems into temporary closure. An application for temporary closure is enclosed.
- Check with the City and the local fire authority to see if they have any permitting, inspection, or other regulatory requirements before proceeding.

6024 piping failure and modification March 17, 2005 Page 2 of 2

- Provide the DEQ with written 30-day notice for modification of the product piping. A copy of the notice form is enclosed.
- Provide the DEQ with verbal 72-hr notice prior to modification of the piping and proceed with piping modifications after receiving the 72-hr confirmation number and scheduling a date and time for the DEQ to inspect. It may be necessary to schedule and coordinate more than one inspection.
- Remove all the single wall steel product piping and upon completion, collect soil samples from under the former piping runs. Samples must be collected beginning at the dispensers and every 20 feet all the way to the USTs, from where contamination is found to be, or as directed by Mr. Hood.
- Install new corrosion resistant UL approved product piping, have the lines pneumatically tested and then hydrostatically according to standard and rule, and report the results of each passing or failing hydrostatic test to the DEQ.
- When the lines are tight and all tests are passing, submit the DEQ's retrofit checklist and copies of passing line tests.
- Resume operation after receiving a new operating certificate from the DEQ.

Additional items to include with the retrofit checklist would be:

- Sampling data, map, chain of custody, and lab results for the former piping run sampling events.
- Documentation showing the type of piping installed.
- Photos to assist with future UST inspections.

I may be reached at 503-229-5496 to record 72-hr notice, schedule inspections or to answer any questions you may have.

Sincerely,

Gregory Toran

Environmental Specialist

cc: Rob Hood DEQ-NWR

enclosures



Department of Environmental Quality

Northwest Region Portland Office 2020 SW 4th Avenue, Suite 400 Portland, OR 97201-4987 (503) 229-5263 FAX (503) 229-6945

TTY (503) 229-5471

March 17, 2005

03 05 0461

LEE POWELL JR
POWELL DISTRIBUTING CO INC
PO BOX 17160
PORTLAND OR 97217

RE:

UST Compliance Inspection

Facility ID No.: 6024

Dear Mr. Powell:

The purpose of this letter is to inform you that the Oregon Department of Environmental Quality (DEQ) would like to schedule an underground storage tank (UST) inspection at your facility located at 307 S MAIN in Molalla, Oregon. DEQ commonly conducts full compliance inspections of UST systems following a confirmed release of petroleum.

A thorough inspection at your facility will be conducted to determine compliance with all State UST requirements. These requirements include release detection, spill and overfill prevention, corrosion protection, release detection, financial responsibility, operator training, equipment operation, maintenance, recordkeeping, and repair procedures. The inspection is not being conducted as technical assistance and items found not to be in compliance with UST rules will result in enforcement action against the permittee and tank owner.

Please have all UST related records available for review including the following:

- Product line and leak detector test results for 2004.
- The last twelve months of inventory control records and the last tank tightness test for each tank.
- The last twelve months of tank leak detection records for any additional leak detection methods being performed.
- Documentation showing the financial responsibility mechanism currently in place.
- Documentation from Tank Liners in 1998 showing results of the assessment of the steel tanks and completion of the tank lining according to standard, rule and code.
- Documentation from 1998 showing the field installed cathodic protection system was designed by an expert, as "expert" is defined in rule.
- Documentation from 1998 and 2002 showing the cathodic protection system design specifications and design drawings.
- Documentation from 1998 and 2002 showing that the cathodic protection system was installed in 1998 and repaired in 2002 according to standard, rule and code.
- Documentation showing what caused the cathodic protection system to fail during or before 2002 and what caused the corrosion of the steel piping that failed in 2005.
- Documentation showing the last three 60-day inspections or system checks noted for the cathodic system.

6024 scheduling SOC inspection March 17, 2005 Page 2 of 2

- Copies of the last two, three-year cathodic protection tests.
- · Copies of any repair or modification records on file.
- Documentation showing who provided operator training and the training date.

The inspection evaluation will also include:

- Review of the equipment installed including the product piping.
- Confirmation of a functional overfill prevention device for each tank. Be prepared to demonstrate functionality during the inspection.
- Confirmation of a functional cathodic protection system that has been properly designed, installed, evaluated, and repaired and is currently protecting the UST system according to standard, rule and code. Please contact a licensed and NACE certified cathodic protection expert to test, make design corrections, and repair as necessary.

The inspection could take up to five hours to complete. Please call me by **March 23, 2005** to schedule the inspection at your facility. The guidance document "How to Prepare for an UST Compliance Inspection" has been enclosed to assist you in preparation for your inspection.

DEQ suggests that you hire a professional UST maintenance company to be there during the inspection providing sump access, verifying operation of overfill protection, testing sensors and tank monitors, pulling drop tubes, printing monitoring and test reports, or to answer specific technical questions regarding your systems.

You may also want to have your UST maintenance company inspect and review equipment and records and to verify compliance with UST rules, prior to the inspection date. As a reminder, the inspection is not being conducted as technical assistance and items found not to be in compliance with UST rules will result in enforcement action against the permittee and tank owner.

I may be reached at 503-229-5496 to schedule the inspection or to answer any questions you may have.

Sincerely,

Gregory Toran

Environmental Specialist

cc: Rob Hood DEQ-NWR

enclosures

6024 Molalla Kwik Gas piping failure Page 1 of 2

State of Oregon

Department of Environmental Quality

Memorandum

To:

UST compliance files 6024

Filename Molalla Kwik gas Date: March 15, 2005

From:

Greg Toran ODEQ-NWR

03 05 0461

Subject:

Piping inspection

Inspection date:

March 15, 2005

Inspection site conditions: Clear

Others onsite: Ray McCall with SME Corp and Keith Iding with DEQ-NWR.

Reason for the inspection: Responding to piping failure.

Basic site information:

Retail service station in area zoned for business use.

Records reviewed prior to the inspection: None

Records reviewed or collected during the inspection:

Cathodic system site check logs.

Inspection findings equipment:

Only the single wall steel product piping was evaluated on this date. At least one run of piping is corroded to the point of failure; it has several corrosion holes and deep pitting. According to Ray McCall, SME received a call on the 9th of March 2005 about one product not properly dispensing.

Ray said the dispenser for super was found to be in slow flow mode and initially a new leak detector was installed. The problem continued after replacement of the leak detector and the product line then failed a hydrostatic test. After performing a locate to identify the steel product lines, possible cathodic cables, utilities, and electrical conduit, SME introduced helium into the failed line and working from the dispenser found the area of the failed product line approximately 12 feet past the front of the building and 11 feet away from the side of the building. (see site map and photos)

The product lines were then exposed by trenching and following examination several holes were found in the super gasoline line. A 20 foot section of the steel product piping was removed and replacement of the piping was underway as DEQ arrived.

I asked SME to stop the installation activities at once. The cathodic protection system may have failed and will require evaluation; the other product lines are also in question. The tank owner will be contacted and a full evaluation of the entire UST system will be scheduled.

Inspection findings operational:

Not evaluated for operational issues.

6024 Molalla Kwik Gas piping failure Page 2 of 2

Records or test results requested and due date:

None today, sending letter to tank owner requesting records as part of full SOC inspection.

Current operational status:

Operating today and I requested system be taken out of service.

TA provided & recommendations to Owner, Operator, or Permittee:


I spoke with Jason Powell (trained operator) by phone today, and requested the UST system be taken out of service and site evaluation begun while the product piping trench is open. Jason said he is going to get two bids for replacement of all the piping and he agreed to begin sampling at the point of the release after taking the UST system out of service.

Other comments:

There was a small covered pile of contaminated materials that will need to go offsite for disposal; it can be seen in the file photos. Digital photos are stored in UST share folder for facility 6024 on the NWR server.

Conclusion:

This site should not operate until further evaluated and deemed safe. End of this initial piping inspection.











Department of Environmental Quality Northwest Region Portland Office

2020 SW 4th Avenue, Suite 400 Portland, OR 97201-4987 (503) 229-5263 FAX (503) 229-6945 TTY (503) 229-5471

March 16, 2005

LEE POWELL JR POWELL DISTRIBUTING PO BOX 17160 PORTLAND OR 97217

RE: Molalla Kwik Gas

File No.: 03-05-0461

On March 15, 2005, a release was reported from an underground storage tank (UST) system at your facility located at 307 S. Main in Molalla, Oregon. As the responsible party for the facility, you are required to clean up the release according to OAR 340-122-201 through 340-122-360. These rules require cleaning up the soil, groundwater, surface water and any other media contaminated by petroleum to the appropriate standards or demonstrating that the contamination does not pose a risk to human health or the environment. We are looking forward to working with you to bring this site to closure.

An Initial Report Form for UST Cleanup Projects is enclosed. This form needs to be completed and returned to this office within twenty (20) days from the date the release was reported. An outline of additional reporting requirements that includes due dates for submittals is also enclosed. A copy of the UST Cleanup regulations or an application for a letter of authorization for soil treatment will be provided upon request. As the responsible party, you should be aware of the requirements for cleanup, even if you have hired a qualified contractor or consultant to assist you.

Please reference the DEQ File Number listed above in all future correspondence and reports.

By law, DEQ is required to recover project oversight costs. DEQ oversight begins with the initial site characterization and continues through site closure. Oversight includes activities such as reviewing reports, preparing correspondence, answering technical questions, site inspections, and enforcement actions. You will be receiving an invoice each month for all oversight activities performed to date.

DEQ's highest priority for oversight are those sites that pose the greatest hazard to human health, safety and the environment. As a result, many lower environmental priority sites will not be reviewed in detail or receive a final "No Further Action" or "closure" letter from DEQ until the higher priority sites are addressed. However, all projects, simple or complex, require at least some oversight. At a minimum, review is conducted to determine the environmental priority of the cleanup project.

For those responsible parties who desire DEQ oversight regardless of environmental priority, we have

Initial Letter March 16, 2005 Page 2

have developed a Responsible Party Priority Site Program. To receive oversight and more effectively schedule your project, you will be asked to sign an agreement requesting priority review and confirming your agreement to pay DEQ oversight costs in a timely manner.

Not entering into the Agreement does not release you from responsibility for investigation and/or cleanup of the contamination, nor does it mean that you are exempt from paying for DEQ oversight costs. Please be aware that there may be a waiting list for assignment to the next available project manager, and that these projects are assigned on a first come, first served basis.

Please read the attached information on the cost recovery and invoice process. We have also included information about the Responsible Party Priority Site Program and an agreement, if you are interested in expediting review of your project. You may contact the Land Quality Division at (503) 229-6635 if you have questions about cost recovery.

Thank you for your cooperation and continued efforts to comply with the regulations. If you have any questions about the regulations and/or your cleanup project, please call (503) 229-5263 and ask to speak to the Underground Storage Tank Duty Officer.

Sincerely,

Andree Pollock, Manager

UST Cleanup and Compliance Section

Enclosures

RAWSON Stephanie

From:

TORAN Greg

Sent:

Tuesday, March 15, 2005 5:52 PM

To:

RAWSON Stephanie

Cc:

IDING Keith; POLLOCK Andree

Subject:

f 6024

Facility ID 6024 SIC 5541 LUST facility N Facility Name MOLALLA KWIK GAS Facility Address 307 S MAIN City, ST Zip MOLALLA

Confirmed release reported today by SME. Cause of the release is corrosion holes in single wall steel piping. Gasoline into soil, depth to groundwater is unknown. Writing up the details to a file memo. I will need the lust number for this initial investigation.

Charging three and a half hours lust time today plus the time to write up the file memo tomorrow. After that, time will be charged to UST O & M inspection.

Gregory Toran
Department of Environmental Quality

UST Compliance Query ---- Facility -----

Facility ID 6024 SIC 5541 LUST facility N Facility Name MOLALLA KWIK GAS

Facility Address 307 S MAIN

City, ST Zip MOLALLA

OR 97038

Comments

91 thru 93 fees PIF on mod app, Tanks #3 and #4 manifolded ----- Tanks

Tank ID Contents:

Tank Status ACTIVE

Empty

Petroleum GASOLINE

Date Decomm.
Permit # ABEEG

Permit # ABEEG
Permit Status ACTIVE Unknown
Installed 08APR1977 Construction STEEL
10000 External Prot EXTERNAL CATHODIC

Count: *5

Leak Detect STOCK INVENTORY,

<Replace>