

# APPENDIX D EMNR CORE SAMPLING CQA REPORT



Daily Repor	t Number:	AMCCO-090	1420-GRK						
<b>Date:</b> 9/4/2020				MAULFOS	TER ALONGI				
W H		AM: Overcast							
Weather:  Temperature:  24hr Precipitation:		PM: Sunny							Broadway Street
		Min:		54 °F		Portland, OR 97232 971-544-2139			
		Мах:		68 °F		-	97	1-544-2139	
		None				Dust Conditions: Light			
Completed by: Garrick Kalmeta, EIT Number of Contractor Emplo							Employees	Ligiti	
Completed	by:	Gaillek Kalli	ieta, cii						1
Contractor:							Supervisory	Operators	Laborers
							0	0	0
					Work Perfor	med Today			
lo.	cation	1	Sub Location		Description of V		Time Charled	Time a Frederic	
				•	Description of Work			Time Started	Time Ended
Lewis and Clark		EMNR Sand Layer Placement Area			EMNR Core Sampling			10:00	11:30
CQA Office	ers on site:	1			1			GRK	1
Additional F									
Additionari	Ciliaiks.								
CQA office	r and Construc	tion Team Ma	nager (and the sit	e owner) perform	ed EMNR Core s	ampling after	r completion of Hot Spo	t 7 and 8 excavation/ba	ckfill. A russian pete bore
									log and figure). The average
									thickness being 10" and the
-		-		_	-		_		d backfilled areas, but the
									ekly progress meeting, and
-		•						was conducted in the dr	3. 0
nave agree	a to revisit the	areage area	sana, scannent pi	ome sampling in	ine apconing w	CCRS. 7 III EIVII I	in oore sampling work	ivas conaactea in the ar	y at low tide conditions.
					Visual Turbidi	ty Monitoring			
Calibration	Record	Technician	GRK		Time				
		Water Der	oth @ Station (ft)	Turbidit	v (NTU)	Delta NTU			
	Time	-	Downcurrent		Downcurrent	(Down-Up)	Direction	Visual	Construction Activity
01 1		Upcurrent	Downcurrent	Upcurrent	Downcurrent	(Болл. ор)			
Start									
+2 Hours									
+4 Hours									
+6 Hours									
+8 Hours									
+10 Hours				1	l .			II.	ı
Comments									
	r work occurre	d todov							
NO III-Water	r work occurre	u louay							
					Inspection	s and Tests			
luono attan /	Took Time o						l a a	atia	N
Inspection/	rest type						Location Form No.		
Additional F	Remarks:								
Daily Repor	t Number:	AMCCO-090	1420-GRK						
Date:		9/4/2020	-		Completed by:	<u></u>	Garrick Kalmeta, EIT		
		•			Subcontrac	etors Onsito	•		
					วนมะบาแโสด	LIGIS OFISILE			
Company N	Name:			Work Area		·			Employees

Additional	Remarks:								
					Visi	tors			
Time	Name(s)				Agency/C	ompany	Remarks		
					0 5				
A -1 -11411	D								
Additional	kemarks:								
				Verk	oal Communicat	ions with Cor	ntractor		
Time	Name(s)		Remarks						Action Item?
Additional	Remarks:		I.						
Daily Report Number:		AMCCO-09	0420-GRK						
Date:		9/4/2020			Completed by:		Garrick Kalmeta, EIT		
					Equipme				
Contractor		Equipment			Quantity	ι	Jsed Today?	Но	urs Used
					Construction Is	ssues Trackin	g		
Location De		Description	Description			Resolution			Action Item?
Location									TOUGH NOTH
Additional	Remarks:							<u>.</u>	
201.05					<b>.</b>		Duele at Manager Day'		
CQA Officer Signature				Date	Project Manager Review				
GRK				9/4/2020	Cem Gokco	ora		9/8/2020	





EMNR Sample 1: A look at the EMNR sand layer horizon.



EMNR Sample 2: A look at the 2nd sample location.



EMNR Sample 2: Photo showing a sand layer thickness of 11".



EMNR Sample 2: A look at the EMNR layer horizon.



EMNR Sample 3: A look at the 3rd sample location.



EMNR Sample 3: Photo showing a sand layer thickness of 10".



EMNR Sample 3: A look at the EMNR layer horizon.



EMNR Sample 4: A look at the 4th sample location.



EMNR Sample 4: Photo showing a sand layer thickness of 12".



EMNR Sample 4: A look at the EMNR layer horizon.



EMNR Sample 5: A look at the 5th sample location.



EMNR Sample 5: Photo showing a sand layer thickness of 14".



EMNR Sample 5: A look at the EMNR layer horizon.



EMNR Sample 6: A look at the 6th sample location.



EMNR Sample 6: Photo showing a sand layer thickness of 12.5".



EMNR Sample 6: A look at the EMNR layer horizon.



EMNR Sample 7: A look at the 7th sample location.



EMNR Sample 7: Photo showing a sand layer thickness of 10".



EMNR Sample 7: A look at the EMNR layer horizon.



EMNR Sample 8: A look at the 8th sample location.



EMNR Sample 8: Photo showing a sand layer depth of 15".



EMNR Sample 8: A look at the EMNR layer horizon.




EMNR Sample 9: A look at the 9th sample location.



EMNR Sample 9: Photo showing an EMNR layer depth of 10".



EMNR Sample 9: A closer look at the EMNR layer horizon.



EMNR Sample 10: A look at the 10th sample location.



EMNR Sample 10: Photo showing a sand layer depth of 14".



EMNR Sample 10: A closer look at the EMNR layer horizon.



EMNR Sample 11: A look at the 11th sample location.



EMNR Sample 10: Photo showing a sand layer depth of 13".




EMNR Sample 11: A closer look at the EMNR layer horizon.

Daily Report Number:	AMCCO-081121-GRK					
Date:	8/11/2021	MAULE	MAUL FOSTER ALONGI			
M4	AM: Sunny					
Weather:	PM: Sunny		3140 NE Broadway Street			
T	Min: 64 °F			and, OR 97232 1-544-2139		
Temperature:	Max: 84 °F		7/1-544-213/			
24hr Precipitation:	None	Dust Conditions:	Dust Conditions: Light			
Completed by:	Garrick Kalmeta, EIT	Number of Contra	Number of Contractor Employees			
Combrantor	NI/A	Supervisory	Operators	Laborers		
Contractor:	N/A	0	1	0		
		Work Performed Today				
Location	Sub Location	Description of Work	Time Started	Time Ended		
Lewis and Clark	EMNR Sand Layer Placement Area	EMNR Core Sampling	8:45	11:30		
Upland	Stormwater Pond	Pond Excavation	8:00	17:00		
				T		
CQA Officers on site:			GRK			
CQA Officers on site:  additional Remarks:		IR Core sampling upon arrival at the site. A rus				
to obtain visual EMNR s. was used to locate pre 12.5", with the minimum sampling work was cor	viously identified sampling locations. The aver a collected sand thickness being 7" and the m aducted in the dry at low tide conditions. ortion of the stormwater pond excavation. The	is (SPs) within the EMNR sand placement area ( ige sand placement depth over the SPs resulte iximum collected sand thickness being 24" (at Contractor had excavated down to three feet	d in an average sand laye the north dredge overlap from existing surface on the	r thickness of approxin area). All EMNR Core ne south end of the pon		
to obtain visual EMNR s. was used to locate pre 12.5", with the minimum sampling work was cor MFA also observed a p The excavated materia	viously identified sampling locations. The aver in collected sand thickness being 7" and the m inducted in the dry at low tide conditions. Ortion of the stormwater pond excavation. The il was being transported to the south yard to b	ge sand placement depth over the SPs resulte eximum collected sand thickness being 24" (at Contractor had excavated down to three feet blended as south yard subgrade. Two large prom existing surface to get to the target pond	d in an average sand laye the north dredge overlap from existing surface on the reviously burried trees had	r thickness of approximarea). All EMNR Core  ne south end of the pon I been removed from th		
to obtain visual EMNR s. was used to locate pre 12.5", with the minimum sampling work was cor MFA also observed a p The excavated materia	viously identified sampling locations. The aver in collected sand thickness being 7" and the m inducted in the dry at low tide conditions. Ortion of the stormwater pond excavation. The il was being transported to the south yard to b	ge sand placement depth over the SPs resulte eximum collected sand thickness being 24" (at Contractor had excavated down to three feet blended as south yard subgrade. Two large p	d in an average sand laye the north dredge overlap from existing surface on the reviously burried trees had	r thickness of approximarea). All EMNR Core  ne south end of the pon I been removed from th		

Additional Remarks:

Daily Report Number:		AMCCO-08	AMCCO-081121-GRK						
Date: 8/11/		8/11/2021			Completed by:	Garrick Kalmeta, EIT			
					Subcontractors Onsite	9			
Company Name:			Work Area	Employees					
Additional	Remarks:								
					Visitors				
Time	Name(s)				Agency/Company	Remarks			
9:30 Erin McDonnell				DEQ	Visited site for general progress and observe EMNR core sampling				
Additional	Remarks:								
				Verb	al Communications with C	Contractor			
Time	Name(s)			Remarks			Action Item?		
Additional	Remarks:								

Daily Report Number:	AMCCO-081121-GRK			
Date:	8/11/2021	Completed by:	Garrick Kalmeta, EIT	
		Equipment	Onsite	
Contractor	Equipment	Quantity	Used Today?	Hours Used
Customs Excavating	Excavator	1	Yes	8
		Construction Iss	ues Tracking	
Location	Description	R	esolution	Action Item?
Attachments: - Sampling Locations M - Photo Log	ар			
CQA Officer Signature		Date	Project Manager Revie	w
	GRK	8/17/2021	Cem Gokcora	8/18/2021



 Daily Report Number:
 AMCCO-081121-GRK

 Date:
 8/11/2021
 Completed by:
 Garrick Kalmeta, EIT



Photo 1: A look at the drive-in location of the russian pete bore at SP 5




Photo 2: A look at the sampled EMNR Sand profile collected at SP 5, with a depth of approximately 14"

Date: AMCCO-081121-GRK

Date: 8/11/2021 Completed by: Garrick Kalmeta, EIT

Photos

DRIVE-IN DEPTH

Photo 3: A look at the drive-in location of the russian pete bore at SP 11




Photo 4: A look at the sampled EMNR Sand profile collected at SP 11, with a depth of approximately 11"


 Daily Report Number:
 AMCCO-081121-GRK

 Date:
 8/11/2021
 Completed by:
 Garrick Kalmeta, EIT

Photos

DRIVE-IN DEPTH

Photo 5: A look at the drive-in location of the russian pete bore at SP 12



 $Photo \ 6: A \ look \ at \ the \ sampled \ EMNR \ Sand \ profile \ collected \ at \ SP \ 12, \ with \ a \ depth \ of \ approximately \ 12"$ 

Daily Report Number: AMCCO-081121-GRK Completed by: Date: 8/11/2021 Garrick Kalmeta, EIT



Photo 7: A look at the drive-in location of the russian pete bore at SP 13




Photo 8: A look at the sampled EMNR Sand profile collected at SP 13, with a depth of approximately 12"

 Daily Report Number:
 AMCCO-081121-GRK

 Date:
 8/11/2021
 Completed by:
 Garrick Kalmeta, EIT



Photo 9: A look at the drive-in location of the russian pete bore at SP 14



Photo 10: A look at the sampled EMNR Sand profile collected at SP 14, with a depth of approximately 13"

 Daily Report Number:
 AMCCO-081121-GRK

 Date:
 8/11/2021
 Completed by:
 Garrick Kalmeta, EIT



Photo 11: A look at the drive-in location of the russian pete bore at SP 15




Photo 12: A look at the sampled EMNR Sand profile collected at SP 15, with a depth of approximately 11"

 Daily Report Number:
 AMCCO-081121-GRK

 Date:
 8/11/2021
 Completed by:
 Garrick Kalmeta, EIT

Photos



Photo 13: A look at the drive-in location of the russian pete bore at SP 16



DRIVE-IN DEPTH

Photo 14: A look at the sampled EMNR Sand profile collected at SP 16, with a depth of over 23" (located within the transition/overlap zone near north dredge area prism)

Daily Report Number: AMCCO-081121-GRK Date: 8/11/2021 Completed by: Garrick Kalmeta, EIT

Photos



Photo 15: A look at the drive-in location of the russian pete bore at SP 17



SAND TRANSITION ZONE

Photo 14: A look at the sampled EMNR Sand profile collected at SP 17, with a depth of approximately 14"

 Daily Report Number:
 AMCCO-081121-GRK

 Date:
 8/11/2021
 Completed by:
 Garrick Kalmeta, EIT

Photos



Photo 15: A look at the drive-in location of the russian pete bore at SP 18



EDGE OF SAMPLER

Photo 14: A look at the sampled EMNR Sand profile collected at SP 18, with a depth of over 24" (located within the transition/overlap zone near north dredge area prism)

 Daily Report Number:
 AMCCO-081121-GRK

 Date:
 8/11/2021
 Completed by:
 Garrick Kalmeta, EIT

Photos



Photo 15: A look at the drive-in location of the russian pete bore at SP 20



DRIVE-IN DEPTH

Photo 14: A look at the sampled EMNR Sand profile collected at SP 20, with a depth of approximately 8"

 Daily Report Number:
 AMCCO-081121-GRK

 Date:
 8/11/2021
 Completed by:
 Garrick Kalmeta, EIT

Photos

DRIVE-IN DEPTH

Photo 15: A look at the drive-in location of the russian pete bore at SP 21



Photo 14: A look at the sampled EMNR Sand profile collected at SP 21, with a depth of approximately 7"

Date:

AMCCO-081121-GRK

B/11/2021

Completed by:

Garrick Kalmeta, EIT

Photos

DRIVE-IN DEPTH

Photo 15: A look at the drive-in location of the russian pete bore at SP 22




Photo 14: A look at the sampled EMNR Sand profile collected at SP 22, with a depth of approximately 13"

Daily Report Number:	AMCCO-080322-GRK					
Date:	8/3/2022	MAUL FOSTER ALONGI				
Weather:	AM: Cloudy					
wediner.	PM: Cloudy		3140 NE Broadway Street Portland, OR 97232			
Temperature:	Min: 64 °F		971-544-2139			
remperatore.	Max: 65 °F					
24hr Precipitation:	None		Dust Conditions:	Light		
Completed by:	Garrick Kalmeta, EIT		Number of Contractor Employees			
Contractor:	N/A		Supervisory	Operators	Laborers	
Commucion.	IVA		0	0	0	
		Work Performed Today	′			
Location	Sub Location	Description of Work		Time Started	Time Ended	
Lewis and Clark	EMNR Sand Layer Placement Area	EMNR Core	Sampling	12:30	13:30	
CQA Officers on site:				GRK		
data at 5 sampling poin sampling locations. The	EMNR Core sampling upon arrival at the site. And the site of the sand placement depth over the SPs the maximum collected sand thickness being	a (see photo log and figure). s resulted in an average sand	A handheld GPS instru d layer thickness of ap	ment was used to locate proximately 10.5", with the	previously identified e minimum collected sand	
		Inspections and Tests				
Inspection/Test Type			Location		Form No.	
Additional Remarks:						

Daily Repo	Daily Report Number: AMCCO-080322-GRK							
<b>Date:</b> 8/3/2022				Completed by:	Garrick Kalmeta, EIT			
Subcontractors Onsite								
Company Name:		Work Area			Employees			
Additional	Remarks:							
Visitors								
Time	Time Name(s)				Agency/Company	Remarks		
Additional	Remarks:							
				Verb	al Communications with Co	ntractor		
Time Name(s) Remarks			Remarks		Action Item?			
Additional Remarks:								

Daily Report Number:	AMCCO-080322-GRK						
Date:	8/3/2022	Completed b	<b>y</b> : Go	Garrick Kalmeta, EIT			
		Equipm	ent Onsite				
Contractor	Equipment	Quantity	Used Today?		Н	Hours Used	
		Construction	Issues Tracking				
Location	Description	Resolution			Action Item?	-	
Additional Remarks:							
CQA Officer Signature		Date		Project Manager Review	ı		
	GRK	8/5/2022	Cem Gokcora				



 Daily Report Number:
 AMCCO-080322-GRK

 Date:
 8/3/2022

 Completed by:
 Garrick Kalmeta, EIT

### Photos



Photo 1: A look at the GPS location for SP-2



DRIVE-IN DEPTH

Photo 2: A look at the drive-in location of the russian pete bore at SP-2

Date:

Daily Report Number: AMCCO-080322-GRK 8/3/2022 Completed by: Garrick Kalmeta, EIT Photos 7" SAND LAYER DRIVE-IN DEPTH SAND TRANSITION ZONE

Photo 3: A look at the sampled EMNR Sand profile collected at SP-2, with a depth of approximately 7"



Photo 4: A look at the event horizon (transition zone between sediment and sand) for SP-2

 Daily Report Number:
 AMCCO-080322-GRK

 Date:
 8/3/2022

 Completed by:
 Garrick Kalmeta, EIT

Photos



Photo 5: A look at the GPS location for SP-5




Photo 6: A look at the drive-in location of the russian pete bore at SP-5

Date:

AMCCO-080322-GRK

Date:

B/3/2022

| Completed by: | Garrick Kalmeta, EIT |

Photos

SAND TRANSITION ZONE

12" SAND LAYER

DRIVE-IN DEPTH

Photo 7: A look at the sampled EMNR Sand profile collected at SP-5, with a depth of approximately 12"



Photo 8: A look at the event horizon (transition zone between sediment and sand) for SP-5

 Daily Report Number:
 AMCCO-080322-GRK

 Date:
 8/3/2022
 Completed by:
 Garrick Kalmeta, EIT




Photo 9: A look at the GPS location for SP-11



Photo 10: A look at the drive-in location of the russian pete bore at SP-11




Photo 11: A look at the sampled EMNR Sand profile collected at SP-11, with a depth of approximately 15"



Photo 12: A look at the event horizon (transition zone between sediment and sand) for SP-11

Daily Report Number: AMCCO-080322-GRK Date: 8/3/2022 Completed by: Garrick Kalmeta, EIT



Photo 13: A look at the GPS location for SP-12



DRIVE-IN DEPTH

Photo 14: A look at the drive-in location of the russian pete bore at SP-12

 Daily Report Number:
 AMCCO-080322-GRK

 Date:
 8/3/2022

 Completed by:
 Garrick Kalmeta, EIT




Photo 15: A look at the sampled EMNR Sand profile collected at SP-12, with a depth of approximately 13"



Photo 16: A look at the event horizon (transition zone between sediment and sand) for SP-12

 Daily Report Number:
 AMCCO-080322-GRK

 Date:
 8/3/2022

 Completed by:
 Garrick Kalmeta, EIT

Photos



Photo 17: A look at the GPS location for SP-14



Photo 18: A look at the drive-in location of the russian pete bore at SP-14

Date: AMCCO-080322-GRK
Date: B/3/2022 | Completed by: Garrick Kalmeta, EIT

Photos

7" SAND LAYER

DRIVE-IN DEPTH

Photo 19: A look at the sampled EMNR Sand profile collected at SP-14, with a depth of approximately 7"



Photo 20: A look at the event horizon (transition zone between sediment and sand) for SP-14