

Department of Environmental Quality Northwest Region

700 NE Multnomah Street, Suite 600 Portland, OR 97232 (503) 229-5263 FAX (503) 229-6945 TTY 711

July 25, 2024

Robert Marble U.S. BanCorp 17650 NE Sandy Blvd Portland, OR 97230-5000

RE: UST Compliance Inspection

DEQ UST #10784

US Bank Operations Center

Attention Mr. Marble,

The Oregon Department of Environmental Quality (DEQ) is conducting underground storage tank (UST) inspections throughout Oregon. The purpose of this letter is to inform you that your facility, among others, has been selected for inspection. A thorough inspection of your facility will be conducted to determine compliance with state and federal UST requirements. **The date you receive this letter is the date that the inspection starts.** If you have work done after that date, you will need to have the previous set of records available for evaluation in addition to the most recent records.

If I do not hear from you, the inspection for this facility is scheduled for August 27, 2024, starting at approximately 9 am. Please note that the inspection will require uninterrupted participation and attendance by you or a knowledgeable assistant. For the inspection you need to provide access to tank sumps, under dispenser areas, cathodic protection rectifiers, and leak monitoring equipment. DEQ will not touch the equipment or enter the facility, if you are unable to assist with equipment access, please have your UST Service Provider there. This inspection may also include review of Stage I Vapor Recovery.

To complete this inspection, you will need to have compliance testing records available on-site on the day of the inspection or sent to me prior to the inspection at mark.drouin@deq.oregon.gov If the records are not available during the day of the inspection, you will have five (5) business days to provide the records to me electronically. After which time this facility will be subject to enforcement actions.

At a minimum the following records are required to complete this inspection:

- Line and leak detector testing results for the past three years,
- Monthly tank leak detection records (12 months),
- Class A, B, and C training documentation.
- Financial responsibility mechanism.
- Annual tank gauge / release detection equipment certification
- Spill prevention testing records
- Overfill Prevention Equipment testing
- Cathodic protection testing (if applicable)
- Tank lining records (if applicable)
- Monthly walkthroughs

As stated previously, DEQ will not touch any equipment and if you are unable to assist with equipment access, please have your UST Service Provider there to remove manway or sump lids. DEQ will need to observe what equipment is in the tank top sumps and under the dispensers. If ball floats are the primary overfill protection device, these will need to be verified during the inspection, please be able to locate and remove the ball floats.

If violations are found at the time of the inspection without prior notification, DEQ is required to initiate enforcement action. For UST violations, enforcement usually begins with a field citation option, which is much like paying a traffic ticket and making corrections.

Some enforcement situations including repeat violations will go through a longer and more formal process including civil penalties.

Thank you for your cooperation. I can be reached at 541-213-1204 or mark.drouin@deq.oregon.gov to answer any questions you may have and assist you in the preparation for your inspection.

Sincerely,

Mark Drouin

UST Compliance Specialist

Mark Drouin

Full Compliance Inspection - Test

Submitted by: mark.drouin_deq

Submitted time: Sep 4, 2024, 10:30:48 AM

Facility Number	Faci	lity	Num	ber
-----------------	------	------	-----	-----


10784

Address

17650 Northeast Sandy Boulevard, Portland, OR, 97230

Мар

Lat: 0 Lon: 0



Date

Sep 4, 2024

Time

09:14

Compliance Determination


Corrosion Protection or Lining

Pass


Spill Prevention

Fail

Overfill Prevention	
Fail	
Release Detection	
Fail	
Operator Training	
Pass	
Financial Responsibility	
Pass	
Walkthrough Requirements	
Pass	
Passing Inspection	
Fail	



Facility_10784_240904101458_stp-sci.jpg





Facility_10784_240904095337_tremch3.jpg





Facility_10784_240904095229_trench2.jpg






Facility_10784_240904092543_.jpg







DEQ State of Oregon Department of Environmental Quality

Program Enforcement No. 2024-FC-9541

Department of Environmental Quality Underground Storage Tank Program

Field Citation For UST Violations

This section for DEQ use only

Page 1 of 3

DEQ Information UST Facility Information				ST Facility Information			
Inspection Date:	09/17/2024		Facility ID#: 10784				
Inspector:	Mark Drouin		Facility Name:	US BANK OPERATIONS CENTER			
DEQ Office:	700 NE Multnomah St. #6	500	Facility Address:	17650 NE SANDY BLVD, PORTLAND,			
	Portland, Oregon 97232			Oregon 97230			
Phone #:	503-229-6155		County:	Multnomah			
Oregon DEQ inspected	the facility listed above	and identified the	UST violations listed o	n page 3 of this Field Citation.			
Field Citation Issued:	☐ In Person	☑ By Mail	☐ Both	Date Issued: 09/17/2024			
Facility Representative Pre	esent During Inspection:			☐ Permittee ☐ Owner ☐ Other			
Name of Permittee or Own	ner:	U.S. BanCorp					
Mailing Address:		17650 NE Sandy B	Blvd , Portland Oregon 972	30			
	See Page 3 for detailed list			\$ 1400 Portland OR 97208-3615			
Underground storage tank (UST) violations, OAR 340-150-0250. Owner or Permittee should select Option 1 or Option 2 below and return a signed copy of this for to DEQ by the following date: 10/17/24 DEQ Revenue Section 700 NE Multnomah St. #600 Portland, Oregon 97232 Check one option Option 1 - I acknowledge that the listed violation(s) have occurred and I am remitting the listed field citation penalty. Option 2 - I do not want to participate in the expedited enforcement process and understand that my file will be referred to the Department's Office of Compliance and Enforcement for formal enforcement action.							
Name:				Owner / Permittee			
Signature:				Date:			
Important Read pages 2 and 3 for more information about your options and a detailed listing of violations and compliance requirements.							

Field Citation Requirements

The permittee or owner should select Option 1 or Option 2 and return a signed copy of Page 1 of the Field Citation form within thirty (30) days of issuance of the Field Citation. If the permittee or owner fails to sign and send Page 1 of the Field Citation form back or pay the penalty within thirty days, Option 1 expires, the Field Citation will serve as a Pre-Enforcement Notice (PEN) and the permittee and owner will be subject to formal enforcement including the imposition of civil penalties in accordance with OAR Chapter 340, Division 12.

The permittee or owner must complete the actions required to correct the violations listed on the Field Citation by the date specified to prevent further enforcement action by DEQ.

Option 1:

By checking Option 1 the permittee or owner acknowledges that the violations listed on Page 3 of this Field Citation have occurred and agrees to pay the established penalty.

By submitting payment of the penalty amount, the responding permittee or owner agrees to accept the field citation as a final order of the Environmental Quality Commission (commission) and waives any and all rights and objections to the form, content, manner of service and timeliness of the Field Citation; to a contested case hearing and judicial review of the Field Citation [OAR 340-150-0250(6)]; and to service of a copy of this Final Order (*i.e.*, no other copy will be provided).

Upon the Department's receipt of payment of the penalty amount set forth in the Field Citation, the Field Citation becomes a Final Order of the Commission that:

- 1. Imposes upon the permittee or owner a civil penalty in the amount listed on Page 1 of this Field Citation; and
- 2. Requires the permittee or owner to satisfactorily complete the requirements and actions necessary to correct the violations documented by the dates set forth on Page 3 of this Field Citation.

Failure by the permittee or owner to complete the actions set forth on Page 3 of the Field Citation by the specified date violates the Commission Order and subjects the permittee and owner to a formal enforcement action including the imposition of additional civil penalties.

Option 2:

The permittee or owner may deny that the violations as listed on Page 3 of this Field Citation have occurred or contest the Field Citation process by checking Option 2 and submitting to the Department a signed copy of Page 1 of the Field Citation. In that event, the Field Citation will serve as a Pre-Enforcement Notice (PEN) and the permittee and owner will be subject to formal enforcement for those violations set forth in the Field Citation, including the imposition of civil penalties in accordance with OAR Chapter 340, Division 12. Civil penalties that will be imposed by the formal enforcement process will exceed the Field Citation penalties for the same violation(s).

The Department appreciates your cooperation and efforts to comply with the regulations for underground storage tank systems.

Page 2 of 3

Department of Environmental Quality (DEQ) Underground Storage Tank Program Facility Representative initials: **UST FIELD CITATION DATE ISSUED: 09/17/2024** PROGRAM ENFORCEMENT No.: 2024-FC-9541 Page 3 of 3 **FACILITY ID: 10784** Violation #1: Failure to conduct annual operability testing of the release detection system (tank gauge, probes, and sensors). *TCR: Corrective Conduct annual release detection operability testing (leak detectors, tank top sump and trench sensors, tank interstitial sensors, tank probes) and submit results to the DEQ by Action: 11/17/24 Rule Citation: OAR 340-150-Penalty 0400(1)(c) 340-150-300 Correct Violation by: 11/17/2024 Date Violation Corrected: Amount: \$ 0400(2) Violation #2: Failure to test spill prevention and containment sumps equipment at least once every 3 years *TCR: Corrective Conduct triennial testing of the spill buckets and tank top sumps and submit records to DEO by 11/17/24 Action: Rule Citation: OAR 340-150-Penalty 500 Correct Violation by: 11/17/2024 Date Violation Corrected: 0310(8)(b) Amount: \$ Violation #3: Failure to inspect overfill equipment at least once every 3 years. *TCR: Corrective Triennial testing of the overfill alarm (this will be conducted when the probes are removed) and submit documents to DEQ by 11/17/24 Action: Rule Citation: OAR 340-150-Penalty 300 Correct Violation by: 11/17/2024 Date Violation Corrected: 0310(9) Amount: \$ Violation #4: Failure to perform an annual test of operation of line leak detector. *TCR: Corrective Conduct annual testing of the tank probes and submit records to DEQ by 11/17/24 Action: Rule Citation: OAR 340-150-Penalty 300 Correct Violation by: 11/17/2024 Date Violation Corrected: 0410(2)(c-) Amount: \$ Violation #5: *TCR: Corrective Action: Penalty Rule Citation: OAR Correct Violation by: Date Violation Corrected: Amount: \$ Violation #6: *TCR: Corrective Action: Penalty Rule Citation: OAR Correct Violation by: Date Violation Corrected: Amount: \$ **Total Penalty Amount** \$1400 (This Page): \$ OU MUST CORRECT THE VIOLATIONS AS REQUIRED, ENTER THE DATES CORRECTED, SIGN THE STATEMENT BELOW AND

RETURN THIS FORM TO THE DEQ INSPECTOR LISTED ON PAGE 1 ON OR BEFORE:_______11/

Retain a copy of this form and all documentation of corrective actions for your records.

Permittee/Owner Signature

Date

Oregon Department of Environmental Quality - Underground Storage Tank Program Technical Compliance Inspection - UST Inspection Report

Inspector: MDR	ouin Date: 9	14/2024	Time: 9A		Facility:	18	784
I. Site Information							
Facility Name: US	Bank Open	atrons	Permittee: Roly	Narble	Contact		
Site Address: 170	OSD NE SA	noy Bluch	Organization: US B	werp	Phone		
1	CHANT		Phone: \$23.401	4790			
II. Tank Information			Frione: XIS 44				
DEQ Permit #	BHGDK	BAGDA					
Estimated Gallons	30,000	30 000					
Substance	Diese	Diese					
Tank Material	DWFRP -						
Tank Install Date	2020 -	->					
Pipe Material	DN FRP -	\rightarrow					
Pipe Type							
Pipe Install Date	2020 -	\rightarrow					
Overfill Device							
lf tanks are manifold	ed which tapke:						
III. Operating Certific				Compliano	e	₩ Yes	□No
Current	P Accurate	e	Ø Posted for deliver				
IV. Operator Training	3			Compliand	e	Yes	□No
Class A/B Operator		Name:	James Emanuelse	~	Date: U	1/2012	
Class C Operator	□Yes □No	ßEgen □ Cardloo	ck				
V. Financial Respons				Complian		Yes	□No
Type of coverage: 🗓			Begin Date: 5/1/203	1	End Date	: 5/1/200	5
Coverage amount co	rrect:	alf insurance honds local	Number of tanks co			1	
VI. Walkthrough Req		answighte, policy, local	bovernment, trust fully, all	Complian		D'Yes'	□No
	release detection equi	pment checked mon	thly?			Yes	□No
Tank top sumps chec						Yes	□No
		Level 3	- Restricted				

/II. Release Detection		Was Substitute			The same of the	Compliance	J.C	Yes	No
) Annual Release Detec	tion Operability 1	esting	(Ensure all re	lease detection	probes and se				
	TESTING	dere e	Stant	-up -no	t since	then			E141
Date of last to			-		Last thre	e tests availabl	le?] Yes	Σίνο
ensors/Probes Tested: 🗆 T	ank Top UDCs	□Annular							
ank gauge manufacture	er make and mode	el: <u>Jæde</u>	1 Ros	T 450)			-	
n-Tank Gauging Probe:								_	
Annular Tank Sensor:									
ank Top / Dispenser Se	ensor: Veeder	Root	79438	U-35D				_	
) Piping Release Detec	tion (Check all that a	pply)							
Pressurized Piping	(Circuit Circ	L	ines a	e man	rholded				
☐ Mechanical Leak	Detector (MIID)	Electron	ic Leak De	tector (ELL	D) - check f	or swiftcheck requ	iirement		
		Tostma	dene a	1 sta	tup.	ee tests availat	.1.2	□ Vo-	r\$AL =
Date of last to	esting:	.632	-					□Yes	ØNo
Number of li	nes tested:		_		Numbe	r of LD tested:_			-
Leak detecto	r manufacturer m	ake and mod	del: <u>Ve</u>	eder Reso	T PLL	Ď			
	bine manifold?							□Yes	□ No
MLLD produc	ct appropriate? (E	xample, dies	el Red Jac	ket FX serie	es on diese	el system?)	I	□Yes	□No
	o line testing: An							□Yes	₽No
Date of last sump tes	iting: 12 38 20	odo duni	ng inst	allatren		o tests availabl		□Yes	□∭No
Date of last sensor to	12/28/:	10)(5			Last thr	ee tests availa	hle?	□Yes	D'No
Float sensors installe	d correctly?	Yes	□No	Prese		ter in sumps?		□Yes	E No
Interstitial space ope		DLYes	□No			,			
□ <u>Safe Suction</u>			□ V	□No					
Check valve	directly below suc	tion pump?	∟Yes	□NO		16 Mars de la Danas Ameri	-l lask d	lataction	
c) Monthly Tank Releas			ply)			If Veeder Root tar CSLD set at 99		letection	
		○ □ Static				☐ Thermal coeff	ficient set corre 00070; Diesel C	•	
Are correct tank size				□Yes	□No	If Incon/Franklin	tank gauge leak	k detection	
Tank diameter/lengt		te?		□Yes	□No	☐ If SCALD is Vo☐ Is API gravity		1% (or 99% c	onfidence)
Are tanks manifolded	/			□Yes	□No	(Regular 63	3.5; Plus 62.8; S		iesel 32.8)
If so, tank gauge te	sting setup for ma	anifolded tar	iks?	□ Yes	□No	For all tank gauge (Static tests req	es doing static t Juire tank to be	tests 50% full for	a valid test)
					hear	No.	Transition .	_	
Interstitial Monitoring									
								.1	
☐ SIR Ensure pass o	r fail results within 30	-day period. Inc	conclusive re	esult means re	lease detec	tion requirement	not met		
Tank release detection	records available	during inspe	ection						
	_Mar ⊊Apr	№ -May	⊅ Jun	'⊠ Jul	⊈ Aug	⊠ Sep	⊈ Oct	⊠ -Nov	□ Dec
,	Mar	₽ -May	ß Jun	₽ Jul	⊠ Aug	⋥ Sep	Ģ Oct	Ø-Nov	□ _y Dec
,	Mar □ Apr	□ May	□Jun	□Jul	☐ Aug	□Sep	□ Oct	□ Nov	□ Dec
	•	•							
14: □Jan □ reb □	Mar □ Apr	□ May	□Jun	□ Jul	□ Aug	□ Sep	□ Oct	☐ Nov	□ Dec □ Dec

Inspector: MANUM Date: 9/4/2024 Time	: 9A	_	Facility:	107	84
VIII. Spill Prevention		Compliance	9	□Yes	No
Date(s) of testing: 12 28 2020 During Marall	Number o	f spill bucke	ts testec	1?	
Did spill bucket pass most recent testing? Yes No If no	, was spill bucke	t replaced/r	epaired?	□Yes	□No
During inspection, visual damage to spill bucket?		tested s			
	Not	tested s	ince	-	
☐ Hydrostatic testing (test takes one hour to complete)					
□ Vacuum test (test takes 1 minute, ending vacuum must be 26 inches water column o	or greater)				
X. Overfill Prevention		Compliand	e	□Yes	No
Date(s) of testing: 13/28/2000 During sinstell					•
	o, overfill device	replaced?		☐ Yes	□No
Overfill method that was tested: Alarm	lapper	□ Ball Floa	it		
Overfill Alarm			1	1 1 1	-
Alarm sounds when tank is 90% full	⋈ Yes	□No	not	rested	Since
Driver can see or hear alarm at point of transfer?	Yes	□No			
Sound alarm from tank gauge during inspection?	Yes	□No			
Flapper Valve					
Testing verified the valve automatically restricts flow at 9!		□No			
Visual observation of flapper on day of inspection?	☐ Ye s	□No			
Ball Float Testing verified the hall float automatically restricts flour	at 0.00/ FIV	C 1 84 -			
Testing verified the ball float automatically restricts flow a Visual observation of ball float during inspection?		□No			
visual observation of ball hoat during inspection?	□ Yes	□ No			
X. Corrosion Protection		Complia	nce	Yes	□No
□ Cathodic □ Galvanic □ Impressed	Current			1	
Steel tank with cathodic?	□Yes	□No		700 7	Tanks
Steel pipes with cathodic?	☐ Yes	□ No	DM	FRY	00. 1
Steel flex-lines with cathodic?	□Yes	□No			
Date of cathodic test:					
Last two tests available?	□ Yes	□ No			
Did last test pass?	□ Yes	□No			
If not:					
Was failed test reported to DEQ?	□Yes	□No			
Was system repaired?	□Yes	□No			
Date of repair?					
Cathodic retested within 6 mos. of repair?	□Yes	□No			
Date of retesting?					
If impressed current system:					
Rectifier Operational?	□Yes	□ No			
Rectifier log maintained?	□ Yes	□No			
Rectifier been operating continuously	□Yes	□No			
□ Tank Lining					
Date of lest test?					
Pressure test conducted after tank lining inspection?	□Yes	□No			

The state of the s	-
XI. General notes from inspection	
Representative onsite: Robert Marble, email: robert marble cusbank	·Com
10/15/2024 mascott testing	
- Missing annual leak detector testing, H2.9 - missing annual leak detector operability testing Gs - missing triennual spill bucket testing CIE - missing triennual over fill prevention testing CIE - missing triennual sump integrity testing CIE	
and had has a tent and a like	
each tank has 2 turbines. Each set of turbines have	one
electronic line leak detectors. Lines are manifolded. No in tank gauge. Need to verily STP-SCI controllers	Porograv
in tank gauge. Need to verily STP-SCI controllers	
- reasont to be present during testing on solts verily sci controllers programmed correctly	
Compliance Determination: No Violations Observed Observed violations resulting in enf	orcement
Inspector Signature: Wave Dyour Date: 9/0/2024	



INVOICE

MacDonald-Miller Facility Solutions LLC. 17930 INTERNATIONAL BLVD STE 120 SEATAC, WA 98188 Phone (206) 763-9400 INVOICE NUMBER

JC97699

INVOICE DATE

10/31/2024

PO Number

092624CCOC-01

Total Due

\$7,420.00

JOB ADDRESS

US BANK CC FUEL OIL DEQ TEST 17650 NE SANDY BLVD PORTLAND, OR 97230

BILL TO

US BANK COLUMBIA CENTER ATTN: ROBERT MARBLE 17650 NE SANDY BLVD PORTLAND, OR 97230

Job 83240148

US BANK CC FUEL OIL DEQ TEST

			Payment Terms	Shipping Method	Due Date
CHRISTOPHER GRIFFITHS	40689		Due On Receipt	TO THE PROPERTY OF THE PROPERT	10/31/2024
Description	OCTOBER BILL FOR	R US BANK CC FU	EL OIL DEQ TEST		

Billing Amount	\$7,420.00
Retention Withheld	\$0.00
Retention Due	\$0.00
Subtotal	\$7,420.00
Miscellaneous	\$0.00
Total Tax	\$0.00
Total	\$7,420,00

11/4/24

Mascott Equipment Co.

	. / I 🗪 T	_ ~ ~	mo les les
	1 / E/ " L	_ / 11.	l Nieule
SER	V 11		. I /IF F

PORTLAN	HANCOCK ND, OR 97212	TRICITIES 2464 ROBERTSON DRIV RICHLAND, WA	SEATTI	TH PLACE SOUTH LE, WA 98108	ANCHORAGE 5610 SILVERA ANCHORAGE,				495431			
503-282-2	2587	509-543-2018	206-763	3-7867	907-561-1119			JOB SITE				
Δ	ACCOUNT N	IIMBÉR				ORDER DATE 10/10/2		JOB PHONE	EO2) OCC 2470			
	411					WORK ORDE		(503) 866-3478			
	411	I					Rol	oert Marve	}			
SOLD TO	Macdo	nald-Miller				<u> </u>	IS Bank					
ADDRESS	P.O. Bo	x 47983				ADDRESS	7650 NI	E Sandy BL	.VD			
CITY	Seattle	, WA				СІТУ	Portland.	OR 97230	STATE			
		DMER P.O. NUMBER	D R	eeves	CHNICIAN			MFG AUTHORIZATIO				
MODEL		SERIAL NUMBER	D. 10		MODEL		SERIALN	UMBER				
PROBLE	M REPORT	ED:	۸۰۰	uol Com		atin a						
 					pliance te Compliance to							
			1116	ailliai LFA C	zomphance u	esung						
				MATER	RIAL USED							
QTY.	WH	PART NUMBER			DESCRIPTIO)N		PRICE	AMOUNT			
2	22	Testing		Line ar	nd line leak d	-	est		0.00			
2	22	Testing		Overfill test at drop tube				0,0				
6	22	Testing		Hydrostatic sump test				0,0				
2	22	Testing			test		olo					
1	22	Testing		N	Monitor Inspection				0.00			
									0,00			
TIME AF	RRIVED	0730 AM PM (cirlcle	one)	TIME DEPART	TED A	AM PM (cirlcle one)	Customer Ini	ials			
WORK DESCRI	PTION: T	ested 2 lines a	nd ELLC)'s.								
Monito	or Inspect	on on TLS-450+.										
Testec	d 6 sumps	at low level and 2 s	pill buckets	, 2 overfill at	t drop tube.							
Tank 2	2 annular	sensor will not alarm	with either	product or v	water. Veede	r-Root di	scriminati	ng sensor, ar	nnular, 10' tank			
	-											
	WAI	RRANTY		COMPL	LETE 🗸			PENDING				
				CHARGES	QT	۲.	RATE		AMOUNT			
SERVICEM	AN S		STAND	ARD LABOR					0.00			
			OVERT	IME LABOR					0.00			
DATE COL	DI ETEN		TRAVE						0.00			
DATE COM		10/15/24	MILEA	3E					0.00			
TEDMO								1				
TERMS:		· · · · · · · · · · · · · · · · · · ·	TOTAL	MATERIAL	0.0	0			0.00			
NET 1	OTH PRO STOMER NAME)X		MATERIAL MATERIAL	0.0	0			0.00			
NET 1 PRINT CUS	OTH PRO			MATERIAL	0.0	0						
NET 1 PRINT CUS	OTH PRO		MISC.	MATERIAL DP FEE	0.0	0			0.00			

From: Marble, Robert D

To: <u>LITKE Emily * DEQ</u>; <u>UST Duty Officer * DEQ</u>

Cc: Knepper, Alan M; DROUIN Mark * DEQ; Hunter, Benjamin C; Montoya, Gabriel

Subject: RE: UST Facility 10784: US Bank Operations

Date: Wednesday, November 20, 2024 1:47:26 PM

Attachments: <u>image001.pnq</u>

Mascott Testing 10.15.24.pdf MacDonald-Miller 11.4.24.pdf

Emily,

Good update and glad to hear the bank got that fine paid in time, that was my concern. Accounts payable has been moving like pond-water lately.

The testing requirements were completed on 10/15/24 by Mascott Equipment, see attached service report. They were subcontracted by MacDonald-Miller Facility Solutions, see attached invoice.

The testing was witnessed by one of Mark Drouin's team members. I don't recall the name but have copied Mark.

Is there anything else needed?

Thanks!

Robert D Marble

Officer | Facility Chief Engineer

p. 503.401.4790 | c. 503.866.3478 | robert.marble@usbank.com

U.S. Bank

OR-Columbia Center

17650 NE Sandy Blvd, Gresham, OR 97230-5000 | PD-OR-C1EG | www.usbank.com

From: LITKE Emily * DEQ < Emily.LITKE@deq.oregon.gov>

Sent: Wednesday, November 20, 2024 1:28 PM

To: UST Duty Officer * DEQ <UST.DutyOfficer@DEQ.oregon.gov>; Marble, Robert D

<robert.marble@usbank.com>

Cc: Knepper, Alan M <alan.knepper@usbank.com>

Subject: [EXTERNAL] RE: UST Facility 10784: US Bank Operations

[WARNING] Use caution when opening attachments or links from unknown senders.

Hey Robert,

I am following up on facility 10784 US Bank Operations located at 17650 NE SANDY BLVD,

PORTLAND, Oregon 97230.

Payment of the \$1400 fine was received and processed on 10/16/24. The deadline for the corrective actions was 11/17/24. Please provide an update.

Corrective Actions:

Violation #1 - Conduct annual release detection operability testing (leak detectors, tank top sump and trench sensors, tank interstitial sensors, tank probes) and submit results to the DEQ by 11/17/24

Violation #2 - Conduct triennial testing of the spill buckets and tank top sumps and submit records to DEQ by 11/17/24

Violation #3 - Triennial testing of the overfill alarm (this will be conducted when the probes are removed) and submit documents to DEQ by 11/17/24

Violation #4 - Conduct annual testing of the tank probes and submit records to DEQ by 11/17/24

Please email work orders, testing reports, and invoices to this email thread.



Emily Litke (she/her)

Emily.LITKE@deq.oregon.gov

Duty Officer, Underground Storage Tanks DEQ Headquarters, Land Quality Division 700 NE Multnomah Street, Suite 600 Portland OR 97232-4100 503-806-9516

From: UST Duty Officer * DEQ

Sent: Saturday, September 28, 2024 6:19 PM

To: Marble, Robert D < <u>robert.marble@usbank.com</u>>; UST Duty Officer * DEQ

<<u>UST.DutyOfficer@DEQ.oregon.gov</u>>

Cc: Knepper, Alan M <<u>alan.knepper@usbank.com</u>> **Subject:** RE: UST Facility 10784: US Bank Operations

Hello Robert.

Thank you for the response.

As for the payment, please do your best to process the payment by the due date. There is a short grace period for payments and understand that it takes some time for checks to be mailed and then processed by the DEQ accounting department.

There are two due dates, one for the payment of the fine and the later due date for the corrective actions. We typically give 30 days for payment of the fine and 60 days to correct any violations witnessed during the inspection. I hope this better explains why there are two due dates listed.

It is not necessary to submit the forms a second time with the completion of the corrective actions. As long as the DEQ has one copy of signed forms with payment.



Emily Litke (she/her)

Duty Officer, Underground Storage Tanks

DEQ Headquarters, Land Quality Division

700 NE Multnomah Street, Suite 600 Portland OR 97232-4100

503-806-9516

Emily.LITKE@deq.oregon.gov

From: Marble, Robert D < <u>robert.marble@usbank.com</u>>

Sent: Friday, September 27, 2024 2:21 PM

To: UST Duty Officer * DEQ < <u>UST.DutyOfficer@DEQ.oregon.gov</u>>

Cc: Knepper, Alan M <<u>alan.knepper@usbank.com</u>> **Subject:** RE: UST Facility 10784: US Bank Operations

Hello Emily,

I'll be submitting this document in lieu of an invoice to my invoice processing team today, it will be paid with the October invoice batch.

Two question though:

Question 1:

I'm unsure if they will be able to pay by the 10/17 date, as the bank processes payments outside of my control. I'm assuming we'll receive an additional fine for that, any idea of what dollar amount to expect?

Otherwise we appear to be on track. I've engaged Mascott and they have confirmed the scheduled date of 10/15 to complete the required testing, and Mark Drouin from DEQ said he'll be onsite for the testing as well.

Ouestion 2:

On the citation letter page 1, it states to select either option 1 or option 2, and return a signed copy of this letter by 10/15/24.

But on page 3, it states to sign the letter, correct the violations, and return the form by 11/17/24.

I'm interpreting this to mean that page 3 is submitted separately, after the violations are corrected, but to return pages 1 and 2 with the option selected prior to the earlier date? Please let me know if I've interpreted it incorrectly.

I've attached the signed copy pages 1 and 2 of the citation, with the Option 1 checkbox selected. And will return page 3 with signature after the violations have been corrected on 10/15. But again, please correct me if I'm misunderstanding the instructions.

Was there anything else needed from us at this point?

Thanks!

Robert D Marble

Vice President | Property/Facility Region Mgr

O: 503-401-4790 | **M**: 503-866-3478 | <u>robert.marble@usbank.com</u>

U.S. Bank Columbia Center

17650 NE Sandy Blvd, Gresham, OR 97230-5000 | PD-OR-C1EG | usbank.com

From: UST Duty Officer * DEQ < <u>UST.DutyOfficer@DEQ.oregon.gov</u>>

Sent: Thursday, September 19, 2024 10:45 AM **To:** Marble, Robert D < <u>robert.marble@usbank.com</u>> **Cc:** Knepper, Alan M < <u>alan.knepper@usbank.com</u>>

Subject: [EXTERNAL] RE: UST Facility 10784: US Bank Operations

[WARNING] Use caution when opening attachments or links from unknown senders.

Hey Robert,

I am following up on the inspection conducted by Mark Drouin on 9/4/2024 for **facility 10784 US Bank Operations**.

I have attached the field citation. Deadline for the \$1400 fine is 10/17/24 and the deadline for the corrective actions is 11/17/24

I know you mentioned that Mascot will be on site on 10/15/24, but please let us know if the

testing date changes.



Emily Litke (she/her)

Duty Officer, Underground Storage Tanks DEQ Headquarters, Land Quality Division 700 NE Multnomah Street, Suite 600 Portland OR 97232-4100 503-806-9516

Emily.LITKE@deq.oregon.gov

From: Marble, Robert D < <u>robert.marble@usbank.com</u>>

Sent: Tuesday, September 10, 2024 12:23 PM

To: UST Duty Officer * DEQ < <u>UST.DutyOfficer@DEQ.oregon.gov</u>>

Cc: Knepper, Alan M <<u>alan.knepper@usbank.com</u>>; SPENCER Alex * DEQ

<Alex.SPENCER@deg.oregon.gov>

Subject: RE: UST Facility 10784: US Bank Operations

Received, thank you Mark.

I've sent this over to Mascott to make sure we're scheduled for the correct testing services for 10/15. I'll follow up once they've assigned the work request, and we have a the start time. Also, I'll discuss the STP devices with them and see if they can handle opening / manipulating them for your review.

Thanks!

Robert D Marble

Vice President | Property/Facility Region Mgr

O: 503-401-4790 | **M**: 503-866-3478 | <u>robert.marble@usbank.com</u>

U.S. Bank Columbia Center

17650 NE Sandy Blvd, Gresham, OR 97230-5000 | PD-OR-C1EG | usbank.com

From: UST Duty Officer * DEQ < UST. Duty Officer@DEQ.oregon.gov >

Sent: Monday, September 9, 2024 4:24 PM

To: Marble, Robert D < <u>robert.marble@usbank.com</u>>

Cc: Knepper, Alan M <<u>alan.knepper@usbank.com</u>>; SPENCER Alex * DEQ

<<u>Alex.SPENCER@deg.oregon.gov</u>>

Subject: [EXTERNAL] UST Facility 10784: US Bank Operations

[WARNING] Use caution when opening attachments or links from unknown senders.

Robert,

Thanks for meeting with us on September 4, 2024, for the UST inspection. As I communicated during the inspection, it appears US Bank is missing the annual and triennial compliance testing for this facility which are violations of the UST rules. Our Enforcement Specialist will issue the enforcement documentation regarding this inspection.

You stated that Mascott will be on-site on October 15, 2024, to complete the 2024 testing. I would like to come out on that day to talk more about the system. I think the dual turbines are operated by the STP-SCI drives. Can you be prepared to open those four STP-SCI drives. Also, do you have the volume of that trench?

I attached a video of how to sound the overfill alarm using the Veeder Root 450. It is a 18 mb file so hopefully it comes through.

Based on your system this is the following testing that is required to be completed on October 15, 2024.

- Annual release detection operability testing, All the following must be tested:
 - Leak detectors
 - Tank top sump and trench sensors (sensors must be removed and tested in water)
 - o Tank interstitial sensors (this sensor must be removed and tested in water)
- Annual testing of the tank probes
- Triennial testing of the overfill alarm (this will be conducted when the probes are removed)
- Triennial testing of the spill buckets and tank top sumps

The following are the violations I observed during the inspection:

- Failure to test spill prevention equipment and sumps used for interstitial monitoring at least once every 3 years (C1e)
- Failure to inspect overfill equipment at least once every 3 years (C2c)
- Failure to perform an annual test of operation of line leak detector. (H2.9)
- Failure to conduct annual operability testing of the release detection system (tank gauge, probes, and sensors). (G5)

Submit the testing results from the October 15, 2024, compliance testing to the DEQ by November 30, 2025.

As I stated previously, our Enforcement Specialist will provide you with the appropriate enforcement documentation.

If you have any questions please do not hesitate to contact me

Mark Drouin 541.213.1204 UST Compliance Program

From: Marble, Robert D <<u>robert.marble@usbank.com</u>>

Sent: Wednesday, August 28, 2024 10:39 AM

To: DROUIN Mark * DEQ < mark.drouin@deq.oregon.gov >

Cc: Knepper, Alan M <<u>alan.knepper@usbank.com</u>>

Subject: RE: UST compliance inspection notice confirmation

The current Financial responsibility document is attached here.

Robert D Marble

Vice President | Property/Facility Region Mgr

O: 503-401-4790 | **M**: 503-866-3478 | <u>robert.marble@usbank.com</u>

U.S. Bank

Columbia Center

17650 NE Sandy Blvd, Gresham, OR 97230-5000 | PD-OR-C1EG | usbank.com

From: Marble, Robert D

Sent: Wednesday, August 28, 2024 10:30 AM

To: mark.drouin@deq.oregon.gov

Cc: Knepper, Alan M <<u>alan.knepper@usbank.com</u>>

Subject: RE: UST compliance inspection notice confirmation

In preparation for your visit on 9/4, I've attached the first batch of requirement documentation. This batch covers the fuel handler certification training for my team.

I'll send over the other items as I get them reviewed and compiled.

Thanks!

Robert D Marble

Vice President | Property/Facility Region Mgr

O: 503-401-4790 | **M**: 503-866-3478 | <u>robert.marble@usbank.com</u>

U.S. Bank Columbia Center

17650 NE Sandy Blvd, Gresham, OR 97230-5000 | PD-OR-C1EG | usbank.com

From: Marble, Robert D

Sent: Monday, August 5, 2024 3:24 PM

To: mark.drouin@deq.oregon.gov

Cc: Knepper, Alan M <<u>alan.knepper@usbank.com</u>> **Subject:** UST compliance inspection notice confirmation

Hello Mark,

I'm confirming receipt of the UST compliance inspection notification, received today. I'll get the necessary documentation compiled and ready for inspection for stated appointment on 9/24 at 0900 Hrs.

A few notes about accessing the site:

- 1. Government issued photo ID required at entrance gate
- 2. Easiest access gate is from 17650 NE Sandy Blvd.
- 3. Once onsite, enter through the front door and check in at the Security desk in the lobby. Let the guard know you are here to see Robert from Engineering. They'll call me on the radio, and I'll come get you signed in and taken to the physical plant where the UST's are located

Thanks!

Robert D Marble

Vice President | Property/Facility Region Mgr

O: 503-401-4790 | **M**: 503-866-3478 | <u>robert.marble@usbank.com</u>

U.S. Bank Columbia Center

17650 NE Sandy Blvd, Gresham, OR 97230-5000 | PD-OR-C1EG | usbank.com

U.S. BANCORP made the following annotations

Electronic Privacy Notice. This e-mail, and any attachments, contains information that is, or may be, covered by electronic communications privacy laws, and is also confidential and proprietary in nature. If you are not the intended recipient, please be advised that you are legally prohibited from retaining, using, copying, distributing, or otherwise disclosing this information in any manner. Instead, please reply to the sender that you have received this communication in error, and then immediately delete it. Thank you in advance for your cooperation.

U.S. BANCORP made the following annotations

Electronic Privacy Notice. This e-mail, and any attachments, contains information that is, or may be, covered by electronic communications privacy laws, and is also confidential and proprietary in nature. If you are not the intended recipient, please be advised that you are legally prohibited from retaining, using, copying, distributing, or otherwise disclosing this information in any manner. Instead, please reply to the sender that you have received this communication in error, and then immediately delete it. Thank you in advance for your cooperation.

U.S. BANCORP made the following annotations

Electronic Privacy Notice. This e-mail, and any attachments, contains information that

is, or may be, covered by electronic communications privacy laws, and is also confidential and proprietary in nature. If you are not the intended recipient, please be advised that you are legally prohibited from retaining, using, copying, distributing, or otherwise disclosing this information in any manner. Instead, please reply to the sender that you have received this communication in error, and then immediately delete it. Thank you in advance for your cooperation.

U.S. BANCORP made the following annotations

Electronic Privacy Notice. This e-mail, and any attachments, contains information that is, or may be, covered by electronic communications privacy laws, and is also confidential and proprietary in nature. If you are not the intended recipient, please be advised that you are legally prohibited from retaining, using, copying, distributing, or otherwise disclosing this information in any manner. Instead, please reply to the sender that you have received this communication in error, and then immediately delete it. Thank you in advance for your cooperation.



DataBase Connection: PROD

Program Enforcement

Program Enforcement Maintenance

Violations List (4)



File # 10	O784 Create PEN Create OCE Enforcement			Related Items	5
		View S	elected		
Name	US BANK OPERATIONS CENTER		ID	Name/Reference	Date
Location	17650 NE SANDY BLVD / PORTLAND /		22057	Full Compliance Inspection (FCI)	09/04/2024
Darmit	MIJITNOMAH UST General Permit.26-10784-2020-INST.Active	Select	PE: 9541	Field Citation	09/17/2024
remit	UST General Permit.20-10784-2020-INST.Active		Vio:	(H2) Release Detection Pressure Piping - TCR	09/04/2024
Recipient	Show Recipient Selection	Select	20450 SV	(G) General Release	09/04/2024
Information:			Vio: 20451	Detection - TCR	
Name / Title	Marble, Rob /	Select	SV Vio:	(C) Spill and Overfill Prevention - TCR	09/04/2024
Address	17650 NE Sandy Blvd / Portland / OR / 97230-	Select	20452 SV	(C) Spill and Overfill	09/04/2024
Db / 5 /	5000		Vio:	Prevention - TCR	
	(503) 401-4790 / 503-257-1833 / robert.marble@usbank.com		20453		
	Edit Delete			Legend	1
_		ID T	уре	Description	
Program Enforcement	2024-FC-9541	SV PE		Site Visit Program Enforceme	ent
Number		SV Vic)	Site Visit Violation	
Number					
Regulatory Program	Underground Storage Tanks				
Staff Assigned	Diana Foss		Con	npliance Events Rep	ort
Enforcement	Field Citation				
Туре					
Enforcement	09/17/2024 Show Calendar				
Action Issued	09/17/2024 Show Calendar				
Date					
Response	Show Calendar				
Received Date	SHOW Calefluar				
Payment Due	10/19/2024 Show Calendar				
Date					
Payment Received Date	10/16/2024 Show Calendar				
Penalty Amount	\$1,400.00				

Corrective Actions (0)

Link Actions

PEN Referral Date	Show Calendar
Closed Date	Show Calendar
Withdrawn Date	Show Calendar
Link To Complaint	
Comments Pd 10/18; ACH 1861392; \$1400.00; US Bank Edit Delete	
Create By 09	
Last Update By 10	7.07.10.BM 7.18/2024 Tanischa Smith
	Create PEN Create OCE Enforcement