



Oregon Department of Environmental Quality
SSO Reporting Form



This information must be submitted within 5 days of becoming aware of the overflow.
Please complete online and print for signature. Be sure to fill out all fields.

FACILITY/CONTACT INFORMATION

Name of Permittee: City of Bend

Contact Name: Justin Young

Phone:

Email:

County:

541-323-8546

jyoung@bendoregon.gov

Deschutes

DEQ Permit # (see permit face page): 101572

DEQ File #:7519

OERS Incident #: 2025-1439

Date Reported to OERS: 6/11/2025

Date Reported To DEQ: 6/11/2025

Today's Date: 6/11/2025

Date SSO Started (if known): 6/11/2025

Time Started (if known): 8:35 am

Date SSO Stopped (if known): 6/11/2025

Time Stopped (if known):

SSO Location: Manhole

CMH003481

SSO Nearest Address: 25 NW Olney Ave

City: Bend

Zip Code: 97703

SSO Latitude (if known):

Longitude (if known):

Estimate of Quantity Overflowed: 50 Gallons or less

(Gallons) [Link to estimation method](#)

Did the SSO discharge to surface water? No

Name of waterbody: N/A

PUBLIC NOTIFICATION

Notified downstream drinking water sources (List Below)? N/A

Name of drinking water facility:

Signs Posted? N/A

Media contacted? N/A

Who?

List any other steps taken to notify the public or state/federal agencies:

CAUSES

Cause or suspected cause of the overflow: Blockage - Other

If needed, attach additional sheets

Blockage caused by contractor equipment used for construction.

Rainfall in the 24 hours prior to SSO (for storm-related overflows):

(inches)

Source of rainfall data:

If needed, attach additional sheets

1-in-5 year 24 hour rainfall for the sewerage system area (if known):

(in/24hr)

EMERGENCY RESPONSE AND MIGRATION

List actions taken to stop and mitigate the impact of the SSO.

For overland flow:	Taped off affected area? No
	Cleaned up affected area? Yes
For SSO to surface water:	Bacteria samples taken to confirm impact? N/A
	Follow up bacteria samples taken to confirm end of impact? N/A

Describe monitoring and results:

For SSOs that impact buildings:	Pumped out flooded buildings? N/A
	Disinfected? N/A

Other measures taken (describe):

The area was already secured as it is an active construction site. A dirt berm was built in case additional spilling occurred while blockage was being removed. Applied lime to spill site for disinfection.


Steps taken or planned to reduce, eliminate, and prevent the reoccurrence of the overflow and schedule for those steps:

City provided contractor with specific instructions on how equipment should be secured in the manholes. Contractor provided city with photos documenting that the equipment is properly secured to prevent issue from reoccurring.

COMMENTS

An air hose that was attached to a pneumatic plug that was installed to aid bypass operations made its way into the gravity pipe and caused blockage, resulting in loss of capacity and small spill at the manhole listed above.

I CERTIFY UNDER PENALTY OF LAW THAT THIS DOCUMENT AND ALL ATTACHMENTS WERE PREPARED UNDER MY DIRECTION OR SUPERVISION IN ACCORDANCE WITH A SYSTEM DESIGNED TO ASSURE THAT QUALIFIED PERSONNEL PROPERLY GATHER AND EVALUATE THE INFORMATION SUBMITTED. BASED ON MY INQUIRY OF THE PERSON OR PERSONS WHO MANAGE THE SYSTEM, OR THOSE PERSONS DIRECTLY RESPONSIBLE FOR GATHERING THE INFORMATION, THE INFORMATION SUBMITTED IS, TO THE BEST OF MY KNOWLEDGE AND BELIEF, TRUE, ACCURATE, AND COMPLETE. I AM AWARE THAT THERE ARE SIGNIFICANT PENALTIES FOR SUBMITTING FALSE INFORMATION, INCLUDING THE POSSIBILITY OF FINE AND IMPRISONMENT FOR KNOWING VIOLATIONS.



Authorized Signature

Justin Young

Name (print)

6/11/2025

Date

541-323-8546

Phone Number

*You may attach additional information to this report before sending to DEQ as needed to explain the circumstances of the overflow. This information may include but is not limited to: maintenance records and bacteria monitoring results.

Upon completion, print out this form and send to the appropriate DEQ Address:

Portland-Permit Coordinator
700 NE Multnomah St., Suite 600
Portland, OR 97232

Salem-Permit Coordinator
4026 Fairview Industrial Dr. SE
Salem, OR 97302

Pendleton-Permit Coordinator
800 SE Emigrant, #330 Pendleton,
OR 97801

FOR DEQ PERSONNEL ONLY

☐ Pre-Enforcement Notice

☐ Warning Letter

No enforcement action was warranted because:

☐ The SSO was caused by unpreventable vandalism or similar force majeure; or

☐ The SSO is allowed as an exception to the permit as maintenance; or

☐ The cause of the current SSO was beyond reasonable control AND we do not expect the permittee to prevent similar SSOs in the future; or

☒ The SSO was 400 gallons or less, spilled to the ground and not reaching surface water; permittee properly reported, cleaned up, and took appropriate public notice measures; and the SSO was not part of a chronic problem.

COMMENTS