From: WESTERSUND Joe
To: JOHNSON Keith
Cc: DAVIS George; artglass2016
Subject: art glass public comment- points we need Keith"s help on
Date: Tuesday, August 23, 2016 5:27:27 PM

Hi Keith,

George and I are working on the public comment response. There are a couple of questions/comments that we'd like your help to respond to.

Would you be willing to draft a response for the two comments below?

-Joe

Comment # (in Joe's spreadsheet)	Comment	DEQ Response
4	The pollution measured around Bullseye may be coming from other sources. DEQ should have collected more wind direction and velocity data. It is likely that metals pollution near Bullseye is actually coming from fly ash used in making cement at the Lehigh Cement facility. There may be other point sources and mobile sources of these pollutants.	DEQ's work to identify and control sources of air toxics around the Bullseye facility is ongoing. [add something about why we think Bullseye is contributing? Did we actually collect wind direction and velocity data? Do we know whether Lehigh uses fly ash?]
41	Ambient concentrations didn't decrease after the temp rule was put in place, so the pollution must be coming from other sources.	

Joe Westersund
Oregon Department of Environmental Quality
811 SW 6th Avenue, Portland, OR 97204
(503) 229-6240 office
westersund.joe@deq.state.or.us
Usual Schedule: 8am - 5pm, M-F