




959 Port Of Columbia County - Former Pope & Talbot PHOTOS
September 24, 2008
Site Visit

#959
PSH: Photos
9/24/08



















959 Port Of Columbia - Former Pope & Talbot PHOTOS
2008
Site Visit - On A Disk

Port of St. Helens
9/24/08

General Views



Photo 1 Looking west from dock



Photo 2 Looking east from dock



Photo 3 Looking east from east end of “turning table” at basalt outcrop.



Photo 4 Basalt outcrop near east end of site. Note seepage from fractures at lower right.

Known seep west of dock



Photo 5 Close-up showing colloidal iron and iron precipitate



Photo 6 Close up of seep water.



Photo 7 Seep location at contact between lower silt/clay layer and overlying alluvium.



Photo 8 Close-up of seep.



Photo 9 Close-up of seep showing contamination seam



Photo 10 Close-up of seep showing contamination seam

Seep area between dock and turning table.



Photo 11 Contamination mixed with wood debris



Photo 12 Wide view of contamination.



Photo 13 “Sheen bursts” in sand.



Photo 14 “Tar ball” composed of oil and woody debris.

Free product in mud, west of dock.



Photo 15 Flowing free product, approximately 2 inches long.



Photo 16 Flowing free product, pool is approximately 4 inches across.




Photo 17 Free product in pool producing sheen.




Photo 18 Small bleb of free product producing long sheen track.

















































