From: HOY Ray
To: LANDES Franziska
Subject: RE: ECSI #2062 Myers Container
Date: Friday, April 3, 2020 8:05:43 AM
Attachments: image001.png

Hi Franziska

I think you're on the right path with the city.
Once you receive the monitoring data
From the permit then that would satisfy ODOT. Thanks

Sent from my Verizon, Samsung Galaxy smartphone

-------- Original message --------
From: LANDES Franziska <Landes.Franziska@deq.state.or.us>
Date: 4/2/20 6:06 PM (GMT-08:00)
To: HOY Ray <HOY.Ray@deq.state.or.us>
Subject: RE: ECSI #2062 Myers Container

Hi Ray,

Yes – I called him. The bullet points below are from our conversation. If you have any guidance on what DEQ typically requests from ODOT for cleanouts of culverts near ECSI sites, please let me know.

Thanks,
Franziska

From: HOY Ray <HOY.Ray@deq.state.or.us>
Sent: Thursday, April 2, 2020 5:59 PM
To: LANDES Franziska <Landes.Franziska@deq.state.or.us>
Subject: RE: ECSI #2062 Myers Container

Thanks Franziska, were you able to follow up with Charles Schwarz? ray

---

From: LANDES Franziska <Landes.Franziska@deq.state.or.us>
Sent: Thursday, April 2, 2020 4:57 PM
To: HOY Ray <HOY.Ray@deq.state.or.us>; SCHWARZ Bob <SCHWARZ.Bob@deq.state.or.us>; MILLER Sarah <MILLER.Sarah@deq.state.or.us>
Cc: SEIDEL Paul <SEIDEL.Paul@deq.state.or.us>; PUGH Mark <PUGH.Mark@deq.state.or.us>; DANA Kevin <DANA.Kevin@deq.state.or.us>
Subject: RE: ECSI #2062 Myers Container

Hi all,

If anyone has more background information on the Myer's site, please let me know. Otherwise, please see below as an FYI.

- It appears the culvert beneath I-205 is at least partially blocked and water is backing up and pooling on the Myers Container (ECSI #2052, NFA Memo) site.
- ODOT wants to clean out the culvert, but wants to make sure that this doesn't release any potentially PCB-contaminated sediments to Johnson Lake (ESCI #1311, NFA Memo) in 2009.
    - I just inherited this site from Kim and they are in long-term O&M.
    - In addition to the Johnson Lake EES, ODOT also signed an EES near Johnson's Lake for their property right of way by I-205. I can't find the final EES, but here is the text, and here is the signage page.
- I reached out to Sarah, who will reach out to the city to see about the status of on-going stormwater permits for

the Myers site. The Myer's NFA indicates that on-going monitoring of stormwater will be handled by a NPDES and a 1200-COLS permit.

Please let me know if you have any questions.

Thanks,
Franziska

From: LANDES Franziska
Sent: Thursday, April 2, 2020 3:28 PM
To: HOY Ray <HOY.Ray@deq.state.or.us>; PUGH Mark <PUGH.Mark@deq.state.or.us>; DANA Kevin <DANA.Kevin@deq.state.or.us>
Cc: SEIDEL Paul <SEIDEL.Paul@deq.state.or.us>
Subject: RE: ECSI #2062 Myers Container

Hi all,

I'm about to call Charles and will update you ASAP.

Franziska

From: HOY Ray <HOY.Ray@deq.state.or.us>
Sent: Thursday, April 2, 2020 3:14 PM
To: SCHWARZ Charles <Charles.SCHWARZ@odot.state.or.us>; PUGH Mark <PUGH.Mark@deq.state.or.us>; LANDES Franziska <Landes.Franziska@deq.state.or.us>; DANA Kevin <DANA.Kevin@deq.state.or.us>
Cc: SEIDEL Paul <SEIDEL.Paul@deq.state.or.us>
Subject: RE: ECSI #2062 Myers Container

Hi Charles,

We don't have a PM assigned to this site currently. I'm ccing a few folks here that might have some history on the site.

Ray

Ray Hoy
Oregon Department of Environmental Quality
NWR Clean-up Project Manager and Site Assessment Coordinator
700 NE Multnomah St., Suite #600
Portland, OR 97232
503 229-5069; 503 537 8718

From: SCHWARZ Charles <Charles.SCHWARZ@odot.state.or.us>
Sent: Thursday, April 2, 2020 2:28 PM
To: HOY Ray <Ray.HOY@state.or.us>
Subject: ECSI #2062 Myers Container

Hi Ray, sorry to bother you. Who can I contact at DEQ about this site?
There's a culvert drainage issue requiring attention and we don't want to impact Johnson Lake (1311).

Charles Schwarz, RG
Senior Environmental Geologist
Oregon Department of Transportation
123 NW Flanders St
Portland, OR 97209
Cell 503-880-9074
Office 503-731-8290