

Art Glass Public Hearing

3/19/2016

Start recording

general glass - As, Cd

Owens Brockaway - Pb

colored cullet = raw material

James Knox → Northstar

- nonweight threshold
- should apply statewide
- grain loading better than 79%.

Abe Fleisman → Northstar

- < 10 tons yes down to 1 lb
- should apply statewide / nationwide
- 99% public shall care what's coming out of the bagsource. Grain loading good.
99% test = \$350k.
- Cd. Tier I have all stopped using Cd voluntarily. 65% so far. voluntary rate.

Craig Parfet - exec director Pollution Clear Air.

- PDX worst for diesel filters

~ 1000 members

Bullseye 7000 lbs heavy metals

DEQ should focus on serious polluters

Owens Brockaway
General Glass

platters using hex chrome
tank farms

OED is charging fees to get info
wants health driven not media driven rules
cooperative
transparent
will do door-to-door calls in Bullseye area

Chris Minn

regional baggage

- concerned role as written will impact hobby artists
- 1 - def of melt / molten glass
 - 2 - def of Kiln
 - 3 - def of colored glass
 - 4 - 1 lb threshold

process of melt shall be regulated
Kiln workers, lamp workers subject?

melt: process of moving to fully liquid

Kiln: refractory lined vessel where raw materials
charged & brought to fully liquid state
to make new glass

colored glass should not count as raw material

unless full melt in gas furnace or ^{outgassing} raw materials

not < 10 ton, other glass processes should be regulated
in other permitting if at all

Statewide: all areas went clean air, why
no users on ad. comm?

Kathleen Solzman ^{not represented} EPA lawyer - private citizen

CRAs law center keep rule comments

- to CRA suggestion for better Toxics rule
- shall include all heavy metals, not just Zn
 - short & long term benchmarks should be most protective
 - no reason to allow unregulated HAP.