

Review Type	DEQ Office	OLPRR Review		Incident Comments	Contractor Maintenance
NEW	MDF	First	Last		
1 of 1 Records		Next	Back		
OLPRR# 31784		Incident Data		Reported By	Kyle Fisher
Lookup LUST		Site Type	Regulated	RepBy Phone	5038608811
Site Name	RB Browns Trucking Inc	Received Date	10/18/2021	Company	DEQ
Site Address	5758 Crater Lake Ave Avenue				
Other Address					
City	Central Point	Zip Code	97502	County	Jackson
				Facility Id	7869 Lookup UST
				Phone	(541) 826-7420

Responsible Party	Mail Contacts	Invoice Contact
First Name	TJ	TJ
Last Name	Davis	Davis
Organization	RB Browns Trucking Inc	RB Browns Trucking Inc
Address	5758 Crater Lake Ave	5758 Crater Lake Ave
Address2		
City	Central Point	Central Point
State	OR	OR
Zip Code	97502	97502
Phone	541-826-0171	541-826-0171
E-Mail	tjdavis@rbrowns.com	tjdavis@rbrowns.com

Site Assessment	Discover Date	Discovery	Cause	Source	Confirmation
	10/15/2021	Decommissioning	Corrosion	Tank	Contractor
Contaminants			Impacted Media		
<input type="checkbox"/> Heating Oil	<input type="checkbox"/> Leaded Gasoline	<input type="checkbox"/> Misc. Gasoline	<input checked="" type="checkbox"/> Diesel (Motor Fuel)	<input type="checkbox"/> Groundwater	<input type="checkbox"/> Free Product
<input type="checkbox"/> Waste Oil	<input type="checkbox"/> Unleaded Gasoline	<input type="checkbox"/> Lubricant	<input type="checkbox"/> Solvent	<input type="checkbox"/> Surface Water	<input type="checkbox"/> Vapor
<input type="checkbox"/> Other Pet. Dist.	<input type="checkbox"/> Chemical	<input type="checkbox"/> MTBE	<input type="checkbox"/> Unknown	<input type="checkbox"/> Drinking Water	<input checked="" type="checkbox"/> Soil
Accept	Hold	Decline	Close		

Database: PROD OLPRR Comments

RB BROWNS TRUCKING; KYLE@POINTSOURCESOLUTIONS.COM; DISCOVERED TWO 1,000 GALLON USTS WHILE DIGGING TO REMOVE PRODUCT LINES CONNECTED TO 10,000 GALLON UST DURING DECOMMISSIONING PROCESS. PRODUCT LINES PLUMBED FROM 10,000 GALLON DIESEL TANK AND TERMINATED IN TOP OF TWO. CONTENTS INCLUDED WATER AND DIESEL. WHEN REMOVING, OBSERVED STAINED SOILS BENEATH TANKS AND HOLES IN TANK BOTTOMS. CONTAMINATED SOIL WAS REMOVED BENEATH TANKS UNTIL BEDROCK AT 7 FEET WAS ENCOUNTERED.