

UST Inspection Survey

Submitted by: blakely.gilbert_deq

Submitted time: Nov 18, 2025, 5:05:22 PM

Date

Nov 18, 2025

Time

11:27

UST Facility ID

7,837

Inspector


Gilbert

Type of Inspection

Full Compliance

Location

Lat: 44.575588 Lon: -123.275474





Esri, FAO, NOAA, USGS

Powered by Esri

Photograph



photos-20251118-201716.jpg



Oregon Department of Environmental Quality - Underground Storage Tank Program
 Technical Compliance Inspection Report - UST Inspection Report

Inspector: Steve Miller Date: 11-14-18 Time: 9:00 Facility: 2837

Site Information	Facility Name: TANK COIL # 21	Site No: 1000	Site Class: 21
	Site Address: 420 NW 7th St	City: Astoria	State: OR
	County: CLATSOP	Zip: 97103	Phone: 503-325-8881
	Owner: P 7776	Operator: KX-766-2500	SW: 766-3483
	UIC Number: 1A	2A	3A
UIC Percent	READG	READH	RESKH
Removal Status	12000	6000	6000

Compliance: Yes No

Notes and Comments from the UST database: Check for before conducting inspection

If tanks are inspected, which tanks: Compliance Yes No

Operating Conditions: Current Idle Planned for delivery/draw to observe

Operator Training: Compliance Yes No

Class A/B Operator: Yes No Name: Date:

Class C Operator: Yes No Cardlock Compliance Yes No

Financial Responsibility: High Date: End Date:

Coverage amount correct: Yes No Number of tanks covered:

Financial responsibility could also be in the form of self insurance, bonds, and guarantees, surety, or a guarantee


Multi-trench Requirements: Compliance Yes No

Spill prevention and release detection equipment checked monthly? Yes No


Tank top cover checked annually: Yes No Page 1 of 4




photos-20251118-201600.jpg



photos-20251118-201055.jpg



photos-20251118-200352.jpg





photos-20251118-193019.jpg



photos-20251118-193003.jpg



Completed

Oregon Department of Environmental Quality - Underground Storage Tank Program
Technical Compliance Inspection - UST Inspection Report

Inspector: Blake Gilbert

Date: ~~11-18-25~~ ~~11-19-25~~ 11-18-25

Time: 2:00 pm

Facility: 7837

I. Site Information

Facility Name: Tank Comp # 21	Permittee: John Hunt	Contact: Tom Cathrop
Site Address: 820 NW St Kings St	Organization:	Phone: 511-775-8871
City: Corvallis OR 97330	Phone: 541-758-1500	503-758-5283

II. Tank Information

	1A	2A	2B
DEQ Permit #	BEADG	BEADH	BEBKA
Estimated Gallons	12000	6000	6000
Substance	R	P	P
Tank Material	Composite fiber	" "	" "
Tank Install Date	11/9/97	" "	" "
Pipe Material DW	Fluor plastic	" "	" "
Pipe Type	Pressure	" "	" "
Pipe Install Date	11/9/97	" "	" "
Overfill Device	Alarm	" "	" "

Check file before conducting inspection

Notes and Comments from the UST database:

If tanks are manifolded, which tanks:

Compliance Yes No

III. Operating Certificate

Current Accurate Posted for delivery drive to observe

Compliance Yes No

IV. Operator Training

Class A/B Operator Yes No Name: Tom Cathrop Date: 2-15-12

Class C Operator Yes No Cardlock

Compliance Yes No

V. Financial Responsibility

Type of coverage: Insurance Begin Date: 11-1-25 End Date: 11-1-26

Coverage amount correct: Yes No Number of tanks covered: 3

Financial responsibility could also be in the form of self insurance, bonds, local government, trust fund, and or guarantee

Compliance Yes No

VI. Walkthrough Requirements

Spill prevention and release detection equipment checked monthly? Yes No

Tank top sumps checked annually? Yes No

VII: Release Detection

Compliance

Yes No

a) Annual Release Detection Operability Testing (Sometimes referred to as Tank Gauge Certification)

Date of last testing: 8-25-25 9-16-24 8-25-27 Last three tests available? Yes No

b) Piping Release Detection (Check all that apply)

Pressurized Piping

Mechanical Leak Detector (MLLD) Electronic Leak Detector (ELLD) - check for swiftcheck requirement

Date of last testing: 8-25-25 Last three tests available? Yes No

Number of lines tested: 3 Number of LD tested: 3

Leak detector manufacturer make and model: 79LD-2000

Tank gauge manufacturer make and model: TLS-450 Plus

MLLD on turbine manifold? Yes No

MLLD product appropriate? (Example, diesel Red Jacket FX series on diesel system?) Yes No

If ELLD and no line testing: Annual 0.1 gph results from tank gauge? Yes No

Interstitial Monitoring

[Monthly records must include, date system was checked, observations made, initials of person checking. Electronic records must include power status (on or off), alarm indication status (yes or no) and sensor malfunction notes (yes or no).]

Date of last sump testing: _____ Last two tests available? Yes No

Date of last sensor testing: _____ Last three tests available? Yes No

Float sensors installed correctly? Yes No

Interstitial space opened to sump? Yes No

Presence of water in sumps? Yes No

Safe Suction

Check valve directly below suction pump? Yes No

c) Monthly Tank Release Detection (Check all that apply)

Tank Gauge CSLD SCALD Static

Are correct tank sizes programmed at tank gauge? Yes No

Tank diameter/length seem appropriate? Yes No

Are tanks manifolded? Yes No

If so, tank gauge testing setup for manifolded tanks? Yes No

If Veeder Root tank gauge leak detection

CSLD set at 99%

Thermal coefficient set correctly?

(Gasoline 0.00070; Diesel 0.00045)

If Incon/Franklin tank gauge leak detection

If SCALD is Vol Qual set to 14% (or 99% confidence)

Is API gravity set correctly?

(Regular 63.5; Plus 62.8; Super 51.3; Diesel 32.8)

For all tank gauges doing static tests

(Static tests require tank to be 50% full for a valid test)

Interstitial Monitoring [Monthly records must include, date system was checked, observations made, initials of person checking. Electronic records must include power status (on or off), alarm indication status (yes or no) and sensor malfunction notes (yes or no).]

SIR Ensure pass or fail results within 30-day period. Inconclusive result means release detection requirement not met

"online print out good"

Tank release detection records available during inspection

T1:	<input type="checkbox"/> Jan	<input type="checkbox"/> Feb	<input type="checkbox"/> Mar	<input type="checkbox"/> Apr	<input type="checkbox"/> May	<input type="checkbox"/> Jun	<input type="checkbox"/> Jul	<input type="checkbox"/> Aug	<input type="checkbox"/> Sep	<input type="checkbox"/> Oct	<input type="checkbox"/> Nov	<input checked="" type="checkbox"/> Dec
T2:	<input type="checkbox"/> Jan	<input type="checkbox"/> Feb	<input type="checkbox"/> Mar	<input type="checkbox"/> Apr	<input type="checkbox"/> May	<input type="checkbox"/> Jun	<input type="checkbox"/> Jul	<input type="checkbox"/> Aug	<input type="checkbox"/> Sep	<input type="checkbox"/> Oct	<input type="checkbox"/> Nov	<input type="checkbox"/> Dec
T3:	<input checked="" type="checkbox"/> Jan	<input type="checkbox"/> Feb	<input type="checkbox"/> Mar	<input type="checkbox"/> Apr	<input type="checkbox"/> May	<input type="checkbox"/> Jun	<input type="checkbox"/> Jul	<input type="checkbox"/> Aug	<input type="checkbox"/> Sep	<input type="checkbox"/> Oct	<input type="checkbox"/> Nov	<input type="checkbox"/> Dec
T4:	<input type="checkbox"/> Jan	<input type="checkbox"/> Feb	<input type="checkbox"/> Mar	<input type="checkbox"/> Apr	<input type="checkbox"/> May	<input type="checkbox"/> Jun	<input type="checkbox"/> Jul	<input type="checkbox"/> Aug	<input type="checkbox"/> Sep	<input type="checkbox"/> Oct	<input type="checkbox"/> Nov	<input type="checkbox"/> Dec
T5:	<input type="checkbox"/> Jan	<input type="checkbox"/> Feb	<input type="checkbox"/> Mar	<input type="checkbox"/> Apr	<input type="checkbox"/> May	<input type="checkbox"/> Jun	<input type="checkbox"/> Jul	<input type="checkbox"/> Aug	<input type="checkbox"/> Sep	<input type="checkbox"/> Oct	<input type="checkbox"/> Nov	<input type="checkbox"/> Dec

Inspector: Blake Gilbert

Date: 11/10/25

Time: 1:00

Facility: 7837

VIII. Spill Prevention Compliance Yes No

Date(s) of testing: 9/25/23 9-15-29 Number of spill buckets tested? 3
Did spill bucket pass most recent testing? Yes No If no, was spill bucket replaced/repared? Yes No
During inspection, visual damage to spill bucket? Yes No

fail then replaced and retested on 1-29-21

Hydrostatic testing (test takes one hour to complete)
 Vacuum test (test takes 1 minute, ending vacuum must be 26 inches water column or greater)

IX. Overfill Prevention Compliance Yes No

Date(s) of testing: 9-16-24 10/6/23
Overfill device pass most recent testing? Yes No If no, overfill device replaced? Yes No

Overfill method that was tested: Alarm Flapper Ball Float
Overfill Alarm
Alarm sounds when tank is 90% full Yes No
Driver can see or hear alarm at point of transfer? Yes No
Sound alarm from tank gauge during inspection? Yes No

Flapper Valve
Testing verified the valve automatically restricts flow at 95% Yes No
Visual observation of flapper on day of inspection? Yes No

Ball Float
Testing verified the ball float automatically restricts flow at 90% Yes No
Visual observation of ball float during inspection? Yes No

X. Corrosion Protection Compliance Yes No

Cathodic Galvanic Impressed Current

Steel tank with cathodic? Yes No
Steel pipes with cathodic? Yes No
Steel flex-lines with cathodic? Yes No

Date of cathodic test: _____
Last two tests available? Yes No
Did last test pass? Yes No
If not:
Was failed test reported to DEQ? Yes No
Was system repaired? Yes No
Date of repair? _____
Cathodic retested within 6 mos. of repair? Yes No
Date of retesting? _____

If impressed current system:
Rectifier Operational? Yes No
Rectifier log maintained? Yes No
Rectifier been operating continuously Yes No

Tank Lining
Date of last test? _____
Pressure test conducted after tank lining inspection? Yes No

XI: General notes from inspection

Representative onsite: Tom Lathrop email: _____

*Al ready
wrote
in* All three spill buckets failed testing on 9-15-20 and
were all replaced and retested on 1-29-21 and passed

Has Vender Robb 450 plus

old notes from last inspection still relevant from - The only thing
is now using TCS-450 plus

Compliance Determination: No Violations Observed Observed violations resulting in enforcement

Inspector Signature: Blake Gilbert

Date: 11/19/25



Oregon

Tina Kotek, Governor

Department of Environmental Quality

Northwest Region

700 NE Multnomah Street, Suite 600

Portland, OR 97232

(503) 229-5263

FAX (503) 229-6945

TTY 711

Tom Lathrop
Truax Corp #21
820 NW Kings
Corvallis, OR 97330

11/18/25

RE: UST Compliance Inspection
DEQ UST #7837
Truax Corp # 21

Attention Tom Lathrop

The Oregon Department of Environmental Quality (DEQ) finalized the underground storage tank (UST) full compliance inspection that was conducted at the facility listed above on November 18, 2025. The purpose of this letter is to inform you of the results of this inspection. Based on the records available and site conditions, the DEQ inspector did not observe any violations with applicable State of Oregon UST rules on this day.

During an inspection, DEQ attempts to conduct a thorough review of the UST system. Nonetheless, you, as the permittee and owner, remain responsible for complying with all applicable UST rules. Therefore, if a violation is observed during a subsequent inspection, the facility will be cited for this violation and may be subject to civil penalties.

The DEQ appreciates your efforts to operate and maintain your UST system in compliance with Oregon environmental law. This facility is subject to future inspections. Please remember to conduct service and maintenance inspections and periodic testing at the required intervals and to implement and/or maintain adequate record keeping. Some general recommendations for maintaining UST compliance are listed below.

- Monitor tanks and piping for leaks and keep twelve months of monthly and or daily records as necessary for your specific systems. **Notify the DEQ any leak test results indicating the possibility of a release (i.e., test failure) within 24 hours as a suspected release (OAR 340-150-0500) and immediately begin investigation under OAR 340-150-0510.**
- Maintain financial responsibility coverage for pollution liability.
- Keep spill prevention devices emptied and clean – particularly just before fuel deliveries.
- Schedule and complete UST system corrosion protection testing on the required 3 year schedule, if necessary.
- Monitor fuel delivery records for signs of overfilling to capacity and make corrections to defective overfill prevention equipment or improper delivery procedures as necessary.

- Be aware of any suspected release condition and keep an alarm log to record any such conditions. Suspected release conditions include failed tank or piping leak tests, fuel or liquid sensor alarms, fuel is found in secondary containments or when liquid of any kind (dry or vacuum systems) is found in a tank interstitial space. Such conditions must be reported to the DEQ within 24 hours and an investigation into the cause must be conducted.
- Contact your service provider for assistance with testing and alarm investigation.
- Contact your service provider and begin an investigation if you suspect fuel loss, equipment is malfunctioning, leak detectors are triggering, or product lines are losing prime.
- Report a confirmed release to the DEQ within 24 hours of confirming product loss into the subsurface in any amount.

Please contact me if you have any questions about this matter at the DEQ Northwest office at 503-360-4408 or blakely.gilbert@deq.oregon.gov.



Blake Gilbert
Natural Resource Specialist
Underground Storage Tank Program



Oregon

Tina Kotek, Governor

Department of Environmental Quality

Headquarters Office

700 NE Multnomah Street, Suite 600

Portland, OR 97232

(503) 229-5263

TTY 711

November 21, 2025

Tom Lathrop
Truax Corp # 21
820 NW 3rd St
Corvallis, Or 97330

RE: UST Compliance Inspection
DEQ UST # 7837

Tom Lathrop

The Oregon Department of Environmental Quality (DEQ) is conducting underground storage tank (UST) inspections throughout Oregon. The purpose of this letter is to inform you that your facility, among others, has been selected for inspection. A thorough inspection of your facility will be conducted to determine compliance with state and federal UST requirements. **The date you receive this letter is the date that the inspection starts.** If you have work done after that date, you will need to have the previous set of records available for evaluation in addition to the most recent records.

If I do not hear from you, the inspection for this facility is scheduled for November 05, 2025, starting at approximately 9:00 am. Please note that the inspection will require uninterrupted participation and attendance by you or a knowledgeable assistant. For the inspection you need to provide access to tank sumps, under dispenser areas, cathodic protection rectifiers, and leak monitoring equipment. DEQ will not touch the equipment or enter the facility, if you are unable to assist with equipment access, please have your UST Service Provider there. This inspection may also include review of Stage I Vapor Recovery.

To complete this inspection, you will need to have compliance testing records available on-site on the day of the inspection or sent to me prior to the inspection at blakely.gilbert@deq.oregon.gov. If the records are not available during the day of the inspection, you will have five (5) business days to provide the records to me electronically. After which time this facility will be subject to enforcement actions.

At a minimum the following records are required to complete this inspection:

- Line and leak detector testing results for the past three years,
- Monthly tank leak detection records (12 months),
- Class A, B, and C training documentation.
- Financial responsibility mechanism.
- Annual tank gauge / release detection equipment certification
- Spill prevention testing records
- Overfill Prevention Equipment testing
- Cathodic protection testing (if applicable)
- Tank lining records (if applicable)
- Monthly walkthroughs

As stated previously, DEQ will not touch any equipment and if you are unable to assist with equipment access, please have your UST Service Provider there to remove manway or sump lids. DEQ will need to observe what equipment is in the tank top sumps and under the dispensers. If ball floats are the primary overfill protection device, these will need to be verified during the inspection, please be able to locate and remove the ball floats.

If violations are found at the time of the inspection without prior notification, DEQ is required to initiate enforcement action. For UST violations, enforcement usually begins with a field citation option, which is much like paying a traffic ticket and making corrections.

Some enforcement situations including repeat violations will go through a longer and more formal process including civil penalties.

Thank you for your cooperation. I can be reached at 503-360-4408 or blakely.gilbert@deq.oregon.gov to answer any questions you may have and assist you in the preparation for your inspection.

Sincerely,

Blake Gilbert
UST Compliance Specialist
Headquarters Office



Oregon

Tina Kotek, Governor

Department of Environmental Quality

Headquarters Office

700 NE Multnomah Street, Suite 600

Portland, OR 97232

(503) 229-5263

TTY 711

September 26, 2025

Tom Lathrop
Truax Corp # 21
820 NW 3rd St
Corvallis, Or 97330

RE: UST Compliance Inspection
DEQ UST # 7837

Tom Lathrop

The Oregon Department of Environmental Quality (DEQ) is conducting underground storage tank (UST) inspections throughout Oregon. The purpose of this letter is to inform you that your facility, among others, has been selected for inspection. A thorough inspection of your facility will be conducted to determine compliance with state and federal UST requirements. **The date you receive this letter is the date that the inspection starts.** If you have work done after that date, you will need to have the previous set of records available for evaluation in addition to the most recent records.

If I do not hear from you, the inspection for this facility is scheduled for November 05, 2025, starting at approximately 9:00 am. Please note that the inspection will require uninterrupted participation and attendance by you or a knowledgeable assistant. For the inspection you need to provide access to tank sumps, under dispenser areas, cathodic protection rectifiers, and leak monitoring equipment. DEQ will not touch the equipment or enter the facility, if you are unable to assist with equipment access, please have your UST Service Provider there. This inspection may also include review of Stage I Vapor Recovery.

To complete this inspection, you will need to have compliance testing records available on-site on the day of the inspection or sent to me prior to the inspection at blakely.gilbert@deq.oregon.gov. If the records are not available during the day of the inspection, you will have five (5) business days to provide the records to me electronically. After which time this facility will be subject to enforcement actions.

At a minimum the following records are required to complete this inspection:

- Line and leak detector testing results for the past three years,
- Monthly tank leak detection records (12 months),
- Class A, B, and C training documentation.
- Financial responsibility mechanism.
- Annual tank gauge / release detection equipment certification
- Spill prevention testing records
- Overfill Prevention Equipment testing
- Cathodic protection testing (if applicable)
- Tank lining records (if applicable)
- Monthly walkthroughs

As stated previously, DEQ will not touch any equipment and if you are unable to assist with equipment access, please have your UST Service Provider there to remove manway or sump lids. DEQ will need to observe what equipment is in the tank top sumps and under the dispensers. If ball floats are the primary overfill protection device, these will need to be verified during the inspection, please be able to locate and remove the ball floats.

If violations are found at the time of the inspection without prior notification, DEQ is required to initiate enforcement action. For UST violations, enforcement usually begins with a field citation option, which is much like paying a traffic ticket and making corrections.

Some enforcement situations including repeat violations will go through a longer and more formal process including civil penalties.

Thank you for your cooperation. I can be reached at 503-360-4408 or blakely.gilbert@deq.oregon.gov to answer any questions you may have and assist you in the preparation for your inspection.

Sincerely,

A handwritten signature in black ink that reads "Blake Gilbert". The signature is written in a cursive style with a large, stylized "G" and "L".

Blake Gilbert
UST Compliance Specialist
Headquarters Office