



WPCF Individual Domestic - Sanitary Sewer Overflow Reporting Form

RID 100018

Submitted Date 01/26/2026

Submitter

Justin Young

Jyoung@bendoregon.gov

5413238546

541-419-8735

City of Bend

144905 Corral Ct, La Pine, OR 97739-9234

Facility Information

Name

Bend, City Of

Site ID

213492

Physical Location

22395 MCGRATH ROAD, BEND, OR 97701 (44.09,-121.29)

Overflow Event Information

This occurrence was not/has not been reported to OERS.

Date Reported to OERS

01/26/2026

OERS Number

2026-0195

Sanitary Sewer Overflow Event Start Date/Time

01/25/2026

Sanitary Sewer Overflow Event End Date/Time

01/25/2026

Sanitary Sewer Overflow Event Cause

Blockage

Sanitary Sewer Overflow Event Duration (hours)

1

Sanitary Sewer Overflow Discharge Volume (gallons)

10

Receiving Water Name

N/A

Impact of Sanitary Sewer Overflow Event

Sanitary Sewer Overflow Affected Private Property

System Component

House Lateral

Sanitary Sewer Overflow Nearest Address

1792 SW Troon Ave, Bend, OR 97702-3149

Latitude 44.050470

Longitude -121.340276

Additional Comments

The spill occurred at 1792 SW Troon Ave due to a privately owned sewer service lateral which serves 1784 SW Troon Ave. Upon staff arrival at 4:15PM the cleanout was no longer spilling, city staff only witnessed evidence of a spill.

Public Notification

Notified downstream drinking water sources (List Below)?

N/A

Signs Posted?

No

Explain

Media contacted?

No

List any other steps taken to notify the public or state/federal agencies

Causes

Cause or suspected cause of the overflow

Blockage - Other

Rainfall in the 24 hours prior to Sanitary Sewer Overflow (for storm-related overflows) (inches)

Source of rainfall data

1-in-5 year 24 hour rainfall for the sewerage system area (if known) (in/24hr)

Emergency Response and Mitigation

List actions taken to stop and mitigate the impact of the Sanitary Sewer Overflow.

For overland flow:

Taped off affected area?

N/A

Cleaned up affected area?

No

For Sanitary Sewer Overflow to surface water:

Bacteria samples taken to confirm impact?

N/A

Follow up bacteria samples taken to confirm end of impact?

N/A

Describe monitoring and results

N/A

For Sanitary Sewer Overflows that impact buildings:

Pumped out flooded buildings?

N/A

Disinfected?

N/A

Other measures taken (describe)

Advised property owner that the issue was property owner's responsibility and recommended calling a plumber to clear blockage and cleanup. City staff will follow up on 1/27/2026 to ensure that site is clean and issue has been resolved.

Steps to Reduce, Prevent, Mitigate

Removed Blockage

Steps taken or planned to reduce, eliminate, and prevent the reoccurrence of the overflow and schedule for those steps

This spill occurred as an issue with a privately owned sewer service lateral that is owned/maintained by the property owner.