



# Oregon

Tina Kotek, Governor

Department of Environmental Quality  
Northwest Region  
700 NE Multnomah Street, Suite 600  
Portland, OR 97232  
(503) 229-5263

**February 11, 2026**

**To: Kevin Parrett, Northwest Region Cleanup Program Manager**  
**From: Rebecca Digiustino, Northwest Region Cleanup Project Manager**  
**Subject: Justification for Administrative Closure of 1982 Spill Incident  
at Dasic International Corp., ECSI No. 0110**

During operation, Dasic International Corp. (Dasic) manufactured marine and industrial detergents and compounds. The facility was located at 3125 NW Front Avenue in Portland, Oregon, Tax Lot 1N1E28BC 100. On January 21, 1982, a spill was reported at the Dasic facility and a DEQ inspector observed a milky white substance along the curb of the property facing NW Front Avenue. According to a Dasic facility representative, the spill consisted of approximately 5 to 40 gallons of water and minor amounts of solvent, kerosene, sulfuric acid, triethanolamine, and Plurafac RA 30 (a low-foaming surfactant used for cleaning applications). Under DEQ instruction, the facility operators created a temporary dike around the storm sewer with sorbent pads and applied sawdust to collect the substance along the curb. No material was observed to be discharging to the Willamette River via the storm sewer.

Dasic submitted a follow-up memorandum on January 22, 1982, that attributed the spill to the washing out of residues from the facility floor the evening of January 20, 1982. The memorandum stated that, following the spill, facility employees were instructed to not wash off anything that could result in the generation of contaminated water and to address any drips on the floor with sawdust or absorption pads. In an interoffice DEQ memorandum dated January 27, 1982, DEQ noted that the substance appeared to be more than washdown residue and believed the washing out of the facility may have been a common practice at the time. No additional follow-up was reported in DEQ records. Due to the open status of the spill, Dasic was entered into the Environmental Cleanup Site Information (ECSI) database in 1992 and was assigned the ECSI file identification number of 0110.

Because the spill was contained to a paved area on the site and the amount of time that has elapsed, DEQ has determined that conditions related to the 1982 spill are unlikely to warrant an investigation and the case should be administratively closed. This letter only applies to the 1982 spill, as discussed above. DEQ will update the Your DEQ Online (YDO) database to reflect this decision.

If you have any questions, please contact Rebecca Digiustino at 503-926-2257, or via email at [rebecca.digiustino@deq.oregon.gov](mailto:rebecca.digiustino@deq.oregon.gov).

Attachments: Site Assessor Details  
1982 Spill Incident Report



## 3125 NW FRONT AVE

PORTLAND, OR 97210

### ASSESSOR

<b>Address</b>	3125 NW FRONT AVE
<b>Address2</b>	PORTLAND, OR 97210
<b>City</b>	PORTLAND
<b>Property ID</b>	R316324
<b>Tax Roll</b>	SECTION 28 1N 1E, TL 100 0.34 ACRES
<b>Use</b>	GENERIC SHOP/GARAGE USE
<b>Lot</b>	TL 100
<b>County</b>	Multnomah
<b>State ID</b>	1N1E28BC 100
<b>New State ID</b>	1N1E28BC -00100
<b>Alt Account Number</b>	R941280430
<b>Map Number</b>	2727
<b>Related Accounts</b>	<input type="text" value=""/>

### Owner

<b>Name</b>	RA PROPERTIES LLC
<b>Address</b>	18028 SKYLAND CIR LAKE OSWEGO OR 97034-6452

<b>Land Type</b>	IND - INDUSTRIAL LAND
<b>Total Land Area</b>	0.34 acres (14,811 sq ft)
<b>Building Area</b>	4,937 sq ft

**Assessor Update Date** 02/09/2026 4:31AM

For more information about data updates or discrepancies, please contact Multnomah County Assessment, Recording & Taxation at (503) 988-2225 or propertytax@multco.us.

### Sales History & Deed



**Silva Environmental Consulting & Assessments, Inc. (SECA)**  
9208 NE Highway 99, Ste. 107-306, Vancouver, Washington 98665  
Ph. (503) 789-1693 \* Fax (360) 263-2522 \* Em. SilvaEnvironmental32@Yahoo.com

**PHASE 1 ENVIRONMENTAL SITE ASSESSMENT OWNER/CLIENT CHECKLIST/  
QUESTIONNAIRE – (SITE-3125 NW Front Street)**

The information below will be useful in preparing the Phase 1 Environmental Site Assessment requested for the site. Please answer the questions to the best of your knowledge, then sign and return along with any copies.

1a Current Property Owner Name: <b>See page 2</b> How long: <b>See page 2</b> 1b Current Occupant (or provide rent roll/list if multiple): <b>Northwest Quadvan, LLC</b>
2. Buildings/Construction Dates/SqFt. (if known) <b>Cinder block with barrel roof / 1950s</b> <b>5,000 square feet</b> # of buildings: <b>One</b>
3. Current Use of Property/Description of activities: <b>Conversion of two-wheel drive Ford Transit vans to four-wheel drive</b>
4. Historical Occupants/Use of Property: <b>See second page</b>
5. Has the property or any adjoining property ever been used as a gas station, dry cleaners, motor repair facility, commercial printing, junkyard/wrecking yard or landfill? <b>No</b>
6. Any Prior Environmental Reports/Subsurface Investigations <b>N/A already provided</b>
7. Any Hazardous Waste Storage or Disposal activities: <b>None to owner's knowledge</b>
8. Any Notices or Correspondence from Regulatory Agencies (DEQ/EPA/City/County) related to: <b>N/A</b> <b>Already obtained</b>
9. Any Environmental Liens or activity and use limitations on the Property that you are aware of: <b>No</b>

10. Any existing or former underground or aboveground storage tanks (if so, please provide report/info):  
**Underground gasoline storage tank that was decommissioned and removed by a certified UST company, Krieg Construction Co, 6937 SW 31st Avenue, Portland, OR 97219, DEQ License #284. Dasic International Corporation oversaw complete decommissioning and removal which was signed off by the Oregon Department of Environmental Quality in 1991 (File No. 26-90-220).**

11. Any dry wells, sumps, pits, or drainage systems on-site: **No**

12.a City water or water well: **City water**

12b. City sewer or septic/cesspool: **City sewer**

Name and title of person completing questionnaire: **Robert S. Auguston, Jr. - Member on behalf of RA Properties, LLC**

Please fax back to (360) 263-2522 or email to [SilvaEnvironmental32@yahoo.com](mailto:SilvaEnvironmental32@yahoo.com).  
Sincerely,  
Misty Silva - SECA

**Question #1a**

**Robert S. Auguston, Sr. & Robert S. Auguston, Jr. / 1979 - 1995**

**Robert S. Auguston, Jr. / 1995 - 2009**

**RA Properties, LLC / 2009 - Present**

**Question #4**

**Dasic International Corporation / 1979 - 1990 / Marine degreasers & detergents**

**Berry-Criswell Company / 1990 - 1994 / Repair logging equipment**

**Turnkey Resources / 1994 - 2001 / Sale, repair, distribution of tube bending equipment**

**NW Quadvan, LLC / 2002 - Present / Conversion of Ford Transit vans from two-wheel drive to four-wheel drive**

9/16

# **APPENDIX F**

DEQ ECSI File #0110 (subject property)

January 23, 1992

Robert S. Auguston  
Dasic International Corporation  
P. O. Box 14907  
Portland, Oregon 97214

Re: Site Assessment  
Information Request:  
Dasic International Corp.

The Oregon Department of Environmental Quality (DEQ) is requesting information from you, as the owner or principle operator of Dasic International Corporation, located at 3125 N. W. Front Avenue in Portland, Oregon. Please read this letter and complete the enclosed Site Assessment Information Request within three weeks of the postmark date on the envelope. Send the completed information request to:

Aaron Bodor  
Site Assessment Section  
Department of Environmental Quality  
811 S. W. 6th, 9th Floor  
Portland, Oregon 97204

DEQ has begun screening facilities included in its Environmental Cleanup Site Information System (ECSI). This database contains information on over nine hundred different facilities in Oregon where hazardous substances are suspected or known to have been improperly handled or released to the environment. Dasic International is currently included on this database. DEQ will use the information you provide, in conjunction with existing site information, to assess whether actual or potential releases of hazardous substances at your facility may require further assessment to protect health and the environment.



811 SW Sixth Avenue  
Portland, OR 97204-1390  
(503) 229-5696  
TDD (503) 229-6993  
DEQ-1



This investigation is being performed under the legal authority of Oregon Environmental Cleanup Law (ORS 465.245).

After screening, a more detailed site assessment will be performed on those sites deemed to pose a significant risk to their surroundings; those found to pose little or no risk will be either monitored or identified as requiring no further action at this time. DEQ will contact you prior to initiating any further action at your site.

If you have questions, or are unable to complete the request in the allotted time period, I can be contacted at (503) 229-5294. Note that site visits will likely be scheduled by DEQ for those facilities failing to return the Site Assessment Information Request as directed. We appreciate your cooperation in this matter.

Sincerely,



Aaron Bodor  
Site Assessment Section  
Environmental Cleanup Division

DH:m

SA\SM35\SM3651

Enclosure

cc: Loretta Pickerell, SAS, DEQ  
Chuck Clinton, NWR, DEQ

SITE NO: 110 SITE NAME: Dasic International Corp

SITE ADDRESS: COUNTY: MULT STATUS: A REGION: NW

3125 N.W. Front Avenue  
Portland, OR 97210

DEQ CONTACT:

SITE CONTACTS:

SIC CODES: 2819

Robert S Auguston  
V P Operations  
Dasic International Corp  
PO Box 14907  
Portland, OR 97214-  
PHONE: (503)238-0399 EXT:

CERCLIS ORD#:

DEQ PROGRAMS: None Listed

CONFIRMED RELEASE?	NO
EVIDENCE VERIFIED?	NO
ON INVENTORY?	NO
SPILL?	YES
COMPLAINT?	NO
PRIOR VISIT?	NO
SOME REMEDIAL ACTION?	NO
ADJACENT PROPERTY?	NO

SIZE: 0.0 TNSHP: 1N RANGE: 1E SECT: 28

\*\*\* FACILITY INFORMATION \*\*\*

FACILITY DESCRIPTION:

Blender and formulator of marine and industrial detergents and compounds

Private site

INDUSTRY TYPE(S): non-classified

WASTE MGMT UNIT	QTY	COMMENTS
-----------------	-----	----------

spills

SITE NO: 110 SITE NAME: Dasic International Corp

\*\*\* HAZARDOUS SUBSTANCES/WASTE TYPES \*\*\*

solvent, kerosene, triethanolamine

\*\*\* CONTAMINATION INFORMATION \*\*\*

DEQ responded to a spill complaint at this site.

\*\*\* OTHER INFORMATION \*\*\*

Spill may have entered into storm sewer that empties into the Willamette River.

\*\*\* POTENTIAL RESPONSIBLE PARTIES \*\*\*

PRP NO. 1 PRP NAME: Dasic International PHONE: ( ) -  
AFFILIATION: Operator STATUS: Current

Dasic International  
1035 S.E. 9th Avenue  
Portland, OR 97214

PRP NO. 2 PRP NAME: Auguston, Robert PHONE:  
AFFILIATION: Legal Owner STATUS: Current

Robert Auguston  
1035 S. E. 9th Ave.  
Portland, OR 97214

\*\*\* INFORMATION AND DATA SOURCES \*\*\*

INFORMATION REVIEWED:

Inspection Reports  
Correspondence from Owner or Operator  
Complaint Form

SITE NO: 110 SITE NAME: Dasic International Corp

DATA SOURCES:

DEQ Brown file

\*\*\* HAZARDOUS SUBSTANCES \*\*\*

SUBSTANCE NAME: triethanolamine

DATE RELEASED: about 6:00PM 1-20-82

QTY RELEASED: Unknown

MEDIA/LEVEL OF CONC: Soil  
Surface Water

DATA SOURCES: DEQ Brown file

SUBSTANCE NAME: kerosene

DATE RELEASED: about 6:00PM 1-20-82

QTY RELEASED: Unknown

MEDIA/LEVEL OF CONC: Soil  
Surface Water

DATA SOURCES: DEQ Brown file

SUBSTANCE NAME: solvent

DATE RELEASED: about 6:00PM 1-20-82

QTY RELEASED: Unknown

MEDIA/LEVEL OF CONC: Soil  
Surface Water

DATA SOURCES: DEQ Brown file

01/23/89 11:10:11

E REPORT

PAGE 4

SITE NO: 110 SITE NAME: Dasic International Corp

\*\*\* MANNER OF RELEASE \*\*\*

Unknown.

\*\*\* STATUS OF REMOVAL OR REMEDIAL ACTION \*\*\*

Emergency cleanup

REMEDIAL ACTION CODES ASSIGNED FOR LEGISLATIVE REPORT:

RPP DEQ Oversight of Responsible Party Partial Cleanup, Closure or Removal

PREPARED BY: Michael Zollitsch

ORIGINATION DATE: 05/09/88

LAST MODIFIED BY:

MODIFICATION DATE: / /

LAST UPDATED: 10/12/88 10:45:26

110 Not on Invo

\*\*\* MULTNOMAH COUNTY DIVISION OF A&T \*\*\* R001-NALMOD 09/21/88 9:59 PAGE 1  
ACCT. NUMBER R-94128-0432 L/C 001 REQUEST BY 006

NAME AUGUSTON, ROBERT SR & PROP 3125 NW FRONT AV  
AUGUSTON, ROBERT JR PORTLAND 97210  
YR-AQ 79 BK/PG 1392/0023 ----- STATUS -----  
MAIL 1035 SE 9TH AVE 1989/90 TO BE REAP FOR JAN 1, 1989  
PORTLAND, OREGON 97214 YR APPR VCHR # ACTION  
MAP 2727 CENSUS TRACT VCHR # DIVISION  
L/C 001 09562 \$6.22 01/15/85

----- LEGAL DESCRIPTION -----

ADD SECTION 28 1 N 1 E LOT BLOCK  
IMPS ONLY  
TL# 43

----- LAND AND IMPROVEMENT CHARACTERISTICS --- \*\*\* / / \*\*\*

RATIO CODE 371 5 APPR DISTRICT AREA 15,025 SF ZONING M1  
CLASS % IMP GOOD NEIGHBORHOOD 190  
USE WHSE YR BUILT 1948 UNITS STORIES .1  
LIVING AREA 4,937 ARCH CONS CL B



SITE DISCOVERY FORM

Site Name: DASIC International Corp.  
Alias: \_\_\_\_\_

Site Address: 3125 NW Front Ave.  
City: Portland  
County: MULTNOMAH

Status: (A) I C U O  
Region: WV C E (NW) SW  
DEQ Contact: \_\_\_\_\_

Site Location: 3125 NW Front Ave

SIC Code: 2819

CERCLIS #: ORD

Confirmed Release AK

Site Contact: Robert S. Auguston Jr.  
Title: V.P. of Operations  
Phone: (503) 238-0399  
238-0399

NPL \_\_\_\_\_  
RCRA \_\_\_\_\_  
ORA \_\_\_\_\_  
SW \_\_\_\_\_  
WQ \_\_\_\_\_  
Spill \_\_\_\_\_  
Public Input X  
Some RA \_\_\_\_\_

Mailing Address: P.O. Box 14907  
Portland OR 97214

Size (Acres): \_\_\_\_\_ Township \_\_\_\_\_ Range \_\_\_\_\_ Section \_\_\_\_\_ Tax Lot \_\_\_\_\_

Facility Type: Blender & Formulator of Marine & Industrial Detergents & Compounds  
Public \_\_\_\_\_ Private \_\_\_\_\_

Years of Operation: \_\_\_\_\_

Permits (Type and Number): \_\_\_\_\_

Years Under DEQ Enforcement: \_\_\_\_\_

Waste Management Units:

tanks \_\_\_\_\_ drums \_\_\_\_\_ sumps \_\_\_\_\_ piles \_\_\_\_\_ wells \_\_\_\_\_

land treatment \_\_\_\_\_ surface impoundments \_\_\_\_\_ landfills \_\_\_\_\_

other: Spills

Hazardous Substances/Waste Types: Solvent, Kerosene, Triethanolamine

CLEARANCE		
TO	INITIAL	DATE
<u>Database</u>	<u>AK</u>	<u>10/4</u>
<u>no vid</u>		
<u>in file</u>		

SITE DISCOVERY FORM  
Page Two

Site Name DASIC Int. Corp

Contaminant Information: DEQ responded to a spill complaint at this site.

Other Information/Comments (Potential Pathways, Hazards): Spill may have entered into storm sewer that empties into the Willamette River.

Owner/Operator Information: Operator is Dasic International, office @ 1035 SE 9th ~~ave~~ ave, Portland.

SITE DISCOVERY FORM  
Page Three

Site Name: Davis International


Information Reviewed: (Circle Appropriate Numbers)

- |   |   |
|---|---|
| <input checked="" type="checkbox"/> 1. Inspection Reports           | <input type="checkbox"/> 9. Lab Results   |
| <input type="checkbox"/> 2. PA SI                                   | <input type="checkbox"/> 10. Other: _____ |
| <input checked="" type="checkbox"/> 3. Corres. from Owner, Operator | _____                                     |
| <input checked="" type="checkbox"/> 4. Notice Of Violation Letter   | _____                                     |
| <input type="checkbox"/> 5. EPA Generator Notification Form         | _____                                     |
| <input type="checkbox"/> 6. Monitoring Data                         | _____                                     |
| <input type="checkbox"/> 7. Hazardous Waste Manifests               | _____                                     |
| <input checked="" type="checkbox"/> 8. Complaint Form               | _____                                     |

Data Source: DEQ Brown File

Preparer: Michael J. Zoltnel

Date: 5/9/88



SITE INVENTORY FORM

Site Name: DASIC International Corp  
Alias: \_\_\_\_\_

Hazardous Substance: Solvent, Petroleum, Triethanolamine

When Released: <sup>about</sup> 6:00 pm; 1/20/82

Quantity Released: \_\_\_\_\_

How Released: \_\_\_\_\_

Media Contaminated: soil; surface water

Concentration: \_\_\_\_\_

Status of Removal or Remedial Action: Emergency Clean-up

PRP: (indicate whether owner, operator, transporter, generator)

The Operator is DASIC Int. Corp

Data Sources: DEQ Brown File

Preparer: Michael J. Zolotarev Date: 5/9/88

*Unzaidous Waste*

*Free Bill Stamp*  
*DS*

STATE OF OREGON

DEPARTMENT OF ENVIRONMENTAL QUALITY

INTEROFFICE MEMO

TO: TRB

DATE: January 27, 1982

FROM: GDB

Solid Waste Division  
Dept. of Environmental Quality

RECEIVED  
JAN 27 1982

SUBJECT: WQ - Dasic International Corp.  
Spill Response  
Multnomah County - Enforcement Referral

After receiving the attached spill reporting form, I proceeded to the spill location. Upon arrival at the scene, I observed a milky-white residue along the curb of the subject company.

I entered the facility and located an employee in the rear warehouse. After identifying myself and the reason for my visit, I asked if it was known what caused the accumulation outside. I was advised that I should speak to Robert Auguston, Jr., at the main office location. I asked for Mr. Auguston's phone number and permission to use the phone. I was supplied with the phone number and granted permission. I spoke with Mr. Auguston and he agreed to meet with me at my location.

Mr. Auguston arrived about 15 minutes after my phone call. After a brief conversation, we both toured the plant. I asked Mr. Auguston if he knew what happened and he said my call was the first he knew of the incident, but that it was probably caused by the washing down of the warehouse the previous evening. I explained that that method of cleanup was not acceptable when the residue was allowed to flow off-site. I asked Mr. Auguston if he thought he could take care of the cleanup or if he needed the telephone number of a private cleanup contractor. He said he thought they could handle it and had the two employees at the warehouse begin applying sawdust to the residue. I then collected a sample for lab analysis (lab results later received revealed a flash point of 165° F and a pH of 8).

Upon further investigation it was determined that the residue had flowed downslope along the curb to a storm sewer (see drawing). At this point I told Mr. Auguston that it appeared to be more than washdown residue - it looked like a quantity of material had been spilled. Mr. Auguston agreed. I advised Mr. Auguston to dike around the storm sewer to contain the material and he complied. Mr. Auguston then left to get more sawdust to absorb the material.

I called the City of Portland to find out where the storm sewer emptied into the Willamette River. I was advised that the storm sewer was connected to a 60-inch culvert by Bingham Willamette Pump. When Mr. Auguston returned, I advised him of the information I had obtained and asked him if he would like to accompany me to the outfall. He agreed to do

WQ - Dasic International Corp. Spill Response  
January 27, 1982  
Page 2

so. Prior to leaving, I advised Mr. Auguston to call the National Spill Response number and he did so.

An inspection was made of the outfall by Bingham Willamette Pump and along the entire length of the dock downstream. I could not find any indication that the material had reached the river. I next checked the storm sewer on NW Front by the entrance to Bingham Willamette Pump. Again, there was no visible residue.

Cleanup was nearly accomplished by the time of our return to Dasic International's building. I asked Mr. Auguston if he would provide me with a list of all material which could have been involved in the spill and he said he would have to pick it up at his office. I followed Mr. Auguston to his office and he provided me with lab results of two possible products involved in the spill. Both products had a flash point of 140° F or above (C.O.C). Mr. Auguston told me that he would have to go through his files to get product data sheets on all of the potential products involved. I also asked that Mr. Auguston provide me with a letter explaining the cause of the spill and what measures he will take to prevent a recurrence (this was received 1/25/82).

I made an appointment to interview Mr. Auguston further the following day to explore his status as a hazardous waste generator.

It is my opinion that the spill resulting in the off-site migration of the residue was intentional and of common occurrence. I would therefore recommend a five-day warning letter be sent to the company.

RC172

Attachment

cc: Enforcement Section  
Water Quality Division

*cc: H<sub>2</sub> Waste*

STORM  
SEWER  
DIKED

DASIC  
INTERNATIONAL  
CORP

RD FRONT STREET

SPILL RESIDUE


STORM SEWER

NO RESIDUE OBSERVED

DOCK

WILLAMETTE RIVER

60" STORM  
SEWER OUTFALL



# DASIC INTERNATIONAL CORP.

Specialists in Marine and Industrial Chemicals

1035 Southeast Ninth Street  
P.O. Box 14907 • Portland, OR 97214  
Telephone 503 / 238-0399  
TWX 910-464-8085  
Cable DASIC



January 22, 1982

Mr. Gregory D. Baesler, R.S.  
Department of Environmental Quality  
P.O. Box 1760  
Portland, OR 97207

Dept. of Environmental Quality

RECEIVED  
JAN 25 1982

Dear Mr. Baesler:

NORTHWEST REGION

RE: Spill at Dasic Plant

Per your request, the following is an account of the recent spill at the Dasic Plant located at 3125 NW Front Avenue, Portland, Oregon.

The spill apparently occurred sometime during the evening of January 20, 1982.

I was notified by DEQ at approximately 10:00 a.m. by Mr. Gregory Baesler, who telephoned me from the Dasic Plant location. I proceeded to the location, inspected the premises and gutter in the street with Mr. Baesler, and it was determined there was a spill.

All employees at the Dasic Plant were immediately activated to clean up the spill using sawdust and absorption pads. All of the waste was collected into an open head fifty-five gallon drum, and the waste totaled approximately twenty gallons. Sawdust barricades were put around the spill so that no material could run to the storm drain.

Mr. Ambrozewicz of the National Spill Response was notified.

Mr. Baesler and I then inspected the outfall of the storm drain that was located at the dock of Bingham Willamette Pump Company. Nothing was coming out into the River. Mr. Baesler and I then walked the entire length of the Bingham Willamette Dock and no contamination was noted.

Upon returning to the Dasic office there was a telephone message to call Lieutenant Hereth concerning the spill. This was done immediately and the findings that no contamination had entered the River were relayed to Lieutenant Hereth, by Mr. Baesler and myself.

It was determined the spill had been caused by washing out the residues from the plant floor.

The possible materials that may have been in the spill are:

<u>Product</u>	<u>Supplier</u>	<u>Quantity</u>
Aromatic Solvent Hi Sol 4-2	Ashland Oil	Trace
Triton N-101	Chemcentral	Trace
Triethanolomine	Ashland Oil	Trace
Sulfonic Acid	Pilot Chemical	Trace
Water		Majority of spill
Pamak WVFA	Hercules	Trace
Plurafac RA30	BASF Wyandotte	Trace
Solvent 450	Chevron	Trace
Propylene Glycol	McKesson	Trace
Emerest 2646	Emery	Trace
Emerest 2660	Emery	Trace
Emerest 2500	Emery	Trace

Material Safety Data Sheets or product information is enclosed.


Because of this spill, our firm has notified our plant employees not to wash off anything which could result in any contaminated water being generated. Any drips on the floor are to be picked up using sawdust or absorption pads and put in a container.

In addition our firm is looking into several alternatives such as a wet/dry vacuum machine, an underground holding tank system, or an above ground tank with a dike.

I would like to take this opportunity to thank you and your Department for its fine assistance and cooperation.

If you have any questions or require additional information, please contact me at 238-0399.

Sincerely,



Robert S. Auguston, Jr.  
Vice President of Operations

RSA, Jr.:dz

Enclosures

Bill Di  
WYA

C. H. Gordon  
EPA-00

11/17/20

Solid Waste Division  
Dept. of Environmental Quality

DEPARTMENT OF ENVIRONMENTAL QUALITY  
SITE INSPECTION REPORT  
HAZARDOUS WASTE GENERATOR

RECEIVED  
JAN 25 1982

C. Van Kollas - Enforcement Section

Facility Name: DASIC INTERNATIONAL CORP.

Address: 3125 NW FRONT ST.  
MAILING ADDRESS 1035 SE 9TH  
PORTLAND, OR.

Phone: \_\_\_\_\_ I.D. No.: NONE

Company Contact: ROBERT AUGUSTON Visited on: 1/21-22/82

By: JLB

BACKGROUND

1. Is generator familiar with DEQ and EPA hazardous waste rules? Are rules available? NO - (HW SENT)  
CONTACT INITIATED BY SPILL COMPLAINT

2. Type of business? Principal products/amount produced? Facility employment 3 in plant 5 in office

BLENDER & FORMULATOR OF POLYMER  
& INDUSTRIAL DETERGENTS & CLEANING  
COMPOUND & MANUFACTURE OF TANK  
CLEANING EQUIPMENT

90,000 & 150,000 gal/yr

PRODUCT DATA SHEETS AVAILABLE AT NWR OFFICE

3. How registered with DEQ? EPA?

NOT REGISTERED WITH DEQ OR EPA

4. DUE TO WASTE CHARACTERISTICS  
IT DOES NOT APPEAR THIS COMPANY  
NEEDS TO REGISTER. (LAB RESULTS  
OF SPILLED MATERIAL SHOW A PH OF 8  
AND A FLASH POINT OF 165°F.

COMPANY TO IMPLEMENT NEW WASTE HANDLING

Waste TRB  
00-43

SPILL REPORTING FORM

PERSON REPORTING SPILL

NAME: Emergency Services

ADDRESS: \_\_\_\_\_

TEL. NO.: \_\_\_\_\_

Dept. of Environmental Quality

RECEIVED  
JAN 21 1982

WHERE/WHEN SPILL OCCURRED

LOCATION: Dr Basic International

3125 NW Front, Portland

COUNTY: Multnomah

DATE: 1/21/82 TIME: A.M.

PERSON RECEIVING REPORT

NAME: Ed Chiong

TEL. NO.: 5326

DATE/TIME RECEIVED

DATE: 1/21/82 TIME: 9:30A.

SPILL DETAILS

HOW SPILL OCCURRED	NORTHWEST REGION	MATERIAL(S) INVOLVED	ACTION TAKEN
TRAFFIC ACCIDENT EXPLAIN:	OTHERS (LEAKAGE). EXPLAIN:	MATERIAL(S) DESCRIPTION: <u>Chemical appeared to be very irritating</u> <u>SOLVENT, KEROSENE, SULFONIC ACID, TRIETHANOLAMINE, PLEURAL RA 30</u> KNOWN USE(S): <u>CLEANER FOR SHIPPING TANKS</u>	<u>SURVEYED AREA. DETERMINE PRODUCT HAD TRAVELED FROM BETWEEN BUILDINGS, TO STREET, ALONG CURB TO CITY STORM SEWER. COMPANY PERSONNEL DIKED AROUND STORM SEWER WITH SORBENT PAD AND APPLIED SAWDUST TO PRODUCT COLLECTED ALONG CURB. NO MATERIAL WAS OBSERVED TO BE DISCHARGING TO RIVER FROM STORM SEWER. SEE DRAWING &amp; LETTER FOR ADDITIONAL INFORMATION</u>
RAIL ACCIDENT EXPLAIN:	Solid Waste Division Dept. of Environmental Quality RECEIVED JAN 25 1982	QUANTITY: <u>Unknown</u> <u>5 to 40 gallons as per R.S. AUGUSTON</u> HAZARD:	NOTE: <u>SPILL OCCURED ABOUT 6:00 PM 1/20/82 AS PER MR AUGUSTON</u>

SITE ID: 110

C O N F I D E N T I A L

*NOT CONFIDENTIAL  
-CWA 12/16/14*

NAME:\*

DASIC INTERNATIONAL CORP

LOCATION:

Multnomah County  
3125 NW Front Ave  
Portland

CURRENT OWNER/OPERATOR:

Dasic International  
Auguston, Robert

PRIOR OWNER/OPERATOR:

Unknown

DESCRIPTION OF THE FACILITY:

Blender and formulator of marine and industrial detergents and compounds

HAZARDOUS SUBSTANCE INFORMATION:

<u>SUBSTANCE</u>	<u>QUANTITY** RELEASED</u>	<u>MEDIA CONTAMINATED</u>	<u>CONCENTRATION IN MEDIA</u>
Solvent	Unknown	Soil Surface Water	Unknown Unknown
Kerosene	Unknown	Soil Surface Water	Unknown Unknown
Triethanolamine	Unknown	Soil Surface Water	Unknown Unknown

HOW RELEASED:

Unknown.

STATUS OF REMOVAL OR REMEDIAL ACTION:

DEQ Oversight of Responsible Party Partial Cleanup,  
Closure or Removal

TIME PERIOD WHEN RELEASE OCCURRED:

About 6:00PM 1-20-82

\* NOT NECESSARILY RESPONSIBLE FOR CONTAMINATION

\*\* QUANTITY RELEASED MAY INCLUDE AMOUNTS OF SUBSTANCES OTHER THAN HAZARDOUS SUBSTANCES

NAME:\* DASIC INTERNATIONAL CORP

LOCATION: Multnomah County  
3125 NW Front Ave  
PortlandCURRENT OWNER/OPERATOR: Dasic International  
Auguston

PRIOR OWNER/OPERATOR: Unknown

DESCRIPTION OF THE FACILITY: Blender and formulator of marine and  
industrial detergents and com-  
pounds

## HAZARDOUS SUBSTANCE INFORMATION:

<u>SUBSTANCE</u>	<u>QUANTITY RELEASED</u>	<u>MEDIA CONTAMINATED</u>	<u>CONCENTRATION IN MEDIA</u>
Solvent	Unknown	Soil Surface Water	Unknown Unknown
Kerosene	Unknown	Soil Surface Water	Unknown Unknown
Triethanolamine <sup>n</sup> ✓	Unknown	Soil Surface Water	Unknown Unknown

HOW RELEASED: Unknown ✓

## STATUS OF REMOVAL OR REMEDIAL ACTION:

Responsible Party Partial Cleanup or Removal

## TIME PERIOD WHEN RELEASE OCCURRED:

About 6:00PM 1-20-82

\* NOT NECESSARILY RESPONSIBLE FOR CONTAMINATION

ENVIRONMENTAL CLEANUP SITE INFORMATION  
SITE SUMMARY REPORT

November 07, 2000 03:11 pm

=====  
SITE ID: 110      SITE NAME: Dasic International Corp.      CERCLIS NO:  
-----  
                 ADDRESS: 3125 NW Front AVE Portland 97210  
                 COUNTY: MULTNOMAH      REGION: NWR  
                 INVG STATUS: SUS      NPL SITE: N      ORPHAN SITE: N      STUDY AREA: N  
PROPERTY:      TWNSHP/RANGE/SECT: 1N,1E,28      TAX LOTS:  
-----  
                 LATITUDE: 45 deg.33'6"      LONGITUDE: 122 deg.42'43"      SITE SIZE: 0 acres  
=====

=====  
STUDY AREAS:      STUDY ID      STUDY NAME      INVG STATUS  
-----  
                 1544 Lower Willamette River Basin Study Area (LWRBSA)      XCN  
                 2340 V.A.- Surface Waters, WQ-Limited for Toxics      XCN  
=====

=====  
FACILITIES:      NAME: Dasic International Corp.  
-----  
                 COMMENTS: Blender and formulator of marine and industrial detergents and com- pounds  
                 YEARS OF OPERATION:  
                 SIC CODES: 2819      OPERATING STATUS: Active  
-----  
=====

HAZARDOUS SUBSTANCES/WASTE TYPES:  
-----  
                 solvent, kerosene, triethanolamine

MANNER AND TIME OF RELEASE:  
-----  
                 Time of release: about 6:00PM 1-20-82

CONTAMINATION INFORMATION:  
-----  
                 DEQ responded to a spill complaint at this site.

PATHWAYS:  
-----

Spill may have entered into storm sewer that empties into the Willamette River.

SUBSTANCE CONTAMINATION

SUBSTANCE	MEDIA CONTAMINATED	CONCENTRATION LEVEL	EVIDENCE	OBSERV. DATE
KEROSENE	Soil Surface Water			
	Date released: about 6:00PM 1-20-82			
	Quantity Released: Unknown			
	Data Source: DEQ Brown file			
SOLVENTS	Soil Surface Water			
	Date released: about 6:00PM 1-20-82			
	Quantity Released: Unknown			
	Data Source: DEQ Brown file			
TRIETHANOLAMINE	Soil Surface Water			
	Date released: about 6:00PM 1-20-82			
	Quantity Released: Unknown			
	Data Source: DEQ Brown file			

STATUS OF INVESTIGATIVE OR REMEDIAL ACTION:

Emergency cleanup

INVESTIGATIVE, REMEDIAL, AND ADMINISTRATIVE ACTIONS

ACTION	START DATE	COMPL. DATE	RESP. STAFF	AGENCY CODE	REGION	LEAD PROGRAM
Site added to database	09MAY1988		Michael Zollitsch	DEQ		SAS
Site Screening recommended (EV)	12FEB1994	12FEB1994	Dan Crouse	DEQ		SAS

PARTY INFORMATION

SITE CONTACT:

=====

ASSOCIATED PARTIES NAME AND ADDRESS -----	AFFILIATION -----	AFFILIATION STATUS -----	INFORMATION AS OF DATE -----
---	----------------------	-----------------------------	------------------------------------

OWNERSHIP COMMENTS:  
=====

DATA SOURCES:  
=====

LAST UPDATED BY: dmc  
-----

DATE: 06-OCT-97  
-----

( site\_report.rpt )