



State of Oregon
Department of
Environmental
Quality

OAR 340-236-8010

Process Weight Table

<i>Process Wt/hr (lbs)</i>	<i>Maximum Weight Discharge/hr (lbs)</i>	<i>Process Wt/hr (lbs)</i>	<i>Maximum Weight Discharge/hr (lbs)</i>
50	0.24	3400	5.44
100	0.46	3500	5.52
150	0.66	3600	5.61
200	0.85	3700	5.69
250	1.03	3800	5.77
300	1.20	3900	5.85
350	1.35	4000	5.93
400	1.50	4100	6.01
450	1.63	4200	6.08
500	1.77	4300	6.15
550	1.89	4400	6.22
600	2.01	4500	6.30
650	2.12	4600	6.37
700	2.24	4700	6.45
750	2.34	4800	6.52
800	2.43	4900	6.60
850	2.53	5000	6.67
900	2.62	5500	7.03
950	2.72	6000	7.37
1000	2.80	6500	7.71
1100	2.97	7000	8.05
1200	3.12	7500	8.39
1300	3.26	8000	8.71
1400	3.40	8500	9.03
1500	3.54	9000	9.36



State of Oregon
Department of
Environmental
Quality

OAR 340-236-8010

Process Weight Table

<i>Process Wt/hr (lbs)</i>	<i>Maximum Weight Discharge/hr (lbs)</i>	<i>Process Wt/hr (lbs)</i>	<i>Maximum Weight Discharge/hr (lbs)</i>
1600	3.66	9500	9.67
1700	3.79	10000	10.00
1800	3.91	11000	10.63
1900	4.03	12000	11.28
2000	4.14	13000	11.89
2100	4.24	14000	12.50
2200	4.34	15000	13.13
2300	4.44	16000	13.74
2400	4.55	17000	14.36
2500	4.64	18000	14.97
2600	4.74	19000	15.58
2700	4.84	20000	16.19
2800	4.92	30000	22.22
2900	5.02	40000	28.30
3000	5.10	50000	34.30
3100	5.18	60000	40.00
3200	5.27	or	
3300	5.36	more	