



OAR 340-226-8010

Particulate Matter Emissions Standards for Process Equipment

Process lbs/hr	Emissions lbs/hr	Process lbs/hr	Emissions lbs/hr	Process lbs/hr	Emissions lbs/hr
50	0.24	2300	4.44	7500	8.39
100	0.46	2400	4.55	8000	8.71
150	0.66	2500	4.64	8500	9.03
200	0.85	2600	4.74	9000	9.36
250	1.03	2700	4.84	9500	9.67
300	1.20	2800	4.92	10000	10.00
350	1.35	2900	5.02	11000	10.63
400	1.50	3000	5.10	12000	11.28
450	1.63	3100	5.18	13000	11.89
500	1.77	3200	5.27	14000	12.50
550	1.89	3300	5.36	15000	13.13
600	2.01	3400	5.44	16000	13.74
650	2.12	3500	5.52	17000	14.36
700	2.24	3600	5.61	18000	14.97
750	2.34	3700	5.69	19000	15.58
800	2.43	3800	5.77	20000	16.19
850	2.53	3900	5.85	30000	22.22
900	2.62	4000	5.93	40000	28.30
950	2.72	4100	6.01	50000	34.30
1000	2.80	4200	6.08	60000	40.00
1100	2.97	4300	6.15	70000	41.30
1200	3.12	4400	6.22	80000	42.50
1300	3.26	4500	6.30	90000	43.60
1400	3.40	4600	6.37	100000	44.60
1500	3.54	4700	6.45	120000	46.30



OAR 340-226-8010

Particulate Matter Emissions Standards for Process Equipment

Process lbs/hr	Emissions lbs/hr	Process lbs/hr	Emissions lbs/hr	Process lbs/hr	Emissions lbs/hr
1600	3.66	4800	6.52	140000	47.80
1700	3.79	4900	6.60	160000	49.00
1800	3.91	5000	6.67	200000	51.20
1900	4.03	5500	7.03	1000000	69.00
2000	4.14	6000	7.37	2000000	77.60
2100	4.24	6500	7.71	6000000	92.70
2200	4.34	7000	8.05		

Interpolation and extrapolation of the data for process unit weight rates in excess of 6,000,000 pounds/hour shall be accomplished by the use of the equation:

$$E = 55.0P^{0.11} - 40$$

where: E = rate of process unit emission in pounds/hour, and

P = process weight in tons/hour