CITY of THE DALLES



313 COURT STREET THE DALLES, OREGON 97058

(541) 296-5481 ext. 1125 FAX: (541) 298-5490 Community Development Dept.

AGENDA CITY OF THE DALLES HISTORIC LANDMARKS COMMISSION

CITY HALL COUNCIL CHAMBERS
313 COURT SREET
THE DALLES, OREGON 97058
CONDUCTED IN A HANDICAP ACCESSIBLE MEETING ROOM

Wednesday, January 30, 2008 @ <u>4 P.M.</u>

- I. Call to order
- II. Roll call
- III. Approval of Agenda
- IV. Approval of Minutes: July 18, 2007
- V. Public Hearing

Historic Landmarks Commission Application #105-08 of Amanda Williams & Matthieu Alirol requesting approval to replace the non-historic windows with new historically accurate windows. The structure is located at 515 W 3rd Place, and is further described as 1N 13E 4AA tax lot 1700. It is historically known as The Donnell House, and is located in the National Trevitt's Historic District.

- VI. Resolution 100-08 Adopting HLC 105-08
- VII. Discussion item Application for Special Assessment; Ben Snipes House
- VIII. Goal Setting for 2008
- IX. Pioneer Cemetery Discussion
- X. Next meeting date: Wednesday, February 27, 2008
- XI. Adjournment

HISTORIC LANDMARK COMMISSION MINUTES

Wednesday, July 18, 2007

City Hall Council Chambers
313 Court Streets
The Dalles, OR 97058
Conducted in a handicap accessible room.

CALL TO ORDER

Chair Eric Gleason called the meeting to order at 4:02 P.M.

ROLL CALL

The following Commissioners were present:

Eric Gleason, John Hashizume & Dixie Parker

The following Commissioners were absent:

Bob McNary

Staff present:

Richard Gassman, Senior Planner City Councilor, Carolyn Woods Denise Ball, Admin. Secretary

APPROVAL OF AGENDA

Commissioner Parker noted that the day on the Agenda says Monday and it should say Wednesday. She then moved to approve the agenda as corrected and Commissioner Hashizume seconded the motion. The motion carried unanimously, McNary absent.

APPROVAL OF MINUTES

Minutes of June 18, 2007: Commissioner Parker moved to approve the minutes as submitted and Commissioner Hashizume seconded. The motion carried unanimously, McNary absent.

<u>PUBLIC HEARING</u> - Historic Landmarks Commission Application #104-07 of The Dalles Civic Auditorium Historical Preservation Committee requesting approval to replace the Mezzanine windows with vinyl windows, replace the roof flashing, complete a door refurbishment and replacement project, and provide display cases on the southeast exterior of the building at Federal and E. 4th Street corners. The building is located at 323 E. 4th Street and the historic name is The Civic Auditorium and Veterans Memorial.

Chair Gleason read the rules for conducting a public hearing. There were no ex-parte contacts, bias, or conflicts of interest by the Commissioners. There were no challenges from the audience. Chair Gleason opened the public hearing and asked for the Staff Report.

Senior Planner Gassman presented the Staff Report. He informed the Commissioners that the applicant has decided to use wood windows and is not requesting the vinyl windows discussed in the Staff Report. Gassman also notified the Commission that Staff will not approve metal frames, plexiglass or back-lighting for the display cases and the applicant will need to find an acceptable alternative. He asked if there were any questions from the Commission.

Proponent: Dennis Morgan, Civic Auditorium Historic Preservation Committee board member, told the Commission he was filling in for the applicant Terry Armentrout, the managing director.

Morgan said the windows in question are on the mezzanine level and are not a part of the original building. They will be replacing four of those windows with new wood windows. Those windows are irreparable being side hinged windows that weren't well constructed, did not fit the space, and over the years have become totally inefficient in blocking drafts or heat.

Morgan added that the display cases proposed will be placed at the non-functional door spaces at the corners of Federal and E. 4th Street. Staff is recommending wood frames, real glass, and direct lighting.

Gleason asked that the two old doors being replaced be saved and stored on site, possibly in place and covered over. Morgan said storage space is at a premium in the Civic. He will bring it up at the next Board meeting.

Opponent: None

Gleason closed the public testimony portion of the hearing.

DELIBERATION:

After deliberating the Commissioners changed two conditions of approval to read as follows:

- 4. The applicant will need to repair the existing windows and doors using techniques supported by both the State Historic Preservation Office as well as the Secretary of Interior Standards. If the applicant feels that the windows and doors are beyond repair, one Planning staff person along with a historic landmarks commissioner will make a determination at a site visit. If it is determined that repair is not feasible, the replacement should match the original windows or doors or as closely as possible with like materials. No vinyl windows or vinyl or metal doors will be allowed.
- 5. The non-functioning doors can be replaced with manufactured wood doors to match the original doors and be located in the original locations. If the original doors are still available, they will need to be repaired rather than replaced with new manufactured wood doors. No vinyl or metal doors will be allowed.

Staff will make the decision on the display cases.

Commissioner Parker moved to approve application HLC 104-07 with conditions of approval as amended. Hashizume seconded, and the motion carried unanimously, McNary absent.

<u>RESOLUTIONS</u> – Commissioner Parker moved to adopt Resolution 99-07 approving HLC 104-07. Commissioner Hashizume seconded the motion and it carried unanimously, McNary absent.

<u>PIONEER CEMETERY DISCUSSION</u> – Discussion was postponed until the next meeting as Commissioner McNary and Associate Planner Hert were absent.

<u>COMMISSIONER/STAFF COMMENTS:</u> The Mayor is actively looking for a replacement for the vacant position of Commissioner Clason. One applicant has submitted an application for consideration.

Commissioner Gleason said he has uncovered the cast iron threshold in his building. It has been covered for thirty to forty years.


ADJOURNMENT: The meeting was adjourned at 5:00 p.m.

Respectfully submitted by Denise Ball, Administrative Secretary.

Eric Gleason, Chair

Historic Landmark Commission





CITY of THE DALLES

313 COURT STREET THE DALLES, OREGON 97058

(541) 296-5481

HLC#105-08


HISTORICAL LANDMARKS APPLICATION

Application is required for modifications and/or alterations to the exterior of certified historic structures and all structures within certified historic districts. Additionally, new construction within established historic districts are also required to appear before the City of The Dalles Historical Landmarks Commission.

Name:	AMANDA WILLIAMS / MATTHIEU ALIROL
Address	3761 BARRETT DR. HOOD RIVER, OR 97631
Site Address	505 W BRD PLACE, THE DALLES
Telephone	541 - 386 - 4471


Please describe your project goals.
We would like to remove the Current picture windows that were
a remode I short Circa 1927 when modification were made to the
house we want to replace those picture windows with energy officiant wood windows that resemble the original windows that fit the how restored 10' Circings. Dur new windows was are an accomption restore the look of the original in
windows that resemble the original windows that fit the how restored 10
Cidlings. Dier new windows will dere an actemption restore the look of the original in
How will your project affect the appearance of the building and or site?
The home will reflect the me height and windows of the
chiqing I home built in 1905.
What efforts are being made to maintain the historic character of this structure?
We are trying to restore the house to what it was like in
1905 to replace the later modifications that were
made & the none around 1927's-1950's.
What is the current use of this property?
Residential
Will the use change as a result of approval of this application? Yes(No)


List any known archeological resources on site.
More that we know of
The review criteria for each application are the Secretary of the Interior's Standards. These standards have been adopted by City Ordinance 94-1194 as local review criteria.
I certify that the above information is correct and submit this application with nine (9) copies of a site plan drawn to scale, nine (9) copies of detailed, elevation drawings with proposed changes, and nine (9) current color photographs (4X6 inch minimum) of the building/structure front.
Amanda William 1/7/08 Applicant Date
Owner (if not the applicant)
I have reviewed the above application and certify that it is complete and accepted for processing.
Dawn Marie Hert by Deace
Secretary, Historical Landmarks Commission
For Office Use Only
Historical Classification
(Primary, Secondary, Historical, Etc.)
Historic Building/Site 🖫 Historic District: Trevitt 🖊 Commercial 🗉
THE REPORT OF THE PARTY OF THE














STAFF REPORT HISTORIC LANDMARKS REVIEW #105-08

TO:

The Dalles Historic Landmarks Commission

FROM:

Dawn Marie Hert, Associate Planner

HEARING DATE: January 30, 2008

ISSUE:

The property owner is requesting to replace the non-historic windows on the historic Donnell House back to original size and

shape with energy efficient wood windows.

SYNOPSIS:

APPLICANT	Amanda Williams & Matthieu Alirol	
PROPERTY OWNER	Same	
LOCATION	515 West Third Place, The Dalles, OR 97058	
ZONING	"CBC" – Central Business Commercial	
EXISTING USE	Residential	
SURROUNDING USE	Primarily Residential	
HISTORIC STATUS	Secondary Contributing in	
	Trevitt's National Historic District	

NOTIFICATION: Published advertisement in local newspaper; notification to property

owners within 100 feet, SHPO.

RECOMMENDATION: Approval, with conditions, based on the following findings

of fact.

BACKGROUND: The applicants recently purchased the house with plans of restoration. During their interior restoration project they found that the picture windows that were installed circa 1927 were obviously not original. They plan to replace the windows with energy efficient wood windows that would resemble the original.

The new owners plan includes repair and replacement of deteriorating porches, painting and other minor repairs to the exterior that would be considered minor alterations that can be approved by the Director. All other planned modifications/repairs/restoration for the interior and are not regulated by the Historic Landmarks Commission.

Most of the proposed restoration could fall under minor modifications and repairs, however, staff wanted to take the application through the formal process for the Commission to give a formal review and approval of the proposed alterations.

The applicant has started a majority of the projects both inside and out and is currently waiting for approval for the window replacement to proceed.

ANALYSIS: The Historic Landmarks Commission is responsible for conducting hearings dealing with proposed alterations to historic buildings. City of The Dalles General Ordinance 94-1194 as well as General Ordinance 96-1207 establishing design guidelines for Historic Resources will serve as a tool to help the Commission make these decisions. The purpose of the Historic Landmarks Commission, the Historic Ordinance and the review criteria are to:

- Protect historic and cultural resources from destruction, inappropriate alteration, and incompatible adjacent development;
- Stabilize and improve property values in historic districts and citywide;
- Enhance the city's attractiveness to visitors and residents, and stimulate business, industry and tourism;
- Educate The Dalles' citizens and visitors concerning the city's heritage;
- Preserve the historic housing stock of The Dalles;
- Comply with The Dalles comprehensive Plan.

A. CITY OF THE DALLES GENERAL ORDINANCE 94-1194—AN ORDINANCE RELATING TO HISTORIC RESOURCES WITHIN THE CITY OF THE DALLES.

Section 7, Subsection A. Review Criteria:

"Secretary's Standards. Commission decisions shall be based on the Secretary of the Interior's Guidelines for the Treatment of Historic Properties." The following are pertinent standards from the "Guide".

1. "A property shall be used as it was historically or be given a new use that requires minimal change to its distinctive materials, features, spaces, and spatial relationships".

FINDING A-1: This structure was historically used as residential. The proposed use will remain the same. Criterion met.

2. "The historic character of a property shall be retained and preserved. The removal of historic materials or alterations to features and spaces that characterize a property shall be avoided."

FINDING-A2: The historic character of the property is being retained and preserved. This application request will remove the deteriorating materials on the structure and replace them with the same or historically accurate materials. All features that characterize the property will be required to be replaced and all alterations/repairs will be required to follow the SHPO's requirements. This will be added as a condition of approval.

3. "Each property shall be recognized as a physical record of its time, place, and use. Changes that create a false sense of historical development, such as adding conjectural features or architectural elements from other buildings, shall not be undertaken."

FINDING-A3: No alternations are planned that would give a false sense of historical development. The structure has had minor alterations over the years

and the applicant plans to follow the restoration guidelines by the SHPO and the City of The Dalles.

4. "Changes to a property that have acquired historic significance in their own right shall be retained and preserved."

FINDING-A4: The picture windows that were installed have not acquired historic significance, the applicants are proposing to remove and replace the windows with historically appropriate windows. Criterion met.

5. "Distinctive features, finishes, and construction techniques or examples of craftsmanship that characterize a property shall be preserved."

FINDING-A5: All of the distinctive architectural elements of the Donnell House shall be preserved. No changes are requested that impact the historic features of the site. Criterion met.

6. "Deteriorating historical features shall be repaired rather than replaced. Where the severity of deterioration requires replacement of a distinctive feature, the new feature shall match the old in design, color, texture, and other visual qualities and, where possible, materials. Replacement of missing features shall be substantiated by documentary and physical evidence."

FINDING-A6: Replacement of the non historic windows is necessary. The applicant is replacing what is not historic and repairing what is salvageable. Criterion will be addressed as a condition of approval.

7. "Chemical or physical treatments, such as sandblasting, that cause damage to historic materials shall not be used. The surface cleaning of structures, if appropriate, shall be undertaken using the gentlest means possible."

FINDING-A7: All exterior surfaces will be required to be surface cleaned using the gentlest means possible. Criterion will be addressed as a condition of approval.

8. "Significant archaeological resources affected by a project shall be protected and preserved. If such resources must be disturbed, mitigation measures shall be undertaken."

FINDING-A8: No excavation is planned with this proposal. Therefore this criterion does not apply.

9. "New additions, exterior alterations, or related new construction shall not destroy historic materials that characterize the property. The new work shall be differentiated from the old and shall be compatible with the massing, size, scale, and architectural features to protect the historic integrity of the property and its environment."

FINDING-A9: The proposed window replacements shall not destroy the historical materials that characterize the property. No new work is proposed with this application other than rebuilding and replacing deteriorated and non-historic elements. Criterion met.

10. "New additions and adjacent or related new construction shall be undertaken in such a manner that, if removed in the future, the essential form and integrity of the historic property and its environment would be unimpaired."

FINDING-A10: No new additions are planned with this application, therefore, this criterion does not apply.

B. Comprehensive Plan (June 1994):

Goal #5 Open Spaces, Scenic and Historic Areas, and Natural Resources lists a City goal applicable to this project as follows:

3. To recognize, protect and enhance the historical importance of the community, and to promote increased public awareness and participation in historic preservation. FINDING B-1: This application is consistent with the Comprehensive Plan by encouraging the restoration and sympathetic renovation of this landmark property. Continued use of this residential resource is vital to our community and its awareness to our historic preservation. The modifications, both interior and exterior will allow for continued use for many years to come. Criterion met.

General Ordinance No. 96-1207 ~ Design Guidelines for The Dalles Commercial Historic District MATERIALS

The sense of cohesiveness and continuity of The Dalles' commercial area derives in part from the consistent use of building materials in building facades. New construction and rehabilitation should use appropriate materials that provide scale making a more pedestrian friendly environment.

GUIDELINES:

a. For building renovations, original materials should be restored wherever possible.

- b. When materials need to be replaced for restoration they should be compatible in quality, color, texture, finish and dimension to the original materials (see page 2, Secretary of the Interior's Standards for Rehabilitation).
- c.New construction should use materials compatible with the historic buildings in quality, color, texture, finish and dimension. Predominant materials of the commercial historic district are:

brick
stone
cast iron
glazed terra cotta
cement plaster (stucco)

- d. The use of wood for windows is recommended.
- e. The use of reflective and smoked glass is prohibited.
- f. Whenever possible, the natural color of the materials should be retained.
- g. An ordinance prohibiting the painting of brick, unless it is damaged or has already been sandblasted, should be adopted.
- h. Sandblasting of brick is prohibited as it severely damages the brick.
- i. When painting a building the following color scheme is recommended:

darkest-window sash medium-building lightest-trim, detail

FINDING B-2: The applicant is proposing wood windows to be built similar to the original historic windows. The applicants were not able to access any historic photos at the time of submittal and were looking to the commission for suggestions on panes or "lights". Staff has contacted retired Judge Donnell and his wife Wendy for assistance with the windows

appearance. At the time the staff report was prepared, no additional information was available. If the Donnell family is unable to give assistance, the Commission will be asked for their professional opinion on the style of the replacement windows. This will be addressed as a condition of approval.

CONCLUSIONS: The proposed replacement of non-historic windows and restoration of the exterior of this historic structure is complimentary to the structure and the historic district in which it is located. In all respects this application meets the standards of the Secretary of the Interior and the City of The Dalles General Ordinance No.94-1194, as the City of The Dalles Comprehensive Land use Plan 1994, with the following conditions:

Recommended Conditions of Approval:

- 1. Work will be completed in substantial conformance to the pictures and proposals as submitted and reviewed.
- 2. The applicant may need to submit plans for a building permit to the local Building Codes Department.
- 3. If any archeological resources or materials are discovered during any excavation, the applicant will need to stop excavation and have the site professionally evaluated prior to continued excavation at the site.
- 4. The applicant will need to avoid removing any historic materials that are on site. Conjectural or architectural features that create a false sense of historical development will not be allowed. Any distinctive features, finishes, or craftsmanship found with construction will need to be preserved by the applicant as best as possible.
- 5. The style of the replacement wood windows will be required to meet the design guidelines of General Ordinance 96-1207, and as directed/approved by the Historic Landmarks Commission.

HISTORIC LANDMARKS RESOLUTION NO. 100-08

Adopting The Dalles Historic Landmarks Commission Application #105-08 of Amanda Williams & Matthieu Alirol requesting approval to replace the non-historic windows with new historically accurate windows. The structure is located at 515 W 3rd Place, and is further described as 1N 13E 4AA tax lot 1700. It is historically known as The Donnell House, and is located in the National Trevitt's Historic District.

I. RECITALS:

- A. The Historic Landmarks Commission of the City of The Dalles has, on January 30, 2008 conducted a public hearing to consider the above request.
- B. A Staff report was presented, stating findings of fact and conclusions of law.
- C. Staff Report number 105-08 and the minutes of January 30, 2008, upon approval, provide the basis for this resolution and are herein attached by reference.
- II. RESOLUTION: Now, Therefore, be it FOUND, DETERMINED, and ORDERED by the Historic Landmarks Commission of the City of The Dalles as follows:
 - A. In all respects as set forth in Recitals, Part "I" of this resolution.
 - B. Historic Landmarks Review No. HLC 105-08 of Amanda Williams & Matthieu Alirol is approved with the following Conditions of Approval:
 - 1. Work will be completed in substantial conformance to the pictures and proposals as submitted and reviewed.
 - 2. The applicant may need to submit plans for a building permit to the local Building Codes Department.
 - 3. If any archeological resources or materials are discovered during any excavation, the applicant will need to stop excavation and have the site professionally evaluated prior to continued excavation at the site.
 - 4. The applicant will need to avoid removing any historic materials that are on site. Conjectural or architectural features that create a false sense of historical development will not be allowed. Any distinctive features, finishes, or craftsmanship found with construction will need to be preserved by the applicant as best as possible.

Resolution No. 100-08 The Donnell House Page 1 of 2 5. The style of the replacement wood windows will be required to meet the design guidelines of General Ordinance 96-1207, and as directed/approved by the Historic Landmarks Commission.

III. APPEALS, COMPLIANCE AND PENALTIES:

- A. Any party of record may appeal a decision of the Historic Landmarks Commission to the City Council for review. Appeals must be made in accordance to Section 9(a) of the Historic Landmarks Ordinance No. 1194, and must be filed with City Clerk within ten (10) days of the date of mailing of this Order.
- B. Failure to exercise this approval within the time line set either by Order or by Ordinance will invalidate this permit.

APPROVED AND ADOPTED THIS 30th DAY OF JANUARY 2008.

Eric Gleason, Chairman Historic Landmarks Commission

I, Dan Durow, Director of the Community Development Department of the City of the Dalles, hereby certify that the foregoing Order was adopted at the meeting of the City Historic Landmarks Commission, held on January 30, 2008.

AYES:	
NAYS:	
ABSENT:	
ABSTAIN:	
ATTEST:	
	Dan Durow, Director Community Development Dept.



Parks and Recreation Department

State Historic Preservation Office 725 Summer St. NE, Suite C Salem, OR 97301-1266 (503) 986-0707 FAX (503) 986-0793 www.hcd.state.or.us



2007

December 26, 2007

Dawn Hert Wasco County Planning Dept 313 Court St The Dalles OR 97058

Dear Ms. Hert:

Enclosed is a copy of an application for the Special Assessment of Historic Property program for a property located in your jurisdiction. We have performed an initial review, and would like to afford you the opportunity to review it as well.

Please submit any comments or recommendations you might have within thirty calendar days of the date on this letter. We will consider your comments with those of the county assessor during the final review of the application.

If approved, special assessment of the enclosed property would begin for the tax year starting July 1, 2008

Thank you for your time. Please contact me at 503-986-0672 if you have any questions.

Sincerely,

Susan Q. Haylock Preservation Specialist

Suran Haylock

SQH:sqh Enclosure

SPECIAL ASSESSMENT OF HISTORIC PROPERTY PROGRAM Application Form/Affidavit

1.	Property Information: Historic Name of Property: <u>Ben Snipes House</u>	Trevitt's Historic District DEC 24 200
	National Register District and rank (if applicable):	Trevitt's Historic District
	Date Listed on the National Register: June 20, 19	995 DEC 9
	Property Address: Street: 218 W 4 th Street	RECREATION DEUA
	City: <u>The Dalles</u>	County: Wasco Zip :97058
2.	Property Tax Information: Tax Account Number: <u>13661</u>	Does owner reside in property?
	Current Assessed Value: \$113,276.00	Current Real Market Value (RM): \$ 222,900.00
	Application Fee (RMV x .0033): \$_735.57	
3.	Preservation Plan Overview Current Use: ☐ Agricultural ☒ Commercial	☐ Industrial ☐ Res./Multi-family
	Estimated Cost of Rehabilitation: \$_34,000.00	Estimated cost of Renovation (for reapplications only): \$\$
	Item Numbers proposed for completion by 5 th year	ar: 1,2,3,4,5,6,,9,10,11,14,15,16,17,18,19,20
	Item Numbers proposed for completion by 10 th ye	ear: 7,8,12,13
4.	Item Numbers proposed for completion by 14 th ye Owner Information:	ear:0
	Owner Name: Alan and Bev Eagy	Organization/business:
	Address: 218 W 4 th Street	City: The Dalles,
	State:OR	
	Phone: <u>541-296-5877</u>	E-mail: eagy@gorge.net
	Representative:	Phone:
	pertains to special assessment of historic propert represent the property to be specially-assessed. Historic Preservation Officer, the State Historic P	gon Administrative Rule (OAR 736-050-0100 through 0150) which try, and that this application and any attachments accurately I agree to grant access for the viewing of the property by the State reservation Officer's staff, the Historic Assessment Review renalties for false swearing as contained in ORS 162.085 that I of my knowledge, it is true, correct, and complete.
SHP	O Determination	
1	Application is acknowledged as complete: SHPO Authorized Signature and Date	2/26/07
•	Property is approved for Special Assessment:	
	SHPO Authorized Signature and Date	
	Property is not approved for Special Assessmen	t. Explanation:
	SHPO Authorized Signature and Date	

7/01/2007 PROPERTY DESCRIPT 218 W 4TH 97058 THE DALLES OR	ION	WASCO COUNDEPT OF ASS	PROPERTY TAX STATEM TY SESSMENT & TAX GTON ST #208 OR 97058 2237	MENT Pa ACCT # 541 506-2	ge 946 13661 540
128243163CWFCWF			LAST YEAR'S TAX		2237.27
CODE: 1211 ACRE MAP: 1N 13E 3BC 4			See back for explanation of	taxes marked	i with (*)
EAGY R ALAN & 218 W 4TH ST THE DALLES OR					
			CGCC REGION 9 ESD SD #21		28.36 49.08 549.55
VALUES: (REAL MARKET)	LAST YEAR	THIS YEAR	EDUCATION TOTAL	• .	626.99
LAND	49180	65080	WASCO COUNTY		446.06
STRUCTURES	136050	157820	PORT OF TD		21.06
TOTAL RMV	185230	222900	PARKS & REC	_	71.33
			MID COL FIRE/RESCU	ΙE	220.33
			DALLES CITY		316.32
ASSESSED	100077	112276	URBAN RENEWAL		177.00 17.72
EXEMPTION	109977	113276	SOIL & WATER DIST 4-H & EXT SVC DIST	1	25.18
	109977	113276	WASCO CO LIBRARY D		71.34
NET TAXABLE:	103377	113270	GENERAL GOVT TOTAL		1366.34
			MID COL FIRE/RESCU		30.36
			SD #12 BONDS		194.60
			CGCC		42.20
•			VA BOND		28.59
			NORCOR BOND		31.56
**.	,		CGCC BOND-WASCO ON	LY	42.69
	company pays your t nt is for your records o		BONDS - OTHER TOTA	L:	370.00
Full Payment with	2/3 Payment with	1/3 Payment	more 2007 20	00 m2 42	2262 22
3% Discount 2292.43	2% Discount 1544.05	No Discount 787.78	TOTAL 2007-20 TOTAL TAX (After Discount)		2363.33 2292.43
▲ Tear Here	PLEASE I	RETURN THIS PORTI	ON WITH YOUR PAYMENT		Tear Here 🛕
2007-2008 PROPERTY	Y TAXES WASCO	COUNTY	REAL	ACCT #	13661
Full Payment Enclose or 2/3 Payment Er		Due: 11/19	5/2007 5/2007		2292.43 1544.05
or 1/3 Payment Er			5/2007		787.78
DISCOUNT IS LOST 8			MATE Mailing address change on back MAKE PAYMENT TO:	\$	ent Amount
EAGY R ALAN (218 W 4TH ST THE DALLES, (DEP1 511 THE 541	CO COUNTY FOR ASSESSMENT & TAX WASHINGTON ST #208 DALLES OR 97058 2237 506-2540 28243163CWFCWF		
		1.	FOE AD TOOCHE CHE		

_____City: The Dalles____County: Wasco

Historic Name: Ben Snipes House
Street: 218 W. 4th Street

1	Architectural feature: Front Steps and Railing Approximate date of feature: 1865 - 1870	Proposed treatment and impact on existing feature:	
escri	be existing feature and its condition:		
	steps have several boards that have rotted on the ends. treads are worn from use.	Replace damaged boards with pressure-treated wood. Prep, prime and paint with sand-infused paint for slip-resistance.	
Bottom rail has been replaced on one side in the past. The replaced rail (left side on photo) does not match the other side. Posts have rotted out on bottom.		Replace bottom rail on west (right side in photo) with new wood to match the other side. Prep, prime, and paint. Replace all posts. Prep, prime, and paint.	
hoto	no.:1 Drawing no.:		
noto	no.:1 Drawing no.:		
	Architectural feature: Porch Roof	Proposed treatment and impact on existing feature:	
2	Architectural feature: Porch Roof Approximate date of feature: 2004	Proposed treatment and impact on existing feature:	
2 escri	Architectural feature: Porch Roof Approximate date of feature: 2004 be existing feature and its condition:		
2 escri	Architectural feature: Porch Roof Approximate date of feature: 2004 be existing feature and its condition: If porch was improperly replaced with shingles. Low angle of auses water to back up and leak through shingles, causing	Remove shingles and underlayment Replace any damaged wood.	
2 escri	Architectural feature: Porch Roof Approximate date of feature: 2004 be existing feature and its condition: If porch was improperly replaced with shingles. Low angle of	Remove shingles and underlayment	
2 escri	Architectural feature: Porch Roof Approximate date of feature: 2004 be existing feature and its condition: If porch was improperly replaced with shingles. Low angle of auses water to back up and leak through shingles, causing	Remove shingles and underlayment Replace any damaged wood.	
2 escri	Architectural feature: Porch Roof Approximate date of feature: 2004 be existing feature and its condition: If porch was improperly replaced with shingles. Low angle of auses water to back up and leak through shingles, causing	Remove shingles and underlayment Replace any damaged wood.	
2 escri	Architectural feature: Porch Roof Approximate date of feature: 2004 be existing feature and its condition: If porch was improperly replaced with shingles. Low angle of auses water to back up and leak through shingles, causing	Remove shingles and underlayment Replace any damaged wood.	
2 escri	Architectural feature: Porch Roof Approximate date of feature: 2004 be existing feature and its condition: If porch was improperly replaced with shingles. Low angle of auses water to back up and leak through shingles, causing	Remove shingles and underlayment Replace any damaged wood.	
2 escri	Architectural feature: Porch Roof Approximate date of feature: 2004 be existing feature and its condition: If porch was improperly replaced with shingles. Low angle of auses water to back up and leak through shingles, causing	Remove shingles and underlayment Replace any damaged wood.	
2 escri	Architectural feature: Porch Roof Approximate date of feature: 2004 be existing feature and its condition: If porch was improperly replaced with shingles. Low angle of auses water to back up and leak through shingles, causing	Remove shingles and underlayment Replace any damaged wood.	
2 escri	Architectural feature: Porch Roof Approximate date of feature: 2004 be existing feature and its condition: If porch was improperly replaced with shingles. Low angle of auses water to back up and leak through shingles, causing	Remove shingles and underlayment Replace any damaged wood.	
2 escri	Architectural feature: Porch Roof Approximate date of feature: 2004 be existing feature and its condition: If porch was improperly replaced with shingles. Low angle of auses water to back up and leak through shingles, causing	Remove shingles and underlayment Replace any damaged wood.	
2 escri	Architectural feature: Porch Roof Approximate date of feature: 2004 be existing feature and its condition: If porch was improperly replaced with shingles. Low angle of auses water to back up and leak through shingles, causing	Remove shingles and underlayment Replace any damaged wood.	

_Historic Name: Ben Snipes House

Photo no.:7

Street: 218 W 4 th Street City: The Dalles County: Wasco					
and w	railed description of rehabilitation/preservation/maintenan ny, clarifying both what is already there and what you plan to d new construction, or alterations.	ce/renovation work. In the boxes below describe what you plan to do o to it/replace it with. Be sure to include any projects that may involve site			
3	Architectural feature: Porch Ceiling Approximate date of feature: 1865-1870	Proposed treatment and impact on existing feature:			
Descri	pe existing feature and its condition:				
Water damage to ceiling. Raining this day, and water is evident leaking through roof.		After roof replacement, remove old paint and fill all holes and damaged areas with appropriate wood putty. Prime and paint.			
Old na	il holes were never sealed.				
Photo	no.:3, 4, 5,6 Drawing no.:				
4	Architectural feature: Front Facade Approximate date of feature: 1865-1870				
Descri	be existing feature and its condition:				
Boards	are warped and sagging.	Remove boards and nail in a few 2×4 cleats so nails will have a better anchor. Replace boards and nail for a better fit. Prep, prime, and paint.			
,					

Historio	o Name: <u>Ben Snipes Hous</u>	e	
Street:		City: <u>The Dalles</u> County:	Wasco
why, cl	iled description of rehab	ilitation/preservation/maintenancy y there and what you plan to do to	ce/renovation work. In the boxes below describe what you plan to do and it/replace it with. Be sure to include any projects that may involve site
5	Architectural feature: <u>Fr</u> Approximate date of feat		Proposed treatment and impact on existing feature:
Describe existing feature and its condition:		condition:	
Paint is peeling, posts are rotted at bottom. Sections of bottom rail are rotted.			Replace rotted sections with matching wood. Replace all posts with exact replicas. Repair or replace damaged sections of bottom rail.
Photo	no.: <u>8</u>	Drawing no.:	
6	Architectural feature: _F Approximate date of feat	ront Porch, floor cure: 1865-1870	Proposed treatment and impact on existing feature:
Describ	pe existing feature and its	condition:	
Water floorbo	damage has caused buckli pards.	ng of tongue-and-groove	After roof repair, I will use weights to flatten boards back down. After assessing condition of boards, I will either replace them with period-appropriate tongue-and-groove boards or prepare the existing
Cracked and peeling paint from the front of the porch. Some latticework is broken.		he front of the porch. Some	wood by scraping paint, priming, and painting. Prep, prime, and paint front of house under porch. Replace or repair broken lattice.

Photo no.:9,10

Historic Name: Ben Snipes House

Photo no.:12

Street	:218 W. 4 th Street	City: The Dalles County: Wasco
and	Detailed description of rehabilitation/preservation/maintenally why, clarifying both what is already there and what you plan to work, new construction, or alterations.	nce/renovation work. In the boxes below describe what you plan to do do to it/replace it with. Be sure to include any projects that may involve
7	Architectural feature: <u>Siding, south side</u> Approximate date of feature: <u>1865-1870</u>	Proposed treatment and impact on existing feature:
Descri	be existing feature and its condition:	
Lap si	ding is weathered and paint is in bad shape.	Prep by removing according to SHPO methods. Prime and paint with SHPO and city-approved color.
		·
	•	
		,
Photo	no.: 11 Drawing no.:	
8	Architectural feature: <u>Siding, West Side</u> Approximate date of feature: <u>1865-1870</u>	Proposed treatment and impact on existing feature:
Descri	be existing feature and its condition:	
Lap si	ding has been damaged by plant trellis. Paint in bad shape.	Repair and re-nail damaged boards with appropriate wood filler. Prep, prime and paint.
]		
1		

Historio	Name: Ben Snipes Hous	se e			
Street:	218 W 4tyh St.		_City:	The Dalles	County: Wasco
and	etailed description of reh why, clarifying both what is work, new construction, or	s already there and what you pla	enance/re n to do to	enovation work it/replace it with	In the boxes below describe what you plan to do Be sure to include any projects that may involve
9	Architectural feature: Si Approximate date of fea	ding, east side ture: 1865-1870	_ Prop	oosed treatment	t and impact on existing feature:
Describ	e existing feature and its	condition:			
Paint p	eeling from west side. Sor	me siding damaged.	Surf	ace prep work r paint with appr	needed according to SHPO specifications. Prime coved color.
		•			
Photo i	no.: <u>13</u>	Drawing no.:			
10	Architectural feature: Approximate date of fea		_ Prop	oosed treatment	t and impact on existing feature:
Describ	be existing feature and its	condition:			
Lower,		perly primed; cracking and	Rem with	nove old paint, n wood filler if p	prime and repaint; repair damaged older wood possible, then prime and paint.
	·				
					•

Photo no.:14

Historic Name: Ben Snipes House						
Street:	Street: 218 W. 4 th Street City: The Dalles County: Wasco					
5. Detailed description of rehabilitation/preservation/maintenance/renovation work. In the boxes below describe what you plan to do and why, clarifying both what is already there and what you plan to do to it/replace it with. Be sure to include any projects that may involve site work, new construction, or alterations.						
11	Architectural feature:_ Approximate date of fea	Gutter, east side ture: 1960	Proposed treatment and impact on existing feature:			
Describe existing feature and its condition:		condition:				
Gutter	broken in recent ice storn	n.	Replace missing section.			
Photo	no.: <u>15</u>	Drawing no.:				
		- Charles - Char				
12	Architectural feature: W Approximate date of fea	ood -shingled Carport #1 & 2 ture: 1865-1870	Proposed treatment and impact on existing feature:			
Describe existing feature and its condition:		condition:				
Wood shingles are rotting and coming off during each significant windstorm.		ming off during each significant	Install underlayment. Replace both carport roofs with shingles that match house or with wood shingles.			
		·				

Photo no.: 16,17

Historic Name: <u>Ben Snipes House</u> Street: 218 W 4 th StreetCity: The DallesCounty: Wasco				
5. Detailed description of rehabilitation/preservation/maintenance/renovation work. In the boxes below describe what you plan to do and why, clarifying both what is already there and what you plan to do to it/replace it with. Be sure to include any projects that may involve site work, new construction, or alterations.				
13	Architectural feature: Roof - House Approximate date of feature: 1960?	Proposed treatment and impact on existing feature:		
Describ	pe existing feature and its condition:			
Shingles are coming off of roof in windstorms.		Replace roof with period-appropriate roofing material.		
Photo r	no.: <u>18</u> Drawing no.:			
4.4				
14	Architectural feature: <u>Entryway stairs to 2nd floor</u> Approximate date of feature: <u>1865-1870</u>	Proposed treatment and impact on existing feature:		
Describ	pe existing feature and its condition:			
Carpet is significantly worn and there is some wood damage to tread underneath.		Remove carpet and remove white paint. Refinish in natural wood color. Fill tread ends with filler/glue/caulk. Install new, periodappropriated carpet runner that will allow wood to be seen.		
Stairs h	nave been painted white.	appropriated carportained state that alone to be seen.		
Treads are cracking apart on edges.				

Photo no.: 19,20,21


Histori	c Name: <u>Ben Snipes House</u>				
Street	218 W 4 th Street	_City: The DallesCounty: Wasco			
why, c	5. Detailed description of rehabilitation/preservation/maintenance/renovation work. In the boxes below describe what you plan to do and why, clarifying both what is already there and what you plan to do to it/replace it with. Be sure to include any projects that may involve site work, new construction, or alterations.				
15	Architectural feature: <u>Picture rail and ceiling</u> Approximate date of feature: 1865-1870	Proposed treatment and impact on existing feature:			
Descri	be existing feature and its condition:				
Picture	e rail moulding is loose and has some paint damage.	Re-nail picture rail moulding and prep and paint.			
Ceiling	, has cracks.	Fill/seal sealing cracks and prep and paint.			
Photo	no.: 22 Drawing no.:				
16	Architectural feature: Ornate moulding Approximate date of feature: 1865-1870	Proposed treatment and impact on existing feature:			
Descri	be existing feature and its condition:				
	e moulding in upper hallway is loose.	Carefully clean and re-nail moulding.			
	, moderning in appear nationally is recorded	- Control of the cont			
	·				
Dist	Danisha and				

Historic Name: Ben Snipes House				
Street:	218 W 4 th Street	City: The DallesCounty: Wasco		
5. Detailed description of rehabilitation/preservation/maintenance/renovation work. In the boxes below describe what you plan to do and why, clarifying both what is already there and what you plan to do to it/replace it with. Be sure to include any projects that may involve site work, new construction, or alterations.				
17	Architectural feature: <u>Upper floor door moulding</u> Approximate date of feature: <u>1865-1870</u>	Proposed treatment and impact on existing feature:		
Describ	e existing feature and its condition:			
Mouldi	ng is damaged in many areas.	Fill with wood filler. Prep and paint		
Dhata	I Downton			
Photo r	o.: 24 Drawing no.:			
18	Architectural feature: <u>Exterior doors</u> Approximate date of feature: <u>1865-1870</u>	Proposed treatment and impact on existing feature:		
Describ	e existing feature and its condition:			
Both exterior doors do not fit properly and there is considerable airflow to/from outside.		Weatherize with weatherstripping/caulking.		
Photo r	n: 25 Prawing no:			

Historic Name: Ben Snipes House				
Street:218 W 4 th Street	City: The DallesCounty: Wasco			
5. Detailed description of rehabilitation/preservation/maintenance/renovation work . In the boxes below describe what you plan to do and why, clarifying both what is already there and what you plan to do to it/replace it with. Be sure to include any projects that may involve site work, new construction, or alterations.				
Architectural feature: <u>Upstairs bathroom - walls</u> Approximate date of feature: <u>1970s?</u>	Proposed treatment and impact on existing feature:			
Describe existing feature and its condition:				
Wall is covered with 1970s?-era shake siding and painted period-inappropriate for the first bathroom with running the city of The Dalles!	white, Remove siding and replace with wallpaper or paint.			
Photo no.: 26 Drawing no.:				
Architectural feature: <u>Upper bathroom floor</u> Approximate date of feature: <u>1970s?</u>	Proposed treatment and impact on existing feature:			
Describe existing feature and its condition:				
Linoleum floor is separating from wall. Some sponginess a toilet and bidet indicating possible water leak.	round Removal of entire floor covering, replace any damaged wood; replace floor with age-appropriate floor covering in consultation with SHPO and local historical society.			
·				
Photo no :27				

Historic Name: Ben Snipes House					
Street:218 W 4 th StreetCity: The DallesCounty: Wasco					
5. Detailed description of rehabilitation/preservation/maintenance/renovation work. In the boxes below describe what you plan to do and why, clarifying both what is already there and what you plan to do to it/replace it with. Be sure to include any projects that may involve site work, new construction, or alterations.					
Architectural feature: Hardwood Floors Approximate date of feature: 1865-1870?	Proposed treatment and impact on existing feature:				
Describe existing feature and its condition:					
Hardwood floors in downstairs bathroom, kitchen, and front room are damaged.	Strip old finish, have floors gently sanded, and re-seal according to SHPO specifications.				
Photo no.: 28 Drawing no.:					
Architectural feature:	Proposed treatment and impact on existing feature:				
Approximate date of feature:					
Describe existing feature and its condition:					
•					
•					


N 4TH STREET



BEN SNIPES SITE PLAN (EXISTING) (C. 1865)


218 W. 4 TH STREET THE DALLES, OR 97058

MAP: IN 13E 38C 4000




BEN SNIPES HOUSE (C. 1865)

MAIN FLOOR



BEN SNIPES HOUSE
(C. 1865)

2ND FLOOR



BEN SNIPES HOUSE

BASEMENT
























1 1







i













Historic Landmarks Commission 2007 Short Term Goals

- 1. Encourage restoration and preservation of the Pioneer Cemetery.
- 2. Provide educational assistance to help individual restorers by setting up a special assessment workshop.
- 3. Establish a Historic resource center. Research grant opportunities to have accessible resource center at local library.
- 4. Assist in saving and completing the Lewis and Clark Memorial and making it a local landmark.
- 5. Update Historic Inventories.
- 6. Actively support Historic The Dalles Days.
- 7. Create Historic Designs for E. 1st Street.
- 8. Establish an Archaeology Testing Plan.
- 9. Support and encourage the preservation and continued use of the Joseph G. Wilson school building.

Long Term Goals

- 1. Continued support for restoration and preservation of the Wasco County Courthouse #2.
- 2. Designate other qualified areas as national historic districts.
- 3. Encourage restoration of the Waldron Drug/Gitchell Building.
- 4. Encourage preservation and restoration of City Hall.
- 5. Maintain CLG status.
- 6. Support Civic Building restoration.
- 7. Continue to supply information on Historic Open Houses and encourage Open House visits during Historic The Dalles Days.
- 8. Continue to assist with historic plaque costs & availability.
- 9. Support and encourage the preparation of a Master Site Plan by the Fort Dalles Museum.
- 10. Encourage restoration and preservation of The Lewis and Clark Rock Fort.

Oregon Heritage Conference Eugene May 6, 2008

Go the Distance! Sustain Oregon's Heritage

Be inspired by the Oregon Heritage Excellence Awards!

Keynote Speaker

James W. Loewen, author of Sundown Towns: A Hidden Dimension of American Racism and Lies My Teacher Told Me: Everything Your High School History Textbook Got Wrong

Conference Topics include:

Oregon's 150th Birthday • Oregon Mainstreet Program • Strengthening Local Preservation • New Archaeological Discoveries • Finding Heritage Tourists • Improving Collections Care • Exhibit Design • Foundation Perspectives • Managing Volunteers • Disaster Tales • Cemetery Care And much more!





Join the crowds gathering for the 2008 Oregon Heritage Conference. May 4-6, Eugene

For information, visit www.oregonheritage.org or contact Kyle Jansson at heritage.info@state.or.us or (503) 986-0673.

Registration begins in February!

PRESORTED
FIRST-CLASS MAII
U.S. POSTAGE
PAID
SALEM OR
Parent No. 87

************************AUTO**3-DIGIT 970
HISTORIC LANDMARKS COMMISSION
313 COURT ST
THE DALLES OR 97058-2111