

**Response to Oregon DEQ Comments
Stormwater Evaluation Report, Terminal 4 Slip 3
September 2021**

Responses to DEQ Comment Received August 31, 2021

ID No.	Section Name/Topic	OR DEQ Comment	Response
7 - RTC, Slip 3	General Comments	The RTC and revised SER were generally responsive to DEQ's June 23, 2021, comments.	Noted.
8 - Specific Comments	Section 7.1.1 Basins J and K2 and Section 7.1.3 Basin D	Section 7.1.1 Basins J and K2 and Section 7.1.3 Basin D – These sections should also reference Section 9 of the SER, which indicates that as part of the performance evaluation for this SCM, the inactive status of the capped outfalls will be verified (i.e., the caps are intact and not leaking).	A cross-reference to Section 9 has been added to these sections.
9 - Specific Comments	Section 9 Next Steps	Section 9 Next Steps – In accordance with the response to Comment 2 in the RTC for Slip 3, this section should include a follow-up investigation of the possible additional outfall pipe discovered in basin D during the July 2021 site visit and if found to be active, capping and inspection during the wet season.	The text of the SER has been updated to note that a follow-up investigation of the possible additional outfall pipe will be conducted.