

Oregon Department of Environmental Quality SSO Reporting Form



This information must be submitted within 5 days of becoming aware of the overflow. Please complete online and print for signature. Be sure to fill out all fields.

	FACILITY/CONTA	ACT INFORMATION		
Name of Permittee: City Of Bend				
Contact Name: Hunter En	sworth			
Phone:	Email:		County:	
(541)-508-7453	HENSWORTH@BENDO	HENSWORTH@BENDOREGON.GOV		
DEQ Permit # (see permit face page): 101572		DEQ F	ile #:7519	
OERS Incident #: 2025-1193		Date Reported to OERS: 05/14/2025		
Date Reported To DEQ: 05/14/2025		Today's Date: 05/15/2025		
Date SSO Started (if known): 05/14/2025		Time Started (if known):		
Date SSO Stopped (if known): 05/14/2025		Time Stopped (if known): 2:00 pm		
SSO Location: Other (explain): Private sewer				
SSO Nearest Address: 61	000 brosterhous Rd			
City: Bend		Zip Code: 97702		
SSO Latitude (if known):		Longitude (if known):		
Estimate of Quantity Overflowed: 250		(Gallor	ns) Link to estimation method	
Did the SSO discharge to	surface water? No	-		
Name of waterbody:				
	PUBLIC NO	OTIFICATION		
Notified downstream drinking water sources (List Below)? N/A				
Name of drinking water facility: N/A				
Signs Posted? N/A				
Media contacted? N/A				
Who?				
List any other steps taken to notify the public or state/federal agencies:				
N/A				
CAUSES				
Cause or suspected cause of the overflow: Other (explain): If needed, attach additional sheets Private contractor cross bored through Private pressure sewer.				
Rainfall in the 24 hours or	rior to SSO (for storm-relate		(inches)	
Source of rainfall data: If needed, attach additional	,	,		

1-in-5 year 24 hour rainfall for t	he sewerage system area (if known): N/A (in/24hr)		
	MERGENCY RESPONSE AND MIGRATION		
	ns taken to stop and mitigate the impact of the SSO.		
For overland flow:	Taped off affected area? Yes		
	Cleaned up affected area? Yes		
For SSO to surface water:	Bacteria samples taken to confirm impact? N/A		
	Follow up bacteria samples taken to confirm end of impact? N/A		
Describe monitoring and results	S:		
N/A			
For SSOs that impact buildings	Pumped out flooded buildings? N/A		
	Disinfected? N/A		
Other measures taken (describ	e):		
•	nch that was made to dig down the the broken sewer pipe, and used		
the Vactor truck to suck up a the affected area.	any sewer that came out of the pipe. We utalized hydrated lime over		
the anected area.			
Steps taken or planned to reduc	ce, eliminate, and prevent the reoccurrence of the overflow and schedule for		
those steps:			
N/A			
	COMMENTS		
Private contractor cross bore	ed through private pressure sewer line on private property.		
	AT THIS DOCUMENT AND ALL ATTACHMENTS WERE PREPARED UNDER MY DIRECTION OR SYSTEM DESIGNED TO ASSURE THAT QUALIFIED PERSONNEL PROPERLY GATHER AND		
	'ED. BASED ON MY INQUIRY OF THE PERSON OR PERSONS WHO MANAGE THE SYSTEM, OR BLE FOR GATHERING THE INFORMATION, THE INFORMATION SUBMITTED IS, TO THE BEST OF		
MY KNOWLEDGE AND BEL <mark>I</mark> EF, TRUE, AC	CCURATE, AND COMPLETE. I AM AWARE THAT THERE ARE SIGNIFICANT PENALTIES FOR LUDING THE POSSIBILITY OF FINE AND IMPRISONMENT FOR KNOWING VIOLATIONS.		
JOBINITY INCOMPLETE IN ORIGINATION, INOI	TO THE TOSSIBLE TO THE AND IMPROGRAMENT OF THE WINDS		
	05/15/2025		
Authorized Signature	Date		
Hunter Ensworth	541-408-7453		
Name (print)	Phone Number		
You may attach additional informa	tion to this report before sending to DEQ as needed to explain the circumstances of		

overflow. This information may include but is not limited to: maintenance records and bacteria monitoring results.

20161221 ~ TLB

Upon completion, print out this form and send to the appropriate DEQ Address:

Portland-Permit Coordinator 700 NE Multnomah St., Suite 600 Portland, OR 97232 **Salem-Permit Coordinator** 4026 Fairview Industrial Dr. SE Salem, OR 97302 **Pendleton-Permit Coordinator** 800 SE Emigrant, #330 Pendleton, OR 97801

FOR DEQ PERSONNEL ONLY			
	Pre-Enforcement Notice		
	Warning Letter		
No enforcement action was warranted because:			
	The SSO was caused by unpreventable vandalism or similar force majeure; or		
	The SSO is allowed as an exception to the permit as maintenance; or		
	The cause of the current SSO was beyond reasonable control AND we do not expect the premittee to prevent similar SSOs in the future; or		
	The SSO was 400 gallons or less, spilled to the ground and not reaching surface water; permittee properly reported, cleaned up, and took appropriate public notice measures; and the SSO was not part of a chronic problem.		
COMMENTS			