
Columbia Forest Products, Inc., Klamath Falls, Oregon
Title V Operating Permit No. 18-0014-TV-01
Cleaner Air Oregon - Air Toxics Emission Inventory Process Flow Diagram

Notes:


- 1) Fugitive and volume sources and locations (e.g., material handling, welding activities, and chemical usages) are included in the Combined Modeling Protocol and Risk Assessment Work Plan.
- 2) Emission release points and modeling input parameters are included in the Combined Modeling Protocol and Risk Assessment Work Plan.

Primary Operations:



(see MP and RAWP)

Material Handling Operations:



Boiler Operations:

