PROJECTED TOTAL COSTS THROUGH PROJECT CLOSEOUT (see last page) - prepared by Paul Chiu on 10/26/2023

Newberg


Bid Date: 5/26/22

7 Pages of Progress Detail

	wberg				Bid Date: 5/26/22								7 Pages of Progress Detail		
						ROAD IMPROVEME		ress Request 17	Pro	gress Request 18	Pro	gress Request 19			
	P	PROGRESS PAYMENT DETAI	IL .		The Saunde	rs Company, Inc.	for wo	rk thru Sep 2023	for w	ork thru Oct 2023	for w	ork thru Nov 2023		SS REQUESTS TOTAL	
Item No.	Spec Sect.	Bid Item	Bid Quan.	Unit	Unit Bid Price	Bid Item Amount	Sep'23 Quantity	Item Amount	Oct'23 Quantity	Item Amount	Nov'23 Quantity	Item Amount	Total Quantity	Item Total	
DIVISION 1	1 - MISCELLAI 102	NEOUS (pre-allocated for Change C Authorized Field Changes	Order Items)	AA	\$ 150,000.00	\$ 150,000.00 \$ 150,000.00									
DIVISION 2	2 - GENERAL 201	Mobilization	1	LS	\$ 481,215.00	\$ 1,712,618.00 \$ 481,215.00		\$ (12,441.00) \$	0.1	\$ 122,271.00 \$ 48,121.50		\$ - \$ -		\$ 2,243,008.00 \$ 481,215.00	
3	202 202	Traffic Control Flaggers	1 650	LS HR	\$ 20,000.00 \$ 60.50	\$ 20,000.00 \$ 39,325.00	0 426	\$ - \$ 25,773.00	0.1 285	\$ 2,000.00 \$ 17,242.50	0	\$ -	1 4570	\$ 20,000.00 \$ 276,485.00	
5	SP305 203	Construction Survey	1	LS LS	\$ 85,000.00 \$ 100,000.00	\$ 85,000.00 \$ 100,000.00	0.2	\$ 17,000.00 \$ -	0	\$ -	0	\$ -	1	\$ 85,000.00 \$ 100,000.00	
7	204	Clearing and Grubbing Erosion & Sediment Control	1	LS	\$ 10,000.00	\$ 10,000.00	0.1	\$ 1,000.00	0	\$ -	0	\$ -	1	\$ 10,000.00	
8 9	205 205	General Excavation Over Excavation	5,979 50	CY CY	\$ 60.00 \$ 40.00	\$ 358,740.00 \$ 2,000.00	613 0	\$ 36,780.00 \$ -	0	\$ -	0		7009 255	\$ 420,540.00 \$ 10,200.00	
10 11	205 206	Foundation Stabilization Subgrade Geotextile	250 11,936	CY SY	\$ 25.00 \$ 1.50	\$ 6,250.00 \$ 17,904.00	0 2278	\$ - \$ 3,417.00	0	\$ - \$ -	0	\$ - \$ -	255 11936	\$ 6,375.00 \$ 17,904.00	
12	207	Seeding, Mix No. 1 Lawn Seeding	0.22	ACRE	\$ 21,500.00	\$ 4,730.00	0	\$ -	0.12	\$ 2,580.00	0		0.22	\$ 4,730.00	
13	207	Seeding, Water Quality Mix	3,706	SF	\$ 1.00	\$ 3,706.00	0	\$ -	0	\$ -	0	'	3706	\$ 3,706.00	
14 15	207 207	Shrubs, 4" Container Shrubs, 1 Gal.	731 188	EA EA	\$ 11.00 \$ 22.00	\$ 8,041.00 \$ 4,136.00	0	\$ - \$ -	731 188	\$ 8,041.00 \$ 4,136.00	0	'	731 188	\$ 8,041.00 \$ 4,136.00	
16	207	Water Quality Plugs	22,930	EA	\$ 0.60	\$ 13,758.00	0	\$ -	0	\$ -	0		22930	\$ 13,758.00	
17	207	Deciduous Trees, 2 inch Caliper	41 295	EA CY	\$ 415.00 \$ 60.00	\$ 17,015.00	0	\$ - \$ -	28 150	\$ 11,620.00 \$ 9,000.00	0	•	28 499	\$ 11,620.00 \$ 29,940.00	
18 19	207	Bark Mulch Newberg WWTP Compost	269	CY	\$ 75.00	\$ 17,700.00 \$ 20,175.00	0	\$ -	150	\$ 11,250.00	0	\$ -	424	\$ 31,800.00	
20 21	207 211	Root Barrier Structure Removal	164 1	FT LS	\$ 20.00 \$ 35,000.00	\$ 3,280.00 \$ 35,000.00	0	\$ - \$ -	164 0	\$ 3,280.00 \$ -		\$ -	164 1	\$ 3,280.00 \$ 35,000.00	
22 23	212 212	Type A Service Conversion	2	EA EA	\$ 6,500.00 \$ 20,000.00	\$ 13,000.00 \$ 80,000.00	0	\$ - \$ -	0	\$ - \$ -	0		2	\$ 13,000.00 \$ 80,000.00	
24	212	Type D Service Conversion 577 Vault	6	EA	\$ 8,750.00	\$ 52,500.00	-11.2013	\$ (98,011.00)	0	\$ -	0	\$ -	6	\$ 52,500.00	
25 26	212 212	644 Vault 1730 Vault	6 27	EA EA	\$ 6,000.00 \$ 1,500.00	\$ 36,000.00 \$ 40,500.00	0	\$ - \$ -	0	\$ - \$ -	0	\$ -	5 28	\$ 30,000.00 \$ 42,000.00	
27 28	212 212	1 Inch Conduit 2 Inch Conduit	253 590	LF LF	\$ 8.00 \$ 15.00	\$ 2,024.00 \$ 8,850.00	0	\$ - \$ -	0	\$ - \$ -	0	'	408 9203	\$ 3,264.00 \$ 138,045.00	
29	212 212	3 Inch Conduit	4,127	LF LF	\$ 17.00	\$ 70,159.00	0	\$ - \$ -	0	\$ -	0	\$ -	4956 5913	\$ 84,252.00	
30 31	212	4 Inch Conduit Joint Utility Trench	1,720 3,200	LF	\$ 19.00 \$ 15.00	\$ 32,680.00 \$ 48,000.00	0	\$ -	0	\$ - \$ -	0	'	3200	\$ 112,347.00 \$ 48,000.00	
32	213	Type CL4-R Black Vinyl Coated Chain Link Fence	58	LF	\$ 30.00	\$ 1,740.00	0	\$ -	0	\$ -	0	\$ -	334	\$ 10,020.00	
33	213	Type CL4-R Black Vinyl Coated	1	EA	\$ 5,000.00	\$ 5,000.00	0	s -	1	\$ 5,000.00	0	\$ -	1	\$ 5,000.00	
33	213	Chain Link Single Gate (Rolling)	•	Ln.	3,000.00	3,000.00				3,000.00		,		3,000.00	
34	213	Type CL6-R Black Vinyl Coated Chain Link Fence	488	LF	\$ 55.00	\$ 26,840.00	0	\$ -	0	\$ -	0	\$ -	100	\$ 5,500.00	
35	213	Type CL6-R Black Vinyl Coated	4	EA	\$ 1,000.00	\$ 4,000.00	0	\$ -	0	\$ -	0	\$ -	2	\$ 2,000.00	
		Chain Link Single Gate (Swing)			, ,							'			
36	213	Type CL6-R Black Vinyl Coated Chain Link Single Gate (Rolling)	2	EA	\$ 14,500.00	\$ 29,000.00	0	\$ -	0	\$ -	0	\$ -	2	\$ 29,000.00	
37	214	Single Mailbox Support	15	EA	\$ 550.00	\$ 8,250.00	0	\$ -	0	\$ -	0	\$ -	15	\$ 8,250.00	
38	214	Multiple Mailbox Support Remove & Reinstall Cluster	4	EA	\$ 725.00	\$ 2,900.00	0	\$ -	0	\$ -	0		4	\$ 2,900.00	
39 DIVISION 3	214 3 - SANITARY	Mailbox	4	EA	\$ 800.00	\$ 3,200.00 \$ 399,265.00	2	\$ 1,600.00 \$ 625.00	0	\$ -		\$ -		\$ 3,200.00 \$ 327.565.00	
40 41	301 301	4 Inch PVC 3034 Pipe 4 Inch PVC C900 Pipe	100 180	LF LF	\$ 65.00 \$ 70.00	\$ 6,500.00 \$ 12,600.00	0	\$ -	0	\$ -	0	\$ - \$ -	183 18	\$ 11,895.00 \$ 1,260.00	
42	301	6 Inch PVC 3034 Pipe	20	LF	\$ 65.00	\$ 1,300.00	0	\$ -	0	\$ -	0	\$ -	12	\$ 780.00	
43 44	301 301	6 Inch PVC C900 Pipe 8 Inch PVC 3034 Pipe	20 0	LF LF	\$ 70.00 \$ -	\$ 1,400.00 \$ -	0	\$ - \$ -	0	\$ - \$ -	0	'	8	\$ 560.00 \$ -	
45		8 Inch Cleanout						\$ -	0	\$ -	0		U		
46	301		0	EA	\$ -	\$ -	0						0	\$ -	
	301	Reconstructed Lateral Connection to 8 inch Main		EA EA	\$ 2,000.00	\$ 12,000.00	0	\$ -	0	\$ -	0	,		\$ -	
47		Reconstructed Lateral Connection to 8 inch Main Reconstructed Lateral Connection to 12 inch Main	0		\$ 2,000.00		0	\$ - \$ -	0	s - s -	0		0	\$ -	
47	303	Reconstructed Lateral Connection to 8 inch Main Reconstructed Lateral	6	EA	\$ 2,000.00 \$ 2,350.00	\$ 12,000.00	0	\$ -			0	\$ - \$ -	0 9 4	\$ -	
	303 303	Reconstructed Lateral Connection to 8 inch Main Reconstructed Lateral Connection to 12 inch Main Lateral Reconnection and Cleanout Sanitary Sewer MH, 48" Over	0 6 4	EA EA	\$ 2,000.00 \$ 2,350.00 \$ 1,975.00	\$ 12,000.00 \$ 9,400.00	0	\$ - \$ -	0	\$ -	0 0	\$ - \$ -	0 9 4	\$ - \$ 18,000.00 \$ 9,400.00 \$ 59,250.00	
48	303 303 303	Reconstructed Lateral Connection to 8 inch Main Reconstructed Lateral Connection to 12 inch Main Lateral Reconnection and Cleanout Sanitary Sewer MH, 48" Over Extg Sanitary Sewer Shallow MH, 48"	0 6 4 30	EA EA	\$ 2,000.00 \$ 2,350.00 \$ 1,975.00 \$ 5,200.00	\$ 12,000.00 \$ 9,400.00 \$ 59,250.00	0 0	s - s -	0	s - s -	0 0 0	\$ - \$ - \$ -	0 9 4 30	\$ - \$ 18,000.00 \$ 9,400.00 \$ 59,250.00	
48 49 50	303 303 303 303 303	Reconstructed Lateral Connection to 8 inch Main Reconstructed Lateral Connection to 12 inch Main Lateral Reconnection and Cleanout Sanitary Sewer MH, 48" Over Extg	0 6 4 30 3	EA EA EA EA	\$ 2,000.00 \$ 2,350.00 \$ 1,975.00 \$ 5,200.00 \$ 4,650.00	\$ 12,000.00 \$ 9,400.00 \$ 59,250.00 \$ 15,600.00 \$ 4,650.00	0 0 0 0	\$ - \$ - \$ -	0 0 0	\$ - \$ - \$ - \$ -	0 0 0 0	\$ - \$ - \$ - \$ -	0 9 4 30 4	\$ 18,000.00 \$ 9,400.00 \$ 59,250.00 \$ 20,800.00 \$ 4,650.00	
48 49 50 51	303 303 303 303 303 303	Reconstructed Lateral Connection to 8 inch Main Reconstructed Lateral Connection to 12 inch Main Lateral Reconnection and Cleanout Sanitary Sewer MH, 48" Over Extg Over Extg Minor Adjustment of MH to Extg Grade	0 6 4 30 3 1	EA EA EA	\$ 2,000.00 \$ 2,350.00 \$ 1,975.00 \$ 5,200.00 \$ 4,650.00 \$ 625.00	\$ 12,000.00 \$ 9,400.00 \$ 59,250.00 \$ 15,600.00 \$ 4,650.00 \$ 3,750.00	0 0 0	\$ - \$ - \$ -	0 0	\$ - \$ - \$ - \$ -	0 0 0 0	\$ - \$ - \$ - \$ - \$ -	0 9 4 30 4 1	\$ 18,000.00 \$ 9,400.00 \$ 59,250.00 \$ 20,800.00 \$ 4,650.00 \$ 3,750.00	
48 49 50	303 303 303 303 303	Reconstructed Lateral Connection to 8 inch Main Reconstructed Lateral Connection to 12 inch Main Lateral Reconnection and Cleanout Sanitary Sewer MH, 48" Over Extg Sanitary Sewer Shallow MH, 48" Over Extg Minor Adjustment of MH to Extg Grade Abandon Extg Sewer Pre-Construction Video	0 6 4 30 3	EA EA EA EA EA EA	\$ 2,000.00 \$ 2,350.00 \$ 1,975.00 \$ 5,200.00 \$ 4,650.00 \$ 625.00 \$ 110.00	\$ 12,000.00 \$ 9,400.00 \$ 59,250.00 \$ 15,600.00 \$ 4,650.00 \$ 3,750.00	0 0 0 0 0	\$ - \$ - \$ - \$ - \$ 5	0 0 0	\$ - \$ - \$ - \$ -	0 0 0 0 0 0 0	\$ - \$ - \$ - \$ - \$ -	0 9 4 30 4 1 6 35	\$ 18,000.00 \$ 9,400.00 \$ 59,250.00 \$ 20,800.00 \$ 4,650.00	
48 49 50 51 52 53	303 303 303 303 303 303 303	Reconstructed Lateral Connection to 8 inch Main Reconstructed Lateral Connection to 12 inch Main Lateral Reconnection and Cleanout Sanitary Sewer MH, 48" Over Extg Sanitary Sewer Shallow MH, 48" Over Extg Whinor Adjustment of MH to Extg Grade Abandon Extg Sewer Pre-construction Video Inspection Post-construction Video	0 6 4 30 3 1 6 35	EA EA EA EA LF LS	\$ 2,000.00 \$ 2,350.00 \$ 1,975.00 \$ 5,200.00 \$ 4,650.00 \$ 625.00 \$ 110.00 \$ 1,500.00	\$ 12,000.00 \$ 9,400.00 \$ 59,250.00 \$ 15,600.00 \$ 4,650.00 \$ 3,750.00 \$ 3,850.00 \$ 1,500.00	0 0 0 0 0 0 1	\$ - \$ - \$ - \$ 625.00 \$ - \$ -	0 0 0 0 0	\$ - \$ - \$ - \$ 5 - \$ 5 5 5 5 5 5 5 5 5 5	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	\$ - \$ - \$ \$ - \$ \$ \$ - \$ \$ \$ - \$ \$ \$ - \$ \$ \$ - \$ \$ \$ - \$ \$ \$ - \$ \$ \$ - \$ \$ \$ - \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ \$ - \$	9 4 30 4 1 6 35	\$ 18,000.00 \$ 9,400.00 \$ 59,250.00 \$ 20,800.00 \$ 4,650.00 \$ 3,750.00 \$ 3,850.00 \$ 1,500.00	
48 49 50 51 52	303 303 303 303 303 303 303 304	Reconstructed Lateral Connection to 8 linch Main Reconstructed Lateral Connection to 12 inch Main Lateral Reconnection and Cleanout Sanitary Sewer MH, 48" Over Extg Sanitary Sewer Shallow MH, 48" Over Extg Minor Adjustment of MH to Extg Grade Abandon Extg Sewer Pre-construction Video Inspection	0 6 4 30 3 1 6 35 1	EA EA EA EA LF	\$ 2,000.00 \$ 2,350.00 \$ 1,975.00 \$ 5,200.00 \$ 4,650.00 \$ 625.00 \$ 110.00 \$ 1,500.00	\$ 12,000.00 \$ 9,400.00 \$ 59,250.00 \$ 15,600.00 \$ 4,650.00 \$ 3,750.00 \$ 3,850.00	0 0 0 0 0	\$ - \$ - \$ - \$ 625.00 \$ - \$ -	0 0 0 0 0 0 0 0 0	\$ - \$ - \$ - \$ 5 - \$ 5 5 5 5 5 5	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	\$ - \$ - \$ \$ - \$ \$ \$ - \$ \$ \$ - \$ \$ \$ - \$ \$ \$ - \$ \$ \$ - \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ \$ \$ - \$	0 9 4 30 4 1 6 35	\$ 18,000.00 \$ 9,400.00 \$ 59,250.00 \$ 20,800.00 \$ 4,650.00 \$ 3,750.00 \$ 3,850.00 \$ 1,500.00	
48 49 50 51 52 53	303 303 303 303 303 303 303 304	Reconstructed Lateral Connection to 8 inch Main Reconstructed Lateral Connection to 12 inch Main Lateral Reconnection and Cleanout Sanitary Sewer MH, 48" Over Extg Sanitary Sewer Shallow MH, 48" Over Extg Minor Adjustment of MH to Extg Grade Abandon Extg Sewer Pre-construction Video Inspection Post-construction Video Inspection	0 6 4 30 3 1 6 35 1	EA EA EA EA LF LS	\$ 2,000.00 \$ 2,350.00 \$ 1,975.00 \$ 5,200.00 \$ 4,650.00 \$ 110.00 \$ 1,500.00 \$ 1,500.00 \$ 8,000.00	\$ 12,000.00 \$ 9,400.00 \$ 59,250.00 \$ 15,600.00 \$ 4,650.00 \$ 3,750.00 \$ 3,850.00 \$ 1,500.00	0 0 0 0 0 0 1 0 0	\$ - \$ - \$ - \$ 625.00 \$ - \$ - \$ -	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	\$ - \$ - \$ - \$ 5 - \$ 5 5 5 5 5 5 5 5 5 5	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	\$ - \$ - \$ \$ - \$ \$ \$ - \$ \$ \$ - \$ \$ \$ - \$ \$ \$ - \$ \$ \$ - \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ - \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ \$ \$ - \$ \$ \$ \$ \$ \$ \$ \$ - \$	0 9 4 30 4 1 6 35 1	\$ 18,000.00 \$ 9,400.00 \$ 59,250.00 \$ 20,800.00 \$ 4,650.00 \$ 3,750.00 \$ 3,850.00 \$ 1,500.00 \$ 1,500.00	
48 49 50 51 52 53 54	303 303 303 303 303 303 303 304 304	Reconstructed Lateral Connection to 8 inch Main Renconstructed Lateral Connection to 12 inch Main Lateral Reconnection and Cleanout Sanitary Sewer MH, 48" Over Extg Sanitary Sewer Shallow MH, 48" Over Extg Minor Adjustment of MH to Extg Grade Abandon Extg Sewer Pre-construction Video Inspection Post-construction Video Inspection By-Pass Pumping	0 6 4 30 3 1 6 35 1	EA EA EA EA LF LS LS	\$ 2,000.00 \$ 2,350.00 \$ 1,975.00 \$ 5,200.00 \$ 4,650.00 \$ 110.00 \$ 1,500.00 \$ 1,500.00 \$ 8,000.00	\$ 12,000.00 \$ 9,400.00 \$ 59,250.00 \$ 15,600.00 \$ 4,650.00 \$ 3,750.00 \$ 3,850.00 \$ 1,500.00 \$ 1,500.00	0 0 0 0 0 0 1 0 0 0	\$ - \$ - \$ - \$ 625.00 \$ - \$ - \$ -	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	\$ - S - S - S - S - S - S - S - S - S -	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	\$ - \$ - \$ 5	0 9 4 30 4 1 6 35 1	\$ 18,000.00 \$ 9,400.00 \$ 59,250.00 \$ 20,800.00 \$ 4,650.00 \$ 3,750.00 \$ 3,850.00 \$ 1,500.00 \$ 1,500.00	
48 49 50 51 52 53 54 55 56	303 303 303 303 303 303 303 304 304 304	Reconstructed Lateral Connection to 8 inch Main Reconstructed Lateral Connection to 12 inch Main Lateral Reconnection and Cleanout Sanitary Sewer MH, 48" Over Extg Sanitary Sewer Shallow MH, 48" Over Extg Over Extg Minor Adjustment of MH to Extg Grade Abandon Extg Sewer Pre-construction Video Inspection By-Pass Pumping Cured In Place Pipe Lining, 4 Inch Cured In Place Pipe Lining, 6 Inch	0 6 4 30 3 1 6 35 1 1 1 760	EA EA EA EA LF LS LS LS LF LF	\$ 2,000.00 \$ 2,350.00 \$ 1,975.00 \$ 5,200.00 \$ 4,650.00 \$ 110.00 \$ 1,500.00 \$ 1,500.00 \$ 100.00 \$ 75.00	\$ 12,000.00 \$ 9,400.00 \$ 59,250.00 \$ 15,600.00 \$ 4,650.00 \$ 3,750.00 \$ 3,850.00 \$ 1,500.00 \$ 1,500.00 \$ 8,000.00 \$ 76,000.00 \$ 25,500.00	0 0 0 0 0 0 1 1 0 0 0	\$ - \$ - \$ \$ - \$ \$ 5 - \$ \$ - \$ \$ 5 - \$ \$ \$ 5 - \$ \$ \$ 5 - \$ \$ \$ 5 - \$ \$ \$ 5 - \$ \$ \$ 5 - \$ \$ \$ 5 - \$ \$ \$ 5 - \$ \$ \$ 5 - \$ \$ \$ 5 - \$ \$ \$ 5 - \$ \$ \$ 5 - \$ \$ \$ \$	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	\$ - \$ - \$ - \$ - \$ 5 - \$	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	\$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ -	0 9 4 30 4 1 6 35 1 1 1 0	\$ 18,000.00 \$ 9,400.00 \$ 59,250.00 \$ 20,800.00 \$ 4,650.00 \$ 3,750.00 \$ 3,850.00 \$ 1,500.00 \$ 8,000.00 \$ - \$ 5	
48 49 50 51 52 53 54 55 56 57 58	303 303 303 303 303 303 304 304 304 304	Reconstructed Lateral Connection to 8 inch Main Reconstructed Lateral Connection to 12 inch Main Lateral Reconnection and Cleanout Sanitary Sewer MH, 48" Over Extg Sanitary Sewer Shallow MH, 48" Over Extg Over Extg Minor Adjustment of MH to Extg Grade Abandon Extg Sewer Pre-construction Video Inspection Post-construction Video Inspection By-Pass Pumping Cured in Place Pipe Lining, 4 Inch Cured in Place Pipe Lining, 6 Inch Cured in Place Pipe Lining, 6 Inch	0 6 4 30 3 1 6 35 1 1 1 760 340	EA EA EA EA EA LF LS LS LF LF LF	\$ 2,000.00 \$ 2,350.00 \$ 1,975.00 \$ 5,200.00 \$ 4,650.00 \$ 110.00 \$ 1,500.00 \$ 1,500.00 \$ 1,500.00 \$ 1,500.00 \$ 5,000.00 \$ 5,000.00	\$ 12,000.00 \$ 9,400.00 \$ 59,250.00 \$ 15,600.00 \$ 4,650.00 \$ 3,750.00 \$ 3,850.00 \$ 1,500.00 \$ 1,500.00 \$ 76,000.00 \$ 69,850.00	0 0 0 0 0 0 1 0 0 0 0 0 0	\$ - \$ - \$ \$ \$ - \$ \$ \$ - \$ \$ \$ - \$ \$ \$ - \$ \$ \$ - \$ \$ \$ - \$ \$ \$ - \$ \$ \$ - \$ \$ \$ - \$ \$ \$ - \$ \$ \$ -	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	\$ - \$ - \$ - \$ - \$ 5 - \$	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	\$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ -	0 9 4 30 4 1 6 35 1 1 1 0 340	\$ 18,000.00 \$ 9,400.00 \$ 59,250.00 \$ 20,800.00 \$ 4,650.00 \$ 3,750.00 \$ 1,500.00 \$ 1,500.00 \$ 8,000.00 \$ 9 25,500.00 \$ 69,850.00	
48 49 50 51 52 53 54 55 56 57 58 59	303 303 303 303 303 303 303 304 304 304	Reconstructed Lateral Connection to 8 inch Main Reconstructed Lateral Connection to 12 inch Main Lateral Reconnection and Cleanout Sanitary Sewer MH, 48" Over Extg Sanitary Sewer Shallow MH, 48" Over Extg Over Extg Minor Adjustment of MH to Extg Grade Abandon Extg Sewer Pre-construction Video Inspection Post-construction Video Inspection By-Pass Pumping Cured In Place Pipe Lining, 4 Inch Cured In Place Pipe Lining, 6 Inch Cured In Place Pipe Lining, 8 Inch Cured In Place Pipe Lining, 12 Inch	0 6 4 30 3 1 6 35 1 1 760 340 1,270	EA EA EA EA EA LF LS LS LF LF LF LF	\$ 2,000.00 \$ 2,350.00 \$ 1,975.00 \$ 5,200.00 \$ 4,650.00 \$ 110.00 \$ 1,500.00 \$ 1,500.00 \$ 100.00 \$ 75.00 \$ 75.00	\$ 12,000.00 \$ 9,400.00 \$ 59,250.00 \$ 15,600.00 \$ 4,650.00 \$ 3,750.00 \$ 3,850.00 \$ 1,500.00 \$ 1,500.00 \$ 76,000.00 \$ 25,500.00 \$ 69,850.00 \$ 67,500.00	0 0 0 0 0 0 1 0 0 0 0 0 0 0	\$ - \$ - \$ \$ \$ - \$ \$ \$ - \$ \$ \$ - \$ \$ \$ - \$ \$ \$ - \$ \$ \$ - \$ \$ \$ - \$ \$ \$ -	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	\$ - \$ - \$ - \$ - \$ 5 - \$	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	\$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ -	0 9 4 30 4 1 6 35 1 1 1 0 340	\$ 18,000.00 \$ 9,400.00 \$ 59,250.00 \$ 20,800.00 \$ 4,650.00 \$ 3,750.00 \$ 1,500.00 \$ 1,500.00 \$ 9,000.00 \$ 9,000.00 \$ 9,000.00 \$ 9,000.00 \$ 9,000.00 \$ 9,000.00 \$ 9,000.00 \$ 9,000.00 \$ 9,000.00 \$ 9,000.00 \$ 9,000.00	
48 49 50 51 52 53 54 55 56 57 58	303 303 303 303 303 303 304 304 304 304	Reconstructed Lateral Connection to 8 inch Main Reconstructed Lateral Connection to 12 inch Main Lateral Reconnection and Cleanout Sanitary Sewer MH, 48" Over Extg Sanitary Sewer Shallow MH, 48" Over Extg Ganitary Sewer Shallow MH, 48" Over Extg Minor Adjustment of MH to Extg Grade Abandon Extg Sewer Pre-construction Video Inspection Post-construction Video Inspection Post-construction Video Inspection Cured In Place Pipe Lining, 4 Inch Cured In Place Pipe Lining, 8 Inch Cured In Place Pipe Lining, 8 Inch Cured In Place Pipe Lining, 12 Inch Service Line Reconnection Chemical Grout Extg Service	0 6 4 30 3 1 6 35 1 1 1 760 340	EA EA EA EA EA LF LS LS LF LF LF	\$ 2,000.00 \$ 2,350.00 \$ 1,975.00 \$ 5,200.00 \$ 4,650.00 \$ 110.00 \$ 1,500.00 \$ 1,500.00 \$ 100.00 \$ 75.00 \$ 75.00 \$ 75.00	\$ 12,000.00 \$ 9,400.00 \$ 59,250.00 \$ 15,600.00 \$ 4,650.00 \$ 3,750.00 \$ 3,850.00 \$ 1,500.00 \$ 1,500.00 \$ 76,000.00 \$ 69,850.00	0 0 0 0 0 0 1 1 0 0 0 0 0 0 0	\$ - \$ - \$ \$ \$ - \$ \$ \$ - \$ \$ \$ - \$ \$ \$ - \$ \$ \$ - \$ \$ \$ - \$ \$ \$ - \$ \$ \$ - \$ \$ \$ - \$ \$ \$ - \$ \$ \$ -	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	\$ - \$ - \$ - \$ - \$ 5 - \$	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	\$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ -	0 9 4 30 4 1 6 35 1 1 1 0 340	\$ 18,000.00 \$ 9,400.00 \$ 59,250.00 \$ 20,800.00 \$ 4,650.00 \$ 3,750.00 \$ 1,500.00 \$ 1,500.00 \$ 8,000.00 \$ 9 25,500.00 \$ 69,850.00	
48 49 50 51 52 53 54 55 56 57 58 59 60 61 DIVISION 4	303 303 303 303 303 303 304 304 304 304	Reconstructed Lateral Connection to 8 inch Main Reconstructed Lateral Connection to 12 inch Main Lateral Reconnection and Cleanout Sanitary Sewer MH, 48" Over Extg Sanitary Sewer Shallow MH, 48" Over Extg Minor Adjustment of MH to Extg Grade Abandon Extg Sewer Pre-construction Video Inspection By-Pass Pumping Cured In Place Pipe Lining, 4 Inch Cured In Place Pipe Lining, 6 Inch Cured In Place Pipe Lining, 8 Inch Cured In Place Pipe Lining, 12 Inch Service Line Reconnection	0 6 4 30 3 1 6 35 1 1 1 760 340 1,270 900 29	EA EA EA EA EA LF LS LS LS LF LF LF LF LF LF LF LF	\$ 2,000.00 \$ 1,975.00 \$ 5,200.00 \$ 4,650.00 \$ 110.00 \$ 11500.00 \$ 15,500.00 \$ 15,500.00 \$ 75.00 \$ 75.00 \$ 8,000.00 \$ 100.00 \$ 8,000.00	\$ 12,000.00 \$ 9,400.00 \$ 59,250.00 \$ 15,600.00 \$ 4,650.00 \$ 3,750.00 \$ 1,500.00 \$ 1,500.00 \$ 1,500.00 \$ 8,000.00 \$ 76,000.00 \$ 25,500.00 \$ 69,850.00 \$ 67,500.00 \$ 3,915.00	0 0 0 0 0 0 1 1 0 0 0 0 0 0 0 0	\$ - \$ - \$ \$	0 0 0 0 0 0 0 0 0 0 0 0	\$ - \$ - \$ - \$ - \$ 5 - \$	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	\$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ 5 - \$	0 9 4 30 4 1 6 35 1 1 1 0 340 1270 900 32 38	\$ 18,000.00 \$ 9,400.00 \$ 59,250.00 \$ 20,800.00 \$ 4,650.00 \$ 3,750.00 \$ 1,500.00 \$ 1,500.00 \$ 25,500.00 \$ 69,850.00 \$ 67,500.00 \$ 15,200.00	
48 49 50 51 52 53 54 55 56 57 58 59 60 61	303 303 303 303 303 303 303 304 304 304	Reconstructed Lateral Connection to 8 inch Main Reconstructed Lateral Connection to 12 inch Main Lateral Reconnection and Cleanout Sanitary Sewer MH, 48" Over Extg Sanitary Sewer Shallow MH, 48" Over Extg Minor Adjustment of MH to Extg Grade Abandon Extg Sewer Pre-construction Video Inspection Post-construction Video Inspection By-Pass Pumping Cured In Place Pipe Lining, 4 Inch Cured In Place Pipe Lining, 6 Inch Cured In Place Pipe Lining, 8 Inch Cured In Place Pipe Lining, 8 Inch Cured In Place Pipe Lining, 12 Inch Service Line Reconnection Chemical Grout Extg Service Lateral	0 6 4 30 3 1 6 35 1 1 760 340 1,270 900 29	EA EA EA EA EA LF LS LS LS LF LF LF LF LF LF LF LF	\$ 2,000.00 \$ 2,350.00 \$ 1,975.00 \$ 5,200.00 \$ 4,650.00 \$ 110.00 \$ 1,500.00 \$ 1,500.00 \$ 100.00 \$ 75.00 \$ 75.00 \$ 75.00	\$ 12,000.00 \$ 9,400.00 \$ 59,250.00 \$ 15,600.00 \$ 4,650.00 \$ 3,750.00 \$ 1,500.00 \$ 1,500.00 \$ 76,000.00 \$ 25,500.00 \$ 69,850.00 \$ 67,500.00 \$ 3,915.00 \$ 15,200.00	0 0 0 0 0 1 0 0 0 0 0 0 0 0 0 0 0 0 0 0	\$ - \$ - \$ \$	0 0 0 0 0 0 0 0 0 0 0 0	\$ - \$ - \$ - \$ - \$ \$ - \$ \$ - \$ \$ - \$ \$ - \$ \$ - \$ \$ - \$ \$ - \$ \$ \$ -	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	\$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ -	0 9 4 30 4 1 6 35 1 1 1 0 0 340 1270 900 32 38	\$ \$ 18,000.00 \$ 9,400.00 \$ 59,250.00 \$ 20,800.00 \$ 4,650.00 \$ 3,750.00 \$ 1,500.00 \$ 1,500.00 \$ 25,500.00 \$ 69,850.00 \$ 69,850.00 \$ 67,500.00 \$ 15,200.00	
48 49 49 50 51 52 53 53 54 55 56 57 58 59 60 61 1	303 303 303 303 303 303 303 304 304 304	Reconstructed Lateral Connection to 8 inch Main Reconstructed Lateral Connection to 12 inch Main Lateral Reconnection and Cleanout Sanitary Sewer MH, 48" Over Extg Sanitary Sewer Shallow MH, 48" Over Extg Minor Adjustment of MH to Extg Grade Abandon Extg Sewer Pre-construction Video Inspection Post-construction Video Inspection Post-construction Video Inspection Cured In Place Pipe Lining, 4 Inch Cured In Place Pipe Lining, 8 Inch Cured In Place Pipe Lining, 12 Inch Cured In Place Pipe Lining, 12 Inch Cured In Place Pipe Lining, 12 Inch Service Line Reconnection Chemical Grout Extg Service Lateral Service Water Pipe Service Water Pipe Type Vater Pipe	0 6 4 30 3 1 1 6 35 1 1 760 340 1,270 900 29 19	EA EA EA EA EA LF LS LS LF LF LF LF LF FT FT FT FT	\$ 2,000.00 \$ 2,350.00 \$ 1,975.00 \$ 5,200.00 \$ 4,650.00 \$ 110.00 \$ 1,500.00 \$ 1,500.00 \$ 100.00 \$ 75.00 \$ 75.00 \$ 355.00 \$ 135.00 \$ 135.00 \$ 30.00	\$ 12,000.00 \$ 9,400.00 \$ 59,250.00 \$ 15,600.00 \$ 4,650.00 \$ 3,750.00 \$ 3,850.00 \$ 1,500.00 \$ 76,000.00 \$ 76,000.00 \$ 25,500.00 \$ 69,850.00 \$ 15,200.00 \$ 3,915.00 \$ 15,200.00 \$ 15,200.00 \$ 10,800.00 \$ 10,800.00 \$ 10,800.00	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	\$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ -	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	\$ - \$ - \$ - \$ \$ -	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	\$ - \$ - \$ - \$ - \$ - \$ 5	0 9 4 30 4 1 1 1 0 0 340 1270 900 32 38 38 2448 140 20 0	\$ 18,000.00 \$ 9,400.00 \$ 99,250.00 \$ 20,800.00 \$ 4,650.00 \$ 3,750.00 \$ 1,500.00 \$ 1,500.00 \$ 25,500.00 \$ 69,850.00 \$ 67,500.00 \$ 15,200.00 \$ 15,200.00 \$ 15,200.00 \$ 15,200.00 \$ 15,200.00	
48 49 50 51 52 53 54 55 56 57 58 59 60 61 DIVISION 4 62 63 64 65 66 66 66 66 66	303 303 303 303 303 303 303 304 304 304	Reconstructed Lateral Connection to 8 inch Main Reconstructed Lateral Connection to 12 inch Main Lateral Reconnection and Cleanout Sanitary Sewer MH, 48" Over Extg Sanitary Sewer Shallow MH, 48" Over Extg Minor Adjustment of MH to Extg Grade Abandon Extg Sewer Pre-construction Video Inspection Post-construction Video Inspection By-Pass Pumping Cured In Place Pipe Lining, 4 Inch Cured In Place Pipe Lining, 6 Inch Cured In Place Pipe Lining, 8 Inch Cured In Place Pipe Lining, 12 Inch Service Line Reconnection Chemical Grout Extg Service Lateral 8" DIP Water Pipe 6" DIP Water Pipe 6" DIP Water Pipe 6" DIP Water Pipe 2" Type L Copper Main 3/4" Water Service	0 6 4 30 3 1 6 35 1 1 1 760 340 1,270 900 29 19 2,529 140 20 28 5	EA EA EA EA EA LF LS LS LF LF LF LF LF EA EA EA	\$ 2,000.00 \$ 1,975.00 \$ 5,200.00 \$ 5,200.00 \$ 4,650.00 \$ 110.00 \$ 1,500.00 \$ 1,500.00 \$ 100.00 \$ 75.00 \$ 575.00 \$ 135.00 \$ 135.00 \$ 137.00 \$ 142.00 \$ 30.00 \$ 2,850.00 \$ 4,400.00	\$ 12,000.00 \$ 9,400.00 \$ 59,250.00 \$ 15,600.00 \$ 4,650.00 \$ 3,750.00 \$ 3,850.00 \$ 1,500.00 \$ 1,500.00 \$ 76,000.00 \$ 69,850.00 \$ 69,850.00 \$ 15,200.00 \$ 19,880.00 \$ 19,880.00 \$ 19,880.00 \$ 19,880.00 \$ 19,880.00 \$ 19,880.00	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	\$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ -	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	\$ - \$ - \$ - \$ - \$ \$ - \$ \$ - \$ \$ - \$ \$ - \$ \$ - \$ \$ - \$ \$ - \$ \$ \$ -	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	\$ - \$ - \$ - \$ - \$ 5 - \$	0 9 4 30 4 11 6 35 11 1 1 0 340 1270 9900 32 2 38 2448 2448 240 20 28 5 5 5	\$ 18,000.00 \$ 9,400.00 \$ 59,250.00 \$ 20,800.00 \$ 4,650.00 \$ 3,750.00 \$ 1,500.00 \$ 1,500.00 \$ 25,500.00 \$ 67,500.00 \$ 67,500.00 \$ 15,200.00 \$ 15,200.00 \$ 15,200.00 \$ 19,880.00 \$ 19,880.00 \$ 286,416.00 \$ 19,880.00 \$ 79,800.00 \$ 79,800.00 \$ 22,000.00	
48 49 50 51 52 53 54 55 56 57 58 59 60 61 10 10 10 10 10 10 10 10 10 10 10 10 10	303 303 303 303 303 303 303 304 304 304	Reconstructed Lateral Connection to 8 inch Main Reconstructed Lateral Connection to 12 inch Main Lateral Reconnection and Cleanout Sanitary Sewer MH, 48" Over Extg Sanitary Sewer Shallow MH, 48" Over Extg Minor Adjustment of MH to Extg Grade Abandon Extg Sewer Pre-construction Video Inspection Post-construction Video Inspection Post-construction Video Inspection Cured In Place Pipe Lining, 4 Inch Cured In Place Pipe Lining, 8 Inch C	0 6 4 30 3 1 6 35 1 1 760 340 1,270 900 29 19	EA EA EA EA EA LF LS LS LS LF LF LF LF LF LF LF LF LF EA EA	\$ 2,000.00 \$ 2,350.00 \$ 1,975.00 \$ 5,200.00 \$ 4,650.00 \$ 110.00 \$ 1,500.00 \$ 1,500.00 \$ 100.00 \$ 75.00 \$ 75.00 \$ 35.00 \$ 135.00 \$ 135.00 \$ 142.00 \$ 30.00 \$ 2,850.00	\$ 12,000.00 \$ 9,400.00 \$ 59,250.00 \$ 15,600.00 \$ 4,650.00 \$ 3,750.00 \$ 1,500.00 \$ 1,500.00 \$ 76,000.00 \$ 69,850.00 \$ 67,500.00 \$ 3,915.00 \$ 15,200.00 \$ 19,800.00 \$ 19,800.00 \$ 295,893.00 \$ 295,893.00 \$ 295,893.00 \$ 19,800.00 \$ 79,800.00	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	\$ - \$ - \$ 5	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	\$ - \$ - \$ - \$ - \$	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	\$ - \$ - \$ - \$ - \$ - \$ - \$ 5 -	0 9 4 30 4 1 1 6 35 1 1 1 1 0 340 1270 900 32 38 140 20 28 8	\$ 18,000.00 \$ 9,400.00 \$ 59,250.00 \$ 20,800.00 \$ 3,750.00 \$ 3,850.00 \$ 1,500.00 \$ 1,500.00 \$ 69,850.00 \$ 67,500.00 \$ 15,200.00 \$ 19,880.00 \$ 19,880.00 \$ 79,800.00 \$ 79,800.00	
48 49 50 51 52 53 54 55 56 57 58 59 60 61 61 64 65 66 66 67 67 66 66 66 66 67	303 303 303 303 303 303 303 304 304 304	Reconstructed Lateral Connection to 8 linch Main Reconstructed Lateral Connection to 12 inch Main Lateral Reconnection and Cleanout Sanitary Sewer MH, 48" Over Extg Sanitary Sewer Shallow MH, 48" Over Extg Minor Adjustment of MH to Extg Grade Abandon Extg Sewer Pre-construction Video Inspection Post-construction Video Inspection By-Pass Pumping Cured In Place Pipe Lining, 4 Inch Cured In Place Pipe Lining, 6 Inch Cured In Place Pipe Lining, 8 Inch Service Line Reconnection Chemical Grout Extg Service Lateral 8" DIP Water Pipe 6" DIP Water Pipe 6" DIP Water Pipe 2" Type L Copper Main 3/4" Water Service 1" Water Service 1" Vater Service 1" Vater Service	0 6 4 30 3 1 6 35 1 1 760 340 1,270 900 29 19 2,529 140 20 22 28 5	EA EA EA EA EA LF LS LS LS LF LF LF LF EA EA EA EA	\$ 2,000.00 \$ 2,350.00 \$ 1,975.00 \$ 5,200.00 \$ 4,650.00 \$ 110.00 \$ 1,500.00 \$ 1,500.00 \$ 75.00 \$ 55.00 \$ 135.00 \$ 142.00 \$ 142.00 \$ 30.00 \$ 2,850.00 \$ 6,500.00	\$ 12,000.00 \$ 9,400.00 \$ 59,250.00 \$ 15,600.00 \$ 4,650.00 \$ 3,750.00 \$ 3,850.00 \$ 1,500.00 \$ 76,000.00 \$ 76,000.00 \$ 39,850.00 \$ 39,915.00 \$ 15,200.00 \$ 15,200.00 \$ 15,200.00 \$ 25,500.00 \$ 39,850.00 \$ 15,200.00 \$ 15,200.00 \$ 295,893.00 \$ 295,893.00 \$ 19,880.00 \$ 295,893.00 \$ 19,880.00 \$ 600.00 \$ 79,800.00 \$ 6,500.00 \$ 6,500.00	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	\$ - \$ - \$ - \$ - \$	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	\$ - \$ - \$ - \$ - \$ 5 - \$	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	\$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ 5 - \$ - \$	0 9 4 30 4 1 1 6 35 1 1 1 1 0 0 340 1270 900 32 38 140 20 8 5 1 1 2 2	\$ 18,000.00 \$ 9,400.00 \$ 59,250.00 \$ 20,800.00 \$ 3,750.00 \$ 3,850.00 \$ 1,500.00 \$ 1,500.00 \$ 69,850.00 \$ 67,500.00 \$ 15,200.00 \$ 15,200.00 \$ 19,800.00 \$ 19,800.00 \$ 19,800.00 \$ 19,800.00 \$ 19,800.00 \$ 19,800.00 \$ 19,800.00 \$ 19,800.00 \$ 11,500.00 \$ 11,500.00 \$ 11,500.00 \$ 11,500.00 \$ 11,500.00 \$ 11,500.00 \$ 11,500.00 \$ 11,500.00 \$ 11,500.00 \$ 11,500.00 \$ 11,500.00 \$ 11,500.00 \$ 11,500.00 \$ 11,500.00 \$ 11,500.00	
48 49 50 51 52 53 54 55 56 57 58 59 60 61 1 DIVISION 4 62 63 64 65 66 66 67 70 68 69 70	303 303 303 303 303 303 303 304 304 304	Reconstructed Lateral Connection to 8 inch Main Reconstructed Lateral Connection to 12 inch Main Lateral Reconnection and Cleanout Sanitary Sewer MH, 48" Over Extg Sanitary Sewer Shallow MH, 48" Over Extg Minor Adjustment of MH to Extg Grade Abandon Extg Sewer Pre-construction Video Inspection Post-construction Video Inspection By-Pass Pumping Cured In Place Pipe Lining, 4 Inch Cured In Place Pipe Lining, 6 Inch Cured In Place Pipe Lining, 8 Inch Cured In Place Pipe Lining, 12 Inch Service Line Reconnection Chemical Grout Extg Service Lateral 8" DIP Water Pipe 6" DIP Water Pipe 6" DIP Water Pipe 1" Type L Copper Main 3,4" Water Service 1-1/2" Water Service 8" Gate Valve w/Box 8" Gate Valve w/Box	0 6 4 30 3 1 6 35 1 1 1 760 340 1,270 900 29 19 2,529 140 20 28 5 1 1 2	EA EA EA EA EA EA LF LS LS LF LF LF LF EA	\$ 2,000.00 \$ 1,975.00 \$ 5,200.00 \$ 5,200.00 \$ 4,650.00 \$ 110.00 \$ 11,500.00 \$ 100.00 \$ 75.00 \$ 555.00 \$ 135.00 \$ 135.00 \$ 2,850.00 \$ 142.00 \$ 3,000.00 \$ 4,400.00 \$ 6,500.00 \$ 6,500.00 \$ 3,000.00	\$ 12,000.00 \$ 9,400.00 \$ 15,600.00 \$ 15,600.00 \$ 3,750.00 \$ 3,850.00 \$ 1,500.00 \$ 1,500.00 \$ 76,000.00 \$ 69,850.00 \$ 69,850.00 \$ 13,200.00 \$ 13,200.00 \$ 69,850.00 \$ 13,200.00 \$ 13,200.00 \$ 13,200.00 \$ 13,200.00 \$ 13,200.00 \$ 13,200.00 \$ 13,200.00 \$ 13,200.00 \$ 13,200.00 \$ 13,200.00 \$ 13,200.00 \$ 13,200.00 \$ 13,200.00 \$ 13,200.00 \$ 13,200.00 \$ 13,200.00 \$ 13,200.00 \$ 13,200.00 \$ 13,200.00	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	\$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ -	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	\$ - \$ - \$ - \$ 5 -	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	\$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ -	0 9 9 4 30 30 4 11 6 35 11 1 1 0 0 340 1270 9900 32 38 140 20 28 5 1 1 2 2 2 14 4	\$ 18,000.00 \$ 9,400.00 \$ 59,250.00 \$ 20,800.00 \$ 4,650.00 \$ 3,750.00 \$ 1,500.00 \$ 1,500.00 \$ 25,500.00 \$ 69,850.00 \$ 15,200.00 \$ 15,200.00 \$ 14,320.00 \$ 19,880.00 \$ 19,880.00 \$ 19,880.00 \$ 19,880.00 \$ 19,880.00 \$ 19,800.00 \$ 19,800.00 \$ 10,000.00	
48 49 50 51 52 53 54 55 56 57 58 59 60 61 60 61 60 67 68 69 70 71	303 303 303 303 303 303 303 304 304 304	Reconstructed Lateral Connection to 8 inch Main Reconstructed Lateral Connection to 12 inch Main Lateral Reconnection and Cleanout Sanitary Sewer MH, 48" Over Extg Sanitary Sewer Shallow MH, 48" Over Extg Minor Adjustment of MH to Extg Grade Abandon Extg Sewer Pre-construction Video Inspection By-Pass Pumping Cured In Place Pipe Lining, 4 Inch Cured In Place Pipe Lining, 6 Inch Cured In Place Pipe Lining, 8 Inch Cured In Place Pipe Lining, 9 Inch Cured In Place Pipe Lining, 12 Inch Cured In Place Pipe Lining, 9 Inch Cured In Place Pipe Lining, 12 Inch Cured In Place Pipe Lining, 13 Inch Cured In Place Pipe Cured Inch Cu	0 6 4 30 3 1 1 6 35 1 1 1 760 340 1,270 900 29 19 2,529 140 20 20 22 28 5 5 1 2 2 2 2 2 2 3 3 3 3 3 3 3 3 4 3 3 3 3 3	EA EA EA EA EA LF LS LS LS LF LF LF LF EA	\$ 2,000.00 \$ 1,975.00 \$ 5,200.00 \$ 4,650.00 \$ 110.00 \$ 11500.00 \$ 15,500.00 \$ 15,500.00 \$ 15,500.00 \$ 15,500.00 \$ 15,500.00 \$ 15,500.00 \$ 117.00 \$ 135.00 \$ 1442.00 \$ 30.00 \$ 1440.00 \$ 30.00 \$ 3,850.00 \$ 3,850.00 \$ 3,900.00 \$ 3,000.00 \$ 1,500.00	\$ 12,000.00 \$ 9,400.00 \$ 15,600.00 \$ 15,600.00 \$ 3,750.00 \$ 3,850.00 \$ 1,500.00 \$ 1,500.00 \$ 76,000.00 \$ 76,000.00 \$ 25,500.00 \$ 3,915.00 \$ 15,200.00 \$ 19,880.00 \$ 19,880.00 \$ 19,800.00	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	\$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ -	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	\$ - \$ - \$ - \$ \$ -	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	\$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ -	0 9 4 30 4 1 1 6 5 5 1 1 0 340 1270 900 32 2 38 140 140 228 5 1 1 2 2 2 2 1 14 4 3 3	\$ 18,000.00 \$ 9,400.00 \$ 20,800.00 \$ 20,800.00 \$ 3,750.00 \$ 3,750.00 \$ 1,500.00 \$ 1,500.00 \$ 4,650.00 \$ 1,500.00	
48 49 50 51 52 53 54 55 56 57 58 60 61 61 62 63 64 66 66 67 68 69 70 71 72	303 303 303 303 303 303 303 304 304 304	Reconstructed Lateral Connection to 8 inch Main Reconstructed Ideral Connection to 12 inch Main Lateral Reconnection and Cleanout Sanitary Sewer MH, 48" Over Extg Sanitary Sewer Shallow MH, 48" Over Extg Minor Adjustment of MH to Extg Grade Abandon Extg Sewer Pre-construction Video Inspection Post-construction Video Inspection Post-construction Video Inspection Post-construction Video Inspection Cured In Place Pipe Lining, 4 Inch Cured In Place Pipe Lining, 8 Inch Cured In Place Pipe Lining, 8 Inch Cured In Place Pipe Lining, 12 Inch Cured In Place Pipe Lining, 12 Inch Service Line Reconnection Chemical Grout Extg Service Lateral 8" DIP Water Pipe ""Type I. Copper Main 3/4" Water Service 1-1/2" Water Service 1-1/2" Water Service 2" Water Service 3" Gate Valve w/Box G" Gate Valve w/Box G" Gate Valve w/Box Combination Air & Vacuum Release Valve W/Box Combination Air & Vacuum Release Valve W/Box	0 6 4 30 3 1 1 6 35 1 1 1 760 340 1,270 900 29 19 20 20 20 22 28 5 1 2 2 2 2 2 3 3 3 3 4 3 3 3 3 3 4 3 3 3 3	EA EA EA EA EA LF LS LS LF LF LF LF EA	\$ 2,000.00 \$ 1,975.00 \$ 5,200.00 \$ 4,650.00 \$ 110.00 \$ 11500.00 \$ 15,500.00 \$ 15,500.00 \$ 100	\$ 12,000.00 \$ 9,400.00 \$ 15,600.00 \$ 4,650.00 \$ 3,750.00 \$ 3,850.00 \$ 1,500.00 \$ 76,000.00 \$ 76,000.00 \$ 22,500.00 \$ 3,910.00 \$ 15,200.00 \$ 15,200.00 \$ 19,800.00 \$ 19,800.00 \$ 19,800.00 \$ 19,800.00 \$ 19,800.00 \$ 19,800.00 \$ 19,800.00 \$ 19,800.00 \$ 19,800.00 \$ 14,000.00 \$ 14,000.00 \$ 14,000.00 \$ 14,000.00 \$ 14,000.00 \$ 14,000.00 \$ 14,000.00 \$ 14,000.00 \$ 14,000.00 \$ 14,000.00	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	\$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ -	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	\$ - \$ - \$ - \$ 5 -	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	\$ - \$ - \$ - \$ - \$ - \$ - \$ 5 - \$ - \$ 5 - \$	0 9 4 30 4 1 1 6 5 5 1 1 0 340 1270 900 32 2 38 2448 140 20 28 5 1 1 2 2 2 2 1 14 4 3 3 2 2	\$ 18,000.00 \$ 9,400.00 \$ 59,250.00 \$ 20,800.00 \$ 4,650.00 \$ 3,750.00 \$ 1,500.00 \$ 1,500.00 \$ 69,850.00 \$ 67,500.00 \$ 15,200.00 \$ 19,800.00 \$ 19,800.00 \$ 19,800.00 \$ 19,800.00 \$ 19,800.00 \$ 19,800.00 \$ 19,800.00 \$ 13,000.00 \$ 42,000.00 \$ 42,000.00 \$ 5 4,500.00 \$ 5 4,500.00	
48 49 50 51 52 53 54 55 56 57 58 59 60 61 60 61 60 66 67 68 69 70 71 72 73 74	303 303 303 303 303 303 303 304 304 304	Reconstructed Lateral Connection to 8 inch Main Reconstructed Lateral Connection to 12 inch Main Lateral Reconnection and Cleanout Sanitary Sewer MH, 48" Over Extg Sanitary Sewer Shallow MH, 48" Over Extg Ganitary Sewer Shallow MH, 48" Over Extg Minor Adjustment of MH to Extg Grade Abandon Extg Sewer Pre-construction Video Inspection Post-construction Video Inspection By-Pass Pumping Cured In Place Pipe Lining, 4 Inch Cured In Place Pipe Lining, 6 Inch Cured In Place Pipe Lining, 8 Inch Cured In Place Pipe Lining, 12 Inch Service Line Reconnection Chemical Grout Extg Service Lateral B" DIP Water Pipe 5" DIP Water Pipe 2" Type L Copper Main 3,4" Water Service 1-1/2" Water Service 1-1/2" Water Service Brod Sleeve for Water Service 8" Gate Valve w/Box 6" Gate Valve w/Box 6 Grate Valve w/Box 6 Grate Valve w/Box 6 Grate Valve w/Box 6 Grate Valve w/Box 8 Fire Hydrant Assembly 8 Blow Off Assembly 8 Fire Hydrant Assembly	0 6 4 30 3 1 6 35 1 1 760 340 1,270 900 29 19 2,529 140 20 28 5 1 1 2 2 1 6 3 5 1 2 1 3 5 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1	EA EA EA EA EA LF LS LS LS LF LF LF LF EA	\$ 2,000.00 \$ 1,975.00 \$ 5,200.00 \$ 4,650.00 \$ 110.00 \$ 11500.00 \$ 15,500.00 \$ 15,500.00 \$ 100	\$ 12,000.00 \$ 9,400.00 \$ 15,600.00 \$ 4,650.00 \$ 3,750.00 \$ 3,850.00 \$ 1,500.00 \$ 76,000.00 \$ 76,000.00 \$ 22,500.00 \$ 3,910.00 \$ 15,200.00 \$ 15,200.00 \$ 19,800.00 \$ 19,800.00 \$ 19,800.00 \$ 19,800.00 \$ 19,800.00 \$ 19,800.00 \$ 19,800.00 \$ 19,800.00 \$ 19,800.00 \$ 14,000.00 \$ 14,000.00 \$ 14,000.00 \$ 14,000.00 \$ 14,000.00 \$ 14,000.00 \$ 14,000.00 \$ 14,000.00 \$ 14,000.00 \$ 14,000.00	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	\$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ -	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	\$ - \$ - \$ - \$ - \$ 5 - 5 5 - 5 5 5 5 5 5	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	\$ - \$ - \$ - \$ - \$ 5 - \$	0 9 9 4 30 4 11 6 35 1 1 1 1 0 0 340 1270 900 32 38 140 20 28 8 5 1 1 2 2 2 2 1 14 3 3 2 2 2 3 3 5 5	\$ 18,000.00 \$ 9,400.00 \$ 59,250.00 \$ 20,800.00 \$ 4,650.00 \$ 3,750.00 \$ 1,500.00 \$ 1,500.00 \$ 6,850.00 \$ 69,850.00 \$ 15,200.00 \$ 15,200.00 \$ 15,200.00 \$ 19,880.00 \$ 19,880.00 \$ 19,800.00 \$ 10,000.00	
48 49 50 51 52 53 54 55 56 57 58 59 60 61 00000000000000000000000000000000	303 303 303 303 303 303 303 304 304 304	Reconstructed Lateral Connection to 8 inch Main Reconstructed Lateral Connection to 12 inch Main Lateral Reconnection and Cleanout Sanitary Sewer MH, 48" Over Extg Sanitary Sewer Shallow MH, 48" Over Extg Minor Adjustment of MH to Extg Grade Abandon Extg Sewer Pre-construction Video Inspection By-Pass Pumping Cured In Place Pipe Lining, 4 Inch Cured In Place Pipe Lining, 6 Inch Cured In Place Pipe Lining, 8 Inch Cured In Place Pipe Lining, 9 Inch Cured In Place Pipe Lining, 12 Inch Service Line Reconnection Chemical Grout Extg Service Lateral 8" DIP Water Pipe 6" DIP Water Pipe 1" Yupe L Copper Main 3/4" Water Service 1" Water Service 1" Water Service 8" Gate Valve w/Box Combination Air & Vacuum Release Valve Assembly Blow Off Assembly	0 6 4 30 3 1 6 35 1 1 760 340 1,270 900 29 19 20 28 5 1 1 2 2 2 2 3 3	EA EA EA EA EA EA LF LS LS LS LF LF LF EA	\$ 2,000.00 \$ 1,975.00 \$ 5,200.00 \$ 4,650.00 \$ 110.00 \$ 1,500.00 \$ 1,500.00 \$ 100.00 \$ 15.00 \$ 175.00 \$ 135.00 \$ 135.00 \$ 142.00 \$ 142.00 \$ 142.00 \$ 142.00 \$ 142.00 \$ 140.00 \$ 1,500.00 \$ 2,850.00 \$ 1,500.00 \$ 2,850.00 \$ 2,850.00 \$ 2,850.00 \$ 2,850.00 \$ 2,850.00 \$ 2,000.00 \$ 2,000.00 \$ 2,000.00 \$ 2,000.00 \$ 2,000.00 \$ 2,000.00 \$ 2,000.00 \$ 2,000.00 \$ 2,000.00 \$ 2,000.00 \$ 2,000.00 \$ 2,000.00 \$ 2,000.00	\$ 12,000.00 \$ 9,400.00 \$ 15,600.00 \$ 15,600.00 \$ 3,750.00 \$ 3,850.00 \$ 1,500.00 \$ 1,500.00 \$ 25,500.00 \$ 69,850.00 \$ 3,915.00 \$ 15,200.00	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	S - S - S - S - S - S - S - S - S - S -	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	\$ - \$ - \$ - \$ \$ -	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	\$ - \$ - \$ - \$ - \$ 5 - \$	0 9 9 4 30 4 11 6 35 1 1 1 1 0 0 340 1270 900 32 38 140 20 28 8 5 1 1 2 2 2 2 1 14 3 3 2 2 2 3 3 5 5	\$ 18,000.00 \$ 9,400.00 \$ 59,250.00 \$ 20,800.00 \$ 4,650.00 \$ 3,750.00 \$ 3,850.00 \$ 1,500.00 \$ 1,500.00 \$ 69,850.00 \$ 67,500.00 \$ 15,200.00 \$ 15,200.00 \$ 19,800.00 \$ 19,800.00 \$ 11,200.00	



ELLIOTT ROAD IMPROVEMENT PROJECT														
	Р	ROGRESS PAYMENT DETA	IL		The Saunders Company, Inc. Progress Request 17 for work thru Sep 2023					ress Request 18 ork thru Oct 2023		ress Request 19 ork thru Nov 2023	PROGRE	SS REQUESTS TOTAL
Item No.	Spec Sect.	Bid Item	Bid Quan.	Unit	Unit Bid Price	Bid Item Amount	Sep'23 Quantity	Item Amount	Oct'23 Quantity	Item Amount	Nov'23 Quantity	Item Amount	Total Quantity	Item Total
77	404	Connect Extg Service to New Meter	35	EA	\$ 1,075.00	\$ 37,625.00	Quantity	\$ -		\$ -		\$ -	35	\$ 37,625.00
78	404	Abandon Existing Main	2,450	EA	\$ 10.00	\$ 24,500.00	0		0	\$ -	0	\$ -	2450	\$ 24,500.00
79	5 - STREET 504	Aggregate Base	5,100	CY	\$ 95.00	\$ 1,666,355.00 \$ 484,500.00	583	\$ 545,416.00 \$ 55,385.00	0	\$ 88,676.00 \$ -	0	\$ -	6581	\$ 1,807,793.00 \$ 625,195.00
80	505	Level 2, 1/2 inch Dense ACP	2,000	CY	\$ 195.00	\$ 390,000.00		\$ 239,265.00	0	\$ -		\$ -	1947	\$ 379,665.00
81	505 505	Extra for Asphalt Approaches	3,652 21,609	SF SF	\$ 10.00 \$ 1.00	\$ 36,520.00 \$ 21,609.00	1500 5843	\$ 15,000.00 \$ 5,843.00	0	\$ - \$ -		\$ - \$ -	3624 9355	\$ 36,240.00 \$ 9,355.00
83	505	Extra for Asphalt Parking Lot Extra for Permanent Trench	3,565	SF	\$ 1.00	\$ 21,609.00		\$ 5,843.00	0	\$ - \$ -		\$ - \$ -		\$ 33,580.00
		Repair												
84	505	Extra for Asphalt Drainage Curb	145	LF	\$ 35.00	\$ 5,075.00		\$ 5,075.00	0	<u> </u>		<u> </u>		\$ 5,075.00
85 86	505 507	Extra for Stamping River Rock	1,290	SF LF	\$ 15.00 \$ 16.00	\$ 19,350.00 \$ 16,192.00		\$ 3,750.00 \$ 3,696.00	660	\$ 9,900.00		\$ - \$ -	1290 1125	\$ 19,350.00 \$ 18,000.00
87	507	Concrete Curbs, Mountable Concrete Curbs, Type C	1,738	LF	\$ 16.00 \$ 19.00	\$ 33,022.00	231 275	\$ 5,225.00	0	\$ -		\$ -	1741	\$ 33,079.00
88	507	Concrete Curbs, Standard Curb and Gutter	3,740	LF	\$ 21.00	\$ 78,540.00	902	\$ 18,942.00	9	\$ 189.00	0	\$ -	3740	\$ 78,540.00
89	507	Concrete Driveways & Approaches - Commercial	3,047	SF	\$ 16.00	\$ 48,752.00	950	\$ 15,200.00	0	\$ -	0	\$ -	3111	\$ 49,776.00
90	507	Concrete Driveways &	5,279	SF	\$ 15.00	\$ 79,185.00	455	\$ 6,825.00	117	\$ 1,755.00	0	\$ -	5279	\$ 79,185.00
91	507	Approaches - Residential Concrete Walks	21,672	SF	\$ 6.00	\$ 130,032.00	6200	\$ 37,200.00	725	\$ 4,350.00		\$ -	21535	\$ 129,210.00
92	507	Thickened Walk	6,964	SF	\$ 7.00	\$ 48,748.00	4600	\$ 32,200.00	76	\$ 532.00		\$ -	6964	\$ 48,748.00
93	507	Extra for New Sidewalk Ramps Truncated Domes on New	32	EA	\$ 1,200.00	\$ 38,400.00	19	\$ 22,800.00	1	\$ 1,200.00		\$ -		\$ 38,400.00
94	507	Surfaces On New	48	EA	\$ 400.00	\$ 19,200.00	34	\$ 13,600.00	2	\$ 800.00	0	\$ -	48	\$ 19,200.00
95	509	Cold Plane Pavement Removal	1,689	SY	\$ 5.00	\$ 8,445.00	787	\$ 3,935.00	0	\$ -		\$ -		\$ 13,170.00
96 97	510 511	Adjusting Boxes Pavement Markings	13 1	EA LS	\$ 425.00 \$ 57,000.00	\$ 5,525.00 \$ 57,000.00	7 0.65	\$ 2,975.00 \$ 37,050.00	0.35	\$ - \$ 19,950.00		\$ - \$ -	13 1	\$ 5,525.00 \$ 57,000.00
98	511	Traffic Signing	1	LS	\$ 15,000.00	\$ 15,000.00	0.5	\$ 7,500.00	0	\$ -		\$ -		\$ 15,000.00
99	512	Light Pole Bases & Ground Rods	1	LS	\$ 14,500.00	\$ 14,500.00	0.1	\$ 1,450.00	0	\$ -	0	\$ -	1	\$ 14,500.00
100	513	Traffic Signal Modification, RRFB	1	LS	\$ 75,000.00	\$ 75,000.00	0	\$ -	0.5	\$ 37,500.00	0	\$ -	1	\$ 75,000.00
101	513	Traffic Signal Modification, Elliott/99W	1	LS	\$ 25,000.00	\$ 25,000.00	0.5	\$ 12,500.00	0.5	\$ 12,500.00	0	\$ -	1	\$ 25,000.00
102	514	Monument Box - Installed	5	EA	\$ 500.00	\$ 2,500.00	0		0	\$ -		\$ -	0	
103	601	6" INCH PVC D3034 Storm	111	FT	\$ 95.00	\$ 1,255,014.00 \$ 10,545.00	0	\$ 64,170.00 \$ -	0	\$ -		\$ -	351	\$ 1,345,904.00 \$ 33,345.00
	601	Sewer Pipe 8" INCH PVC D3034 Storm	104	FT			0			\$ -		\$ -		
104		Sewer Pipe 10 INCH PVC D3034 Storm				, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			0				244	
105	601	Sewer Pipe	418	FT	\$ 140.00	\$ 58,520.00	58	\$ 8,120.00	0	\$ -	0	\$ -	418	\$ 58,520.00
106	601	10 INCH PVC C900 Storm Sewer Pipe	27	FT	\$ 160.00	\$ 4,320.00	0	\$ -	0	\$ -	0	\$ -	27	\$ 4,320.00
107	601	10 INCH DIP Storm Sewer Pipe	16	FT	\$ 215.00	\$ 3,440.00	0	\$ -	0	\$ -	0	\$ -	16	\$ 3,440.00
108	601	12 INCH PVC D3034 Storm Sewer Pipe	1,242	FT	\$ 120.00	\$ 149,040.00	0	\$ -	0	\$ -	0	\$ -	1285	\$ 154,200.00
109	601	15 INCH PVC D3034 Storm	258	FT	\$ 120.00	\$ 30,960.00	0	\$ -	0	\$ -	0	\$ -	252	\$ 30,240.00
110	601	Sewer Pipe 16 INCH DIP Storm Sewer Pipe	134	FT	\$ 215.00	\$ 28,810.00	0	\$ -	0	\$ -	0	\$ -	147	\$ 31,605.00
111	601	24 INCH PVC F679 Storm Sewer	1,201	FT	\$ 275.00	\$ 330,275.00		\$ -	0	\$ -		\$ -		
		Pipe												
112	601	24 INCH DIP Storm Sewer Pipe 48" Shallow Manhole	219	FT EA	\$ 280.00 \$ 4,650.00	\$ 61,320.00 \$ 23,250.00	0	\$ - \$ 4,650.00	0	\$ - \$ -		\$ - \$ -	172	\$ 48,160.00 \$ 23,250.00
114	602	48" Standard Manhole	12	EA	\$ 5,500.00	\$ 66,000.00		\$ -	0	\$ -	0	\$ -		\$ 82,500.00
115 116	602 602	60" Flat Top Manhole 60" Oversized Manhole	3 2	EA EA	\$ 6,850.00 \$ 8,500.00	\$ 20,550.00 \$ 17,000.00	0	\$ - \$ -	0	\$ - \$ -	0	\$ - \$ -	3	
117	602 602	84" Water Quality Manhole	1	EA	\$ 15,000.00	\$ 15,000.00 \$ 25,000.00	0		0	\$ - \$ -		\$ - \$ -	1	,
118 119	602	96" Flow Control Manhole Catch Basin, G2	1	EA EA	\$ 25,000.00 \$ 5,250.00	\$ 25,000.00 \$ 5,250.00	0			\$ -		\$ -	1	
120 121	602 602	Catch Basin, CG2 Standard Inlet Manhole	4 17	EA EA	\$ 8,250.00 \$ 8,650.00	\$ 33,000.00 \$ 147,050.00	0 2	\$ - \$ 17,300.00	0	\$ - \$ -		\$ - \$ -	5 17	\$ 41,250.00 \$ 147,050.00
122	602	Oversized Inlet Manhole	2	EA	\$ 8,750.00	\$ 17,500.00	2	\$ 17,500.00	0	\$ -	0	\$ -	2	\$ 17,500.00
123 124	602 602	Super Sized Inlet Manhole Private Lynch Catch Basin	1	EA EA	\$ 13,750.00 \$ 1,475.00	\$ 13,750.00 \$ 1,475.00		\$ - \$ -	0	\$ - \$ -		\$ - \$ -	0 4	\$ - \$ 5,900.00
125	602	Paved End Slope With Trash Rack	3	EA	\$ 3,500.00	\$ 10,500.00	0	s -	0	\$ -	0	\$ -	3	\$ 10,500.00
126	602	Paved End Slope Without Trash	1	EA	\$ 3,000.00	\$ 3,000.00	0	\$ -	0	\$ -	0	\$ -	0	\$ -
		Rack												
127	603	Construct 60" Flat Top Manhole Over Existing Storm Drain Pipe	1	EA	\$ 8,850.00	\$ 8,850.00	0	\$ -	0	\$ -	0	\$ -	1	\$ 8,850.00
128	603	Construct Catch Basin (CG2)	2	EA	\$ 6,500.00	\$ 13,000.00	1	\$ 6,500.00	0	\$ -	0	\$ -	2	\$ 13,000.00
120	003	Over Existing Storm Drain Pipe	2	LA	\$ 6,500.00	\$ 13,000.00	1	3 6,300.00	U	-	, o	-		3 13,000.00
129	603	Construct Ditch Inlet Basin Over Existing Storm Drain Pipe	1	EA	\$ 4,500.00	\$ 4,500.00	1	\$ 4,500.00	0	\$ -	0	\$ -	1	\$ 4,500.00
130	603	Construct Cleanout Over Existing 10" Storm Drain Pipe	3	EA	\$ 2,500.00	\$ 7,500.00	2	\$ 5,000.00	0	\$ -	0	\$ -	3	\$ 7,500.00
131	603	Construct Cleanout Over	3	EA	\$ 1,500.00	\$ 4,500.00	0	\$ -	0	\$ -	0	\$ -	4	\$ 6,000.00
132	603	Existing 6" Storm Drain Pipe Connect Existing Storm Drain	9	EA	\$ 750.00	\$ 6,750.00			0	\$ -		\$ -	9	
		Service Install 6" Single Check on												
133	603	Existing Storm Drain Pipe	2	EA	\$ 1,150.00	\$ 2,300.00				\$ -		\$ -	2	
134	603	Connect to Existing 48" Manhole	1	EA	\$ 650.00	\$ 650.00	0	\$ -	0	\$ -	0	\$ -	3	\$ 1,950.00
135	603	Abandon Existing Storm Drain Pipe	565	FT	\$ 70.00	\$ 39,550.00	0	\$ -	0	\$ -	0	\$ -	565	\$ 39,550.00
136	603	Abandon Existing Storm Drain Pipe - Grout Full with lean	125	FT	\$ 45.00	\$ 5,625.00	0	\$ -	0	\$ -	0	\$ -	125	\$ 5,625.00
	303	concrete			, 45.00	, 3,023.00						·	123	, 3,023.00
137	603	Adjust (Minor) Existing Storm Drain Manhole	1	EA	\$ 650.00	\$ 650.00	0	\$ -	0	\$ -	0	\$ -	1	\$ 650.00
138	603	Adjust (Minor) Existing Storm Drain Inlet	1	EA	\$ 600.00	\$ 600.00	1		0			\$ -	1	
139	SP1012	Water Quality Swale	1	LS	\$ 75,000.00	\$ 75,000.00	0	\$ -	0	\$ -	0	\$ -	1	\$ 75,000.00





Newhero Bid Date: 5/26/22 7 Pages of Progress Detail

Nev	vberg				Bid Date: 5/26/22							/ Pages 0	f Progress Detail
					ELLIOTT	ROAD IMPROVEME							
	Р	ROGRESS PAYMENT DETA	IL		The Saunde	ers Company, Inc.	Progress Re for work thr		rogress Request 18 r work thru Oct 2023		gress Request 19 ork thru Nov 2023	PROGRE	SS REQUESTS TOTAL
Item No.	Spec Sect.	Bid Item	Bid Quan.	Unit	Unit Bid Price	Bid Item Amount	Sep'23 Quantity	em Amount Oct'2 Quant		Nov'23 Quantity	Item Amount	Total Quantity	Item Total
1.09		Saunders performed additional potholing from 8/3/22 to 8/26/22 for areas that they have encountered utility conflicts during construction. The additional potholing revealed information that has helped the City and the design consultants to provide revised alignments or allow adjustments to resolve conflicts identified during construction (See COR-009R1).	1	LS	\$ 20,720.00	\$ 20,720.00	0 \$	-	0 S -	o	\$ -	1	\$ 20,720.00
1.10		Saunders encountered PGE conflicts with the proposed storm lines at several locations of the project: (1) the pond exit of the stormwater management facility; (2) the E Norwood Court intersection area; and (3) at the 710 and 720 N Elliott Road area in October 2022. Contractor provided documentation for the additional costs (See COR-012) .	1 CHANGE ORD	LS ER NO. 1 =	\$ 23,389.00	\$ 23,389.00	0 \$		0 \$ -	0	s -	1	\$ 23,389.00
ChO Item No.	Spec Sect.	Change Order Item	ChO Quan.	Unit	Unit ChO Price	ChO Item Amount	Sep'23 Quantity	em Amount Oct'2 Quant		Nov'23 Quantity	Item Amount	Total Quantity	Item Total
AUTHORIZ	ZED CHANGE	ORDERS (above and beyond the o	riginal contrac	t)									
2.01		Saunders performed additional potholing on the following days in September 2022 for areas that they had encountered utility conflicts in construction: 9/1/22 Private storm line by pond—53113 9/9/22 Ziply—53533 9/12/22 Ziply—53533 9/12/22 Ziply—53533 9/12/29 Ziply—65092 9/21 Ziply—65092 9/21 Ziply—65092 9/21 Ziply—65092 9/21 Ziply—63513 The additional potholing was necessary because City's contractor encountered unknown or unmarked utilities during excavation, and often did not find utilities at locations marked by utility locating companies. City, with contractor, brought these very poor locate problems to franchies utilities in an attempt to resolve the conflicts identified during construction (See COR-010).	1	ts	\$ 25,511.00	\$ 25,511.00	0 \$	-	0 \$ -	0	s -	1	\$ 25,511.00
2.02		Saunders encountered private water conflict with the proposed 24" storm line at 710 and 720 N Elliott Road (the 4-plexes). The work required the hiring of a plumbing subcontractor to perform the work with Saunders construction crew in October 2022. (See COR-011).	1	LS ER NO. 2 =	\$ 10,453.00	\$ 10,453.00 \$ 35,964.00	0 \$		0 \$ -	0	\$ -	1	\$ 10,453.00
3.01	<spec></spec>	Saunders performed additional potholing on the following days in October 2022 for areas that they had encountered utility conflicts in construction: 10/6/22 [pip-98,990.01; NW Natural\$2,247.50 10/17/22 Piphy-\$5,62.01; NW Natural\$2,3102.45 10/14/22 Ziphy-\$5,62.01; NW Natural-\$1,375.34 10/24/22 NW Natural-\$7,182.72 10/25/22 Ziphy-\$1,207.29; PGE-\$1,207.29; Water-\$1,207.29 The additional potholing was necessary because City's contractor encountered unknown or unmarked utilities during excavation, or did not find utilities at locations marked by utility locating companies (See COR-013).	1	LS	\$ 44,420.00		0 \$		0 \$ -		\$ -	1	\$ 44,420.00





**Nev	vberg	•			FLUOTT	POAD IMPROVES	ENIT PRO	ECT						i Flogress Detail
		PROGRESS PAYMENT DETA				ROAD IMPROVEMI	Prog	ress Request 17		gress Request 18		gress Request 19	PROCE	ESS REQUESTS TOTAL
				I			for w	ork thru Sep 2023	for v	vork thru Oct 2023	for w	ork thru Nov 2023	Total	
Item No.	Spec Sect.	Bid Item	Bid Quan.	Unit	Unit Bid Price	Bid Item Amount	Quantity	Item Amount	Quantity	Item Amount	Quantity	Item Amount	Quantity	Item Total
3.02	<spec></spec>	Saunders performed additional potholing on the following days in November 2022 for areas that they had encountered utility conflicts in construction: 11/23/22 Ziphy-51,104.33; NW Natural-51,104.33; PGE-51,104.33; PGE-53,796.26; NW Natural-51,898.13; PGE-53,796.26 11/29/22 Ziphy-54,884.83; PGE-54,884.83 The additional potholing was necessary because City's contractor encountered unknown or unmarked utilities during excavation, or did not find utilities at locations marked by utility locating companies. City, and contractor, brought these very poor locate problems to franchise utilities in an attempt to resolve the conflicts identified during construction (See COR-015).	1	LS	\$ 22,585.00	\$ 22,585.00	o	\$ -	o	\$ -	o	\$ -	1	\$ 22,585.00
3.03	<spec></spec>	Saunders performed additional potholing on the following days in December 2022 for areas that they had encountered utility conflicts in construction: 12/1/22 Ziply-51,693.00 12/6/22 Ziply-52,951.00 12/6/22 Ziply-52,951.00 12/6/22 Ziply-52,951.00 12/8/22 Ziply-52,982.38; PGE-54,323.56 12/8/22 Ziply-52,882.38; PGE-54,323.56 12/9/22 Ziply-52,366.74; NW Natural-5946.69; PGE-51,420.04 12/14/22 Ziply-51,503.00 The additional potholing was necessary because City's contractor encountered unknown or unmarked utilities during excavation, or did not find utilities at locations marked by utility locating companies (See COR-019)	1	LS	\$ 31,849.00	\$ 31,849.00	0	\$ -	o	\$ -	0	\$ -	1	\$ 31,849.00
3.04	<spec></spec>	Saunders performed additional potholing on the following days in January 2023 for areas that they had encountered utility conflicts in construction: 1/11/23 Ziply-52,175.00 1/12/32 Ziply-52,175.00 1/12/32 Ziply-52,275.00 1/12/32 Ziply-52,473.00 1/12/32 Ziply-52,473.00 1/12/32 Ziply-52,693.00 1/23/23 Ziply-52,693.00 1/23/23 Ziply-52,693.00 The additional potholing was necessary because City's contractor encountered unknown or unmarked utilities during excavation, or did not find utilities at locations marked by utility locating companies. City, and contractor, brought these very poor locate problems to franchise utilities in an attempt to resolve the conflicts identified during construction (See COR-020).	1	LS	\$ 20,146.00	\$ 20,146.00	0	\$ -	o	\$ -	0	ş -	1	\$ 20,146.00
3.05	<spec></spec>	Saunders installed concrete retaining wall blocks in two layers behind the new sidewalk at 1202, 1204, 1206 and 1210 N Elliott Road for supporting the compacted crushed rock without 31 slope to existing front yard. The work would be compensated according to the unit cost proposal received on 1/12/23 (Reference COR-017).	600	SF	\$ 46.75	\$ 28,050.00	0	s -	0	S -	0	\$ -	600	\$ 28,050.00
3.06	<spec></spec>	Saunders relocated a catch basin at the SW corner of the church parking near the Elliott-Haworth intersection and adjusted the downstream pipe for positive drainage. Compensation would be at a lump sum cost of \$3,774.00 (Reference COR-018).	1	LS	\$ 3,774.00	\$ 3,774.00	0	\$ -	0	s -	0	s -	1	\$ 3,774.00

Bid Date: 5/26/22







~Newberg 3													r Progress Detail	
					ELLIOTT	ROAD IMPROVEMI								
	Р	ROGRESS PAYMENT DETA	IL		The Saunde	rs Company, Inc.		gress Request 17 ork thru Sep 2023		gress Request 18 vork thru Oct 2023	Pro for w	gress Request 19 ork thru Nov 2023	PROGRE	ESS REQUESTS TOTAL
Item No.	Spec Sect.	Bid Item	Bid Quan.	Unit	Unit Bid Price	Bid Item Amount	Sep'23 Quantity	Item Amount	Oct'23 Quantity	Item Amount	Nov'23 Quantity	Item Amount	Total Quantity	Item Total
3.07		Saunders relocated the proposed 24" storm line between MH8 and MH9A out of the sidewalk area into E Haworth Avenue. Compensation would be at a lump sum cost of \$32,354.00 (Reference COR-016).	1	LS	\$ 32,354.00	\$ 32,354.00		\$ -	0	\$ -	0	s -	1	\$ 32,354.00
		SUBTOTAL OF	CHANGE ORD	ER NO. 3 =		\$ 183,178.00		\$ -		\$ -		\$ -		\$ 183,178.00
4.01	≪spe⇔	Saunders performed additional potholing on the following days in February 2023 for areas that they had encountered utility conflicts in construction: 2/2/23 FGE-5795.25; Zpjy-5795.25; Comcast-5795.25; NW Natural-5795.25; Comcast-5795.25; NW Natural-5795.25; NW Natural-5135.25; Comcast-5135.25; NW Natural-5135.25; SW-524.25; Comcast-5135.25; NW Natural-5135.25; NW Natural-524.25; Zpjy-5824.25; Comcast-5917.25; NW Natural-524.25; Zpjy-5271.75; Comcast-5971.75; DW Natural-5917.75; Zpjy-571.75; Comcast-5971.75; NW Natural-5917.75; DW Natural-5917.75; DW Natural-5917.75; Comcast-5971.75; DW Natural-5917.75; DW Natural-5917.75; Comcast-5971.75; NW Natural-5402.50; Zpjy-542.50; Comcast-5402.50; Zpjy-5402.50; Comcast-5402.50; NW Natural-5402.50; NW Natural-5402.50; NW Natural-5402.50; NW Natural-5402.50; NW Natural-5402.50; New Natural-5402.50; NW Natural-5402.5	1	LS	\$ 15,647.00	\$ 15,647.00	0	ş -	0	\$ -	o	\$ -	1	\$ 15,647.00
4.02	<spec></spec>	Saunders installed utility vaults supplied by Ziply Fiber and Comcast for undergrounding franchise utilities (See COR-022).	17	EA	\$ 1,342.00			\$ -	0	s -	0	s -	17	\$ 22,814.00
		SUBTOTAL OF	CHANGE ORD	EK NO. 4 =		\$ 38,461.00		\$ -		\$ -		\$ -		\$ 38,461.00
5.01	<spec></spec>	Saunders to relocate driveway for 1302 N Elliott due to steep grade (See COR-023).	1	LS	\$ 3,842.00	\$ 3,842.00	0	\$ -	0	\$ -	0	\$ -	1	\$ 3,842.00
5.02		Saunders to switch to cantilever gate at Newberg High School (See COR-024).	1	LS	\$ 3,693.00	\$ 3,693.00	0	\$ -	0	\$ -	0	\$ -	1	\$ 3,693.00
5.03	<spec></spec>	Saunders to install additional fittings at water tie-in locations (See COR-025).	1	LS	\$ 5,180.00	\$ 5,180.00	0	\$ -	0	\$ -	0	\$ -	1	\$ 5,180.00
5.04	<spec></spec>	Saunders to provide excavation support for NW Natural gas line relocation around PGE vault (See COR-026).	1	LS	\$ 11,162.00	\$ 11,162.00	0	\$ -	0	\$ -	o	s -	1	\$ 11,162.00
5.05	<spec></spec>	Saunders to install sewer cleanouts around transite pipe (See COR-027).	1	LS	\$ 14,242.00	\$ 14,242.00	0	\$ -	0	\$ -	0	\$ -	1	\$ 14,242.00
5.06	≪эре⇔	Saunders performed add'l potholing in March 2023 for areas with utility conflicts: 3/1 PGE-51,865.07 jply-\$1,846.50; 3/2 PGE-\$1,094.00; 2/1ply-\$1,846.50; 3/2 PGE-\$1,094.00; 3/3 PGE-\$932.75; 10/9-932.7	1	LS S	\$ 37,828.00	\$ 37,828.00		\$ -	0	\$ -	0	\$ -	1	\$ 37,828.00
						,								
6.01	<spec></spec>	Saunders performed additional potholing on the following days in April 2023 for areas that they had encountered utility conflicts in construction: 4/4/23 PGE/Ziply—\$1,156.00 4/7/23 Comcast/Ziply—\$2,504.00 4/17/32 Gcmcast-21,727.00 The additional potholing was necessary (See COR-029).	1	LS	\$ 6,592.00	\$ 6,592.00	0	\$ -	0	ş -	o	\$ -	1	\$ 6,592.00
		SUBTUTAL UP	AITGE URD	_A 140. 0 =		0,552.00		•		-		·		0,352.00



*Newberg

					ELLIOTT	ROAD IMPROVEME	NT PROJ	IECT							
	P	PROGRESS PAYMENT DETA	IL		The Saunde	rs Company, Inc.		gress Request 17 ork thru Sep 2023		gress Request 18 ork thru Oct 2023		gress Request 19 ork thru Nov 2023			
Item No.	Spec Sect.	Bid Item	Bid Quan.	Unit	Unit Bid Price	Bid Item Amount	Sep'23 Quantity	Item Amount	Oct'23 Quantity	Item Amount	Nov'23 Quantity	Item Amount	Total Quantity	Item Total	
7.01	<spec></spec>	Saunders to provide colored concrete at stamped concrete areas (See COR-031).	1	LS	\$ 1,800.00	\$ 1,800.00	0	s -	0	\$ -	0	\$ -	1	\$ 1,800.00	
7.02	<spec></spec>	Saunders to provide 6 CROSSWALK CLOSED signs and 4 STOP signs (See COR-032).	1	LS	\$ 921.00	\$ 921.00	0	s -	0	ş -	0	\$ -	1	\$ 921.00	
		SUBTOTAL OF	CHANGE ORD	ER NO. 7 =		\$ 2,721.00		\$ -		\$ -		\$ -		\$ 2,721.00	
8.01	<spec></spec>	Provide additional support for PGE tie-ins (or utility conflict modifications) (See COR-030).	1	LS	\$ 98,011.00	\$ 98,011.00	1	\$ 98,011.00	0	\$ -	0	\$ -	1	\$ 98,011.00	
		SUBTOTAL OF	CHANGE ORD	ER NO. 8 =		\$ 98,011.00		\$ 98,011.00		\$ -		\$ -		\$ 98,011.00	
9.01	<spec></spec>	Provide concrete block retaining wall and irrigation replacement at 2409 E Haworth Avenue (See COR-035).	1	LS	\$ 18,525.00	\$ 18,525.00	0	\$ -	1	\$ 18,525.00	0	\$ -	1	\$ 18,525.00	
9.02	<spec></spec>	Provide additional asphalt and concrete work due to Ziply's delay (See COR-033 and COR-	1	LS	\$ 6,633.00	\$ 6,633.00	0	s -	1	\$ 6,633.00	0	\$ -	1	\$ 6,633.00	
9.03	<spec></spec>	Provide major adjustment for sewer manhole between 2500 E Norwood and 803 Elliott (See COR-040).	1	LS	\$ 6,165.00	\$ 6,165.00	0	s -	1	\$ 6,165.00	0	\$ -	1	\$ 6,165.00	
9.04	<spec></spec>	Trim the incense cedar and the English walnut (See COR-041).	1	LS	\$ 2,369.00	\$ 2,369.00	0	\$ -	1	\$ 2,369.00	0	\$ -	1	\$ 2,369.00	
		SUBTOTAL OF	CHANGE ORD	ER NO. 9 =		\$ 33,692.00		\$ -		\$ 33,692.00	1	\$ -		\$ 33,692.00	
TOTAL OF ALL CHANGE ORDER ITEMS = (Div 1 provides \$150K for field changes - authorization required)					\$ 624,308.00		\$ 98,011.00		\$ 33,692.00		\$ -		\$ 613,193.00		
		ITEMS = 848M orig contract incl \$150K	for field cha	nges		\$ 6,322,308.00		\$ 695,781.00		\$ 247,294.00		\$ 25,200.00		\$ 6,986,734.00	
RETAI	NAGE (5	%) =						\$ 34,789.05		\$ 12,364.70		\$ 1,260.00		\$ 349,336.70	
PAYM	ENT AFT			\$ 660,991.95		\$ 234,929.30		\$ 23,940.00		\$ 6,637,397.30					

☐ Finance file

7 Pages of Progress Detail