



Oregon

Kate Brown, Governor

Department of Environmental Quality

Northwest Region

700 NE Multnomah Street, Suite 600

Portland, OR 97232

(503) 229-5263

FAX (503) 229-6945

TTY 711

December 6, 2020

sent via email

Deborah Taege
The Boeing Company
EHS Remediation
Bldg. 10-20, MC 9U4-26
800 N 6th Street
Renton, WA 98055-1409

**RE: Work Plan: Shallow Subsurface Investigation,
Building 85-001 Former Vapor Degreaser Source Area
Boeing Portland. Gresham, Oregon. ECSI #13**

Dear Ms. Taege:

The Oregon Department of Environmental Quality (DEQ) has reviewed the document entitled *Work Plan: Shallow Subsurface Investigation, Building 85-001 Former Vapor Degreaser Source Area for the Boeing Portland Facility*, dated November 20, 2020. This work plan was prepared on your behalf by Landau Associates.

DEQ approves the *Work Plan* as presented and thanks you for your continued proactive remediation work at the Boeing Portland Facility. Please keep DEQ informed if there are changes from the late December 2020 implementation schedule.

Please feel free to call me with questions.

Sincerely,

Kenneth Thiessen, CEG
Northwest Region Cleanup Section

cc: Evelyn Ives, PE, Landau Associates
Erin Waibel, RG, Landau Associates
ECSI #13

