


Imerys Lakeview Process Flow Diagram



LEGEND TEUs

Point Emission Source

RDO – Rotary Dryer

Point Sources/PCDs

Pollution Control Devices

NEW – New Baghouse

MAIN – Main Baghouse

RDB – Dryer Baghouse

Fugitive Emission Sources

Fugitives

ASMH/ASWE – Active Raw Ore Stockpile –

Material Handling and Wind Erosion

ISMH/ISWE – Inactive Raw Ore Stockpile –

Material Handling and Wind Erosion

WELD – Welding from Maintenance Building

MA1-6 – Maintenance Activity Fugitives

DP1 – DP6 --Drop Point Fugitives

ROAD – Unpaved Road Fugitives

SCALP – Primary Scalper Fugitives

TANK 1&2 – Oil Storage Tanks Fugitives

MAIN-U – Uncontrolled Emissions from areas

controlled by Main Baghouse.

NEW-U – Uncontrolled Emissions from areas

controlled by New Baghouse