

A RESOLUTION DETERMING THAT CERTAIN
SIDEWALKS WITHIN THE CITY OF LEBANON
ARE UNSAFE AND PROVIDING FOR NOTICE TO
BE GIVEN TO THE ABUTTING PROPERTY OWNERS.

)
) RESOLUTION NO. 17
)
) for 1957.

BE IT RESOLVED BY THE COMMON COUNCIL OF THE CITY OF LEBANON:

That the following sidewalks are deemed to be unsafe:


OWNER	WALK REPAIR FT.	TOTAL FOOTAGE
1. Ralph K. Watts 408 Tenth St. Ferris 618 Broad St. Warrensburg, Missouri 237 Hiatt Street	20 ft. on Hiatt	20
2. Walter Janke 412 East Ash St. Lebanon, Oregon	10 ft. on Hiatt	10
3. Durwood Smith 417 Mayer Drive Lebanon, Oregon	10 ft. on Hiatt	10
4. Raymond Hoy 960 Hiatt Street Lebanon, Oregon	20 ft. on Hiatt	20
5. William J. Kietzke 989 Williams St. Lebanon, Oregon	10 ft. on Williams	10
6. Robert Wiper 980 Williams Street Lebanon, Oregon	5 ft. on Williams	5
7. Blewford Osburn 521 Williams St. Lebanon, Oregon	10 ft. on Williams	10
8. Martin J. Hainz 310 Grove Street Lebanon, Oregon	about 2 sq. ft. repair hole in walk	2
9. John A. Baker 101 Williams St. Lebanon, Oregon	25 ft. on Williams	25
10. L. Boots (190 East Ash St.) 535 Grove Street Lebanon, Oregon	5 ft. (tree stump)	5
11. Mrs. John Thoma 208 Park Street Lebanon, Oregon	10 ft. on Carolina	10
12. Mrs. M. C. Manela 131 E. Carolina St. Lebanon, Oregon	12 ft. (tree stump)	12
13. City of Lebanon North end of Park St.	60 ft.	60
14. Otto Ohm 960 5th Street Lebanon, Oregon	Lot on Carolina & Park Street 60 ft.	60
15. Ben Lentz 175 East Carolina Lebanon, Oregon	5 ft.	5
16. Mrs. Josephine Gross Second Street Lebanon, Oregon Property at 55 E. Carolina	10 ft. E. Carolina	10

OWNER (Cont'd)	WALK REPAIR FT.	TOTAL FOOTAGE
17. City of Lebanon between Main & Grove	Alley on Isabella	12
18. Chet McMain 290 Hiatt Street Lebanon, Oregon	12 ft. on Isabella Street	12
19. George Surry 357 East Rose Lebanon, Oregon	2 ft. repair (raise in sidewalk)	2
20. Roy Gunderson 380 Williams St. Lebanon, Oregon	15 ft. in driveway	15
21. City of Lebanon	Alley between Grove & Williams	12
22. Ross O'Brien 389 Grove Street Lebanon, Oregon	35 ft. on Rose St. side	35
23. City of Lebanon	South East corner Intersection	15
24. Lebanon Independent Full Gospel Church 159 East Vine St. Lebanon, Oregon	25 ft. East Vine	25
25. Claude Cox 165 E. Vine St. Lebanon, Oregon	40 ft. repair	40
26. City of Lebanon	Alley between Grove & Park	12
27. W. A. Pollard 192 E. Vine St. Lebanon, Oregon	40 ft. repair	40
28. City of Lebanon	Alley between Williams & Grove	12
29. Charles E. Little 347 East Vine Lebanon, Oregon	40 ft. repair	40
30. Warren Walker 444 E. Vine St. Lebanon, Oregon	40 ft. Repair	40
31. Russell Slocum 472 E. Vine Street Lebanon, Oregon	15 ft. repair	15
32. Dr. J. L. Gross 480 E. Vine Street Lebanon, Oregon	5 ft. repair	5
33. E. R. Liggett Rt. 2, Box 143 Lebanon, Oregon	2 ft. (driveway) Corner Grant & Cleveland	2
34. J. L. Durst 643 East Grant Lebanon, Oregon	5 ft.	5

OWNER (Cont'd)	WALK REPAIR FT.	TOTAL FOOTAGE
35. David George 666 East Grant Lebanon, Oregon	25 ft.	25
36. Dave Copland 255 Elmore St. Lebanon, Oregon	25 ft. repair	25
37. H. O. Van Loovan 445 W. Grant Lebanon, Oregon	5 ft. repair	5
38. Ronald Cox 786 5th Street Lebanon, Oregon	35 ft. repair	35
39. <i>Jess</i> Moss 429 West Sherman Lebanon, Oregon	About 75 ft. walk must be replaced	
40. Ray D. McCall 310 West Grant St. Lebanon, Oregon	10 ft. repair	10
41. Claude Bowman 480 Vine Street Lebanon, Oregon	10 ft. Repair on 348 West Grant St.	10
42. Jennie V. Zemlicka 492 West Grant St. Lebanon, Oregon	15 ft. repair	15
43. John Simi 491 W. Grant St. Lebanon, Oregon	15 ft. repair	15
44. Norm Duncan Stevenson, Washington	5 ft. repair on 570 West Grant property	5

and the Street Superintendent is hereby directed to give written notice to the abutting property owners and/or the person in charge of the abutting premises to restore the above described walks to a safe condition within 72 hours.

Passed by the Council and approved by the Mayor on the 2nd day of April, 1957.



Mayor

ATTEST:



City Recorder