

## DECK Ginny \* DEQ

---

**From:** Kyle Fisher <kyle@pointsourcesolutions.com>  
**Sent:** Friday, July 16, 2021 12:38 PM  
**To:** DECK Ginny \* DEQ  
**Cc:** Andy Klopfenstein  
**Subject:** Re: OLPRR Incident Report in Accepted Status. Log Number: 15-21-0678, RB BROWNS TRUCKING INC

**Follow Up Flag:** Follow up  
**Flag Status:** Flagged

Hello Ginny,

The tank we discovered is in all likelihood the 10K tank that was filled in place in 1988.

Our mailing address is:  
10445 SW Canyon Rd  
Suite 266  
Beaverton, Oregon 97005

Thank you!

On Fri, Jul 16, 2021 at 12:08 PM DECK Ginny \* DEQ <[ginny.deck@deq.state.or.us](mailto:ginny.deck@deq.state.or.us)> wrote:  
Hello Kyle.

Your on-line tank data submittal has been reviewed and accepted by the State of Oregon DEQ.  
New LUST Incident Log Number: 15-21-0678  
New LUST Site Name: RB BROWNS TRUCKING INC

Please reference the Log number and Site Name in your reports and correspondence to DEQ.

Although you reported this as an Unregulated site, I am changing it to Regulated. I assume the tank you discovered is the 10K tank that was filled in place in 1988, and not an additional tank. Is that correct?

Finally, please provide me with your mailing address at Point Source Solutions.

Sincerely,

Ginny Deck  
DEQ Western Region Cleanup Program  
4026 Fairview Industrial Dr SE  
Salem, OR 97302  
503-378-8240 ext. 85046

Reported by: KYLE FISHER  
Company Name: POINT SOURCE SOLUTIONS  
Phone Number: (503) 860-8811

Site Name: RB BROWNS TRUCKING INC  
Site Address: 5758 Crater Lake Avenue  
Site County: JACKSON  
Site City: CENTRAL POINT  
Site Zip Code: 97502  
Site Phone: (541) 826-7420  
Comments: POINT SOURCE

SOLUTIONS; [KYLE@POINTSOURCESOLUTIONS.COM](mailto:KYLE@POINTSOURCESOLUTIONS.COM); DISCOVERED SUSPECTED 10,000 GAL UST DURING GEOPHYSICAL & PHASE II SITE ASSESSMENT. CONSISTENT DRILLING REFUSAL AT 9 FT PREVENTED PROBE FROM ADVANCING BELOW TANK BOTTOM, ESTIMATED AT 11.5 FT. WEST TANK END SAMPLE AT 9 FT. RETURNED DX RESULTS AT 1060 MG/KG AND GX RESULTS AT 71.3 MG/KG; SOUTH TANK END SAMPLE AT 4 FT. RETURNED DX AT 115 MG/KG AND GX AT 16.8 MG/KG. UST IS FULL OF WHAT APPEARS TO BE DIESEL CONTAMINATED SAND AND WATER.

Date Received: 6/25/2021  
Release Type: Regulated  
Facility ID: 7869

---

RESPONSIBLE PARTY INFORMATION

First Name: TJ  
Last Name: Davis  
Organization: RB Browns Trucking Inc  
City: Central Point  
Phone: 541-826-0171  
Address: 5758 Crater Lake Avenue  
State: OR  
Zip: 97502  
Email: [tjdavis@rbbrowns.com](mailto:tjdavis@rbbrowns.com)

INVOICE CONTACT INFORMATION

First Name: TJ  
Last Name: Davis  
Organization: RB Browns Trucking Inc  
City: Central Point  
Phone: 541-826-0171  
Address: 5758 Crater Lake Avenue  
State: OR  
Zip: 97502  
Email: [tjdavis@rbbrowns.com](mailto:tjdavis@rbbrowns.com)

---

Confirmation: Contractor  
Discovery: SiteAssessment Cause: Unknown

MEDIA TYPE

CONTAMINANT TYPE

Soil

Diesel (Motor Fuel)  
Misc. Gasoline

---

--

Kyle Fisher

Environmental Technician

Point Source Solutions

Mobile: (503) 860-8811

<https://www.pointsourcesolutions.com/>