



TL-F-6

Broken line with  
PVC pipe placed  
over main.

Significant belly  
and elevation  
change.

Approximate length  
of repair 87' - 90'

TL-F-9