



1. The Subject Property and Neighboring Properties - view to the east, note the backfilled pipe trench.



4. The Subject Property and Neighboring Properties – view to the southeast, canopy and former dispenser island.



2. The Subject Property and Neighboring Properties – view to the west, truck parked on former UST pit.



5. The Subject Property – view to the north-northeast.



3. The Subject Property and Neighboring Property – view to the south across Rogue River Drive.



6. The Subject Property – former garage shop interior, above-ground hoist.



7. The Subject Property – former garage shop interior, above ground hoist and AST, presumably waste oil.



10. The Subject Property – view to the northwest, immediately prior to UST decommissioning.



8. The Subject Property and Neighboring Properties – view to the west.



11. The Subject Property – view to the northwest, immediately prior to UST decommissioning.



9. The Subject Property and Neighboring Properties – view to the south.



12. The Subject Property and Neighboring Properties – Decommissioning by removal.



13. The Subject Property – Decommissioning by removal.



16. The Subject Property – Piping Trench.



14. The Subject Property – Decommissioning by removal.



17. The Subject Property – Close up of puncture in the number 3 gasoline UST, likely associated with installation of a new pump that was immediately followed by a water alarm.



15. The Subject Property – Backfill and compaction.