



Sample Receipt Checklist
COC Seal Present/Intact: ☒ Y ☐ N If Applicable
COC Signed/Accurate: ☒ Y ☐ N VOA Zero Headspace: ☒ Y ☐ N
Bottles arrive intact: ☒ Y ☐ N Pres. Correct/Check: ☒ Y ☐ N
Correct bottles used: ☒ Y ☐ N
Sufficient volume sent: ☒ Y ☐ N
RAD Screen <0.5 mR/hr: ☒ Y ☐ N

PROJECT INFORMATION

Turnaround:

Same Day

Next Day

35 day

L1427021

Company/Customer: Cascade Environmental	Project Name: Carol Glover BP, Yamhill, OR
Address: 4346 NE 73 rd Avenue	Collection Date: 11-2-21
Address: Portland, Or 97218	Customer Number/P.O.: DEQ 71-1829
Phone: 503.984.9737	Collection Address: 185 S. Maple St Yamhill, OR
Customer Contact: Bob Burns	Email: bob@cascadenviro.com

Special Instructions: PLM (EPA 600/R-93/116, Please composite all Wallboard/Joint Compound samples)

Results to Bob Burns

(Sample #s)

Bill DEQ Dan Hanson dan.hanson@DEP.state.or.us
541.687.7349

BULK SAMPLE LOCATION

Page 1 of 3

Acc/Rej	Sample Number	Sample Material	Sample Location	Friable ?	App. Qty.	
	GCA-01	Wall board/joint compound	Kitchen	No	71800 Si	-01
	-02	↓	Dining		11	-02
	-03	Spray on wall texture	Lobby		71800 Si	-03
	-04	↓	Prep Area		11	-04
	-05	↓	Dining Area		11	-05
	-06	Drop-in Ceiling Tile > 2'x3', Fiberglass	Lobby		850 Si	-06
	-07	↓	Dining Area		11	-07
	-08	12" x 12" ceramic tile, pink, Gray Quick Set, white grout	Kitchen	No	405 Si	-08
	-09	3" vinyl core base white, & Tan mastek	Kitchen	No	204 Si	-09
	✓ 10	Sink under coating, black	Kitchen, south sink	No	65 Si	-10

Note: Sample collector is responsible for ensuring that all samples have been preserved and prepared to the appropriate and applicable methodology. If package has sustained damage during transit, notify collector and shipper. Turnaround time begins upon receipt of sample (s) by laboratory. All material was considered in good condition unless otherwise noted.

CHAIN OF CUSTODY

Relinquished By:	Date:	Time:	Received By:	Date:	Time:
K. Burns	11/3/21	1100	John E. Nelson	11/3/21	1100
John E. Nelson	11/3/21	1200	Unborn Sisters	11/4/21	0900

Tracking 5433 8379 2928

G040

PROJECT INFORMATION

Turnaround:

Same Day

Next Day

3-5 day

Company/Customer: Cascade Environmental	Project Name: Carol Glover SP
Address: 4346 NE 73 rd Avenue	Collection Date:
Address: Portland, Or 97218	Customer Number/P.O.:
Phone: 503.984.9737	Collection Address:
Customer Contact: Bob Burns	Email: bob@cascadenviro.com

Special Instructions: PLM (EPA 600/R-93/116, Please composite all Wallboard/Joint Compound samples

(Sample #s)

BULK SAMPLE LOCATION

Page 2 of 3

Acc/Rej	Sample Number	Sample Material	Sample Location	Friable ?	App. Qty.
	GCA-11	Linoleum, Tan Fox Marble	Kitchen Counter	NO	155F-11
	-12	12" x 12" vinyl Floor tile, Tan Fox Marble & Tan mastic	Restroom	NO	425F-12
	-13	3" vinyl core base Tan & Tan mastic	Lobby	NO	552F-13
	-14	Carpet mastic, Tan under Blue Carpet	Dining Area	NO	4005F-14
	-15	3" x 3" Ceramic Tile, white, white quick set & white Grout	Kitchen (Accent tile)	NO	202F-15
	-16	Tar Paper under wood shingle	Exterior	NO	700 ₅ F-16
	17	Composite Roofing, Rolled & 1/4" Gray Ice Paper	Roof	NO	1,000 ₅ F-17
	18	Composite Roofing, Rolled, Patch, Brown and black patching	Roof	NO	NO SF-18
	19	Roof Patch on metal	Awnings	NO	104F-19
	20				

Note: Sample collector is responsible for ensuring that all samples have been preserved and prepared to the appropriate and applicable methodology. If package has sustained damage during transit, notify collector and shipper. Turnaround time begins upon receipt of sample (s) by laboratory. All material was considered in good condition unless otherwise noted.

CHAIN OF CUSTODY

Relinquished By:	Date:	Time:	Received By:	Date:	Time:
			Therome Sistrunk	11/4/21	0900



L1427021

PROJECT INFORMATION

Turnaround:

Same Day

Next Day

3-5 day

Company/Customer: Cascade Environmental	Project Name: Carol Glover BP
Address: 4346 NE 73 rd Avenue	Collection Date:
Address: Portland, Or 97218	Customer Number/P.O.:
Phone: 503.984.9737	Collection Address:
Customer Contact: Bob Burns	Email: bob@cascadenviro.com

Special Instructions: PLM (EPA 600/R-93/116, Please composite all Wallboard/Joint Compound samples

(Sample #s)

BULK SAMPLE LOCATION

Page 3 of 3

Acc/ Rej	Sample Number	Sample Material	Sample Location	Friable ?	App. Qty.
	6A-20	Ceiling Texture, knockdown	Kitchen		1/25-20
	21	↓	↓		11 21
	22	↓	↓		11 23

Note: Sample collector is responsible for ensuring that all samples have been preserved and prepared to the appropriate and applicable methodology. If package has sustained damage during transit, notify collector and shipper. Turnaround time begins upon receipt of sample (s) by laboratory. All material was considered in good condition unless otherwise noted.

CHAIN OF CUSTODY

Relinquished By:	Date:	Time:	Received By: <i>Ulronn Sistink</i>	Date:	Time:
				11/4/21	0900