



Professional Laboratory Services

ANALYSIS REPORT

13035 SW Pacific Hwy
Tigard, OR 97223
Tel.: (503) 639-9311 Fax: (503) 684-1588

Reported: 10/19/2022
Received: 10/18/22 11:55
Temp. on Receipt: 10.8 °C
Sampled By: Jeff McCrum
Work Order: 2291014

C
L
I
E
N
T
Molalla, City of
Attn: Ryan Hepler
PO Box 248
Molalla OR, 97038
Phone: (503) 829-5408

Project # : N/A

PWSID # : 4100534

Lab Number

2291014-01 Sampled At: Sample Station Address: 205 W Hauntz St. Sample Type: Routine Sample Matrix: Drinking Water Sampled: 10/18/22 10:25 Res. Cl: 0.87 mg/L

Table with 4 columns: Method, Result, Analysis Begun / Ended. Rows for Microbiological Analysis: A Total Coliforms, A E. coli.

2291014-02 Sampled At: Sample Station Address: 606 Taylor Ct. Sample Type: Routine Sample Matrix: Drinking Water Sampled: 10/18/22 10:00 Res. Cl: 0.80 mg/L

Table with 4 columns: Method, Result, Analysis Begun / Ended. Rows for Microbiological Analysis: A Total Coliforms, A E. coli.

2291014-03 Sampled At: Sample Station Address: 357 Francis St. Sample Type: Routine Sample Matrix: Drinking Water Sampled: 10/18/22 10:12 Res. Cl: 0.75 mg/L

Table with 4 columns: Method, Result, Analysis Begun / Ended. Rows for Microbiological Analysis: A Total Coliforms, A E. coli.

Send results to DHS-DWP P.O. Box 14350, Portland, OR 97293-0350

A = All procedures for this analysis are accredited in accordance with NELAP standards. Lab Accreditation No. OR-100013

Approved by: [Signature] Vandana Gade Microbiology Technical Director