

## DANA Kevin

---

**From:** DANA Kevin  
**Sent:** Monday, October 13, 2014 10:45 AM  
**To:** 'Zachary Goodman'  
**Cc:** DANA Kevin; GAMOLO Gerald  
**Subject:** RE: OLPRR Incident Report in Accepted Status. Log Number: 26-14-1234

There's no fine involved. We just wouldn't be able to issue an NFA for the site knowing that there's an unaddressed leaking tank there. Plus there's the general warning we give that not addressing a release may allow the contamination to spread (especially if it impacts groundwater) and may end up costing more to address later.

-----Original Message-----

**From:** Zachary Goodman [<mailto:zachary@alphaenvironmental.net>]  
**Sent:** Monday, October 13, 2014 10:07 AM  
**To:** DANA Kevin  
**Cc:** GAMOLO Gerald  
**Subject:** RE: OLPRR Incident Report in Accepted Status. Log Number: 26-14-1234

Sounds good. The RP may not pursue cleanup of the diesel tank at this time; is there any penalty/fine for that?

Thanks,  
Zach

-----Original Message-----

**From:** DANA Kevin [<mailto:DANA.Kevin@deq.state.or.us>]  
**Sent:** Monday, October 13, 2014 9:45 AM  
**To:** Zachary Goodman  
**Cc:** DANA Kevin; GAMOLO Gerald  
**Subject:** RE: OLPRR Incident Report in Accepted Status. Log Number: 26-14-1234

The new release should be added to the existing LUST number. It makes it easier for everybody, as both releases can be combined into one report and one NFA letter.

Thanks! Kevin

-----Original Message-----

**From:** GAMOLO Gerald  
**Sent:** Monday, October 13, 2014 9:14 AM  
**To:** 'Zachary Goodman'  
**Cc:** DANA Kevin  
**Subject:** RE: OLPRR Incident Report in Accepted Status. Log Number: 26-14-1234

I'll let Kevin Dana answer this question.  
Thanks.

Gerald M. Gamolo  
Oregon Department of Environmental Quality  
2020 SW 4th Avenue, Suite 400,  
Portland, OR 97201  
Office: (503) 229-6361

Fax: (503) 229-6899  
Email: [gamolo.gerald@deq.state.or.us](mailto:gamolo.gerald@deq.state.or.us)

-----Original Message-----

From: Zachary Goodman [<mailto:zachary@alphaenvironmental.net>]  
Sent: Monday, October 13, 2014 9:11 AM  
To: GAMOLO Gerald  
Cc: DANA Kevin  
Subject: RE: OLPRR Incident Report in Accepted Status. Log Number: 26-14-1234

We recently sampled a second tank at this site (a heating oil tank) and it was found to be leaking. Should a report that as a new LUST or should it be added to this entry?

Sincerely,  
Zach

-----Original Message-----

From: GAMOLO Gerald [<mailto:GAMOLO.Gerald@deq.state.or.us>]  
Sent: Wednesday, September 10, 2014 5:50 PM  
To: Zachary Goodman  
Cc: DANA Kevin  
Subject: OLPRR Incident Report in Accepted Status. Log Number: 26-14-1234

Your on-line tank data submittal has been reviewed and accepted by the State of Oregon DEQ.  
New LUST Incident Log Number: 26-14-1234

---

Reported by: ZACHARY GOODMAN  
Company Name: ALPHA ENVIRONMENTAL SERVICES Phone Number: 503-292-5346

Site Name: GRAHAM  
Site Address: 5104 SE Long Street  
Site County: MULTNOMAH  
Site City: PORTLAND  
Site Zip Code: 97206

Date Received: 9/10/2014  
Release Type: UnRegulated

---

RESPONSIBLE PARTY INFORMATION

First Name:  
Clinton & Isabel  
Last Name:  
Graham  
City:  
Portland  
Phone:  
000 000 0000  
Address:

INVOICE CONTACT INFORMATION

First Name:  
Clinton & Isabel  
Last Name:  
Graham  
City:  
Portland  
Phone:  
000 000 0000  
Address: