

DANA Kevin

From: Zachary Goodman [zachary@alphaenvironmental.net]
Sent: Monday, October 13, 2014 11:00 AM
To: DANA Kevin
Cc: GAMOLO Gerald
Subject: RE: OLPRR Incident Report in Accepted Status. Log Number: 26-14-1234

I understand; we have been pushing for remediation while the leak is small, but we will see what the RP's response is. Hopefully we can make it more practical to address the 2 tanks.

Zach

-----Original Message-----

From: DANA Kevin [<mailto:DANA.Kevin@deq.state.or.us>]
Sent: Monday, October 13, 2014 10:45 AM
To: Zachary Goodman
Cc: DANA Kevin; GAMOLO Gerald
Subject: RE: OLPRR Incident Report in Accepted Status. Log Number: 26-14-1234

There's no fine involved. We just wouldn't be able to issue an NFA for the site knowing that there's an unaddressed leaking tank there. Plus there's the general warning we give that not addressing a release may allow the contamination to spread (especially if it impacts groundwater) and may end up costing more to address later.

-----Original Message-----

From: Zachary Goodman [<mailto:zachary@alphaenvironmental.net>]
Sent: Monday, October 13, 2014 10:07 AM
To: DANA Kevin
Cc: GAMOLO Gerald
Subject: RE: OLPRR Incident Report in Accepted Status. Log Number: 26-14-1234

Sounds good. The RP may not pursue cleanup of the diesel tank at this time; is there any penalty/fine for that?

Thanks,
Zach

-----Original Message-----

From: DANA Kevin [<mailto:DANA.Kevin@deq.state.or.us>]
Sent: Monday, October 13, 2014 9:45 AM
To: Zachary Goodman
Cc: DANA Kevin; GAMOLO Gerald
Subject: RE: OLPRR Incident Report in Accepted Status. Log Number: 26-14-1234

The new release should be added to the existing LUST number. It makes it easier for everybody, as both releases can be combined into one report and one NFA letter.

Thanks! Kevin

-----Original Message-----

From: GAMOLO Gerald
Sent: Monday, October 13, 2014 9:14 AM
To: 'Zachary Goodman'
Cc: DANA Kevin
Subject: RE: OLPRR Incident Report in Accepted Status. Log Number: 26-14-1234

I'll let Kevin Dana answer this question.
Thanks.

Gerald M. Gamolo
Oregon Department of Environmental Quality
2020 SW 4th Avenue, Suite 400,
Portland, OR 97201
Office: (503) 229-6361
Fax: (503) 229-6899
Email: gamolo.gerald@deq.state.or.us

-----Original Message-----

From: Zachary Goodman [<mailto:zachary@alphaenvironmental.net>]
Sent: Monday, October 13, 2014 9:11 AM
To: GAMOLO Gerald
Cc: DANA Kevin
Subject: RE: OLPRR Incident Report in Accepted Status. Log Number: 26-14-1234

We recently sampled a second tank at this site (a heating oil tank) and it was found to be leaking. Should a report that as a new LUST or should it be added to this entry?

Sincerely,
Zach

-----Original Message-----

From: GAMOLO Gerald [<mailto:GAMOLO.Gerald@deq.state.or.us>]
Sent: Wednesday, September 10, 2014 5:50 PM
To: Zachary Goodman
Cc: DANA Kevin
Subject: OLPRR Incident Report in Accepted Status. Log Number: 26-14-1234

Your on-line tank data submittal has been reviewed and accepted by the State of Oregon DEQ.
New LUST Incident Log Number: 26-14-1234

Reported by: ZACHARY GOODMAN
Company Name: ALPHA ENVIRONMENTAL SERVICES Phone Number: 503-292-5346

Site Name: GRAHAM
Site Address: 5104 SE Long Street
Site County: MULTNOMAH
Site City: PORTLAND
Site Zip Code: 97206

Date Received: 9/10/2014
Release Type: UnRegulated