

03-92-0125, meadowbrook Grocery

looks like The most recent file
is missing !!! Check box #5...
Check anywhere !!!

9/9/04
(JMS)

☺
Box 5

Box #5

NWR UST FIELD INSPECTION REPORT

Inspection Date: Aug. 27, 2002

Site Name: Meadowbrook Grocery

Total Time* 3 hrs

Site Address: _____

*Include inspection, travel, paperwork

DEQ Inspector: H. Larsen

File/Facility No: 03-92-025
(both UST & UST Cleanup file #'s as appropriate)

Others Onsite: Don Williams (owner)

(include company name)

Supervisor License No. : _____ Exp. date _____
(note the name of the license holder with **)

Inspection Type

Y---N---Decommissioning

Y---N---Install-New

☒ Y---N---Complaint

Y---N---1998 Compliance (full)

Y---N---Upgrade-Retrofit

Y---N---WQ-New Permit

Partial Compliance

Y---N---Service Provider Audit

Y---N---WQ-Exist Permit

Y---N---Leak Detection

Y---N---Cleanup

Y---N---Financial Responsibility

Y---N---SWLA/Soil Treatment

Y---N---Corrosion Protection

Y---N---Distributor Audit

Y---N---NA Spill & Overfill

Circle Y for.....Yes = inspected & in compliance (Y for data entry)

Circle N for.....No = inspected & **NOT** in compliance (N for data entry)

Leave Blank for.....Inspection not performed (no data entry necessary)

Photos Taken? Y---☒ N (attach)

Samples Taken? Y---☒ N (attach results)

Notes (use back of form as necessary)

I met Mr. Williams on-site to discuss PGE complaint and SMH issues. I inspected leak detection system, obtained copies of tank tightness tests performed by ATG. I also opened up monitoring wells and made visual and olfactory observations regarding petroleum contamination in the two wells. I also ~~observed~~ ^{inspected} the location of the PGE excavation. It was located adjacent to culvert draining service station filling area.

Christmas Tree Farm

