



# Oregon

Kate Brown, Governor

Department of Environmental Quality

Northwest Region

700 NE Multnomah Street, Suite 600

Portland, OR 97232

(503) 229-5263

FAX (503) 229-6945

TTY 711

November 18, 2022

Kirk & Mary Ann Crawford  
3428 North Ridge Dr.  
Klamath Falls, OR 97601

RE: Annual Inspection for Parcel H (part of)  
North Ridge Estates Superfund Site  
ECSI No. 5998

Dear Kirk & Mary Ann Crawford:

The Oregon Department of Environmental Quality (DEQ) completed an annual inspection of the protective cap on your property located on North Ridge Drive during the week of June 27, 2022. The protective cap appears to be in good condition with a few minor areas to watch. Enclosed for your information is a summary of the inspection.

The next inspection will be performed in May or June 2023. Please continue to contact DEQ prior to any disturbing any of the protective caps on your property with the exception of soil disturbances less than 2 feet below the ground surface. A fact sheet with additional information is enclosed.

If you have any questions, please contact me at 503-860-3943, or via email at [Katie.Daugherty@deq.oregon.gov](mailto:Katie.Daugherty@deq.oregon.gov).

Sincerely,

*Katie Daugherty*

Katie Daugherty, R.G.  
Project Manager  
NWR Cleanup and Leaking UST Section

Enclosures