



DEQ

State of Oregon
Department of
Environmental
Quality

Oregon Department of Environmental Quality SSO Reporting Form



This information must be submitted within 5 days of becoming aware of the overflow.
Please complete online and print for signature. Be sure to fill out all fields.

FACILITY/CONTACT INFORMATION

Name of Permittee: City of Corvallis		
Contact Name: Max Hildebrand		
Phone:	Email:	County:
541-754-1757	Max.hildebrand@corvallisoregon.gov	Benton
DEQ Permit # (see permit face page): 101714		DEQ File #: 20151
OERS Incident #: 2024-2623	Date Reported to OERS: 10/08/2024	
Date Reported To DEQ: 10/08/2024	Today's Date: 10/08/2024	
Date SSO Started (if known): 10/08/2024	Time Started (if known): 0740 am	
Date SSO Stopped (if known): 10/08/2024	Time Stopped (if known): 0810 am	
SSO Location: Manhole	Satinwood and Conifer	
SSO Nearest Address:		
City: Corvallis	Zip Code: 97339	
SSO Latitude (if known):	Longitude (if known):	
Estimate of Quantity Overflowed: 3,000 gallons	(Gallons) Link to estimation method	
Did the SSO discharge to surface water? Yes		
Name of waterbody: Sequoia Creek		

PUBLIC NOTIFICATION

Notified downstream drinking water sources (List Below)? N/A	
Name of drinking water facility:	
Signs Posted? N/A	
Media contacted? N/A	
Who?	
List any other steps taken to notify the public or state/federal agencies:	

CAUSES

Cause or suspected cause of the overflow: Other (explain): <i>If needed, attach additional sheets</i> Root incursion with Rag build up.
Rainfall in the 24 hours prior to SSO (for storm-related overflows): 0 (inches)
Source of rainfall data: <i>If needed, attach additional sheets</i>

RECEIVED

OCT 16 2024

DEQ-SALEM OFFICE

1-in-5 year 24 hour rainfall for the sewerage system area (if known):

(in/24hr)

EMERGENCY RESPONSE AND MIGRATION

List actions taken to stop and mitigate the impact of the SSO.

For overland flow:	Taped off affected area? No
	Cleaned up affected area? Yes
For SSO to surface water:	Bacteria samples taken to confirm impact? Yes
	Follow up bacteria samples taken to confirm end of impact? Yes

Describe monitoring and results:
The spill area was cleaned, and disinfected by the collections crew. The Environmental Services group has been collected upstream and downstream samples of the storm water discharge pipe that discharges to Sequoia Creek. At this time of year, there is not much water running in Sequoia Creek. Samples will be collected again tomorrow.

For SSOs that impact buildings:	Pumped out flooded buildings? N/A
	Disinfected? N/A

Other measures taken (describe):

Steps taken or planned to reduce, eliminate, and prevent the reoccurrence of the overflow and schedule for those steps:

The crew ran a camera in the pipe to make sure it was properly cleaned. The pipe had been looked at recently.

COMMENTS

Two separate sets of samples have been collected for analysis. Some of the spill was collected in catch basins. The area was washed and disinfected.

I CERTIFY UNDER PENALTY OF LAW THAT THIS DOCUMENT AND ALL ATTACHMENTS WERE PREPARED UNDER MY DIRECTION OR SUPERVISION IN ACCORDANCE WITH A SYSTEM DESIGNED TO ASSURE THAT QUALIFIED PERSONNEL PROPERLY GATHER AND EVALUATE THE INFORMATION SUBMITTED. BASED ON MY INQUIRY OF THE PERSON OR PERSONS WHO MANAGE THE SYSTEM, OR THOSE PERSONS DIRECTLY RESPONSIBLE FOR GATHERING THE INFORMATION SUBMITTED IS, TO THE BEST OF MY KNOWLEDGE AND BELIEF, TRUE, ACCURATE, AND COMPLETE. I AM AWARE THAT THERE ARE SIGNIFICANT PENALTIES FOR SUBMITTING FALSE INFORMATION, INCLUDING THE POSSIBILITY OF FINE AND IMPRISONMENT FOR KNOWING VIOLATIONS.


Authorized Signature

Max HILDEBRAND
Name (print)

4	5	6	7	8	9	10
11	12	13	14	15	16	17
18	19	20	21	22	23	24
25	26	27	28	29	30	31

Oct. 9, 2024
541-754-1757
Phone Number

*You may attach additional information to this report before sending to DEQ as needed to explain the circumstances of the overflow. This information may include but is not limited to: maintenance records and bacteria monitoring results.

Upon completion, print out this form and send to the appropriate DEQ Address:

Portland-Permit Coordinator
700 NE Multnomah St., Suite 600
Portland, OR 97232

Salem-Permit Coordinator
4026 Fairview Industrial Dr. SE
Salem, OR 97302

Pendleton-Permit Coordinator
800 SE Emigrant, #330 Pendleton,
OR 97801

FOR DEQ PERSONNEL ONLY

- Pre-Enforcement Notice
- Warning Letter

No enforcement action was warranted because:

- The SSO was caused by unpreventable vandalism or similar force majeure; or
- The SSO is allowed as an exception to the permit as maintenance; or
- The cause of the current SSO was beyond reasonable control AND we do not expect the permittee to prevent similar SSOs in the future; or
- The SSO was 400 gallons or less, spilled to the ground and not reaching surface water; permittee properly reported, cleaned up, and took appropriate public notice measures; and the SSO was not part of a chronic problem.

COMMENTS

Attn: Brad Eagleson

