CAMERON Kenneth A

DANA Kevin From:

Sent: Monday, July 24, 2017 9:24 AM

GAMOLO Gerald To:

CAMERON Kenneth A; DANA Kevin; ISMERIO Dawn Cc:

Q-Time Number Needed for LUST 26-17-0573 Subject:

Gerald,

We need to have a Q-Time number assigned to LUST project #26-17-0573 (Portland Public Schools). Ken Cameron will be the Project Manager.

We haven't received a signed Cost Recovery Agreement for this project, but we usually don't require local governments to sign a CRA.

Let me know if you have any questions. Thanks!

Kevin Dana

Oregon Department of Environmental Quality Northwest Region Office 700 NE Multnomah St., Suite 600 Portland, OR 97232-4100

Phone: (503) 229-5369



26-17-0573

TRANSMITTAL

DATE:

June 21, 2017

TO:

Eric Kelley

Oregon Department of Environmental Quality

700 NE Multnomah Street, Suite 600

Portland, Oregon 97232

FROM:

Scott Braunsten, RG, CES

PROJECT NO:

22589.000

RE:

Underground Storage Tank Decommissioning Report

Portland Public Schools 501 N Dixon Street Portland, Oregon 97227 DEQ Facility Number 7666 LUST File Number 26-17-0573

Attached is one hard copy of the Underground Storage Tank Decommissioning Report for Facility 7666 located at 501 N Dixon Street in Portland, Oregon. I have sent you an electronic version of the report via email.

If you have any questions regarding this report, please contact me at 503.417.7737.

Thank you.

cc: Mr. Jeff Brandt, Portland Public Schools

GAMOLO Gerald

From:

Dana Domenighini [Dana.Domenighini@pbsusa.com]

Sent:

Monday, June 05, 2017 11:22 AM

To:

gerald.gamolo@state.or.us

Cc:

Scott Braunsten; jbrandt1@pps.net

Subject:

UST Initial 20 Day Report

Attachments:

USTInitial20DayReport_Completed.pdf

#26-17-0573

Mr. Gamolo,

Please find attached to this email a completed 20 day report for the Portland Public School facility located at 501 N Dixon Street in Portland, Oregon.

If you have any questions, feel free to contact me.

Thank you,

Dana Domenighini

Staff Scientist

PBS

4412 SW Corbett Ave., Portland, OR 97239 office: 503.248.1939 | direct: 503.417.7681 | cell: 503.407.1166 dana.domenighini@pbsusa.com pbsusa.com

PBS is the assumed business name of PBS Engineering and Environmental Inc., an Oregon Domestic Corporation. This electronic communication and its attachments are intended only for the person(s) to whom it is addressed and may contain confidential information. If you are not the intended recipient of this message, you are hereby notified that any use, retransmission, distribution, reproduction or any action relying upon this message is prohibited. If you have received this information in error, please notify the sender.



OREGON DEPARTMENT OF ENVIRONMENTAL QUALITY UNDERGROUND STORAGE TANK PROGRAM

Initial (Twenty Day) Report Form for UST Cleanup Projects

Quality	
	This report is due twenty (20) days from the date of the release.
DEQ USTC File No.	26-17-0573
DEQ Facility ID No.	7666
Site Name:	Portland Public Schools
Site Address:	501 N Dixon Street, Portland, OR 97227
INITIAL CLEAN	NUP INFORMATION
Gasolin	nation (check √ all that apply): e
(2) Estimate quantit <100 gal.	y of release (based on information known to date – ● select only one): 100-499 gal. 500-999 gal. 1,000-5,000 gal. >5,000 gal.
SITE INFORMA	$\underline{\text{TION}}$ (check $\underline{}$ yes or $\underline{}$ no)
(3) Y V	Did any water enter the excavation? If yes, please describe and identify the depth to groundwater in feet below ground surface:
(4) Y V	Was a sheen or odor observed on any water in the excavation?
	ter is encountered, soil samples from the soil/water interface must be collected and analyzed be appropriate TPH method.
At sites where die screened or tested	esel or other non-gasoline products have been released, the water may also have to be for polynuclear aromatic hydrocarbons (PAHs). <i>Please refer to OAR 340-122-0218</i> .
(5) Y V	Was water pumped from the excavation?
<u> </u>	If yes, did groundwater recharge within 24 hours after pumping?
Please describe	the pumping procedure and disposal option selected for the purged excavation water:
(6) Y V	Were any water samples collected from the excavation? If yes, please describe:
(7) Y	N Have any soil and/or water sample results been received at this time? If so, please attach any lab reports.

IF GROUNDWATER HAS BEEN ENCOUNTERED, PLEASE ANSWER QUESTIONS #8-13, BELOW. IF NO WATER HAS BEEN ENCOUNTERED, PLEASE SKIP TO QUESTION #14

(8) What are the known uses of groundwater within a 500-foot radius of the release site (check $\sqrt{\text{all}}$ that apply)?
non-use agricultural drinking supply
(9) If groundwater in this area is being used as a drinking water supply, please check √ the type and size of population served by the supply:
Community (community well used for drinking water year round – • select only one)
size: <1,000 people 1,000 - 5,000 people >5,000 people
Intermittent use (public water used for drinking water only on a part-time basis - • select only one)
size: <pre> <50 people </pre> <pre>50 - 300 people </pre> <pre> > 300 people</pre>
Private wells (individual private well or wells used for drinking water - • select only one)
size: <10 people 10 - 25 people >25 people
(10) Y N Is there any evidence this water supply has been or is likely to be impacted from the petroleum product release? If yes, estimate how difficult it would be to replace the existing supply: bottled water is the only alternative
on-site water treatment; bulk water delivery; new wells are available
able to connect to existing water supply
do not know what alternatives would be available
(11) Y N Are/were vapors present in on-site or nearby buildings? If yes:
A. Are you monitoring and/or mitigating any potential fire and safety hazards posed by vapors
and free product? Explain:
B. Estimate the number of people potentially affected by vapors − • select only one:
1-2 people 3-10 people >10 people
(12) Y N Are vapors or is petroleum contamination present in the utility corridors?
If yes, please explain:
(13) Y N Are natural areas located within 1/4 mile of the site? If so, please describe types (parks,
rivers, wetlands, sensitive habitats, etc.) and proximity:
(14) Y N If groundwater was not encountered in the excavation, do you believe that this cleanup project can be conducted under the requirements for an UST Cleanup Matrix site? If yes, then refer to OAR 340-122-0305 through 0360.

AREA	/SITE CONDITIONS:
(15)	Mean annual rainfall: <a> <20 inches <a> 20-45 inches <a> >45 inches
(16)	Soil type(s) of the naturally occurring soils, not the backfill around the tank - ● select only one:
	clays, compact tills, shales, and unfractured metamorphic and igneous rocks
	sandy loams, loamy sands, silty clays, clay loams, moderately permeable limestone, dolomite, sandstones, moderately fractured igneous and metamorphic rock
	fine and silty sands, sands and gravels, highly fractured igneous and metamorphic rock, permeable basalts and lavas, karst limestones and dolomites
SOIL	MANAGEMENT
(17)	If soil sample results have been received:
	Y Will the level of contamination detected require removal of contaminated soil for treatment or disposal?
(18)	All contaminated soil temporarily stockpiled on-site prior to treatment or disposal must be contained within a bermed area, kept covered, and the entire area secured to prevent unauthorized access by the public. If you haven't done this, please explain why:
Note: withou	It is a violation to stockpile petroleum contaminated soil (PCS) on-site for greater than 30 days ut a DEQ Solid Waste Letter Authorization (SWLA) Permit.
(19)	If contaminated soil is currently stockpiled on-site, please indicate when disposal will occur or when treatment will begin:
(20)	Estimated volume of contaminated soil (specify tons or cubic yards):
(21)	Intended disposition of soils (please • select only one):
	On-site/off-site treatment, Solid Waste Letter Authorization Permit Application attached.
	Thermal treatment off-site at an authorized facility.
	Facility name:
	Name of Landfill:
Note:	Please attach additional information as necessary to explain any unusual circumstances stated with this project.

January 2008 Page 3 of 4 05-LQ-089A

This initial report is intended to provide the Department with the basic initial information about activities associated with the release. Future reports should provide a more detailed and complete picture of the cleanup project.

Please be aware that a DEQ permit/authorization is required for the following activities:

- 1) Soil aeration, bioremediation (on-site or off-site), or on-site thermal treatment.
- 2) Water discharges to a stream/storm drain from the excavation or treatment tank.

If these activities will be included in your cleanup project, contact the regional DEQ office for the appropriate application forms, information on permit fees and guidance documents.

THIS REPORT WAS PREPARED BY:

Individual:	Dana Domenighini	Date: 6/5/17
Company:	PBS Engineering & Environmental	Phone: 503-417-7681
Address:	4412 SW Corbett Avenue	
City:	Portland	State OR Zip 97239

- 1. Please return this form to the regional office in which the site is located. If you have questions, call the contact person in your regional office.
- 2. For all tanks, except heating oil tanks, you must submit an UST Decommissioning

 Checklist and Site Assessment Report to the appropriate regional office

 within 30 days of the UST decommissioning.

 Failure to do so can result in delays to your project and
 may result in continued billing for the annual tank permit fees.
 - 3. Addresses and phone numbers for the regional offices can be found in the UST Cleanup Manual or viewed and downloaded from this DEQ Webpage: http://www.deq.state.or.us/about/locations.htm
- 4. Copies of the *UST Cleanup Manual* and other UST program forms and checklists can be viewed and downloaded from DEQ's Website: http://www.deq.state.or.us/lq/tanks/ust/index.htm

or in the Portland area by calling Steve Paiko at 503-229-6652

or outside the Portland area leaving a message on the UST Help Line (toll-free in Oregon) at 1-800-742-7878

KEEP A COPY OF THIS REPORT FOR YOUR FACILITY RECORDS

January 2008 Page 4 of 4 05-LQ-089A



ANALYTICAL REPORT

May 22, 2017



PBS Engineering & Env.- POR

Sample Delivery Group:

L910572

Samples Received:

05/19/2017

Project Number:

22589.000

Description:

PPS UST Decommissioning

Report To:

Scott Braunsten

4412 SW Corbett Ave

Portland, OR 97239

Entire Report Reviewed By:

Buar Ford

Brian Ford

Technical Service Representative

Results relate only to the items tested or calibrated and are reported as rounded values. This test report shall not be reproduced, except in full, without written approved of the lubbratory. Where applicable, sampling conducted by ESC is performed per guidance provided in lubbratory standard operating procedures; 060307, 060303, and 060304.



Cp: Cover Page	1
Tc: Table of Contents	2
Ss: Sample Summary	3
Cn: Case Narrative	4
Sr: Sample Results	5
PIPE20-3 L910572-01	5
DISPENSER1-4 L910572-02	6
DISPENSER2-4 L910572-03	7
DISPENSER3-4 L910572-04	8
Qc: Quality Control Summary	9
Total Solids by Method 2540 G-2011	9
Volatile Organic Compounds (GC) by Method NWTPHGX	10
Semi-Volatile Organic Compounds (GC) by Method NWTPHDX-SGT	11
GI: Glossary of Terms	12
Al: Accreditations & Locations	13
Sc: Chain of Custody	14





















SAM

1PI	F	SUMMARY	0
II L	-	O O IVIIVITALL	



WG981488



















ACM

Semi-Volatile Organic Compounds (GC) by Method NWTPHDX-SGT

05/19/17 21:33

05/20/17 18:29



All sample aliquots were received at the correct temperature, in the proper containers, with the appropriate preservatives, and within method specified holding times. All MDL (LOD) and RDL (LOQ) values reported for environmental samples have been corrected for the dilution factor used in the analysis. All Method and Batch Quality Control are within established criteria except where addressed in this case narrative, a non-conformance form or properly qualified within the sample results. By my digital signature below, I affirm to the best of my knowledge, all problems/anomalies observed by the laboratory as having the potential to affect the quality of the data have been identified by the laboratory, and no information or data have been knowingly withheld that would affect the quality of the

Ср

















Brian Ford

Technical Service Representative

Buar Ford

PIPE20-3

SAMPLE RESULTS - 01

ONE LAB. NATIONWIDE.

Collected date/time: 05/18/17 11:50

Total Solids by Method 2540 G-2011

M	Result	Qualifier	Dilution	Analysis	Batch
Analyte	%			date / time	
Total Solids	88.9		1	05/19/2017 14:24	WG981348



Ss

Volatile Organic Compounds (GC) by Method NWTPHGX

	Result (dry)	Qualifier	RDL (dry)	Dilution	Analysis	Batch	
Analyte	mg/kg		mg/kg		date / time		
Gasoline Range Organics-NWTPH	ND		4.81	1.07	05/21/2017 22:20	WG981771	
(S) a,a,a-Trifluorotoluene(FID)	98.0		77.0-120		05/21/2017 22:20	WG981771	





Semi-Volatile Organic Compounds (GC) by Method NWTPHDX-SGT

	Result (dry)	Qualifier	RDL (dry)	Dilution	Analysis	Batch	
Analyte	mg/kg		mg/kg		date / time		
Diesel Range Organics (DRO)	ND		4.50	1	05/20/2017 17:48	WG981488	
Residual Range Organics (RRO)	ND		11.2	1	05/20/2017 17:48	WG981488	
(S) o-Terphenyl	89.4		18.0-148		05/20/2017 17:48	WG981488	









DISPENSER1-4

Collected date/time: 05/18/17 12:25

SAMPLE RESULTS - 02

ONE LAB. NATIONWIDE.



Total Solids by Method 2540 G-2011

	Result	Qualifier	Dilution	Analysis	Batch		
Analyte	%			date / time			
Total Solids	89.0		1	05/19/2017 14:24	WG981348	AND A STREET STREET STREET STREET STREET STREET	

Volatile Organic Compounds (GC) by Method NWTPHGX

	Result (dry)	Qualifier	RDL (dry)	Dilution	Analysis	Batch	
Analyte	mg/kg		mg/kg		date / time		
Gasoline Range Organics-NWTPH	ND		4.67	1.04	05/21/2017 22:42	WG981771	
(S) a,a,a-Trifluorotoluene(FID)	98.0		77.0-120		05/21/2017 22:42	WG981771	



Semi-Volatile Organic Compounds (GC) by Method NWTPHDX-SGT

	Result (dry)	Qualifier	RDL (dry)	Dilution	Analysis	Batch	
Analyte	mg/kg		mg/kg		date / time		
Diesel Range Organics (DRO)	ND		4.49	1	05/20/2017 18:02	WG981488	
Residual Range Organics (RRO)	ND		11.2	1	05/20/2017 18:02	WG981488	
(S) o-Terphenyl	94.3		18.0-148		05/20/2017 18:02	WG981488	













DISPENSER2-4

SAMPLE RESULTS - 03

ONE LAB. NATIONWIDE.

1910572



	Result	Qualifier	Dilution	Analysis	Batch
Analyte	%			date / time	1.
Total Solids	94.1		1	05/19/2017 14:24	WG981348

Ср





	Result (dry)	Qualifier	RDL (dry)	Dilution	Analysis	Batch
Analyte	mg/kg		mg/kg		date / time	
Gasoline Range Organics-NWTPH	ND		4.72	1.11	05/21/2017 23:04	WG981771
(S) a,a,a-Trifluorotoluene(FID)	98.3		77.0-120		05/21/2017 23:04	WG981771





,	Result (dry)	Qualifier	RDL (dry)	Dilution	Analysis	Batch
Analyte	mg/kg		mg/kg		date / time	
Diesel Range Organics (DRO)	28.6		4.25	1	05/20/2017 18:15	WG981488
Residual Range Organics (RRO)	ND		10.6	1	05/20/2017 18:15	WG981488
(S) o-Terphenyl	72.3		18.0-148		05/20/2017 18:15	WG981488











DISPENSER3-4

Collected date/time: 05/18/17 12:10

SAMPLE RESULTS - 04

ONE LAB. NATIONWIDE.



Total Solids by Method 2540 G-2011

	Result	Qualifier	Dilution	Analysis	Batch
Analyte	%			date / time	
Total Solids	88.5		1	05/19/2017 14:24	WG981348





Volatile Organic Compounds (GC) by Method NWTPHGX

	Result (dry)	Qualifier	RDL (dry)	Dilution	Analysis	Batch	
Analyte	mg/kg		mg/kg		date / time		
Gasoline Range Organics-NWTPH	ND		4.66	1.03	05/21/2017 23:26	WG981771	
(S) a,a,a-Trifluorotoluene(FID)	97.0		77.0-120		05/21/2017 23:26	WG981771	



Semi-Volatile Organic Compounds (GC) by Method NWTPHDX-SGT

	Result (dry)	Qualifier	RDL (dry)	Dilution	Analysis	Batch
Analyte	mg/kg		mg/kg		date / time	
Diesel Range Organics (DRO)	ND		4.52	1	05/20/2017 18:29	WG981488
Residual Range Organics (RRO)	ND		11.3	1	05/20/2017 18:29	WG981488
(S) o-Terphenyl	76.5		18.0-148		05/20/2017 18:29	WG981488











QUALITY CONTROL SUMMARY

ONE LAB. NATIONWIDE.

Total Solids by Method 2540 G-2011

L910572-01,02,03.04

Method Blank (MB)

(MB) R3219571-1 05/19	9/17 14:24					
	MB Result	MB Qualifier	MB MDL	MB RDL		
Analyte	%		%	%		
Total Solids	0.000600					





L910553-43 Original Sample (OS) • Duplicate (DUP)

(OS) L910553-43 05/19	9/17 14:24 • (DUP) R	23219571-3 0	5/19/17 14:2	24		
	Original Result	DUP Result	Dilution	DUP RPD	DUP Qualifier	DUP RPD Limits
Analyte	%	%		%		%
Total Solids	95.2	93.5	1	1.79		5





Laboratory Control Sample (LCS)

(LCS) R3219571-2 05/19/17	7 14:24						
	Spike Amount	LCS Result	LCS Rec.	Rec. Limits	LCS Qualifier		
Analyte	%	%	%	%			
Total Solids	50.0	50.0	100	85.0-115			







QUALITY CONTROL SUMMARY

ONE LAB. NATIONWIDE.

Volatile Organic Compounds (GC) by Method NWTPHGX

L910572-01,02,03,04

Method Blank (MB)

(MB) R3219856-3 05/20/17	18:46			
Analyte	MB Result mg/kg	MB Qualifier	MB MDL mg/kg	MB RDL mg/kg
Gasoline Range Organics-NWTPH	U		0.0339	4.00
(S) a,a,a-Trifluorotoluene(FID)	100			77.0-120









(LCS) R3219856-1 05/20/	17 17:39 • (LCSD) R3219856-2	05/20/17 18:0	1						
	Spike Amount	LCS Result	LCSD Result	LCS Rec.	LCSD Rec.	Rec. Limits	LCS Qualifier	LCSD Qualifier	RPD	RPD Limits
Analyte	mg/kg	mg/kg	mg/kg	%	%	%			%	%
Gasoline Range Organics-NWTPH	5.50	5.94	5.51	108	100	70.0-133			7.50	20
(S) a,a,a-Trifluorotoluene(FIL))			101	101	77.0-120				







L909393-21 Original Sample (OS) • Matrix Spike (MS) • Matrix Spike Duplicate (MSD)

(OS) L909393-21 05/20/17 22:42 · (MS) R3219856-4	05/20/17 19:46 • (MSD) R3219856-5 05/20/17 20:08
--	--

	Spike Amount (dry)	Original Result (dry)	MS Result (dry)	MSD Result (dry)	MS Rec.	MSD Rec.	Dilution	Rec. Limits	MS Qualifier	MSD Qualifier	RPD	RPD Limits
Analyte	mg/kg	mg/kg	mg/kg	mg/kg	%	%		%			%	%
Gasoline Range Organics-NWTPH	6.39	181	261	270	25.4	28.2	49.5	10.0-146			3.35	30
(S) a,a,a-Trifluorotoluene(FID))				100	99.4		77.0-120				







QUALITY CONTROL SUMMARY

ONE LAB. NATIONWIDE.

Semi-Volatile Organic Compounds (GC) by Method NWTPHDX-SGT

L910572-01,02,03,04

Method Blank (MB)

(MB) R3219804-1 05/20/17	16:27			
Analyte	MB Result mg/kg	MB Qualifier	MB MDL mg/kg	MB RDL mg/kg
Diesel Range Organics (DRO)	U		1.33	4.00
Residual Range Organics (RRO)	U		3.33	10.0
(S) o-Terphenyl	85.5			18.0-148











(LCS) R3219804-2 05/20/1	7 16:39 • (LCSI	D) R3219804-	3 05/20/17 16:5	53							
	Spike Amount	LCS Result	LCSD Result	LCS Rec.	LCSD Rec.	Rec. Limits	LCS Qualifier	LCSD Qualifier	RPD	RPD Limits	
Analyte	mg/kg	mg/kg	mg/kg	%	%	%			%	%	
Diesel Range Organics (DRO)	30.0	26.5	25.7	88.3	85.8	50.0-150			2.86	20	
Residual Range Organics (RRO)	30.0	20.3	20.0	67.5	66.8	50.0-150			1.14	20	
(S) o-Terphenyl				76.0	74.0	18.0-148					











GLOSSARY OF TERMS

Abbreviations and Definitions

	-
SDG	Sample Delivery Group.
MDL	Method Detection Limit.
RDL (dry)	Reported Detection Limit.
RDL	Reported Detection Limit.
ND	Not detected at the Reporting Limit (or MDL where applicable).
U	Not detected at the Reporting Limit (or MDL where applicable).
RPD	Relative Percent Difference.
(dry)	Results are reported based on the dry weight of the sample. [this will only be present on a dry report basis for soils].
Original Sample	The non-spiked sample in the prep batch used to determine the Relative Percent Difference (RPD) from a quality control sample. The Original Sample may not be included within the reported SDG.
(S)	Surrogate (Surrogate Standard) - Analytes added to every blank, sample, Laboratory Control Sample/Duplicate and Matrix Spike/Duplicate; used to evaluate analytical efficiency by measuring recovery. Surrogates are not expected to be detected in all environmental media.
Rec.	Recovery.
Qualifier	Description

The remainder of this page intentionally left blank, there are no qualifiers applied to this SDG. $\frac{1}{2} \int_{\mathbb{R}^{n}} \left(\frac{1}{2} \int_{\mathbb{R}^{n}} \left(\frac$























ESC Lab Sciences is the only environmental laboratory accredited/certified to support your work nationwide from one location. One phone call, one point of contact, one laboratory. No other lab is as accessible or prepared to handle your needs throughout the country. Our capacity and capability from our single location laboratory is comparable to the collective totals of the network laboratories in our industry. The most significant benefit to our "one location" design is the design of our laboratory campus. The model is conducive to accelerated productivity, decreasing turn-around time, and preventing cross contamination, thus protecting sample integrity. Our focus on premium quality and prompt service allows us to be YOUR LAB OF CHOICE. * Not all certifications held by the laboratory are applicable to the results reported in the attached report.

State Accreditations

Alabama	40660	Nevada	TN-03-2002-34
Alaska	UST-080	New Hampshire	2975
Arizona	AZ0612	New Jersey-NELAP	TN002
Arkansas	88-0469	New Mexico	TN00003
California	01157CA	New York	11742
Colorado	TN00003	North Carolina	Env375
Conneticut	PH-0197	North Carolina 1	DW21704
Florida	E87487	North Carolina ²	41
Georgia	NELAP	North Dakota	R-140
Georgia 1	923	Ohio-VAP	CL0069
Idaho	TN00003	Oklahoma	9915
Illinois	200008	Oregon	TN200002
Indiana	C-TN-01	Pennsylvania	68-02979
lowa	364	Rhode Island	221
Kansas	E-10277	South Carolina	84004
Kentucky 1	90010	South Dakota	n/a
Kentucky ²	16	Tennessee 14	2006
Louisiana	Al30792	Texas	T 104704245-07-TX
Maine	TN0002	Texas ⁵	LAB0152
Maryland	324	Utah	6157585858
Massachusetts	M-TN003	Vermont	VT2006
Michigan	9958	Virginia	109
Minnesota	047-999-395	Washington	C1915
Mississippi	TN00003	West Virginia	233
Missouri	340	Wisconsin	9980939910
Montana	CERT0086	Wyoming	A2LA
Nebraska	NE-OS-15-05		

Third Party & Federal Accreditations

A2LA - ISO 17025	1461.01	AIHA-LAP,LLC	100789	
A2LA - ISO 170255	1461.02	DOD	1461.01	
Canada	1461.01	USDA	S-67674	
EPA-Crypto	TN00003			

¹ Drinking Water ² Underground Storage Tanks ³ Aquatic Toxicity ⁴ Chemical/Microbiological ⁵ Mold ^{nb} Accreditation not applicable

Our Locations

ESC Lab Sciences has sixty-four client support centers that provide sample pickup and/or the delivery of sampling supplies. If you would like assistance from one of our support offices, please contact our main office. ESC Lab Sciences performs all testing at our central laboratory.





Ss













			Billing Inform	nation:					Ana	alysis/C	ontainer	/ Prese	vative			Chain	of Custody	Pageof
BS Engineering and Env 412 SW Corbett Avenue	vironmen 2	tal	PBS Engi	neering and nental		Pres Chk						_			_	_4	大上	SC
ortland, Oregon 97239				Corbett Ave , Oregon 97											:		· B · B · C Flat Alexand S Labanon Rd	DIESCHOSTE DIESCHOSTE
eport to: cott Braunsten	-		Email To: scott.bra	unsten@pb	susa.com											Mour Phone Phone	nt Juliet, TN 371 e: 615-758-5856 e: 600-767-5855	
roject escription: PPS UST Decommis:	sioning			City/State Collected: Portland, OR			,										L910	G72
hone: 503-417-7737	Client Project : 22589.000			Lab Project #													F01	2
ax: 866-727-0140 collected by (print): Dana Domenighini	Site/Facility ID	#		P.O. #												24 11	thum: nplate:	
Collected by (signature):	Same D	Bb MUST Be	Day	Quote#			×	×								1	login:	
mmediately Packed on ice N Y	X Next Da	y500 y100	y (Rad Only) ay (Rad Only)	Date Results Needed		No. of	NWTPH-GX	NWTPH-Dx	9							PB		
Sample ID	Comp/Grab	Matrix *	Depth	Date	Time	Cntrs	1	Ž	НОГР								Remarks	Sample # (Izb only)
Pine 20-3	Grab	SS	3F+	E/18/17	।(क	5		X										_
Dispenser1-4			44		1225		×	\ <u>`</u>							4			03
Dispenser 7 - 4	1		11		1205		X	×										
Pipe 20-3 Dispenser1-4 Dispenser2-4 Dispenser3-4	V	Ψ	*	V	12/0	1	X	X	ļ							_		GU
						+	+		-	-					12			
																		i .
							+-	+		 								
	-	 				十	†											
Matrix: SS - Soil AIR - Air F - Filter GW - Groundwater B - Bioassay WW - WasteWater	Remarks:	1			1					pł Flo	1	Tem Oth			Coc s	eal Prod igned/A es arriv et bott	ient/Inter curate: vo intert les used:	2
DW - Drinking Water Samples returned v OT - Other UPS Fedex		rned via: fedExC	ourler		Tracking#					1=:						sufficient volume Agate If Applicable vol Here Readupte: Preservation Correct/Checked:		
Relinquished by: (Signature)	Q.	Date:	ו/וי	Time: 1310	Received by: (Sig				-		Trip Blank Received: Yes 1659 HCLI/ MecH							
Relinquished by : (Signature)		Date:		Time:	Received by: (Sig	nature			Temp: °C Bootles Sectived:				If preservation required by Login: Date/Time					
Relinquished by : (Signature) Dat		Date:		Time:	Received for lab	by: 150	nature)	u	.)	Date:	947	Tì	84	5	Hold			NCF / O



ANALYTICAL REPORT

May 23, 2017



PBS Engineering & Env.- POR

Sample Delivery Group:

L910875

Samples Received:

05/20/2017

Project Number:

22589.000

Description:

PPS UST Decommissioning

Report To:

Scott Braunsten

4412 SW Corbett Ave

Portland, OR 97239

Entire Report Reviewed By:

Buar Ford

Brian Ford

Technical Service Representative

Pesults relate only to the items tested or calibrated and are reported as rounded values. This test report shall not be reproduced, except in full, without writer approval of the laboratory. Where applicable, sampling conducted by ESC is performed per guidance provided in laboratory standard operating procedures (86302, 063033, and 063304.

TABLE OF CONTENTS

ONE LAB. NATIONWIDE.

17

Cp: Cover Page	1
Tc: Table of Contents	2
Ss: Sample Summary	3
Cn: Case Narrative	4
Sr: Sample Results	5
TANK1N-16 L910875-01	5
TANK1S-15 L910875-02	6
TANK1E-15 L910875-03	7
TANK2N-13 L910875-04	8
TANK2S-13 L910875-05	9
TANK2W-13 L910875-06	10
PIPE30-5 L910875-07	11
Qc: Quality Control Summary	12
Total Solids by Method 2540 G-2011	12
Volatile Organic Compounds (GC) by Method NWTPHGX	13
Semi-Volatile Organic Compounds (GC) by Method NWTPHDX-SGT	14
GI: Glossary of Terms	15
Al: Accreditations & Locations	16
























Sc: Chain of Custody

SAM

IPLE	SUMMARY	ONE LAB.
	O O IVIIVII VII I	





















All sample aliquots were received at the correct temperature, in the proper containers, with the appropriate preservatives, and within method specified holding times. All MDL (LOD) and RDL (LOQ) values reported for environmental samples have been corrected for the dilution factor used in the analysis. All Method and Batch Quality Control are within established criteria except where addressed in this case narrative, a non-conformance form or properly qualified within the sample results. By my digital signature below, I affirm to the best of my knowledge, all problems/anomalies observed by the laboratory as having the potential to affect the quality of the data have been identified by the laboratory, and no information or data have been knowingly withheld that would affect the quality of the data.

Ср

















Brian Ford Technical Service Representative

Buar Ford

TANK1N-16

SAMPLE RESULTS - 01

ONE LAB. NATIONWIDE.

Total Solids by Method 2540 G-2011

Collected date/time: 05/19/17 08:30

	Result	Qualifier	Dilution	Analysis	Batch	
Analyte	%			date / time		
Total Solids	91.3		1	05/20/2017 14:11	WG981745	





	Result (dry)	Qualifier	RDL (dry)	Dilution	Analysis	Batch	
Analyte	mg/kg		mg/kg		date / time	5000 pm-50	
Gasoline Range Organics-NWTPH	ND		5.39	1.23	05/22/2017 17:12	WG982036	
(S) a,a,a-Trifluorotoluene(FID)	96.7		77.0-120		05/22/2017 17:12	WG982036	















TANK1S-15

SAMPLE RESULTS - 02

ONE LAB. NATIONWIDE.

910875



Collected date/time: 05/19/17 09:25

	Result	Qualifier	Dilution	Analysis	Batch	_
Analyte	%			date / time		
Total Solids	89.4		1	05/20/2017 14:11	WG981745	





	Result (dry)	Qualifier	RDL (dry)	Dilution	Analysis	Batch	
Analyte	mg/kg		mg/kg		date / time		
Gasoline Range Organics-NWTPH	ND		4.70	1.05	05/23/2017 13:52	WG982036	
(S) a,a,a-Trifluorotoluene(FID)	103		77.0-120		05/23/2017 13:52	WG982036	















TANK1E-15

SAMPLE RESULTS - 03

ONE LAB. NATIONWIDE.



Collected date/time: 05/19/17 11:00

Total Solids by Method 2540 G-2011

	Result	Qualifier	Dilution	Analysis	Batch
Analyte	%			date / time	
Total Solids	86.5		1	05/20/2017 14:11	WG981745

2_



Volatile Organic Compounds (GC) by Method NWTPHGX

	Result (dry)	Qualifier	RDL (dry)	Dilution	Analysis	Batch	
Analyte	mg/kg		mg/kg		date / time	5000-000	
Gasoline Range Organics-NWTPH	ND		4.63	1	05/23/2017 14:13	WG982036	
(S) a,a,a-Trifluorotoluene(FID)	102		77.0-120		05/23/2017 14:13	WG982036	



Ss













TANK2N-13

SAMPLE RESULTS - 04

ONE LAB. NATIONWIDE.



Collected date/time: 05/19/17 10:20

Total Solids by M	lethod 2540 G-2	2011				
73	Result	Qualifier	Dilution	Analysis	Batch	
Analyte	%			date / time		
Total Solids	90.5		1	05/20/2017 14:11	WG981745	

Ср



Semi-Volatile Organic Compounds (GC) by Method NWTPHDX-SGT

	Result (dry)	Qualifier	RDL (dry)	Dilution	Analysis	Batch	
Analyte	mg/kg		mg/kg		date / time		
Diesel Range Organics (DRO)	ND		4.42	1	05/23/2017 07:05	WG981802	
Residual Range Organics (RRO)	ND		11.0	1	05/23/2017 07:05	WG981802	
(S) o-Terphenyl	108		18.0-148		05/23/2017 07:05	WG981802	



Ss













TANK2S-13 Collected date/time: 05/19/17 10:00

SAMPLE RESULTS - 05

ONE LAB. NATIONWIDE.

3 - 03



Total Solids by Method 2540 G-2011

	Result	Qualifier	Dilution	Analysis	Batch	
Analyte	%			date / time		
Total Solids	91.2		1	05/20/2017 14:11	WG981745	



Semi-Volatile Organic Compounds (GC) by Method NWTPHDX-SGT

	Result (dry)	Qualifier	RDL (dry)	Dilution	Analysis	Batch
Analyte	mg/kg		mg/kg		date / time	
Diesel Range Organics (DRO)	ND		4.38	1	05/23/2017 07:57	WG981802
Residual Range Organics (RRO)	ND		11.0	1	05/23/2017 07:57	WG981802
(S) o-Terphenyl	93.5		18.0-148		05/23/2017 07:57	WG981802

















TANK2W-13

SAMPLE RESULTS - 06

ONE LAB. NATIONWIDE.

910875

Total Solids by Method 2540 G-2011

Collected date/time: 05/19/17 09:05

the second secon						
	Result	Qualifier	Dilution	Analysis	Batch	*
Analyte	%			date / time		
Total Solids	86.0		1	05/20/2017 14:11	WG981745	





Semi-Volatile Organic Compounds (GC) by Method NWTPHDX-SGT

	Result (dry)	Qualifier	RDL (dry)	Dilution	Analysis	Batch	
Analyte	mg/kg		mg/kg		date / time		
Diesel Range Organics (DRO)	8.47		4.65	1	05/23/2017 07:22	WG981802	
Residual Range Organics (RRO)	ND		11.6	1	05/23/2017 07:22	WG981802	
(S) o-Terphenyl	93.7		18.0-148		05/23/2017 07:22	WG981802	















PIPE30-5

SAMPLE RESULTS - 07

ONE LAB. NATIONWIDE.

910875

Total Solids by Method 2540 G-2011

Collected date/time: 05/19/17 09:20

	Result	Qualifier	Dilution	Analysis	Batch
Analyte	%	,		date / time	(5
Total Solids	78.3		1	05/20/2017 14:11	WG981745

2



Ss

Volatile Organic Compounds (GC) by Method NWTPHGX

	Result (dry)	Qualifier	RDL (dry)	Dilution	Analysis	Batch	
Analyte	mg/kg		mg/kg		date / time		
Gasoline Range Organics-NWTPH	ND		5.88	1.15	05/23/2017 14:34	WG982036	
(S) a,a,a-Trifluorotoluene(FID)	103		77.0-120		05/23/2017 14:34	WG982036	





	Result (dry)	Qualifier	RDL (dry)	Dilution	Analysis	Batch
Analyte	mg/kg		mg/kg		date / time	ar-sociales
Diesel Range Organics (DRO)	ND		5.11	1	05/23/2017 07:40	WG981802
Residual Range Organics (RRO)	ND		12.8	1	05/23/2017 07:40	WG981802
(S) o-Terphenyl	101		18.0-148		05/23/2017 07:40	WG981802











QUALITY CONTROL SUMMARY

ONE LAB. NATIONWIDE.

Total Solids by Method 2540 G-2011

L910875-01,02,03,04,05,06,07

Method Blank (MB)

(MB) R3219734-1 05/2	0/17 14:11				
	MB Result	MB Qualifier	MB MDL	MB RDL	
nalyte	%		%	%	
Total Solids	0.000300				



L910875-02 Original Sample (OS) • Duplicate (DUP)

(OS) L9108/5-02 05/20/	17 14:11 • (DUP) R	3219/34-3 05	0/20/1/ 14:	П		
	Original Result	DUP Result	Dilution	DUP RPD	DUP Qualifier	DUP RPD Limits
Analyte	%	%		%		%
Total Solids	89.4	89.2	1	0.255		5



Laboratory Control Sample (LCS)

(LCS) R3219734-2 05/	20/17 14:11				
	Spike Amount	LCS Result	LCS Rec.	Rec. Limits	LCS Qualifier
Analyte	%	%	%	%	
Total Solids	50.0	50.0	100	85.0-115	





QUALITY CONTROL SUMMARY

ONE LAB. NATIONWIDE.

L910875-01,02,03,07

Method Blank (MB)

(MB) R3220132-5 05/22/17	13:52			
Analyte	MB Result mg/kg	MB Qualifier	MB MDL mg/kg	MB RDL mg/kg
Gasoline Range Organics-NWTPH	0.0508	7	0.0339	4.00
(S) a.a.a-Trifluorotoluene(FID)	98.2			77.0-120

Volatile Organic Compounds (GC) by Method NWTPHGX







Laboratory Control Sample (LCS) • Laboratory Control Sample Duplicate (LCSD)

(LCS) R3220132-1 05/2	22/17 11:16 • (LCSD)	R3220132-2	05/22/17 11:38							
	Spike Amount	LCS Result	LCSD Result	LCS Rec.	LCSD Rec.	Rec. Limits	LCS Qualifier	LCSD Qualifier	RPD	RPD Limits
Analyte	mg/kg	mg/kg	mg/kg	%	%	%			%	%
Gasoline Range Organics-NWTPH	5.50	5.83	5.76	106	105	70.0-133			1.16	20
(S) a,a,a-Trifluorotoluene	e(FID)			105	105	77.0-120				













QUALITY CONTROL SUMMARY

ONE LAB. NATIONWIDE.

Semi-Volatile Organic Compounds (GC) by Method NWTPHDX-SGT

L910875-04,05,06,07

Method Blank (MB)

(MB) R3220129-1 05/22/17	19:09			
	MB Result	MB Qualifier	MB MDL	MB RDL
Analyte	mg/kg		mg/kg	mg/kg
Diesel Range Organics (DRO)	U		1.33	4.00
Residual Range Organics (RRO)	U		3.33	10.0
(S) o-Terphenyl	102			18.0-148









Laboratory Control Sample (LCS) • Laboratory Control Sample Duplicate (LCSD)

(LCS) R3220129-2 05/22/1	7 19:26 • (LCS	D) R3220129-	3 05/22/17 19:4	13							
	Spike Amount	LCS Result	LCSD Result	LCS Rec.	LCSD Rec.	Rec. Limits	LCS Qualifier	LCSD Qualifier	RPD	RPD Limits	
Analyte	mg/kg	mg/kg	mg/kg	%	%	%			%	%	
Diesel Range Organics (DRO)	30.0	24.0	21.5	0.08	71.7	50.0-150			10.8	20	
Residual Range Organics (RRO)	30.0	19.1	16.9	63.8	56.3	50.0-150			12.5	20	
(S) o-Terphenyl				80.6	69.6	18.0-148					















GLOSSARY OF TERMS

ONE L

Abbreviations and Definitions

J	The identification of the analyte is acceptable; the reported value is an estimate.
Qualifier	Description
Rec.	Recovery.
(S)	Surrogate (Surrogate Standard) - Analytes added to every blank, sample, Laboratory Control Sample/Duplicate and Matrix Spike/Duplicate; used to evaluate analytical efficiency by measuring recovery. Surrogates are not expected to be detected in all environmental media.
Original Sample	The non-spiked sample in the prep batch used to determine the Relative Percent Difference (RPD) from a quality control sample. The Original Sample may not be included within the reported SDG.
(dry)	Results are reported based on the dry weight of the sample. [this will only be present on a dry report basis for soils].
RPD	Relative Percent Difference.
U	Not detected at the Reporting Limit (or MDL where applicable).
ND	Not detected at the Reporting Limit (or MDL where applicable).
RDL	Reported Detection Limit.
RDL (dry)	Reported Detection Limit.
MDL	Method Detection Limit.
SDG	Sample Delivery Group.























Ss

Cn

Sr

Qc

GI

ESC Lab Sciences is the only environmental laboratory accredited/certified to support your work nationwide from one location. One phone call, one point of contact, one laboratory. No other lab is as accessible or prepared to handle your needs throughout the country. Our capacity and capability from our single location laboratory is comparable to the collective totals of the network laboratories in our industry. The most significant benefit to our "one location" design is the design of our laboratory campus. The model is conducive to accelerated productivity, decreasing turn-around time, and preventing cross contamination, thus protecting sample integrity. Our focus on premium quality and prompt service allows us to be **YOUR LAB OF CHOICE.*** Not all certifications held by the laboratory are applicable to the results reported in the attached report.

State Accreditations

Alabama	40660	Nevada	TN-03-2002-34
Alaska	UST-080	New Hampshire	2975
Arizona	AZ0612	New Jersey-NELAP	TN002
Arkansas	88-0469	New Mexico	TN00003
California	01157CA	New York	11742
Colorado	TN00003	North Carolina	Env375
Conneticut	PH-0197	North Carolina 1	DW21704
Florida	E87487	North Carolina ²	41
Georgia	NELAP	North Dakota	R-140
Georgia 1	923	Ohio-VAP	CL0069
Idaho	TN00003	Oklahoma	9915
Illinois	200008	Oregon	TN200002
Indiana	C-TN-01	Pennsylvania	68-02979
lowa	364	Rhode Island	221
Kansas	E-10277	South Carolina	84004
Kentucky 1	90010	South Dakota	n/a
Kentucky ²	16	Tennessee 14	2006
Louisiana	Al30792	Texas	T 104704245-07-TX
Maine	TN0002	Texas 5	LAB0152
Maryland	324	Utah	6157585858
Massachusetts	M-TN003	Vermont	VT2006
Michigan	9958	Virginia	109
Minnesota	047-999-395	Washington	C1915
Mississippi	TN00003	West Virginia	233
Missouri	340	Wisconsin	9980939910
Montana	CERT0086	Wyoming	A2LA
Nebraska	NE-OS-15-05		

Third Party & Federal Accreditations

A2LA - ISO 17025	1461.01	AIHA-LAP,LLC	100789	
A2LA - ISO 17025 ⁵	1461.02	DOD	1461.01	
Canada	1461.01	USDA	S-67674	
EPA-Crypto	TN00003			

¹ Drinking Water ² Underground Storage Tanks ³ Aquatic Toxicity ⁴ Chemical/Microbiological ⁵ Mold ^{n/e} Accreditation not applicable

Our Locations

ESC Lab Sciences has sixty-four client support centers that provide sample pickup and/or the delivery of sampling supplies. If you would like assistance from one of our support offices, please contact our main office. ESC Lab Sciences performs all testing at our central laboratory.



				Billing Inf	formation:		T				Analysis / Con	tainer / Prese	ervative		Chain of Custo	dy Page of 2	
PBS Engineering & Env 4412 SW Corbett Aven Portland, Oregon 9723	ue	enta	al	44125	3S Engineering & Environmenta 112 SW Corbett Avenue ortland, Oregon 97239										*	ESC	
Report to: Scott Braunsten				Email To:		pbsusa.com									12065 Lebanon R Mount Juliet, TN		
Project Description: PPS UST Decommi	ssionir	ıg			City/State	Portland, OR	- 4								Phone: 615-758-5 Phone: 800-767-5 Fax: 615-758-585	858 SS 13	
Phone: 503-417-7737		Project			Lab Project	tt									L# 9/16	275	
Fax: 866-727-0140	2258	9.000													F04		
Collected by (print): Dana Domenighini	Site/Fa	cility 10	#		P.O. #		Ą	×							Acctnum:		
Collected by (signature):	Re	ish? (L	ab MUST Be	Notified)	Quote #		100	0	ă						Template:		
Jana Domenight		Same Da	v five D	av					F.	-					10以其代表的。12		
Immediately Packed on Ice NY_X	-	Next Day Two Day Three Da	5 Day 10 Da	(Rad Only) y (Rad Only)	Date	Results Needed	No.	またろろ	LWAPA	FOLL)				TSR:		
Sample ID	Comp	/Grab	Matrix *	Depth	Date	Time	Cntrs	2	3	E					PB: Shipped Via:		
Tank IN-110	Gy	wo	SS	16	5/19/17	830	5	×	-						Hemarks	Sample # (lab only)	
Tank 11-18				18	1 7/1/1	840	17	^		***						01	
Tanzis-15	+			15		925	1	×	-	×	`						
Tank 15-17	1			17		930	H	×	\vdash	×						OL	
Tankle-15	11			15		1100	H	×		×						THE RESERVE	
Tank15-17	$\dagger \dagger$	76		17	++-	1605	H		\vdash	./						03	
Tank 2N-13				13	++-	1020	1		×	×				+			
Tanken-15				15		1025	1			~						14	
Tank 25-13			17358	13		1000	1		X	×							
Tank 25-15	1		V	15	1	1005	V		_	×		-				05	
Matrix: S - Soil AIR - Air F - Filter W - Groundwater B - Bioassay W - WasteWater	Remark	cs:	haza Bil			1333				_	pH	Temp		COC Sea	Sample Receipt C 11 Present/Intact med/Accurate:	necklist	
W - Drinking Water T - Other	Sample: UPS	Fed	ed via: Ex Couri	er		Tracking# [[]	36	-	7133		9897	Other		Correct	arrive intact: bottles used: ent volume sent: If Applicab	A N	
elinquished by: (Signature) Dana Domeng	e:		Date: 5/19/1		ime: [200	Received by: (Signatu	ire)	- /	121		Trip Blank Reco	elved: Yes/ HCL	No / MeoH	VOA Zer Preserv	o Headspace: ation Correct/Che	9 17	
delinquished by : (Signature)	Table 1	* 15	Date:	To The	ime:	Received by: (Signatu	ire)				Temp:	*C Bottles R	eceived:	If preserv	ration required by Log	in: Date/Time	
telinquished by : (Signature)		1	Date:	Ti	ime:	Received for lab by: (5	The second second	200	nt		Date:	Time:	:45	5-	086	Condition:	

			Billing Info	rmation:		T				Analysi	is / Con	ainer/	Prese	vative			Chain of Custon	ly Page 2 of 2
PBS Engineering & Envi 4412 SW Corbett Avenu	ie	al	PBS Eng	jineering & V Corbett /	k Environmental Avenue	Pres Chik				Í								
Portland, Oregon 97239				d, Oregon													L·A·B S	C-1-E-N-C-E-
Report to: Scott Braunsten			Email To: scott.br	aunsten@j	obsusa.com								ļ		ŀ		12055 Laboron Ro Mount Juliet, TN 3	
Project Description: PPS UST Decommis	sioning			City/State Collected: P	ortiand, OR												Phone: 615-758-5 Phone: 600-767-5 Fex: 615-758-5859	na 555
Phone: 503-417-7737	Client Project 22589.000			Lab Project	y												# 910	875
Fax: 866-727-0140 Callected by (print): Dana Domenighini	Site/Facility II			P.O. #				×									Tables	
Collected by (signature):		ab MUST 8e		Quote #			-Ç.	0	240						,		Acctrium: Template:	
Jana Briegt Immediately Packed on Ice N_ Y_X		y 5 Day y 10 Da		Date	Results Needed	No.	VW-TPH	MW TPH	四二年		.,						Prelogin: TSR: PB:	
Sample ID	Comp/Grab	Matrix *	Depth	Date	Time	Cntrs	2	٤	1	1							Shipped Via:	Sample & (lab cody)
Tank2N-13	Greet	\$2	13	5/19/1	1 905	G		X		1	†	†	+	+	-	+	 	Ola Cap any
Tank 2W-15			15		910				V	1	1		\top	+		1		1
Pipe 30-5	\ \\	V	5	1	920	4	X	X					-		1			n
									 -	+	-	+	+	+	+-	-		
													1					
				<u> </u>						 	1	-	1	+	+			
* Matric: SS - Soil AiR - Air F - Filter GW - Groundwater B - Bloassay WW - WasteWater	Remarks:					<u> </u>		K		рH	•		mp		(COC)	Soul Pr	lo Receipt d' caont/Introt Accurato:	neck) jet
DW - Orinking Water OT - Other	Samples return _ UPS	ned via: dExCou	ter		Tracking Ø					Flor	w	Ot	her_		Buff	ici bot Iciant	tion interior tion week volume pents	
Relinquished by: (Signature) Dama Damey	Q.,	Date: 5/19/		me: 1200	Received by: (Signati	ire)	·i			Trip Bit	ink Rec	lved:		MegH	Pres	Zero He ervatio	If Applicable Adapace: In Correct/Che	icked: X N
Relinquished by : (Signature)		Date:	Π	me:	Received by: (Signatu	ire)				Temp:	A)	_	nies R	onived:	If pre	ervation	required by Log	n: Oste/Time
Relinquished by : (Signature)		Date:	Ti	me:	Received for lab by: (Signati	le le	n	-	Date:	1	7	me:	45	Hold:			Candition:





SOURCE: © 2017 GOOGLE EARTH PRO


LEGEND

TANK 1N

SOIL BORING NUMBER AND LOCATION

DISPENSER 1

GRAB SAMPLE NAME AND LOCATION




PREPARED FOR: PORTLAND PUBLIC SCHOOLS

SITE PLAN - UST AND SAMPLING LOCATIONS

501 N DIXON STREET PORTLAND, OREGON JUNE 2017 22589.000

FIGURE





501 N DIXON ST

PORTLAND, OR 97227

PROPERTY Assessor Year Built 1980 Description **MISCELLANEOUS** Property Values (2016) **Building Area** 515,400 sq ft Market Value \$88,765,800.00 Neighborhood **ELIOT** Assessed Value \$0.00 Jurisdiction Portland / Multnomah Zoning IG1 - General Industrial 1 Taxes (2016) Elevation 95 ft (approximate) \$0.00 **Property Taxes** Owner SCHOOL DISTRICT NO 1 \$0.00 **Total Taxes** (LEASED MULTNOMAH **COUNTY ATTN** FINANCE DEPT **Owner Address** PO BOX 3107 PORTLAND, OR 97208-3107 **Related Accounts** Permits & Zoning **Parks**

Bureau of Development Services

Phone: 503-823-7300

Zoning Hotline: 503-823-7526



501 N DIXON ST

PORTLAND, OR 97227

ASSESSOR

Address	501 N DIXON ST	Owner	
Address2	PORTLAND, OR 97227	Name	SCHOOL DISTRICT NO 1(LEASED
City	PORTLAND		MULTNOMAH
Property ID	R156146		COUNTY ATTN FINANCE DEPT
Tax Roll	ELIZABETH IRVINGS ADD, BLOCK 18 TL	Туре	OWNER (PRIMARY)
	6600	Address	PO BOX 3107
Use	PUBLIC BLDG	City	PORTLAND
Block	18 TL 6600	State	OR
County	Multnomah	Zip Code	97208-3107
State ID	1N1E27DC 6600		
Alt Account Number	R244902080		
Map Number	2829 OLD		
Related Accounts	\vee		
Land Type	INDUSTRIAL LAND		
Total Land Area	2.89 acres		
Assessor Update Date Sales History & Deed	05/29/2017 7:24AM		

Sale Date	Туре	Instrument	Sale Price

Sale Date	Туре	Instrument	Sale Price
	OTHER		\$0.00
	INST		\$0.00

Improvements

Improvement TypeMISCELLANEOUSImprovement Value\$86,203,760.00Building ClassPUBLIC BLDG

Actual Year Built 1980 Number Of Segments 2

Segment Number	Segment Type	Class	Area Sq Ft	a Sq Ft		
1	MAIN		257700			
2	BSMT FINISHED		257700			

Assessment History

Year	Improvements	Land	Special Use	Real Market	Exemptions	Assessed
2016	\$86,203,760.00	\$2,562,040.00	\$0.00	\$88,765,800.00	\$88,765,800.00	\$0.00
2015	\$71,836,470.00	\$2,135,040.00	\$0.00	\$73,971,510.00	\$73,971,510.00	\$0.00
2014	\$66,515,250.00	\$1,976,880.00	\$0.00	\$68,492,130.00	\$68,492,130.00	\$0.00
2013	\$66,515,250.00	\$1,976,880.00	\$0.00	\$68,492,130.00	\$68,492,130.00	\$0.00
2012	\$66,515,250.00	\$1,976,880.00	\$0.00	\$68,492,130.00	\$68,492,130.00	\$0.00
2011	\$66,515,250.00	\$1,976,880.00	\$0.00	\$68,492,130.00	\$68,492,130.00	\$0.00
2010	\$66,515,250.00	\$1,976,880.00	\$0.00	\$68,492,130.00	\$68,492,130.00	\$0.00
2009	\$66,515,250.00	\$1,976,880.00	\$0.00	\$68,492,130.00	\$68,492,130.00	\$0.00
2008	\$66,515,250.00	\$1,976,880.00	\$0.00	\$68,492,130.00	\$68,492,130.00	\$0.00
2007	\$63,347,860.00	\$1,882,750.00	\$0.00	\$65,230,610.00	\$65,230,610.00	\$0.00
2006	\$63,347,860.00	\$1,882,750.00	\$0.00	\$65,230,610.00	\$65,230,610.00	\$0.00
2005	\$63,347,860.00	\$1,743,280.00	\$0.00	\$65,091,140.00	\$65,091,140.00	\$0.00
2004	\$57,588,960.00	\$1,584,800.00	\$0.00	\$59,173,760.00	\$59,173,760.00	\$0.00
2003	\$57,588,960.00	\$1,584,800.00	\$0.00	\$59,173,760.00	\$59,173,760.00	\$0.00
2002	\$55,374,000.00	\$1,523,850.00	\$0.00	\$56,897,850.00	\$56,897,850.00	\$0.00

Year	Improvements	Land	Special Use	Real Market	Exemptions	Assessed	
2001	\$55,374,000.00	\$1,523,850.00	\$0.00	\$56,897,850.00	\$56,897,850.00	\$0.00	
2000	\$44,299,200.00	\$1,219,080.00	\$0.00	\$45,518,280.00	\$45,518,280.00	\$0.00	
1999	\$36,916,000.00	\$1,015,900.00	\$0.00	\$37,931,900.00	\$37,931,900.00	\$0.00	
1998	\$33,257,700.00	\$915,200.00	\$0.00	\$34,172,900.00	\$34,172,900.00	\$0.00	
1997	\$31,065,700.00	\$871,600.00	\$0.00	\$31,937,300.00	\$31,937,300.00	\$0.00	

Tax Districts

Code	Description
101	PORT OF PORTLAND
130	CITY OF PORTLAND
130L	CITY OF PORTLAND - NEW LEVIES
130M	CITY OF PORTLAND PARKS LOP
143	METRO
164	EAST MULT SOIL/WATER
170	MULTNOMAH COUNTY
170L	MULT CO LIBRARY LOCAL OPT TAX
171	URBAN RENEWAL PORTLAND
173	URB REN SPECIAL LEVY - PORTLAND
198	TRI-MET TRANSPORTATION
304	MULTNOMAH ESD
309	PORTLAND COMM COLLEGE
311	PORTLAND SCHOOL DIST #1

Tax History

Year	Property Tax	Total Tax
2016	\$0.00	\$0.00
2015	\$0.00	\$0.00
2014	\$0.00	\$0.00
2013	\$0.00	\$0.00

Year	Property Tax	Total Tax
2012	\$0.00	\$0.00
2011	\$0.00	\$0.00
2010	\$0.00	\$0.00
2009	\$0.00	\$0.00
2008	\$0.00	\$0.00
2007	\$0.00	\$0.00
2006	\$0.00	\$0.00
2005	\$0.00	\$0.00
2004	\$0.00	\$0.00
2003	\$0.00	\$0.00
2002	\$0.00	\$0.00
2001	\$0.00	\$0.00
2000	\$0.00	\$0.00
1999	\$0.00	\$0.00
1998	\$0.00	\$0.00
1997	\$0.00	\$0.00

Tax Maps

Quarter Section	Size
1n1e27dc (Current Property)	124.8 KB
1n1e27	117.5 KB
1n1e27aa	567.8 KB
1n1e27ab	581.9 KB
1n1e27abd	19.7 KB
1n1e27ac	170.5 KB
1n1e27ad	288.2 KB
1n1e27ba	292.7 KB
1n1e27bb	147.2 KB
1n1e27bc	59.4 KB
1n1e27bd	153.6 KB

THIS MAP WAS PREPARED FOR ASSESSMENT PURPOSE ONLY

SWI/4 SEI/4 SEC. 27 T.IN. R.IE. W.M. MULTNOMAH COUNTY

IN IE 27DC PORTLAND











Department of Environmental Quality Northwest Region

700 NE Multnomah Street, Suite 600 Portland, OR 97232 (503) 229-5263 FAX (503) 229-6945 TTY 711

May 23, 2017

Jeff Brandt Portland Public Schools PO Box 3107 Portland, OR 97208

RE: Cleanup Needed for Petroleum Leak

Portland Public Schools 501 N. Dixon Street, Portland, OR 97227 DEQ File No.: 26-17-0573

Dear Mr. Brandt,

The Oregon Department of Environmental Quality (DEQ) was notified on May 23, 2017 of a petroleum leak associated with an underground storage tank system at 501 N. Dixon Street, Portland, Oregon. This leak appears to have contaminated soil and/or groundwater with petroleum products.

We understand that you have current or past ownership or operational responsibility for the property and the underground storage tank system. Oregon law considers you a responsible party for environmental cleanup, and you are required to clean up this contamination to a level that protects human health and the environment. If you believe you are not a responsible party for this petroleum leak, please contact us immediately so that we can review the ownership and facility operation records for the property.

If you choose to hire and rely upon a qualified contractor or consultant, DEQ recommends that you still become familiar with Oregon's environmental cleanup requirements. A copy of the Underground Storage Tank Cleanup Manual and other guidance documents can be obtained by calling our toll-free number at 1-800-742-7878 or by visiting the following web sites:

http://www.deq.state.or.us/lq/pubs/docs/tanks/USTCleanupManual.pdf http://www.deq.state.or.us/pubs/reports.htm#cuguidance

We are committed to helping you achieve a cost-effective environmental cleanup of the release from this underground storage tank system. When the cleanup of this petroleum release meets Oregon standards, DEQ will be able to close the file by issuing a "No Further Action" letter to you.

You will need DEQ oversight for your work to help you make sure that your environmental cleanup

Portland Public Schools File #26-17-0573 May 23, 2017 Page 2

meets minimum regulatory and technical standards. Oregon law requires DEQ to invoice responsible parties for staff time spent on oversight of cleanup projects. DEQ tracks and bills for this time monthly, beginning with the reporting of the release and continuing through project oversight and final site closure. Staff time may include reviewing reports, preparing correspondence, answering technical questions, meeting with you or your contractor, site inspections, and enforcement actions.

Please complete, sign, and submit the enclosed Cost Recovery Agreement if you would like to expedite assignment of a DEQ project manager to your project. Even if you do not sign the agreement, you are still responsible for investigation and/or cleanup of the contamination, as well as for DEQ oversight costs. Note that DEQ staff workloads are heavy and there may be a delay in assigning your cleanup project to a project manager.

Please also complete and return the enclosed <u>20-day Report</u> within twenty (20) days from the date of this letter, as required under Oregon Administrative Rule (OAR) 340-122-0225(3). You also have additional reporting obligations, as listed in the attachment, including due dates for various documents that you will need to provide to DEQ.

We realize that environmental cleanups are expensive and that our requirements can be difficult to understand, so please do not hesitate to contact the DEQ with any questions you may have. Please reference the DEQ file number and site name listed above in all inquiries and reports. If you have any questions, please contact our Program Coordinator, Kevin Dana, at (503) 229-5369.

Sincerely,

Kevin Parrett, Manager

DEQ NWR Cleanup and Tanks

Enclosures

GAMOLO Gerald

From:

GAMOLO Gerald

Sent:

Tuesday, May 23, 2017 2:20 PM

To:

'SCOTT_BRAUNSTEN@PBSENV.COM'

Cc:

DANA Kevin

Subject:

OLPRR Incident Report in Accepted Status. Log Number: 26-17-0573

Your on-line tank data submittal has been reviewed and accepted by the State of Oregon DEO. New LUST Incident Log Number: 26-17-0573

Reported by:

SCOTT BRAUNSTEN

Company Name: PBS ENGINEERING & ENVIRONMENTAL Phone Number: 503-417-7737

Site Name:

PORTLAND PUBLIC SCHOOLS

Site Address: 501 N DIXON ST

Site County:

MULTNOMAH

Site City:

Site Zip Code: 97227

PORTLAND

Date Received: 5/23/2017 Release Type: Regulated

Facility ID:

7666

RESPONSIBLE PARTY INFORMATION

First Name:

Jeff

Last Name:

Brandt

Organization:

Portland Public Schools

City:

Portland

Phone:

(503) 916-2000

Address:

PO Box 3107

State: OR

Zip:

97208

Email: jbrandt1@pps.net INVOICE CONTACT INFORMATION

First Name:

Jeff

Last Name:

Brandt

Organization:

Portland Public Schools

City:

Portland

Phone:

(503) 916-2000

Address:

PO Box 3107

State:

OR

Zip:

97208

Email:

jbrandt1@pps.net

Confirmation:

Lab:RP

Discovery:

Decommissioning

Cause:

Unknown

MEDIA TYPE

Soil

CONTAMINANT TYPE Diesel (Motor Fuel)

1



Department of Environmental Quality
Northwest Region
700 Multnomah Street Suite 600
Portland OR 97232
800-452-4011

September 7, 2017

Mr. Jeff Brandt Portland Public Schools P.O Box 3107 Portland, OR 97208

RE: No Further Action Determination

for Portland Public Schools

501 N. Dixon Street, Portland OR 97227

LUST #26-17-0573

Dear Mr. Brandt:

The Oregon Department of Environmental Quality (DEQ) has completed a review of the available information and the closure report entitled Underground Storage Tank Decommissioning Report, dated June 21, 2017 and submitted to DEQ on your behalf. The Portland Public Schools address is 501 N Dixon Street, Portland, OR 97227, Tax Lot 06600 on Multnomah County Map No. 1N 1E 27DC.

DEQ has determined that remedial action to address environmental contamination at Portland Public Schools is complete, and no further action is required. This determination is based on DEQ regulations and the facts as we now understand them including, but not limited to the following:

- In May, 2017, two underground storage tanks, one for gasoline (12,000 gallon capacity) and the other for diesel (2,500 gallon capacity) were abandoned in place.
- Dispensers and product lines were removed and 227 gallons of residual material was taken from the tanks and piping and disposed of at ORRCO Inc. in Portland, Oregon. The interior of the tanks were cleaned.
- A direct push drilling rig was use to advance 7 temporary wells for soil sampling around the tanks and product lines. No groundwater was encountered during the drilling which reached a maximum depth of 16 feet below ground surface (bgs)
- During drilling no odor or visible contamination was detected in the cuttings.
- Two compliance soil samples showed trace amounts of diesel-heavy oil product; one next to the diesel tank at 8.47 milligrams per kilogram (mg/kg) at 13 feet bgs and the other from beneath the dispensers at 28.6 mg/kg from 4 feet bgs. Both results are below the threshold level for the most stringent matrix cleanup level of 100 mg/kg.

The tanks were opened and back filled with controlled density fill.

Based on the available information, Portland Public Schools is currently protective of public health and the environment. The site requires no further action under Oregon Administrative Rules (OAR 340-122-0205 through 340-122-0360) unless new or previously undisclosed information becomes available, or there are changes in site development or land and water uses, or more contamination is discovered. DEQ has updated the Leaking Underground Storage Tank (LUST) database to reflect this decision.

This letter only applies to the release discussed above. If any contaminated soil or groundwater is encountered in the future, it must be handled and disposed of in accordance with local, state and federal regulations.

A copy of the reports supporting this No Further Action decision can be viewed at http://www.deq.state.or.us/WebDocs/Forms/Output/LustOutput.aspx?SourceId=48433&SourceIdType=10. DEQ recommends keeping a copy of all of the documentation associated with this remedial action with the permanent facility records. If you have any questions, please contact Kenneth Cameron at 503-229-5251 or via email at cameron.kenneth@deq.state.or.us.

Sincerely,


Kevin Parrett, Manager


Northwest Region Cleanup Section

cc:

Jeff Schatz

LUST File #26-17-0573





Review Type NEW	DEQ Office	<u>F</u> irst	<u>L</u> ast		OLPRR R	Review	0		Contractor laintenance	1
1 of	1 Records	<u>N</u> ext	<u>B</u> ack	OLPRR# 25719	Incident D)ata	Reported By - RepBy Phone	-		
Lookup LUST		Log N	umber	26-17-0573	Site Type	Regulated			EERING & ENVIF	ONIME
Site Name	PORTLAND	PUBLIC	SCHOO	LS	Received Date	5/23/2017	Company	JEDO ENGIN	EENING & ENVIR	TOTAINET
Site Address	501 N DIXON	1ST					County	Multnomah	-	
Other							Facility Id	7666	Lookup UST	
City	PORTLAND				Zip Code 9	7227	Phone			
	Responsible	e Party			Mail Conta	icts	Invoice Contact			
First Name	Jeff					First Name	Jeff			
Last Name					and the same of th	Last Name Brandt				
Organization	Desired Control of the Control of th	ic Scho	ols		(Organization Portland Public Schools				
Address	Address PO Box 3107				Address PO Box 3107					
Address2						Address2				
City	Portland					City	Portland			
State	7	-	Zip Code	97208		State		Zip Code 97	'208	
Phone	(503) 916-200	00				good .	(503) 916-2000			
	jbrandt1@pps					A LINCOLD HOLD BOOK	brandt1@pps.net			-
Site Assessme	-	over Da 22/2017	-	Discovery Decommissioning	Cause Unknown		Source Dispenser		onfirmation ab:RP	
Contamina Heating Oil Waste Oil Other Pet. Dis	□ L ₁		Gasoline d Gasoli I	, who, out	and the same of th	nown	☐ Sur	<u>Imp</u> oundwater face Water nking Water	Dacted Media ☐ Free Prod ☐ Vapor ☐ Soil	

at# 45591

FIRZ 9/18/17 Closed = 12/15/17

Underground Storage Tank Decommissioning Report

Portland Public Schools 501 N Dixon Street Portland, Oregon 97227 DEQ Facility Number 7666 LUST File Number 26-17-0573

Prepared for:
Portland Public Schools
301 N Dixon Street
Portland, Oregon 97227

June 2017 PBS Project No. 22589.000



TABLE OF CONTENTS

L	BACKGROUND	j
2	UNDERGROUND STORAGE TANK DECOMMISSIONING IN PLACE	1
=	2.1 UST Decommissioning	
	2.2 Soil Sampling	
	2.3 Soil Field Observations	
	2.4 Laboratory Results	•
	2.5 DEQ Reporting	2
	2.6 Soil Matrix Evaluation	2
3	CONCLUSION	2
1	LIMITATIONS	7
•		٠

SUPPORTING DATA

FIGURES

Figure 1. Vicinity Map

Figure 2. Site Plan

Figure 3. Site Plan – UST and Sampling Locations

TABLE

Table 1. Soil Analytical Results

APPENDICES


APPENDIX A: Disposal Receipts

APPENDIX B: Photographic Documentation

APPENDIX C: Boring Logs

APPENDIX D: Laboratory Reports

APPENDIX E: DEQ Forms





1 BACKGROUND

This report details the decommissioning of one 12,000-gallon gasoline underground storage tank (Tank 1) and one 2,500-gallon diesel underground storage tank (Tank 2) at the Portland Public Schools facility (site) located at 501 N Dixon Street in Portland, Oregon (Figures 1 through 3). Portland Public Schools (Client) contracted directly with Cowlitz Clean Sweep (CCS) of Longview, Washington, for underground storage tank (UST) decommissioning services. PBS Engineering and Environmental Inc. (PBS) provided oversight of decommissioning and backfill activities, the collection and analysis of confirmation soil samples, and reporting.

2 UNDERGROUND STORAGE TANK DECOMMISSIONING IN PLACE

2.1 UST Decommissioning

CCS began decommissioning activities on May 17, 2017. The dispensers were removed, product lines were rinsed, and the residual product flowed back to the tanks. The manway into the diesel UST was then opened and residual product removed. CCS cut a hole in the base of the diesel tank and water began flowing into the UST. The water was believed to be interstitial brine between the two walls of the tank and not groundwater. The hole was plugged and CCS finished cleaning the interior of the tank. An alternative method of soil sampling via direct push probe was conducted in lieu of sample collection through the bottom of the UST (see Section 2.2 below).

On May 18, 2017, CCS and PBS returned to the site to decommission the gasoline UST. Residual product was removed and the interior of the tank was cleaned. A total of 227 gallons of product was removed and transported to ORRCO Inc. in Portland, Oregon for recycling. A copy of the disposal receipt is included in Appendix A.

All product lines and piping were removed for disposal. PBS collected four soil samples, one beneath each of the three dispensers and one 20 feet from the westernmost dispenser along the product line. The soils retrieved beneath the dispensers and along the product line were absent of field evidence of contamination.

On May 24, 2017, the tanks were filled with controlled density fill (CDF). Photographic documentation of decommissioning activities is provided in Appendix B.

2.2 Soil Sampling

PBS was on site on May 19, 2017 to conduct the drilling investigation, with Western States Soil Conservation, Inc. of Hubbard, Oregon, providing drilling services. A direct-push drill rig was used to advance seven borings at the site. Borings were advanced to depth of 15 to 20 feet below ground surface (bgs) except for boring Pipe30, which was advanced to 5 feet bgs to collect a sample along the former pipe run. With the exception of the Pipe30 sample, all soil samples were collected from between 13 and 16 feet bgs (shallow sample) and between 15 and 18 feet begs (deeper sample) for each of the borings.

Figure 3 shows the locations of the temporary boreholes advanced at the site. In all borings, soils were logged continuously, noting grain size, color, odor, and moisture. Photoionization detector (PID) measurements were taken to assess for the presence of volatile contaminants. For the PID screening, soil was placed in a disposable zipper-type plastic bag that was sealed, gently shaken, and allowed to rest for 5 to 15 minutes. The PID tip was then inserted into the bag to measure total volatile compounds.

All samples were collected in laboratory-supplied containers, sealed, labeled, and placed on ice in a cooler and transported to ESC Lab Sciences of Mt. Juliet, Tennessee, with chain-of-custody documentation. Analyses were



conducted under normal turnaround time. Selected soil samples were analyzed for one or more of the following:

- Gasoline-range total petroleum hydrocarbon (TPH) by NW Method TPH-Gx
- Diesel- and heavy oil-range TPH by NW Method TPH-Dx

Sampling equipment and drill rods were decontaminated between borings using a detergent wash and tap water rinse. PBS personnel wore new disposable nitrile gloves when collecting samples. Upon completion of sampling, temporary boreholes were backfilled and sealed with bentonite to 6 inches below grade, and the surface was restored to match the surrounding area.

2.3 Soil Field Observations

The surface of most of the site was covered by pavement. Generally, the subsurface across the site consisted of gravel with sand to depths ranging from 0 to 13 feet bgs, below which was brown sand with variable amounts of silt. Groundwater was not encountered in any of the boreholes. Graphic boring logs are provided in Appendix C.

No field evidence of contamination, such as staining or odors, was observed during drilling. Specifically, no olfactory or visual impacts were detected in soils collected from the seven borings advanced at the site. PID readings of soil headspace ranged from zero parts per million (ppm) to 0.9 ppm.

2.4 Laboratory Results

Laboratory testing revealed no detectable petroleum hydrocarbons except in samples Tank-2W-13 and Dispenser 2-4, in which diesel-range petroleum hydrocarbons were detected. Sample Tank 2W-13 contained 8.47 milligrams per kilogram (mg/kg) diesel-range petroleum hydrocarbons, and sample Dispenser 2-4 contained 28.6 mg/kg. Table 1 summarizes the analytical results; the laboratory reports are provided in Appendix D.

2.5 DEQ Reporting

Based on the concentrations of diesel detected in the soil samples, a release was reported by PBS to the Oregon DEQ on May 23, 2017. The DEQ assigned Leaking Underground Storage Tank (LUST) File Number 26-17-0573.

2.6 Soil Matrix Evaluation

Based on the laboratory results, it is appropriate to pursue LUST file closure under soil matrix rules. As the detections for all confirmation soil samples were below the most stringent (Level 1) Soil Matrix cleanup level of 100 mg/kg, completion of a Soil Matrix Scoresheet is not necessary.

3 CONCLUSION

The USTs were decommissioned in place between May 17 and May 24, 2017. A confirmed release of diesel was detected beneath Tank 2 and Dispenser 2, but at concentrations below the most stringent Soil Matrix cleanup levels. The completed Initial (Twenty Day) Report Form for UST Cleanup Projects and UST Checklist are included in Appendix E. No further action is warranted at this time. It is recommended that this Underground Storage Tank Decommissioning Report be submitted to DEQ to consider LUST File No. 26-17-0573 for regulatory closure.



LIMITATIONS

PBS has prepared this report for use by Portland Public Schools. This report is for the exclusive use of the Client and is not to be relied upon by other parties. It is not to be photographed, photocopied, or similarly reproduced in total or in part without the express written consent of the client and PBS.

This study was limited to the tests, locations, and depths as indicated to determine the absence or presence of certain contaminants. The site as a whole may have other contamination that was not characterized by this study. The findings and conclusions of this report are not scientific certainties but probabilities based on professional judgment concerning the significance of the data gathered during the course of this investigation. PBS is not able to represent that the site or adjoining land contain no hazardous waste, oil, or other latent conditions beyond that detected or observed by PBS.

PBS Engineering and Environmental Inc.

Dana Domenighini

Date

Staff Scientist

Dennis Terzian, RG


6/20/2017

Senior Geologist

Date

FIGURES

Figure 1. Vicinity Map Figure 2. Site Plan Figure 3. Site Plan – UST and Sampling Locations







SOURCE: © 2017 GOOGLE EARTH PRO



SCALE: 1" = 140'

0 70' 140' 280'

PREPARED FOR: PORTLAND PUBLIC SCHOOLS

SITE PLAN

501 N DIXON STREET PORTLAND, OREGON

JUNE 2017 22589.000

FIGURE

2



TANK 1N SOIL BORING NUMBER AND LOCATION

TANK 1N

TANK 2W

• DISPENSER 1

PRODUCT


PIPING

PIPE30

PIPE20 DISPENSER 3

DISPENSER 2

GRAB SAMPLE NAME AND LOCATION DISPENSER 1



SOURCE: © 2017 GOOGLE EARTH PRO

PREPARED FOR: PORTLAND PUBLIC SCHOOLS



22589.000 **FIGURE**

JUNE 2017

TABLE

Table 1. Soil Analytical Results

Table 1. Soil Analytical Results 501 N Dixon Street Portland, Oregon Portland Public Schools

			Total Petroleum Hydrocarbons			
Sample ID	Sampling Depth (feet bgs)	Sampling Date	Gasoline	Diesel	Heavy Oil	
				mg/kg		
Tank 1N-16	16	5/19/2017	<5.39			
Tank 1S-15	15	5/19/2017	<4.70			
Tank 1E-15	15	5/19/2017	<4.63			
Tank 2N-13	13	5/19/2017		<4.42	<11.0	
Tank 2S-13	13	5/19/2017		<4.38	<11.0	
Tank 2W-13	13	5/19/2017		8.47	<11.6	
Dispenser 1-4	4	5/18/2017	<4.67	<4.49	<11.2	
Dispenser 2-4	4	5/18/2017	<4.72	28.6	<10.6	
Dispenser 3-4	4	5/18/2017	<4.66	<4.52	<11.3	
Pipe20-3	3	5/18/2017	<4.81	<4.50	<11.2	
Pipe30-5	5	5/19/2017	< 5.88	< 5.11	<12.8	
		Occupational	20,000	14,000		
Oregon RBC - Soil Contact, and	Ingestion, Dermal Inhalation ¹	Construction Worker	9,700	4,600		
		Excavation Worker	>MAX	>MAX		
Oregon RBC - Volatiliz	zation to Outdoor Air ¹	Occupational	69,000	>MAX		
Oregon RBC - Va Build	N	Occupational	>MAX	>MAX		
Oregon RBC - Leach	ing to Groundwater ¹	Occupational	130	>MAX		

See laboratory report for full list of analytes and quality-control data.

Bold text, if present, indicates an exceedance of one or more of the cleanup levels.



^{--:} analyte not tested

<: Not detected above the laboratory reporting limit

>MAX: The RBC for this pathway is greater than 1,000,000 mg/kg. This substance is not deemed to pose a risk in this scenario

¹Oregon Risk-Based Decision-Making for the Remediation of Petroleum-Contaminated Sites, Oregon DEQ Sept. 2003, Revised RBCs November 1, 2015.

APPENDIX A

Disposal Receipts



Head Office 4150 N. Suttle Rd. Portland, OR 97217 1-800-367-8894

RECEIVING RECORD

R 01-17-0614-006

Received From:

Cowlitz Clean Sweep 55 International Way Longview WA 98632 EPA# WAD988467197

Phone:

Customer ID#

360-423-6316

Driver:

711

josh

Receiving Location: Plant #

FPI

4150 N. Suttle Road Portland, OR 97217

Phone

503-286-8352

EPA#

ORD980975692

	Date)	Terms		Written By		Sales Rep.		Page
	06/14/	17	-0-		Cody				1 of 1
Line	Qty.	Unit	Item			%H20	Manifest #	B/L#	Net Qty
1	1	Each	Hydro Clor-D-Tect I Generator ID# 0	Kit See Comment	s		8517158		
			Total Each	1.					

131110	wil.	01111	1,0111			the second secon
1	1	Each	Hydro Clor-D-Tect I	Kit	8517158	
1			Generator ID# 0	See Comments		
			Total Each	1.		
2	201	Gal.	Emulsified Fuel		8517158	
III			Generator ID# 0 profile on file, hodt nd	See Comments		
3	26	Gal.	Suspended Solids Generator ID# 0	See Comments	8517158	
			Total Gal.	227.		

Customer warrents that the waste petroloum products being received do not contain any contaminants including, without limitation, pesticides, chlorinated solvents at total concentrations greater than 1000 PPM, PCB's greater than 2 PPM, or any other material classified as hezardous waste by 40 CFR part 261, Subparis C and D (implementing the Federal Resource Conservation and Recovery Act) or by any other state or local hazardous waste classification program. Should Laboratory tests find this product not in compliance with 40 CFR part 261 customer agrees to pay all disposal costs incurred.

Signed X	DATE:	08/14/17
----------	-------	----------

Plea	iasa print or type irm lasigned (or usa on elite (12 piloh) typewriter.)	•	(d) p								
A	NON-HAZARDOUS WASTE MANIFEST 1. Generator ID Number CEG	2. Page 1 of 3. Emerg	ency Response Phone 8-423-6316	4. Waste Tracking Nu	758						
1	5. Generator's Name and Mailing Address Puttland Public S	Chools Generate	or's Site Address (if different t	han mailing address)							
1	5. Generator's Name and Mailing Address Portland Public Schools Generator's Site Address (if different than mailing address) 503-916-2000 Generator's Phone: Generator's Name and Mailing Address (if different than mailing address) Generator's Site Address (if different than mailing address)										
	6. Transporter 1 Company Name COS A DIVISION OF PNE CORP. U.S. EPA ID Number WAH000014944										
	7. Transporter 2 Company Name U.S. EPA ID Number										
	8. Designated Facility Name and Site Address ORRCO INC.			U.S. EPA ID Number							
	4150 N. SUTTLE ROAD - PORTLAND, OR 97	217 USA	*:	ORD980976	892						
	Facility's Phone: 888-367-8894 HM 9. Waste Shipping Name and Description		10. Containers	11. Total 12. Unit -							
	LIANTON Flammable Liquel N.	0.9, 3, 各田	No. Type	Quantity Wt./Vol.							
GENERATOR	gas/wates/diese/ Mixtule		01 1	227 G.							
- GENE	2.	4 *									
	3. C(-707/)										
***************************************	(2.10) (2.10) (3.10) (4	1. 5.1.01	ร์ -	15	5/7158						
	13. Special Handling Instructions and Additional Information	•		1 7	Menz.						
 ,	RECEIVING RECORD#	8517/58	3	337/67							
		v 0	i Al	· · · · · · · · · · · · · · · · · · ·							
	14. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents marked and labeled/placarded, and are in all respects in proper condition for trans	port according to applicable interi	accurately described above national and national government	by the proper shipping name nental regulations.							
V	Scott Giffullan on behalf of PPS	Signafure L&L	t Zydans	lan	16015 D18 Year 7						
TRANSPORTER INTL	15. International Shipments Import to U.S. Transporter Signature (for exports only):	Export from U.S.	Port of entry/exit: Date leaving U.S.:								
RTER	16. Transporter Acknowledgment of Receipt of Materials Transporter 1 Printed/Typed Name	Signature	177111		Month Dayo Year						
ANSPC	Transporter 2 Printed/Typed Name	Signature	(Colle		Month Day Year						
H H	17. Discrepancy			2	, O · · · · · ·						
Î	17a. Discrepancy Indication Space Quantity	уре	Residue	Partial Rejection	Full Rejection						
	17b. Alternate Facility (or Generator)	Manif	est Reference Number:	U.S. EPA ID Number							
D FACILITY	Facility's Phone:			,							
ATED	17c. Signature of Alternate Facility (or Generator)	1			Month Day Year						
DESIGNATE											
1	18. Designated Facility Owner or Operator, Certification of receipt of materials covered	I by the manifest except as noted	in (lem 17a								
\\	Printed/Typed Name Cody Namy	Signature	Calf	-	Month Day Year						

GC Labels • Printed in the USA 1-800-997-6966

TRANSPORTER #1

Reorder Part# MANIFEST-C6NHWC 913-897-6966



Photographic Documentation



Photo 1. View of the pump island and former dispenser locations. Area of product lines is indicated by arrow.




Photo 2. Removal of product lines and piping.



Photo 3. Opening of the manway cover to the diesel UST.



Photo 4. View of the interior of the diesel UST.




Photo 5. Diesel tank being filled with controlled density fill (CDF).



Photo 6. Gasoline tank filled with CDF.


APPENDIX C


Boring Logs

1	DDC	PC	1 N DIX RTLAN	KON S ND, OR	EGON	İ		BORING Pipe 30
	PBS	PBS	PROJ 225	ECT NU 589.000		₹:		BORING Pipe 30 LOCATION: (See Site Plan)
GRAPHIC LOG	MATERIAL DESCRIPT	ION	GROUND- WATER	PID (PPM)	SAMPLE	SAMPLE/ TEMPORARY WELL(S)	RECOVERY (%)	COMMENTS/ WELL INSTALLATION
0.0	Well graded GRAVEL (GW) with fine sand; fine to coarse, subrou gravel; dry FILL Brown silty SAND (SM); non-plasand; damp	nded	-	0.0	Pipe 30-5		60	No odor throughout
6.0 — 8.0 — 10.0 — 11.0	Final depth 5.0 feet bgs; boring to with bentonite. Groundwater not encountered at time of exploration							

72	DDC		01 N DIX ORTLAN					BORING Tank 1 E
2	PBS	PB	S PROJ 225	ECT NU 589.000		₹:		BORING Tank 1 E LOCATION: (See Site Plan)
GRAPHIC GRAPHIC	MATERIAL DESCRIPT	ION	GROUND- WATER	PID (PPM)	SAMPLE	SAMPLE/ TEMPORARY WELL(S)	RECOVERY (%)	COMMENTS/ WELL INSTALLATION
0.0	CONCRETE							
×	Gray poorly graded GRAVEL (G	P) with						
-8	sand; fine sand; fine, subrounded dry	d gravel;	_					No odor throughout
2.0			-					
	0 20		-				30	
			_					
4.0	3.5.0		_					
\otimes	FILL		-					
\boxtimes	2.00 2.00 2.00 2.00 2.00 2.00 2.00 2.00			0.3			_	
6.0			_					
-	y b C		-					
							50	
8.0	78Q						50	
	Ø 3		_					
	Brown poorly graded SAND (SP-	SM) with	+					
10.0	silt; non-plastic; fine sand; damp			0.2			_	
10.0	Gray poorly graded GRAVEL (Gl sand; fine sand; fine, rounded gr) with	_	0.2				
-8	damp	avei,	-					
	FILL		-					
12.0	Brown poorly graded SAND (SP-	SM) with					50	
4.1	silt; low plasticity; fine sand; dan	тр	-					
+:			-					
14.0								
4.1			_	0.3	Ω.		_	
-	1.1 1.1		-		Tank 1E-15	E		
16.0					lank			
1.1								
4:1	'		_		Tank 1E-17		80	
18.0	11 1-1		-		ank			
1 1	1		_		-	_		
4.1	-1-1 -1-1 -1-1							
20.0	Final depth 20.0 feet bgs; boring		-	0.4				
1	backfilled with bentonite. Ground							
]	encountered at time of exploration	n.	_					
22.0			_					
-			-					
1								
24.0			_					
-			-					

BORING METHOD: Push Probe DRILLED BY: Western States Soil Conservation, Inc. BORING BIT DIAMETER: 21/4-inch OD LOGGED BY: D. Domenighini COMPLETED: 5/19/17





7		DDC		01 N DIX ORTLAN					BORING Tank 2 N
		PBS	PB	S PROJ 225	ECT NI 589.000		₹:		BORING Tank 2 N LOCATION (See Site Plan)
EPTH FEET	GRAPHIC LOG	MATERIAL DESCRIPT	ION	GROUND- WATER	PID (PPM)	SAMPLE NUMBER	SAMPLE/ TEMPORARY WELL(S)	RECOVERY (%)	COMMENTS/ WELL INSTALLATION
0.0 —	P 5 4	CONCRETE							
2.0 —	0.0.00.0.00	Gray well graded GRAVEL (GW sand; fine sand; fine to coarse, resubrounded gravel; dry) with ounded to					50	No odor throughout
4.0	0.0 bd 0.0			-					
6.0 —	\$0.00 a 0.0	FILL		_	0.4			_	
8.0 —	0.000.00			_				30	
10.0 —		Brown silty SAND (SM); low plas	ticity; fine	-	0.3			_	
12.0 —		sand; damp		_		Tank 2N-13		70	
14.0 —				_	0.8	 Tank 2N-15 Tar 			
16.0 —		Final depth 15.0 feet bgs; boring backfilled with bentonite. Ground encountered at time of exploration	water not n.	-		Ţ			
18.0 —				_					
20.0 —				_					
22.0 —				- - -					
24.0 —				_					

X	PBS		PROJE	ID, OR	JMBEF			BORING Tank 2 S BORING Tank 2 S LOCATION (See Site Plan)
			225	89.000				
GRAPHIC GRAPHIC	MATERIAL DESCRIPTION		GROUND- WATER	PID (PPM)	SAMPLE	SAMPLE/ TEMPORARY WELL(S)	RECOVERY (%)	COMMENTS/ WELL INSTALLATION
0.0								
2.0	Gray poorly graded GRAVEL (GI sand; fine sand; fine, rounded to subrounded gravel; dry	P) with	-				20	No odor throughout
4.0		-						
6.0	FILL	-		0.8			_	
8.0		-	2				40	
10.0	Brown poorly graded SAND (SP-	SM) with	-	0.4			-	
12.0	silt; low plasticity; fine sand; dam	p			Tank 2S-13		70	
14.0 —		-		0.9	 Tank 2S-15 Tar 		_	
16.0 —	Final depth 15.0 feet bgs; boring backfilled with bentonite. Ground encountered at time of exploratio	water not n.			_			
18.0 —		-						
20.0 —		-						
22.0 —		-						
24.0		-	-					
RILLED BY: W	IOD: Push Probe Vestern States Soil Conservation, Inc. IAMETER: 21/4-inch OD	C	OGGE OMPLI	D BY: D ETED: 5	. Domer /19/17	nighini		

	DDC)1 N DI) ORTLAN					BORING Tank 2 W
	PBS	РВ	S PROJ 225	ECT NU 589.000	JMBEF	₹:		BORING Tank 2 W LOCATION: (See Site Plan)
LATA GRAPHIC LOG	MATERIAL DESCRIPT	ION	GROUND- WATER	PID (PPM)	SAMPLE	SAMPLE/ TEMPORARY WELL(S)	RECOVERY (%)	COMMENTS/ WELL INSTALLATION
0.0								
2.0	Gray well graded GRAVEL (GW sand; fine sand; fine to coarse, subrounded gravel; dry	_					No odor throughout	
						10		
4.0			_	0.2			_	
6.0	FILL		_					
8.0							20	
10.0			-	0.1			_	
× č	Brown poorly graded SAND (SP-silt; low plasticity; fine sand; dam	-SM) with						
12.0			-		Tank 2W-13		80	
14.0 —			_	0.0	Tank 2W-15			
16.0	Final depth 15.0 feet bgs; boring backfilled with bentonite. Ground encountered at time of exploration	lwater not	-	0.0	Tan		-	
-								
18.0 —								
20.0								
22.0								
24.0								
	OD: Push Probe		LOGG	ED BY: [). Dome	nighini		

APPENDIX D

Laboratory Reports



ANALYTICAL REPORT

May 22, 2017



PBS Engineering & Env.- POR

Sample Delivery Group:

L910572

Samples Received:

05/19/2017

Project Number:

22589.000

Description:

PPS UST Decommissioning

Report To:

Scott Braunsten

4412 SW Corbett Ave

Portland, OR 97239

Entire Report Reviewed By:

Brian Ford

Buar Ford

Technical Service Representative




TABLE OF CONTENTS

ONE LAB. NATIONWIDE.

Cp: Cover Page	1	Co
Tc: Table of Contents	2	Ср
Ss: Sample Summary	3	² Tc
Cn: Case Narrative	4	2
Sr: Sample Results	5	Ss
PIPE20-3 L910572-01	5	4 ()
DISPENSER1-4 L910572-02	6	Cn
DISPENSER2-4 L910572-03	7	⁵ Sr
DISPENSER3-4 L910572-04	8	
Qc: Quality Control Summary	9	°Qc
Total Solids by Method 2540 G-2011	9	7 (1
Volatile Organic Compounds (GC) by Method NWTPHGX	10	GI_
Semi-Volatile Organic Compounds (GC) by Method NWTPHDX-SGT	11	8 Al
GI: Glossary of Terms	12	
Al: Accreditations & Locations	13	Sc
Sc: Chain of Custody	14	















	۳.
4	K

-PIPE20-3 L910572-01 Solid			Collected by Dana Domenighini	Collected date/time 05/18/17 11:50	Received date/time 05/19/17 08:45
Method	Batch	Dilution	Preparation	Analysis	Analyst
			date/time	date/time	
■otal Solids by Method 2540 G-2011	WG981348	1	05/19/17 14:16	05/19/17 14:24	MLW
'olatile Organic Compounds (GC) by Method NWTPHGX	WG981771	1.07	05/18/17 11:50	05/21/17 22:20	BMB
Semi-Volatile Organic Compounds (GC) by Method NWTPHDX-SGT	WG981488	1	05/19/17 21:33	05/20/17 17:48	ACM
			Collected by	Collected date/time	Received date/time
DISPENSER1-4 L910572-02 Solid			Dana Domenighini	05/18/17 12:25	05/19/17 08:45
Hethod	Batch	Dilution	Preparation	Analysis	Analyst
			date/time	date/time	
Total Solids by Method 2540 G-2011	WG981348	1	05/19/17 14:16	05/19/17 14:24	MLW
Volatile Organic Compounds (GC) by Method NWTPHGX	WG981771	1.04	05/18/17 12:25	05/21/17 22:42	BMB
emi-Volatile Organic Compounds (GC) by Method NWTPHDX-SGT	WG981488	1	05/19/17 21:33	05/20/17 18:02	ACM
DISPENSER2-4 L910572-03 Solid			Collected by Dana Domenighini	Collected date/time 05/18/17 12:05	Received date/time 05/19/17 08:45
Method	Batch	Dilution	Preparation	Analysis	Analyst
=			date/time	date/time	
otal Solids by Method 2540 G-2011	WG981348	1	05/19/17 14:16	05/19/17 14:24	MLW
volatile Organic Compounds (GC) by Method NWTPHGX	WG981771	1.11	05/18/17 12:05	05/21/17 23:04	· BMB
Semi-Volatile Organic Compounds (GC) by Method NWTPHDX-SGT	WG981488	1	05/19/17 21:33	05/20/17 18:15	ACM
DISPENSER3-4 L910572-04 Solid			Collected by Dana Domenighini	Collected date/time 05/18/17 12:10	Received date/time 05/19/17 08:45
lethod	Batch	Dilution	Preparation	Analysis	Analyst
			date/time	date/time	
Total Solids by Method 2540 G-2011	WG981348	1	05/19/17 14:16	05/19/17 14:24	MLW
olatile Organic Compounds (GC) by Method NWTPHGX	WG981771	1.03	05/18/17 12:10	05/21/17 23:26	вмв
Lemi-Volatile Organic Compounds (GC) by Method NWTPHDX-SGT	WG981488	1	05/19/17 21:33	05/20/17 18:29	ACM

^¹Cp

²Tc



⁴Cn

Sr

⁶Qc

'GI

⁸Al





3 Ss











⁹Sc

All sample aliquots were received at the correct temperature, in the proper containers, with the appropriate preservatives, and within method specified holding times. All MDL (LOD) and RDL (LOQ) values reported for environmental samples have been corrected for the dilution factor used in the analysis. All Method and Batch Quality Control are within established criteria except where addressed in this case narrative, a non-conformance form or properly qualified within the sample results. By my digital signature below, I affirm to the best of my knowledge, all problems/anomalies observed by the laboratory as having the potential to affect the quality of the data have been identified by the laboratory, and no information or data have been knowingly withheld that would affect the quality of the data.

Buar Ford

Brian Ford Technical Service Representative

PIPE20-3

SAMPLE RESULTS - 01

ONE LAB. NATIONWIDE.

L910572

Total Solids by Method 2540 G-2011

Collected date/time: 05/18/17 11:50

- I otal collabory	Result	Qualifier	Dilution	Analysis	Batch	
Analyte	%	dumer	Dilation	date / time	buen	
Total Solids	88.9		1	05/19/2017 14:24	WG981348	

²TC

Volatile Organic Compounds (GC) by Method NWTPHGX

	Result (dry)	Qualifier	RDL (dry)	Dilution	Analysis	Batch
nalyte	mg/kg		mg/kg		date / time	
Gasoline Range Organics-NWTPH	ND		4.81	1.07	05/21/2017 22:20	WG981771
(S) a,a,a-Trifluorotoluene(FID)	98.0		77.0-120		05/21/2017 22:20	WG981771



Semi-Volatile Organic Compounds (GC) by Method NWTPHDX-SGT

	Result (dry)	Qualifier	RDL (dry)	Dilution	Analysis	Batch
nalyte	mg/kg		mg/kg		date / time	
iesel Range Organics (DRO)	ND		4.50	1	05/20/2017 17:48	WG981488
Residual Range Organics (RRO)	ND		11.2	1	05/20/2017 17:48	WG981488
(S) o-Terphenyl	89.4		18.0-148		05/20/2017 17:48	WG981488









PAGE:

DISPENSER1-4

Collected date/time: 05/18/17 12:25

SAMPLE RESULTS - 02

ONE LAB. NATIONWIDE.

L910572



	2 (1) (1) (1) (1) (1) (1) (1) (1) (1) (1)											
	Result	Qualifier	Dilution	Analysis	Batch							
Analyte	%			date / time								
Total Solids	89.0		1	05/19/2017 14:24	WG981348							

Ср





	Result (dry)	Qualifier	RDL (dry)	Dilution	Analysis	Batch
nalyte	mg/kg		mg/kg		date / time	
Gasoline Range Organics-NWTPH	ND		4.67	1.04	05/21/2017 22:42	WG981771
(S) a,a,a-Trifluorotoluene(FID)	98.0		77.0-120		05/21/2017 22:42	WG981771





	Result (dry)	Qualifier	RDL (dry)	Dilution	Analysis	Batch	
nalyte	mg/kg		mg/kg		date / time		
iesel Range Organics (DRO)	ND		4.49	1	05/20/2017 18:02	WG981488	
Residual Range Organics (RRO)	ND		11.2	1	05/20/2017 18:02	WG981488	
(S) o-Terphenyl	94.3		18.0-148		05/20/2017 18:02	WG981488	









-DISPENSER2-4

Collected date/time: 05/18/17 12:05

SAMPLE RESULTS - 03

ONE LAB. NATIONWIDE.

L910572

Total Solids by Method 2540 G-2011

	Result	Qualifier	Dilution	Analysis	Batch	
\nalyte	%			date / time		
Total Solids	94.1		1	05/19/2017 14:24	WG981348	

Volatile Organic Compounds (GC) by Method NWTPHGX

	Result (dry)	Qualifier	RDL (dry)	Dilution	Analysis	Batch
nalyte	mg/kg		mg/kg		date / time	
Gasoline Range Organics-NWTPH	ND		4.72	1.11	05/21/2017 23:04	WG981771
(S) a,a,a-Trifluorotoluene(FID)	98.3		77.0-120		05/21/2017 23:04	WG981771

Semi-Volatile Organic Compounds (GC) by Method NWTPHDX-SGT

	Result (dry)	Qualifier	RDL (dry)	Dilution	Analysis	Batch	
-\nalyte	mg/kg		mg/kg		date / time		
iesel Range Organics (DRO)	28.6		4.25	1	05/20/2017 18:15	WG981488	
Residual Range Organics (RRO)	ND		10.6	1	05/20/2017 18:15	WG981488	
(S) o-Terphenyl	72.3		18.0-148		05/20/2017 18:15	WG981488	





















DISPENSER3-4

SAMPLE RESULTS - 04

ONE LAB. NATIONWIDE.

910572

Total Solids by Method 2540 G-2011

Collected date/time: 05/18/17 12:10

	Result	Qualifier	Dilution	Analysis	Batch	
Analyte	%			date / time		
Total Solids	88.5		1	05/19/2017 14:24	WG981348	

²Tc

Volatile Organic Compounds (GC) by Method NWTPHGX

	Result (dry)	Qualifier	RDL (dry)	Dilution	Analysis	Batch	
inalyte	mg/kg		mg/kg		date / time		
iasoline Range Organics-NWTPH	ND		4.66	1.03	05/21/2017 23:26	WG981771	
(S) a,a,a-Trifluorotoluene(FID)	97.0		77.0-120		05/21/2017 23:26	WG981771	



Cn

Semi-Volatile Organic Compounds (GC) by Method NWTPHDX-SGT

	Result (dry)	Qualifier	RDL (dry)	Dilution	Analysis	Batch	
nalyte	mg/kg		mg/kg		date / time		
iesel Range Organics (DRO)	ND		4.52	1	05/20/2017 18:29	WG981488	
Residual Range Organics (RRO)	ND		11.3	1	05/20/2017 18:29	WG981488	
(S) o-Terphenyl	76.5		18.0-148		05/20/2017 18:29	WG981488	









V D81_	. B	-]	ı iQl	J 11TY 11DN 1.1DL 1.1MN	.TY		1	10	B . NA⁻	IDE.
Method Blank	(MB)										ſ i
(MB) R3219571-1 O											—— Ср
	MB Result	MB Qualifier	MB MDL	MB RDL							2_
Analyte	%		%	%						and the state of t	² Tc
Total Solids	0.000600										³ Ss
L910553-43 C	Original Sample	(OS) • Dup	licate (Dl	JP)							<u> </u>
(OS) L910553-43 (05/19/17 14:24 • (DUP)										⁴Cn
	Original Result		Dilution	_	JP Qualifier DUP RPD Limits						5
Analyte	%	%		%	%		ne ven venner ann an a	·			⁵Sr
Total Solids	95.2	93.5	1	1.79	5						⁶ Qc
Laboratory Co	ontrol Sample (L	CS)									
(LCS) R3219571-2	05/19/17 14:24										¹GI
	Spike Amount	LCS Result	LCS Rec.	Rec. Limits	LCS Qualifier						
Analyte	%	%	%	%							8AI
Total Solids	50.0	50.0	100	85.0-115							
											⁹ Sc

ACCOUNT:


PROJECT:

SDG:

DATE/TIME:

PAGE:

Method Blank (MB))													
/B) R3219856-3 05/20/	17 18:46								1	· · · · · · · · · · · · · · · · · · ·				
	MB Result	MB Qualifier	MB MDL	MB RDL					•					
nalyte asoline Range	mg/kg		mg/kg	mg/kg					-					
rganics-NWTPH	U		0.0339	4.00										
(S) a,a,a-Trifluorotoluene(FIL	0) 100			77.0-120										
aboratory Control				<u>-</u>	le Duplicate	e (LCSD)								
1.00		י הממומחרת מ	OE /20/47 10:01	1										
.CS) R3219856-1 05/20/														
	Spike Amount	LCS Result	LCSD Result	LCS Rec.	LCSD Rec.	Rec. Limits	LCS Quali	ier <u>LCSD Q</u>		RPD Lim	iits			
nalyte	Spike Amount mg/kg	LCS Result mg/kg	LCSD Result mg/kg	LCS Rec. %	%	%	LCS Qual	ier <u>LCSD Q</u>	%	%	iits	and a second control of the second and an experience of the se	**************************************	
nalyte osoline Range ganics-NWTPH	Spike Amount mg/kg 5.50	LCS Result	LCSD Result	LCS Rec. % 108	% 100	% 70.0-133	LCS Quali	ier <u>LCSD Q</u>			iits		TO PARTIE WOULD BE AND BOOM	
CS) R3219856-1 05/20/ malyte asoline Range rganics-NWTPH (S) a,a,a-Trifluorotoluene(FIL	Spike Amount mg/kg 5.50	LCS Result mg/kg	LCSD Result mg/kg	LCS Rec. %	%	%	LCS Quali	ier <u>LCSD Q</u>	%	%	its		***************************************	
nalyte asoline Range rganics-NWTPH	Spike Amount mg/kg 5.50	LCS Result mg/kg	LCSD Result mg/kg	LCS Rec. % 108	% 100	% 70.0-133	LCS Quali	ier <u>LCSD Q</u>	%	%	iits			
nalyte asoline Range rganics-NWTPH (S) a,a,a-Trifluorotoluene(FIL	Spike Amount mg/kg 5.50	LCS Result mg/kg 5.94	LCSD Result mg/kg 5.51	LCS Rec. % 108 101	% 100 <i>101</i>	% 70.0-133 <i>77.0-120</i>		ier <u>LCSD Q</u>	%	%	iits			
nalyte asoline Range rganics-NWTPH	Spike Amount mg/kg 5.50 D)	LCS Result mg/kg 5.94 OS) • Matr	LCSD Result mg/kg 5.51 ix Spike (M	LCS Rec. % 108 101 S) • Matrix	% 100 <i>101</i> x Spike Du _l	% 70.0-133 <i>77.0-120</i> plicate (MS		ier <u>LCSD Q</u>	%	%	iits			
nalyte asoline Range rganics-NWTPH (S) a.a.a-Trifluorotoluene(FIL 909393-21 Origin	Spike Amount mg/kg 5.50 Sample (7 22:42 • (MS) F Spike Amount	LCS Result mg/kg 5.94 OS) • Matr R3219856-4 O Original Result	LCSD Result mg/kg 5.51 ix Spike (M 5/20/17 19:46 •	LCS Rec. % 108 101 (S) • Matrix (MSD) R3219 MSD Result	% 100 <i>101</i> x Spike Du _l	% 70.0-133 <i>77.0-120</i> plicate (MS		ier <u>LCSD Q</u>	%	%	RPD	RPD Lim	its	
nalyte asoline Range rganics-NWTPH (S) a,a,a-Trifluorotoluene(FIL 909393-21 Origin OS) L909393-21 05/20/1	Spike Amount mg/kg 5.50 D) al Sample (7 22:42 • (MS) F	LCS Result mg/kg 5.94 OS) • Matr	LCSD Result mg/kg 5.51 ix Spike (M 5/20/17 19:46 •	LCS Rec. % 108 101 S) • Matrix (MSD) R3219	% 100 101 × Spike Du _l 856-5 05/20/1	% 70.0-133 <i>77.0-120</i> plicate (MS	D)		7.50	20		RPD Lim	its	
nalyte pasoline Range rganics-NWTPH (S) a,a,a-Trifluorotoluene(FIL 909393-21 Origin ps) L909393-21 05/20/1	Spike Amount mg/kg 5.50 2) al Sample (7 22:42 • (MS) F Spike Amount (dry)	LCS Result mg/kg 5.94 OS) • Matr R3219856-4 O Original Result (dry)	LCSD Result mg/kg 5.51 ix Spike (M 5/20/17 19:46 •	LCS Rec. % 108 101 (S) • Matrix (MSD) R3219 MSD Result (dry)	% 100 101 x Spike Du _l 856-5 05/20/1 MS Rec.	% 70.0-133 77.0-120 plicate (MS 7 20:08 MSD Rec.	D)	Rec. Limits	7.50	20	RPD		ts	
nalyte asoline Range rganics-NWTPH (S) a.a.a-Trifluorotoluene(FIL 909393-21 Origin	Spike Amount mg/kg 5.50 Signature (Amount (Am	LCS Result mg/kg 5.94 OS) • Matr R3219856-4 O Original Result (dry) mg/kg	LCSD Result mg/kg 5.51 ix Spike (M 5/20/17 19:46 • MS Result (dry) mg/kg	LCS Rec. % 108 101 (S) • Matrix (MSD) R3219 MSD Result (dry) mg/kg	% 100 101 x Spike Du _l 856-5 05/20/1 MS Rec. %	% 70.0-133 77.0-120 Dlicate (MS 7 20:08 MSD Rec. %	D) Dilution	Rec. Limits	7.50	20	RPD %	%	its	



ACCOUNT:

PROJECT:

SDG:

DATE/TIME:

PAGE:

GLOSSARY OF TERMS

Abbreviations and Definitions

SDG	Sample Delivery Group.
MDL	Method Detection Limit.
RDL (dry)	Reported Detection Limit.
RDL	Reported Detection Limit.
ND	Not detected at the Reporting Limit (or MDL where applicable).
U	Not detected at the Reporting Limit (or MDL where applicable).
RPD	Relative Percent Difference.
(dry)	Results are reported based on the dry weight of the sample. [this will only be present on a dry report basis for soils].
Original Sample	The non-spiked sample in the prep batch used to determine the Relative Percent Difference (RPD) from a quality control sample. The Original Sample may not be included within the reported SDG.
(S)	Surrogate (Surrogate Standard) - Analytes added to every blank, sample, Laboratory Control Sample/Duplicate and Matrix Spike/Duplicate; used to evaluate analytical efficiency by measuring recovery. Surrogates are not expected to be detected in all environmental media.
Rec.	Recovery.
Qualifier	Description

The remainder of this page intentionally left blank, there are no qualifiers applied to this SDG.

, Ck

²Tc

3Ss

^⁴Cn

°Sr

QC ---









GI

PAGE:

ESC Lab Sciences is the only environmental laboratory accredited/certified to support your work nationwide from one location. One phone call, one point of contact, one laboratory. No other lab is as accessible or prepared to handle your needs throughout the country. Our capacity and capability from our single location laboratory is comparable to the collective totals of the network laboratories in our industry. The most significant benefit to our "one location" design is the design of our laboratory campus. The model is conducive to accelerated productivity, decreasing turn-around time, and preventing cross contamination, thus protecting sample integrity. Our focus on premium quality and prompt service allows us to be **YOUR LAB OF CHOICE**.

* Not all certifications held by the laboratory are applicable to the results reported in the attached report.

State Accreditations

Alabama	40660	Nevada	TN-03-2002-34
Alaska	UST-080	New Hampshire	2975
Arizona	AZ0612	New Jersey-NELAP	TN002
Arkansas	88-0469	New Mexico	TN00003
California	01157CA	New York	11742
Colorado	TN00003	North Carolina	Env375
Conneticut	PH-0197	North Carolina 1	DW21704
Florida	E87487	North Carolina ²	41
Georgia	NELAP	North Dakota	R-140
Georgia 1	923	Ohio-VAP	CL0069
Idaho	TN00003	Oklahoma	9915
Illinois	200008	Oregon	TN200002
Indiana	C-TN-01	Pennsylvania	68-02979
lowa	364	Rhode Island	221
Kansas	E-10277	South Carolina	84004
Kentucky 1	90010	South Dakota	n/a
Kentucky ²	16	Tennessee 14	2006
Louisiana	Al30792	Texas	T 104704245-07-TX
Maine	TN0002	Texas ⁵	LAB0152
Maryland	324	Utah	6157585858
Massachusetts	M-TN003	Vermont	VT2006
Michigan	9958	Virginia	109
Minnesota	047-999-395	Washington	C1915
Mississippi	TN00003	West Virginia	233
Missouri	340	Wisconsin	9980939910
Montana	CERT0086	Wyoming	A2LA
Nebraska	NE-OS-15-05		

Third Party & Federal Accreditations

A2LA - ISO 17025	1461.01	AIHA-LAP,LLC	100789
A2LA - ISO 170255	1461.02	DOD	1461.01
Canada	1461.01	USDA	S-67674
FPA-Crypto	TN00003		

¹ Drinking Water ² Underground Storage Tanks ³ Aquatic Toxicity ⁴ Chemical/Microbiological ⁵ Mold ^{n/a} Accreditation not applicable

Our Locations

ESC Lab Sciences has sixty-four client support centers that provide sample pickup and/or the delivery of sampling supplies. If you would like assistance from one of our support offices, please contact our main office. ESC Lab Sciences performs all testing at our central laboratory.



1 1 1	1	1	1]	. 3	1	3)	.]]]		1	Chain of Custody	Page of
BS Engineering and En 412 SW Corbett Avenu	6	men	tal	PBS Engi Environr 4412 SW	neering a		Į	Pres Chik			Ana	lysis /	Container / F	reservative		LIA-B B	ESC C-1-E-N-C-E-S
ortland, Oregon 97239) 			Portland Email To:												12065 Lebanon Rd Mount Juliet, TN 3 Phone: 615-758-50	7122
cott Braunsten roject escription: PPS UST Decommis	sionin			scott.bra	City/State Collected:											Phone: 800-767-54 Fest: 615-758-5855	
hone: 503-417-7737	Client P 22589	roject			Lab Projec								(1) (1) (1)	in the second		FO	0977 12
collected by (print): Dana Domenighini	Site/Fa	dilty ic) #		P.O. #											Accinum: Template:	
Collected by (signature): Owna Boneigh.	1	Same D.	ab MUST Be	Day	Quote#		h. Nandad			ă						Prelogint, TSR:	
mmediately Packed on Ice N Y		Next Da Two Oa Three D		iy (Rad Only) Jay (Rad Only)	Dat	e Resu	its Needed	No. of	NATION CO.	NWTPH-Dx	9					TSR: 98: Shipped Vie:	
Sample ID	Comp	/Grab	Matrix *	Depth	Date	c .	Time	Cntrs	3	1	Q Q		1			Ramarka	Sample # (lab only)
Pipe 20-3	Grab		SS	36+	E/18	10	1150	15	×	X			Pass (49.2 h	\$ 18 20 0 0 0		67
				44			1225	11	×	\ <u> </u>					() A		03
Dispenserz-4					\perp		1205	11	X	×			1.5 mg		2		GU
Dispensers-4 Dispensers-4 Dispensers-4	1	V	Ψ	-	1		1210	1	<u>*</u>	×							
	-			-	-			+	A								
	+		 	-				十	1	1							
	+			-				+	+	1			2 () () () () () () () () () (
	┿		+		-		 	十	1			T					
	┼				-			+-	1	1							
• Matrix: SS - Soil AIR - Air F - Filter GW - Groundwater B - Bloassay MW - WasteWater	Rema	erks:						l		.	. I I	•	oH	Temp	- Coc s	damale Record and Present/Int Igned/Accurates an arrive frace the bottler und clost which are	
DW - Drinking Water OT - Other	Semp U	les ret	imed via: FederC	ouder			racking# leceived by: (Sign	ature)				Trip	Blank Receiv	ed: Yes ASP	VOA Z	te Appl oro Headapaco reation Correct	Leania.
Relinquished by : (Signature)		_	Date:	klin -	Time:	1	PEPEIAEN AA- IN-RIS							HCL/Me TER	GH 1		
Relinquished by : (Signature)	<u> </u>		Date:	-1.	Time:	- 1	Received by: (Sign	ature)	l			Ten 3.	ZA		H Pres		y Login: Date/Time
Relinquished by : (Signature)			Date:		Time:	1	Company of the Company	vo (Sig	nature)	u	1	3	1947	Time 445	Hold:		Condition: NCF / OK



ANALYTICAL REPORT May 23, 2017

PBS Engineering & Env.- POR

Sample Delivery Group:

L910875

Samples Received:

05/20/2017

Project Number:

22589.000

Description:

PPS UST Decommissioning

Report To:

Scott Braunsten


4412 SW Corbett Ave

Portland, OR 97239

Entire Report Reviewed By:

Brian Ford

Buar Ford



17



Cp: Cover Page	1
Tc: Table of Contents	2
Ss: Sample Summary	3
Cn: Case Narrative	4
Sr: Sample Results	5
TANK1N-16 L910875-01	5
TANK1S-15 L910875-02	6
TANK1E-15 L910875-03	7
TANK2N-13 L910875-04	8
TANK2S-13 L910875-05	9
TANK2W-13 L910875-06	10
PIPE30-5 L910875-07	11
Qc: Quality Control Summary	12
Total Solids by Method 2540 G-2011	12
Volatile Organic Compounds (GC) by Method NWTPHGX	13
Semi-Volatile Organic Compounds (GC) by Method NWTPHDX-SGT	14
GI: Glossary of Terms	15
Al: Accreditations & Locations	16















Sc: Chain of Custody



TANK1N-16 L910875-01 Solid			Collected by Dana Domenighini	Collected date/time 05/19/17 08:30	Received date/time 05/20/17 08:45
lethod	Batch	Dilution	Preparation	Analysis	Analyst
			date/time	date/time	
Total Solids by Method 2540 G-2011	WG981745	1	05/20/17 14:03	05/20/17 14:11	KDW
olatile Organic Compounds (GC) by Method NWTPHGX	WG982036	1.23	05/19/17 08:30	05/22/17 17:12	DWR
ANK1S-15 L910875-02 Solid			Collected by Dana Domenighini	Collected date/time 05/19/17 09:25	Received date/time 05/20/17 08:45
Method	Batch	Dilution	Preparation	Analysis	Analyst
			date/time	date/time	
otal Solids by Method 2540 G-2011	WG981745	1	05/20/17 14:03	05/20/17 14:11	KDW
Volatile Organic Compounds (GC) by Method NWTPHGX	WG982036	1.05	05/19/17 09:25	05/23/17 13:52	JAH
TANK1E-15 L910875-03 Solid			Collected by Dana Domenighini	Collected date/time 05/19/17 11:00	Received date/time 05/20/17 08:45
ethod	Batch	Dilution	Preparation date/time	Analysis date/time	Analyst
Total Solids by Method 2540 G-2011	WG981745	1	05/20/17 14:03	05/20/17 14:11	KDW
Volatile Organic Compounds (GC) by Method NWTPHGX	WG982036	1	05/19/17 11:00	05/23/17 14:13	JAH
TANK2N-13 L910875-04 Solid			Collected by Dana Domenighini	Collected date/time 05/19/17 10:20	Received date/time 05/20/17 08:45
ethod	Batch	Dilution	Preparation	Analysis	Analyst
			date/time	date/time	
otal Solids by Method 2540 G-2011	WG981745	1	05/20/17 14:03	05/20/17 14:11	KDW
emi-Volatile Organic Compounds (GC) by Method NWTPHDX-SGT	WG981802	1	05/22/17 07:23	05/23/17 07:05	ACM
ANK2S-13 L910875-05 Solid			Collected by Dana Domenighini	Collected date/time 05/19/17 10:00	Received date/time 05/20/17 08:45
Method	Batch	Dilution	Preparation	Analysis	Analyst
			date/time	date/time	
otal Solids by Method 2540 G-2011	WG981745	1	05/20/17 14:03	05/20/17 14:11	KDW
Semi-Volatile Organic Compounds (GC) by Method NWTPHDX-SGT	WG981802	1	05/22/17 07:23	05/23/17 07:57	ACM
			Collected by	Collected date/time	Received date/time
TANK2W-13 L910875-06 Solid			Dana Domenighini	05/19/17 09:05	05/20/17 08:45
ethod	Batch	Dilution	Preparation	Analysis	Analyst
Total Solids by Method 2540 G-2011	WG981745	1	date/time 05/20/17 14:03	date/time 05/20/17 14:11	KDW
emi-Volatile Organic Compounds (GC) by Method NWTPHDX-SGT	WG981802	1	05/22/17 07:23	05/23/17 07:22	ACM
Con Volume Organic Compounds (OC) by Method WWT TibA-301	WG361602		03/22/1/ 07.23	03/23/1/ 07.22	ACM
PIPE30-5 L910875-07 Solid			Collected by Dana Domenighini	Collected date/time 05/19/17 09:20	Received date/time 05/20/17 08:45
ethod	Batch	Dilution	Preparation date/time	Analysis date/time	Analyst
otal Solids by Method 2540 G-2011	WG981745	1	05/20/17 14:03	05/20/17 14:11	KDW
olatile Organic Compounds (GC) by Method NWTPHGX	WG982036	1.15	05/19/17 09:20	05/23/17 14:34	JAH
Semi-Volatile Organic Compounds (GC) by Method NWTPHDX-SGT	WG981802	1	05/22/17 07:23	05/23/17 07:40	ACM

′Ср

²Tc

⁴Cn

⁵Sr

⁶Qc

⁷GI

⁸AI





³Ss













All sample aliquots were received at the correct temperature, in the proper containers, with the appropriate preservatives, and within method specified holding times. All MDL (LOD) and RDL (LOQ) values reported for environmental samples have been corrected for the dilution factor used in the analysis. All Method and Batch Quality Control are within established criteria except where addressed in this case narrative, a non-conformance form or properly qualified within the sample results. By my digital signature below, I affirm to the best of my knowledge, all problems/anomalies observed by the laboratory as having the potential to affect the quality of the data have been identified by the laboratory, and no information or data have been knowingly withheld that would affect the quality of the data.

Buar Ford

Brian Ford Technical Service Representative

TANK1N-16

SAMPLE RESULTS - 01

ONE LAB. NATIONWIDE.

Total Solids by Method 2540 G-2011

Volatile Organic Compounds (GC) by Method NWTPHGX

Collected date/time: 05/19/17 08:30

	Result	Qualifier	Dilution	Analysis	Batch	
Analyte	%			date / time		
Total Solids	91.3		1	05/20/2017 14:11	WG981745	







	Result (dry)	Qualifier	RDL (dry)	Dilution	Analysis	Batch
nalyte	mg/kg		mg/kg		date / time	
Sasoline Range Organics-NWTPH	ND		5.39	1.23	05/22/2017 17:12	WG982036
(S) a,a,a-Trifluorotoluene(FID)	96.7		77.0-120		05/22/2017 17:12	WG982036













TANK1S-15 Collected date/time: 05/19/17 09:25

SAMPLE RESULTS - 02

ONE LAB. NATIONWIDE.

Total Solids by Method 2540 G-2011

	200 Maria (200 Maria (
	Result	Qualifier	Dilution	Analysis	Batch
Analyte	%			date / time	
Total Solids	89.4		1	05/20/2017 14:11	WG981745



	Result (dry)	Qualifier	RDL (dry)	Dilution	Analysis	Batch	
nalyte	mg/kg		mg/kg		date / time		
Gasoline Range Organics-NWTPH	ND		4.70	1.05	05/23/2017 13:52	WG982036	
(S) a,a,a-Trifluorotoluene(FID)	103		77.0-120		05/23/2017 13:52	WG982036	













TANK1E-15

SAMPLE RESULTS - 03

ONE LAB. NATIONWIDE.

L910875

Total Solids by Method 2540 G-2011

Collected date/time: 05/19/17 11:00

entro.						
	Result	Qualifier	Dilution	Analysis	Batch	
inalyte	%			date / time		
Total Solids	86.5		1	05/20/2017 14:11	WG981745	

/olatile Organic Compounds (GC) by Method NWTPHGX

	Result (dry)	Qualifier	RDL (dry)	Dilution	Analysis	Batch	
nalyte	mg/kg		mg/kg		date / time		
asoline Range Organics-NWTPH	ND		4.63	1	05/23/2017 14:13	WG982036	
(S) a,a,a-Trifluorotoluene(FID)	102		77.0-120		05/23/2017 14:13	WG982036	





















TANK2N-13

nalyte

(S) o-Terphenyl

iesel Range Organics (DRO)

Residual Range Organics (RRO)

SAMPLE RESULTS - 04

ONE LAB. NATIONWIDE.

Collected date/time: 05/19/17 10:20

Total Solids by Method 2540 G-2011

Semi-Volatile Organic Compounds (GC) by Method NWTPHDX-SGT

Qualifier

Result (dry)

mg/kg

ND

ND

108

	Result	Qualifier	Dilution	Analysis	Batch	
. nalyte	%			date / time		
Total Solids	90.5		1	05/20/2017 14:11	WG981745	

RDL (dry)

mg/kg

4.42

11.0

18.0-148

Dilution

1

date / time

05/23/2017 07:05

05/23/2017 07:05

05/23/2017 07:05

Batch

WG981802

WG981802

WG981802

















TANK2S-13

SAMPLE RESULTS - 05

ONE LAB. NATIONWIDE.

Collected date/time: 05/19/17 10:00

Total Solids by Method 2540 G-2011

	Result	Qualifier	Dilution	Analysis	Batch
Analyte	%	-		date / time	
Total Solids	91.2		1	05/20/2017 14:11	WG981745



















	Result	Qualifier	Dilution	Analysis	Batch
.\nalyte	%			date / time	
Total Solids	91.2		1	05/20/2017 14:11	WG981745

	Result (dry)	Qualifier	RDL (dry)	Dilution	Analysis	Batch
nalyte	mg/kg		mg/kg		date / time	
iesel Range Organics (DRO)	ND		4.38	1	05/23/2017 07:57	WG981802
Residual Range Organics (RRO)	ND		11.0	1	05/23/2017 07:57	WG981802
(S) o-Terphenyl	93.5		18.0-148		05/23/2017 07:57	WG981802

TANK2W-13

nalyte

(S) o-Terphenyl

iesel Range Organics (DRO)

Residual Range Organics (RRO)

SAMPLE RESULTS - 06

ONE LAB. NATIONWIDE.

Dilution

Analysis

date / time

05/23/2017 07:22

05/23/2017 07:22

05/23/2017 07:22

Batch

WG981802 WG981802

WG981802

Total Solids by Method 2540 G-2011

Semi-Volatile Organic Compounds (GC) by Method NWTPHDX-SGT

Qualifier

Result (dry)

mg/kg

8.47

ND

93.7

Collected date/time: 05/19/17 09:05

_						
	Result	Qualifier	Dilution	Analysis	Batch	
Analyte	%			date / time		
Total Solids	86.0		1	05/20/2017 14:11	WG981745	

RDL (dry)

mg/kg

4.65

11.6

18.0-148





I	
-	
I	5
ı	Sr









PIPE30-5

SAMPLE RESULTS - 07

ONE LAB. NATIONWIDE.

L910875

Total Solids by Method 2540 G-2011

Collected date/time: 05/19/17 09:20

		T-1,770,000				The state of the s	
	Result	Qualifier	Dilution	Analysis	Batch		
.\nalyte	%			date / time			
Total Solids	78.3		1	05/20/2017 14:11	WG981745		

Volatile Organic Compounds (GC) by Method NWTPHGX

	Result (dry)	Qualifier	RDL (dry)	Dilution	Analysis	Batch
nalyte	mg/kg		mg/kg		date / time	
Gasoline Range Organics-NWTPH	ND		5.88	1.15	05/23/2017 14:34	WG982036
(S) a,a,a-Trifluorotoluene(FID)	103		77.0-120		05/23/2017 14:34	WG982036

Semi-Volatile Organic Compounds (GC) by Method NWTPHDX-SGT

	Result (dry)	Qualifier	RDL (dry)	Dilution	Analysis	Batch	
malyte	mg/kg		mg/kg		date / time		
Diesel Range Organics (DRO)	ND		5.11	1	05/23/2017 07:40	WG981802	
Residual Range Organics (RRO)	ND		12.8	1	05/23/2017 07:40	WG981802	
(S) o-Terphenyl	101		18.0-148		05/23/2017 07:40	WG981802	























ACCOUNT:


PROJECT:

SDG:

DATE/TIME:

PAGE:





Abbreviations and Definitions

SDG	Sample Delivery Group.
MDL	Method Detection Limit.
RDL (dry)	Reported Detection Limit.
RDL	Reported Detection Limit.
ND	Not detected at the Reporting Limit (or MDL where applicable).
U	Not detected at the Reporting Limit (or MDL where applicable).
RPD	Relative Percent Difference.
(dry)	Results are reported based on the dry weight of the sample. [this will only be present on a dry report basis for soils].
Original Sample	The non-spiked sample in the prep batch used to determine the Relative Percent Difference (RPD) from a quality control sample. The Original Sample may not be included within the reported SDG.
(S)	Surrogate (Surrogate Standard) - Analytes added to every blank, sample, Laboratory Control Sample/Duplicate and Matrix Spike/Duplicate; used to evaluate analytical efficiency by measuring recovery. Surrogates are not expected to be detected in all environmental media.
Rec.	Recovery.
Qualifier	Description
J	The identification of the analyte is acceptable; the reported value is an estimate.









PAGE:



GI

PAGE:

ESC Lab Sciences is the only environmental laboratory accredited/certified to support your work nationwide from one location. One phone call, one point of contact, one laboratory. No other lab is as accessible or prepared to handle your needs throughout the country. Our capacity and capability from our single location laboratory is comparable to the collective totals of the network laboratories in our industry. The most significant benefit to our "one location" design is the design of our laboratory campus. The model is conducive to accelerated productivity, decreasing turn-around time, and preventing cross contamination, thus protecting sample integrity. Our focus on premium quality and prompt service allows us to be **YOUR LAB OF CHOICE.*** Not all certifications held by the laboratory are applicable to the results reported in the attached report.

State Accreditations

Alabama	40660	Nevada	TN-03-2002-34
Alaska	UST-080	New Hampshire	2975
Arizona	AZ0612	New Jersey-NELAP	TN002
Arkansas	88-0469	New Mexico	TN00003
California	01157CA	New York	11742
Colorado	TN00003	North Carolina	Env375
Conneticut	PH-0197	North Carolina 1	DW21704
Florida	E87487	North Carolina ²	41
Georgia	NELAP	North Dakota	R-140
Georgia ¹	923	Ohio-VAP	CL0069
daho	TN00003	Oklahoma	9915
Ilinois	200008	Oregon	TN200002
ndiana	C-TN-01	Pennsylvania	68-02979
owa	364	Rhode Island	221
Kansas	E-10277	South Carolina	84004
Kentucky 1	90010	South Dakota	n/a
Kentucky ²	16	Tennessee 14	2006
ouisiana	Al30792	Texas	T 104704245-07-TX
Maine	TN0002	Texas ⁵	LAB0152
Maryland	324	Utah	6157585858
Massachusetts	M-TN003	Vermont	VT2006
Michigan	9958	Virginia	109
Minnesota	047-999-395	Washington	C1915
Mississippi	TN00003	West Virginia	233
Missouri	340	Wisconsin	9980939910
Montana	CERT0086	Wyoming	A2LA
Nebraska	NE-OS-15-05		

Third Party & Federal Accreditations

A2LA - ISO 17025	1461.01	AIHA-LAP,LLC	100789
A2LA - ISO 17025 ⁵	1461.02	DOD	1461.01
Canada	1461.01	USDA	S-67674
EPA-Crypto	TN00003		

¹ Drinking Water ² Underground Storage Tanks ³ Aquatic Toxicity ⁴ Chemical/Microbiological ⁵ Mold ^{n/s} Accreditation not applicable

Our Locations

ESC Lab Sciences has sixty-four client support centers that provide sample pickup and/or the delivery of sampling supplies. If you would like assistance from one of our support offices, please contact our main office. ESC Lab Sciences performs all testing at our central laboratory.



ACCOUNT: PROJECT: SDG: DATE/TIME:

				Billing Inf	ormation:		1	-	- 1		- 3							
PBS Engineering & Env 4412 SW Corbett Aven Portland, Oregon 9723	ue	mental PRS Engineering & Environmental				Pre: Chk				Analysi	s / Conta	ner / Pres	ervative			Chain of Custo	ESC	
Report to: Scott Braunsten				Email To:		@pbsusa.com	- E.									1 1:	12065 Lebenon I	
Project Description: PPS UST Decommi	ission	ing		<u> </u>	City/Stat		- 8										Mount Juliet, TN Phone: 615-758- Phone: 800-767- Fax: 615-758-585	87122 5858 5859
Phone: 503-417-7737 Fax: 866-727-0140	1	t Project 89.00 0			Lab Proje	ect#										1	# 9/4 F04	275
Collected by (print): Dana Domenighini	Site/	Facility II	#		P.O. #		薦	×								Į.	Acctnum:	U
Collected by (signature):		Same Du	ab MUST Be y five I y 5 Day	Dav		Quote#		TPH-6	H-Dx							Т	emplate:	
racked on Ice NY_X	-	_Two Day _Three D	10 Da	y (Rad Only)		te Results Needed	No.	FZZ	-HALM7	FIL						T	5R: B:	
Sample ID	Com	p/Grab	Matrix *	Depth	Dat	e Time	Cntrs	2	Z	士						S	hipped Via:	A Marinery
Tank IN-16	G	rab	SS	16	5/19	17 830	5	X			-					+	Remarks	Sample # (lab only)
Tank IN-18				18		840	13			×						-		01
Tankls-15				15		925		X							-			
Tank18-17				17		930	1			X						\rightarrow		OL
Tankle-is			Class I.	15		1100		×		_						-		
Tankle-17		-71		17		1605	+			×								03
TankeN-13				13		1020	39		X	_			188		+	-		
Tanken-15		211		15		1052	13			×					7	_		24
Tank 25-13				13		1000	11		X	^						_		
Tank 25-15	1	1	Y	15	V	1005	V			×								05
Matrix: 5-Soil AIR - Air F - Filter W - Groundwater B - Bioassay W - WasteWater N - Drinking Water	Remai			95%							pH Flow		Temp		COC Sea COC Sig Bottles	l Prese med/Acc	intace.	hecklist : 900 Y N
T - Other	UPS	es return Fed	ed via: ExCour	er		Tracking# 6U	36	7	130	3	98	250.0	Ouvel _		Suffici	bottle ent vol	es used: lumm sent: Applicab	
elinquished by: (Signature) American	e		Date: 5/19/1		me: 1200	Received by: (Signatu	re)		1//		****	Tracket Control		No / MeoH	VOA Zer Preserv	o Heads	mace: Correct/Ch	V 11
elinquished by : (Signature)		e Provi	Date:	TI A	me:	Received by: (Signatur	re)				Temp:	°C	TBR Bottles R	eceived:	If preserv	vation rec	quired by Lo	gin: Date/Time
elinquished by : (Signature)			Date:	Ti	me:	Received for lab by: (S	makes the	Market Street	N-		Date:	2011	Time:	:40	5-1	086		Condition: NCF / OK

PBS Engineering & Env	rironmenta	bining information:			Pres				Analysis	/ Contain	ner / Pres	ervative		Chain of Custo	dy Page 20	
4412 SW Corbett Avenue 4412		441251	W Corbett A d, Oregon 9									L·A·B S	ESC.			
Report to: Scott Braunsten			Email To: scott.br	Email To: scott.braunsten@pbsusa.com											12065 Lebanon 9 Mount Juliet, TN	37122
Project Description: PPS UST Decomm	issioning			City/State Collected: Po	Portland, OR										Phone: 615-758- Phone: 800-767- Fax: 615-758-585	saso 23734)
Phone: 503-417-7737 Fax: 866-727-0140	22589.000			Lab Project #											1 9/1	875
Collected by (print): Dana Domenighini	Site/Facility II	D#:	14	P.O. #			S,x	š						Table #		
Collected by (signature): Auna Briesser Immediately Packed on Ice Ny_X	X Next Da	Lab MUST Be ay Five by 5 Day y 10 Day ay	Day (Rad Only)	Quote #			-Hall	TPH-	四四里						Template: Prelogin: TSR: PB:	
Sample ID	Comp/Grab	Matrix *	Depth	Date			2	2	1						Shipped Via:	
Tank2W-13	Grub	Ss	13	5/19/17	5/19/17 905			X							Remarks	Sample # (lab o
Tank 2W-15			15		910	T			V							26
Pipe 30-5	1	V	5	1	920	V	X	Х								07
				1												
	-			-		- 2										
						7										
	· ·				200	- 1				j						
Matrix: 55 - Soil AIR - Air F - Filter 5W - Groundwater B - Bioassay NW - WasteWater	Remarks:							Visit		рН		Temp_		COC Second	Sample Receipt C al Present/Intact gned/Accurate:	hecklist
Samples returned via:UPSFedExCourier			rier		Tracking #			Flow Other				Correct Suffic	s arrive intact: IN t bottles used: IN lent volume sent: IN If Applicable			
Relinquished by: (Signature) Date: 5/19/17			Time: Received by: (Signature)						Trip Blan	k Receiv	но	L/MeoH	Preser	ro Headspace: vation Correct/Ch	v	
Delle-off of the state of the s			ime:	Received by: (Signatu	re)			47	Temp:	°C	Bottles	Received:	If preser	vation required by Lo	gin: Date/Time	
Relinquished by : (Signature)		Date: Time: Received for lab by: (S			ARTHUR STATE	PSE 0.000000	n		Date:	US	Time:	:45	Hold:		Condition: NCF / Dig	

APPENDIX E

DEQ Forms



OREGON DEPARTMENT OF ENVIRONMENTAL QUALITY UNDERGROUND STORAGE TANK PROGRAM

Initial (Twenty Day) Report Form for UST Cleanup Projects

	This report is due twenty (20) days from the date of the release.
DEQ USTC File No.	26-17-0573
DEQ Facility ID No.	
	Portland Public Schools
Site Address:	501 N Dixon Street, Portland, OR 97227
INITIAL CLEAN	<u>UP INFORMATION</u>
Gasoline	e
(2) Estimate quantity <a> <100 gal.	of release (based on information known to date – ● select only one): 100-499 gal.
SITE INFORMAT	$\underline{\text{TION}}$ (check $\underline{}$ yes or $\underline{}$ no)
(3) Y V N	Did any water enter the excavation? If yes, please describe and identify the depth to groundwater in feet below ground surface:
(4) Y N	Was a sheen or odor observed on any water in the excavation?
	er is encountered, soil samples from the soil/water interface must be collected and analyzed appropriate TPH method.
	sel or other non-gasoline products have been released, the water may also have to be for polynuclear aromatic hydrocarbons (PAHs). <i>Please refer to OAR 340-122-0218.</i>
(5) Y N	Was water pumped from the excavation?
Y N	If yes, did groundwater recharge within 24 hours after pumping?
Please describe	the pumping procedure and disposal option selected for the purged excavation water:
(6) Y V N	Were any water samples collected from the excavation? If yes, please describe:
(7) Y N	Have any soil and/or water sample results been received at this time? If so, please attach any lab reports.

IF GROUNDWATER HAS BEEN ENCOUNTERED, PLEASE ANSWER QUESTIONS #8-13, BELOW. IF NO WATER HAS BEEN ENCOUNTERED, PLEASE SKIP TO QUESTION #14

(8) What are the known uses of groundwater within a 500-foot radius of the release site (check √ all that apply)? ☐ non-use ☐ industrial ☐ agricultural ☐ drinking supply
(9) If groundwater in this area is being used as a drinking water supply, please check yeth the type and size of population served by the supply:
Community (community well used for drinking water year round – • select only one)
size: < <1,000 people
Intermittent use (public water used for drinking water only on a part-time basis – • select only one)
size: <pre> <50 people</pre> <pre> 50 - 300 people</pre> <pre> > 300 people</pre>
Private wells (individual private well or wells used for drinking water - • select only one)
size: <10 people 10 - 25 people >25 people
(10) Y N Is there any evidence this water supply has been or is likely to be impacted from the petroleum product release? If yes, estimate how difficult it would be to replace the existing supply: bottled water is the only alternative
on-site water treatment; bulk water delivery; new wells are available
able to connect to existing water supply
do not know what alternatives would be available
(11) Y N Are/were vapors present in on-site or nearby buildings? If yes:
A. Are you monitoring and/or mitigating any potential fire and safety hazards posed by vapors
and free product? Explain:
B. Estimate the number of people potentially affected by vapors - • select only one:
1-2 people 3-10 people >10 people
(12) Y N Are vapors or is petroleum contamination present in the utility corridors?
If yes, please explain:
(13) Y N Are natural areas located within 1/4 mile of the site? If so, please describe types (parks,
rivers, wetlands, sensitive habitats, etc.) and proximity:
(14) Y N If groundwater was not encountered in the excavation, do you believe that this cleanup project can be conducted under the requirements for an UST Cleanup Matrix site? If yes, then refer to OAR 340-122-0305 through 0360.

AREA/SITE CONDITIONS:
(15) Mean annual rainfall: <a> <20 inches <a> 20-45 inches <a> >45 inches
Soil type(s) of the naturally occurring soils, not the backfill around the tank - • select only one:
clays, compact tills, shales, and unfractured metamorphic and igneous rocks
sandy loams, loamy sands, silty clays, clay loams, moderately permeable limestone, dolomite, sandstones, moderately fractured igneous and metamorphic rock
fine and silty sands, sands and gravels, highly fractured igneous and metamorphic rock, permeable basalts and lavas, karst limestones and dolomites
SOIL MANAGEMENT
(17) If soil sample results have been received:
Y Will the level of contamination detected require removal of contaminated soil for treatment or disposal?
(18) All contaminated soil temporarily stockpiled on-site prior to treatment or disposal must be contained withir a bermed area, kept covered, and the entire area secured to prevent unauthorized access by the public. I you haven't done this, please explain why:
Note: It is a violation to standard material and a sit (DCC) on aits for most at them 20 days
Note: It is a violation to stockpile petroleum contaminated soil (PCS) on-site for greater than 30 days without a DEQ Solid Waste Letter Authorization (SWLA) Permit.
(19) If contaminated soil is currently stockpiled on-site, please indicate when disposal will occur or when treatment will begin:
(20) Estimated volume of contaminated soil (specify tons or cubic yards):
(21) Intended disposition of soils (please • select only one):
On-site/off-site treatment, Solid Waste Letter Authorization Permit Application attached.
Thermal treatment off-site at an authorized facility. Facility name:
Landfill disposal.
Name of Landfill:
Note: Please attach additional information as necessary to explain any unusual circumstances

January 2008 Page 3 of 4 05-LQ-089A

This initial report is intended to provide the Department with the basic initial information about activities associated with the release. Future reports should provide a more detailed and complete picture of the cleanup project.

Please be aware that a DEQ permit/authorization is required for the following activities:

- 1) Soil aeration, bioremediation (on-site or off-site), or on-site thermal treatment.
- 2) Water discharges to a stream/storm drain from the excavation or treatment tank.

If these activities will be included in your cleanup project, contact the regional DEQ office for the appropriate application forms, information on permit fees and guidance documents.

THIS REPORT WAS PREPARED BY:

Individual:	Dana Domenighini	Date: 6/5/17
Company:	PBS Engineering & Environmental	Phone: 503-417-7681
Address:	4412 SW Corbett Avenue	
City:	Portland	State OR Zip 97239

- 1. Please return this form to the regional office in which the site is located. If you have questions, call the contact person in your regional office.
- 2. For all tanks, except heating oil tanks, you must submit an UST Decommissioning

 Checklist and Site Assessment Report to the appropriate regional office

 within 30 days of the UST decommissioning.

 Failure to do so can result in delays to your project and
 may result in continued billing for the annual tank permit fees.
 - 3. Addresses and phone numbers for the regional offices can be found in the UST Cleanup Manual or viewed and downloaded from this DEQ Webpage: http://www.deq.state.or.us/about/locations.htm
- 4. Copies of the *UST Cleanup Manual* and other UST program forms and checklists can be viewed and downloaded from DEQ's Website:

 http://www.deq.state.or.us/lq/tanks/ust/index.htm

or in the Portland area by calling Steve Paiko at 503-229-6652

or outside the Portland area leaving a message on the UST Help Line (toll-free in Oregon) at 1-800-742-7878

KEEP A COPY OF THIS REPORT FOR YOUR FACILITY RECORDS



A. FACILITY INFORMATION:

OREGON DEPARTMENT OF ENVIRONMENTAL QUALITY UNDERGROUND STORAGE TANK PROGRAM

UNDERGROUND STORAGE TANK DECOMMISSIONING CHECKLIST AND SITE ASSESSMENT REPORT

DEQ FACILITY NUMB	BER:		
FACILITY NAME: PO	ortland Public Scho	ools	· · · · · · · · · · · · · · · · · · ·
FACILITY ADDRESS:	501 N Dixon St, F	Portland, OR 97227	
PERMITTEE PHONE:			/2/17
B. WORK PERFORI			
NATIONAL IESTIN	G SERVICE (SEE	OAR 340-150-0156 for requirements).	
DEQ Service Provider's l		Construction Contractors Board I	
DEQ Service Provider's l	Name:	Pacific Northern Enviro. Corp dba: CC	
	Name: Telephone:	Pacific Northern Enviro. Corp dba: CC 360-423-2245	
DEQ Service Provider's I DEQ Decommissioning S	Name: Telephone: Supervisor's License #:	Pacific Northern Enviro. Corp dba: CC 360-423-2245	
	Name: Telephone: Supervisor's License #: Name:	Pacific Northern Enviro. Corp dba: CCi 360-423-2245 13090	
DEQ Decommissioning S	Name: Telephone: Supervisor's License #: Name: Telephone:	Pacific Northern Enviro. Corp dba: CC 360-423-2245 13090 Scott Gilfillan 360-957-2018	<u>S</u>
DEQ Decommissioning S	Name: Telephone: Supervisor's License #: Name: Telephone:	Pacific Northern Enviro. Corp dba: CC 360-423-2245 13090 Scott Gilfillan	S
DEQ Decommissioning S	Name: Telephone: Supervisor's License #: Name: Telephone: Provider's License #: Name:	Pacific Northern Enviro. Corp dba: CC 360-423-2245 13090 Scott Gilfillan 360-957-2018	S
DEQ Decommissioning S	Name: Telephone: Supervisor's License #: Name: Telephone: Provider's License #: Name: Telephone:	Pacific Northern Enviro. Corp dba: CC 360-423-2245 13090 Scott Gilfillan 360-957-2018	S

I	Decommissioning	g/Change-in-Servic	e Notice - Date	Submitted:	3/28/17	(30 days b	efore work sta	rts).	
1	Work Start Telep	hone Notice - Num	ber issued by I	DEQ: 5/18/1	7(3 v	vorking days b	oefore work sta	arts).	
		fied: Eric Cloug							
I	Date Work Starte	d:	Date V	Vork Complet	ed: 5/31/17				
vice. C	Contamination mu	ng information if ar ust be reported by the ours after discovery	he UST permitt	tee within 24 l					-
I	Date Contaminati	on Reported: 5/2	3/17 By	,: Scott Bra	unsten				
		fied: on-line							
		_							
		narge Permit #:	····				QUIRED.		
V	Water Disposed to	o (Location):							
Ι	DEQ Solid Waste	: Disposal Permit #	:	Date:		·			
S	Soil Disposal or T	Treatment Location	:						
		ON.							
T A NIL	Z INICODNA A TIA				ar corman c	D CHANCE D			
TANK	(INFORMATIO	0,11.	PRODUCT: DIESEL, U	JSED OIL,	CLOSURE C	IK CHANGE-UN	- SERVICE?	REPL	
TANK	DEQ-UST PERMIT #	TANK SIZE IN GALLONS		JSED OIL,	TANK REMOVAL	CLOSURE IN PLACE+	CHANGE IN SERVICE+	•	ACE N

TANK ID#	DEQ-UST PERMIT #	TANK SIZE IN GALLONS	PRESENT	NEW	TANK REMOVAL	CLOSURE IN PLACE+	CHANGE IN SERVICE+	YES	NO
1	ВСНАВ	2,500	Diesel			\checkmark			V
2	ВСНАС	12,000	Gasoline			\checkmark			\checkmark
				:					

NOTE 1: Where decommissioned tank(s) are replaced by new underground storage tanks the UST permittee must submit a General Permit Registration Form to Install and Operate USTs containing information on the new tanks 30 days before installing them.

NOTE 2: Submit a soil sampling plan to the DEQ regional office and receive plan approval prior to starting work if 1) tank is to be decommissioned in-place, 2) tank contents are changed to a non-regulated substance, 3) tank contains a regulated substance other than petroleum, or 4) tank changed to non-regulated use.

TC	DICEC	TAD	INFORMATIO	NI.
H	DISPU	SAI.	. IIV H C HCIVI A I ICI	IN.

	Т	'ANK ANI	D PIPING	DISPOSAL METHOD	DISPOSAL LOCATION	OF TANK CONTENTS
TANK ID#	SCRAP	LAND- FILL	OTHER	IDENTIFY LOCATION & PROPERTY OWNER	LIQUIDS	SLUDGES
1				in place	ORRCO-Portland	
2				in place	ORRCO-Portland	
	[

NOTE 1: The tank contents, the tank and the piping may be subject to the requirements of Hazardous Waste regulations. If you have questions, contact the DEQ regional office for your area.

NOTE 2: Attach copies of the disposal receipts for the tanks and piping. If the tanks are shipped off-site for reuse provide the name, address and phone number of the person or business receiving the tanks for reuse.

NOTE 3: Attach copies of the disposal receipts for the disposal or treatment of liquid or sludge removed from the tanks

G. CONTAMINATION INFORMATION:

TANK ID#	GROUND WATER IN PIT ?	PRODUCT ODOR IN SOIL ?	PRODUCT STAINS IN SOIL ?	NUMBER OF SAMPLES	LABORATORY (NAME, CITY, STATE, PHONE)
1				:3	ESC Lab Sciences, Mt. Juliet, TN
2				3	ESC Lab Sciences, Mt. Juliet, TN

NOTE 1: Attach a copy of the laboratory report showing the results of all tests on all soil and water samples. The laboratory report must identify sample collection methods, sample location, sample depth, sample type (soil or water), type of sample container, sample temperature during transportation, types of tests, and copies of analytical laboratory reports, including QA/QC information. Include laboratory name, address and copies of chain-of-custody forms.

NOTE 2: If contamination is detected and a Level 2 or Level 3 soil matrix cleanup standard is applied to the site, attach a copy of the soil matrix analysis including methods of determining soil type, depth to groundwater, and sensitivity of uppermost aquifer.

H. SITE SKETCH general direction of separate drawing.)	: (Show location of ground slope and soi	adjacent roads, pro l sample locations.	perty lines, structur Sketch does not nee	es, dispensers, & all U d to be drawn to scale.	STs. Show North, You may attach a
	ached from PBS Engi	pooring and Environ	omontol		
See alle	ached from FBS Eligi	neering and Environ	mena		

I. SAFETY EQUIPMENT ON JOB SITE:				
Fire Extinguisher: Type/Size: ABC 20# 2ea	R	echarge Date:	1/1/18	
Combustible Gas Detector: Model: Diager xcum 2500		ibration Date:		
Oxygen Analyzer: Model: Diager xcum 2500		ibration Date:		
J. DECOMMISSIONING:				
All Tanks: N/A = Not Applicable (Check (√) Appropriate Box)	YES	NO	UNKNOWN	N/A
1. All electrical equipment grounded and explosion proof?	$\overline{\mathbf{A}}$			
2. Safety equipment on job site?	\checkmark			
3. Overhead electrical lines located?	√			
4. Subsurface electrical lines off or disconnected?	√			
5. Natural gas lines off or disconnected?				V
6. No open fires or smoking material in area?	√			
7. Vehicle and pedestrian traffic controlled?	V			
8. Excavation material area cleared? limited - in place	V			
9. Rainwater runoff directed to treatment area?				√
10. Drained and collected product from lines?	√			
11. Removed product and residual from tank?	√			
12. Cleaned tank?	✓			
13. Excavated to top of tank? limited - in place				√
14. Removed tank fixtures? (pumps, leak detection equipment)	√			
15. Removed product, fill and vent lines?	✓			
K. TANK ABANDONMENT IN-PLACE:				
All Tanks: N/A = Not Applicable (Check (√) Appropriate Box)	YES	NO	UNKNOWN	N/A
16. Sampling plan approved by DEQ? Date: 5/19/17 DEQ Staff: Eric Kelley	✓			
17. Contamination concerns fully resolved?	√			
18 Fill Material? Type: CDF - Cal Portland	√			

All Tanks: N/A * Not Applicable (Check (V) Ap	opropriste Box)	YES	NO.	UNKNOWN	515
19 Tank placement area cleared, chocks placed?	and a second				
20 Purged or ventilated tank to prevent explosion? Method used purge Texp. pre Meter reading 20.8% osy c	of elizated	Ø			
21. Were chants or sucel cables wrapped around tan					N
22. Tank removed, set on ground, blocked to preven	nt movement?				
23. Tank set on truck and secured with straps(s)?					V
24. Tank labeled before leaving site?					M
M. SITE ASSESSMENT:					
All Tanks: N/A = Not Applicable (Check (V) Ap	propriate Box)	YES	ŅO	UNKNOWN	NIA
25. Site assessed for contamination? See OAR 340-	122-0340	X			
26. Soil samples taken and analyzed?		X		F-12 25	1 1 1 1
27. Was contamination found? Date/Time: 5/23/1	7 16:30	X			
28. Was hazardous waste determination made for tar				17	X
(Liquids/shudges)? N. REQUIRED SIGNATURES:					
Permittee or Tank Owner: (Please Print) (Please Print) (Signature)	Mon			Date:	16/17
have personally reviewed this decommissioning chem to be true and complete.	ecklist and site a	ssessment	report and	the attachme	ents and find
icensed Supervisor. Scott 6.18 Wan (Please Prin					
A Peace A Mar	·/			. 1	
censed Supervisor Lett (Signature)			Date:	6/0	2/17
ave personally reviewed this decommissioning che m to be true and complete		ssessment	report and	the attachm	ents and find
	MOSE				
	ase Print)			,1	1
ensed Service Provider (Ple	<u>e</u>		Date:	6/02	417
ensed Service Provider (Ple	ase Print) ignature)		Date:	6/62	417

I.. TANK REMOVAL:

O. REPORT FILING:

This report signed by the permittee or tank owner, licensed supervisor and executive officer of the Service Provider, complete with all applicable attachments, must be filed with the DEQ regional office within 30 days after the excavation is backfilled or change-in-service is complete. **Do not wait until any site related cleanup project is completed.** Contact the DEQ regional office prior to filing this report where special circumstances exist at the site (such as water in pit, remaining pockets of contamination, etc.).

P. HELP WITH THIS REPORT:


If you have any questions about this decommissioning checklist and site assessment report, please phone your DEQ Regional Office. You can also phone the UST Program's toll-free number, 1-800-742-7878. This is a message answering machine for calls made within Oregon. Underground Storage Tank Program staff will return your calls within 24 hours. You can also send an e-mail to tanks.info@deq.state.or.us. Our regional staff are also available to answer questions regarding tank decommissioning or change-in-service requirements (see below for telephone numbers).

Q. COPIES OF THE GENERAL PERMIT TO DECOMMISSION OR COMPLETE A CHANGE-IN-SERVICE:

Obtain copies of the general permit to decommission or complete a change-in-service conditions and requirements, UST Program rules and laws and UST Cleanup rules and laws at:

- 1. Any of the DEQ offices listed below,
- 2. By calling the UST HELPLINE at 1-800-742-7878,
- 3. Send an e-mail to tanks.info@deq.state.or.us or
- 4. Downloading from the UST home page at:

http://www.deg.state.or.us/lg/tanks/ust/index.htm



EASTERN REGION / BEND

475 NE BELLEVUE, SUITE 110

BEND, OR 97701 Phone: 541-388-6146 Fax: 541-388-8283

NORTHWEST REGION 700 NE MULTNOMAH ST. PORTLAND, OR 97232

Phone: 503-229-5263 Fax: 503-229-6945 WESTERN REGION / COOS BAY

381 N SECOND STREET

COOS BAY 97420 Phone: 541-269-2721 Fax: 541-269-7984

WESTERN REGION / EUGENE 165 EAST 7TH AVE., SUITE 100

EUGENE, OR 97401 Phone: 541-686-7838 Fax: 541-686-7551 WESTERN REGION / MEDFORD 221 STEWART AVE., SUITE 201

MEDFORD, OR 97501 Phone: 541-776-6010 Fax: 541-776-6262