




Photograph shows sonic drill rig used to install extraction wells along the Tanner Creek Sewer on May 6, 2020.



Photograph shows soil removed from 7-10 feet below ground surface in Extraction Well 1 along the south side of the Tanner Creek Sewer. Dated May 6, 2020.





Photograph shows woody debris removed from 7-10 feet below ground surface in Extraction Well 2 along the north side of the Tanner Creek Sewer. Dated May 6, 2020.



Photograph shows representative woody debris and soil removed from sonic borings during installation of Extraction Wells 1 and 2. Dated May 6, 2020.





Photograph shows extraction wells installation nearly complete at the Tanner Creek Sewer site on May 6, 2020. These monuments will be removed during Phase I groundwater extraction system installation.



Photograph shows extraction wells temporarily covered with steel plate by tenants of the site on May 6, 2020.