



Oregon Department of Environmental Quality
SSO Reporting Form



This information must be submitted within 5 days of becoming aware of the overflow.
Please complete online and print for signature. Be sure to fill out all fields.

FACILITY/CONTACT INFORMATION

Name of Permittee: Eugene/Springfield Water Pollution Control Facility		
Contact Name: Matthew Green		
Phone:	Email:	County:
541-682-8617	MaGreen@eugene-or.gov	Lane ☐
DEQ Permit # (see permit face page): 102486		DEQ File #: 55999
OERS Incident #: 2024-3038	Date Reported to OERS:	
Date Reported To DEQ: 11/25/24	Today's Date: 11/26/24	
Date SSO Started (if known): 11/25/24	Time Started (if known): 10:30 am	
Date SSO Stopped (if known): 12:00 pm	Time Stopped (if known): 12:00 pm	
SSO Location: Cleanout ☐		
SSO Nearest Address: 1940 Lemming Ave.		
City: Eugene	Zip Code: 97401	
SSO Latitude (if known): 44.084860	Longitude (if known): -123.082630	
Estimate of Quantity Overflowed: 30		(Gallons) Link to estimation method
Did the SSO discharge to surface water? No ☐		
Name of waterbody:		

PUBLIC NOTIFICATION

Notified downstream drinking water sources (List Below)?
Name of drinking water facility:
Signs Posted?
Media contacted?
Who?
List any other steps taken to notify the public or state/federal agencies:

CAUSES

Cause or suspected cause of the overflow: Blockage - Other ☐ <i>If needed, attach additional sheets</i> A private contractor damaged and blocked the main line.
Rainfall in the 24 hours prior to SSO (for storm-related overflows): (inches)
Source of rainfall data: <i>If needed, attach additional sheets</i>

RECEIVED

DEC 04 2024

DEQ-SALEM OFFICE

1-in-5 year 24 hour rainfall for the sewerage system area (if known):

(in/24hr)

EMERGENCY RESPONSE AND MIGRATION

List actions taken to stop and mitigate the impact of the SSO.

For overland flow:

Taped off affected area? No



Cleaned up affected area? Yes



For SSO to surface water:

Bacteria samples taken to confirm impact?

Follow up bacteria samples taken to confirm end of impact?

Describe monitoring and results:

Affected area was disinfected and cleaned by the responding public works vector team.

For SSOs that impact buildings:

Pumped out flooded buildings?

Disinfected?

Other measures taken (describe):

Public works monitored the emergency repair work to verify that the six effected residences still had service while the repair was taking place.


Steps taken or planned to reduce, eliminate, and prevent the reoccurrence of the overflow and schedule for those steps:


N/A

COMMENTS

A private contractor damaged and blocked a main line down stream of six residences near the reported address. The contractor contacted City of Eugene PW and a subsurface vector team was sent to respond. The vector team was able to assist in removing the blockage, cleaning and disinfecting the curb drain and catch basin (#59671). 30 gallon estimate was made from cleaning the catch basin. None of the contents in the catch basin was discharged to a stormwater drain.

I CERTIFY UNDER PENALTY OF LAW THAT THIS DOCUMENT AND ALL ATTACHMENTS WERE PREPARED UNDER MY DIRECTION OR SUPERVISION IN ACCORDANCE WITH A SYSTEM DESIGNED TO ASSURE THAT QUALIFIED PERSONNEL PROPERLY GATHER AND EVALUATE THE INFORMATION SUBMITTED. BASED ON MY INQUIRY OF THE PERSON OR PERSONS WHO MANAGE THE SYSTEM, OR THOSE PERSONS DIRECTLY RESPONSIBLE FOR GATHERING THE INFORMATION, THE INFORMATION SUBMITTED IS, TO THE BEST OF MY KNOWLEDGE AND BELIEF, TRUE, ACCURATE, AND COMPLETE. I AM AWARE THAT THERE ARE SIGNIFICANT PENALTIES FOR SUBMITTING FALSE INFORMATION, INCLUDING THE POSSIBILITY OF FINE AND IMPRISONMENT FOR KNOWING VIOLATIONS.


Authorized Signature


Name (print)

11/26/2024

Date

541-682-8617

Phone Number

*You may attach additional information to this report before sending to DEQ as needed to explain the circumstances of the overflow. This information may include but is not limited to: maintenance records and bacteria monitoring results.

Upon completion, print out this form and send to the appropriate DEQ Address:

Portland-Permit Coordinator
700 NE Multnomah St., Suite 600
Portland, OR 97232

Salem-Permit Coordinator
4026 Fairview Industrial Dr. SE
Salem, OR 97302

Pendleton-Permit Coordinator
800 SE Emigrant, #330 Pendleton,
OR 97801

FOR DEQ PERSONNEL ONLY

☐ Pre-Enforcement Notice

☐ Warning Letter

No enforcement action was warranted because:

☐ The SSO was caused by unpreventable vandalism or similar force majeure; or

☐ The SSO is allowed as an exception to the permit as maintenance; or

☐ The cause of the current SSO was beyond reasonable control AND we do not expect the permittee to prevent similar SSOs in the future; or

☐ The SSO was 400 gallons or less, spilled to the ground and not reaching surface water; permittee properly reported, cleaned up, and took appropriate public notice measures; and the SSO was not part of a chronic problem.

COMMENTS

