

A. Ulrich



Oregon Department of Environmental Quality

SSO Reporting Form



This information must be submitted within 5 days of becoming aware of the overflow.
Please complete online and print for signature. Be sure to fill out all fields.

FACILITY/CONTACT INFORMATION

Name of Permittee: ROSEBURG URBAN SANITARY AUTHORITY

Contact Name: STEPHEN T. LUSCH

Phone:

Email:

County:

(541) 672-1551

STLUSCH@RUSA-OR.ORG

Douglas

DEQ Permit # (see permit face page): 100981

DEQ File #: 76771

OERS Incident #: 2025-0695

Date Reported to OERS: 03/17/2025

Date Reported To DEQ: 03/17/2025

Today's Date: 03/18/2025

Date SSO Started (if known): 03/16/2025

Time Started (if known):

Date SSO Stopped (if known): 03/16/2025

Time Stopped (if known):

SSO Location: Other (explain):

See attached

SSO Nearest Address: See attached

City: Roseburg

Zip Code: 97470

SSO Latitude (if known):

Longitude (if known):

Estimate of Quantity Overflowed: 692,000

(Gallons) [Link to estimation method](#)

Did the SSO discharge to surface water? Yes

Name of waterbody: Newton Creek, Deer Creek, South Umpqua River

PUBLIC NOTIFICATION

Notified downstream drinking water sources (List Below)? Yes

Name of drinking water facility: City of Elkton

Signs Posted? No

Media contacted? No

Who? N/A

List any other steps taken to notify the public or state/federal agencies:

Called City of Elkton, OERS, and DEQ

CAUSES

Cause or suspected cause of the overflow: Rainfall in excess of 5 years, 24 hours design storm
If needed, attach additional sheets

Rainfall in the 24 hours prior to SSO (for storm-related overflows): 2.85 - 3.79 see attached (inches)

Source of rainfall data: National Weather Services Advanced Hydrologic Prediction Service
If needed, attach additional sheets

1-in-5 year 24 hour rainfall for the sewerage system area (if known):	3.0	(in/24hr)
---	-----	-----------

EMERGENCY RESPONSE AND MIGRATION

List actions taken to stop and mitigate the impact of the SSO.

For overland flow:	Taped off affected area? No
	Cleaned up affected area? Yes
For SSO to surface water:	Bacteria samples taken to confirm impact? No
	Follow up bacteria samples taken to confirm end of impact? No

Describe monitoring and results:

South Umpqua River was flowing at 29.47 ft and 86400 cfs
Deer Creek was flowing at 15.91 ft and 6360 cfs

For SSOs that impact buildings:	Pumped out flooded buildings? N/A
	Disinfected? N/A

Other measures taken (describe):


RUSA crews monitored surcharging manholes and cleaned up debris from overland flow areas.

Steps taken or planned to reduce, eliminate, and prevent the reoccurrence of the overflow and schedule for those steps:

Roseburg Urban Sanitary Authority consistently develops and completes annual collection system improvement projects that target I&I and other problem areas to improve capacity and integrity of the system.

COMMENTS

I CERTIFY UNDER PENALTY OF LAW THAT THIS DOCUMENT AND ALL ATTACHMENTS WERE PREPARED UNDER MY DIRECTION OR SUPERVISION IN ACCORDANCE WITH A SYSTEM DESIGNED TO ASSURE THAT QUALIFIED PERSONNEL PROPERLY GATHER AND EVALUATE THE INFORMATION SUBMITTED. BASED ON MY INQUIRY OF THE PERSON OR PERSONS WHO MANAGE THE SYSTEM, OR THOSE PERSONS DIRECTLY RESPONSIBLE FOR GATHERING THE INFORMATION, THE INFORMATION SUBMITTED IS, TO THE BEST OF MY KNOWLEDGE AND BELIEF, TRUE, ACCURATE, AND COMPLETE. I AM AWARE THAT THERE ARE SIGNIFICANT PENALTIES FOR SUBMITTING FALSE INFORMATION, INCLUDING THE POSSIBILITY OF FINE AND IMPRISONMENT FOR KNOWING VIOLATIONS.


Authorized Signature

03/18/2025

Date

Stephen T Lusch

(541) 672-1551

Name (print)

Phone Number

*You may attach additional information to this report before sending to DEQ as needed to explain the circumstances of the overflow. This information may include but is not limited to: maintenance records and bacteria monitoring results.

Upon completion, print out this form and send to the appropriate DEQ Address:

Portland-Permit Coordinator
700 NE Multnomah St., Suite 600
Portland, OR 97232

Salem-Permit Coordinator
4026 Fairview Industrial Dr. SE
Salem, OR 97302

Pendleton-Permit Coordinator
800 SE Emigrant, #330 Pendleton,
OR 97801

FOR DEQ PERSONNEL ONLY

☐ Pre-Enforcement Notice

☐ Warning Letter

No enforcement action was warranted because:

☐ The SSO was caused by unpreventable vandalism or similar force majeure; or

☐ The SSO is allowed as an exception to the permit as maintenance; or

☐ The cause of the current SSO was beyond reasonable control AND we do not expect the permittee to prevent similar SSOs in the future; or

☐ The SSO was 400 gallons or less, spilled to the ground and not reaching surface water; permittee properly reported, cleaned up, and took appropriate public notice measures; and the SSO was not part of a chronic problem.

COMMENTS

ROSEBURG URBAN SANITARY AUTHORITY
SURCHARGED MANHOLES
3/16/2025

Rainfall Previous 24
hour period from
start time

1st Observed
Surcharge

Approximate End of Surcharge

Best guess total


DC3015	2077 Diamond Lake BLVD/Fulton	650 feet to Deer Creek	50 GPM	13:50	15:00	3500	3.79
DC3174	2077 Diamond Lake BLVD/Fulton	650 feet to Deer Creek	250 GPM	13:50	15:00	17,500	3.79
DC3008	1409 Diamond Lake BLVD/Fowler	350 feet to Deer Creek	100 GPM	10:30	unknown - best guess 19:00	51,000	3.1
DC6444	2115 Fowler St	100 feet to Deer Creek	100 GPM	10:30	unknown - best guess 19:00	51,000	3.1
DC5040	2115 Fowler St	100 feet to Deer Creek	100 GPM	10:30	unknown - best guess 19:00	51,000	3.1
DC6443	2115 Fowler St	100 feet to Deer Creek	100 GPM	10:30	unknown - best guess 19:00	51,000	3.1
DC4278	2115 Fowler St	100 feet to Deer Creek	100 GPM	10:30	unknown - best guess 19:00	51,000	3.1
DC3216	2115 Fowler St	100 feet to Deer Creek	150 GPM	10:30	unknown - best guess 19:00	76,000	3.1
DB210	125 Mosher	200 feet to South Umpqua River	250 GPM	11:00	17:00	90,000	3.15
C10857	371 Willow Street	3200 feet to South Umpqua River	100 GPM	9:00	15:00	36,000	2.85
C10858	371 Willow Street	3200 feet to South Umpqua River	100 GPM	9:00	15:00	36,000	2.85
N10039	Intersection of Newton Creek and Ne Stephens	2000 feet to Newton Creek	200 GPM	10:00	14:30	54,000	2.99
N10033	451 Newton Creek	2350 feet to Newton Creek	100 GPM	10:00	15:15	31,500	2.99
N10214	2655 Stewart Park	199 feet to Storm Sewer 1300 feet to Newton Creek	100 GPM	13:00	15:30	15,000	3.67
H6117	1789 Riverview (Syphon)	100 feet to South Umpqua River	225 GPM	13:00	unknown - best guess 19:00	81,000	3.67
G6288	1970 W Harvard	100 feet to South Umpqua River	Did not see surcharge, but there was evidence that it did.				
F3025	530 Portland	200 feet to South Umpqua River	Did not see surcharge, but there was evidence that it did.				
						692,000	TOTAL

The surcharge manholes where I used a best guess for ending time. I used the river levels from NOAA to gauge the stop time.

The total rainfall for the previous 24 hours was based of the start time using NOAA data from the Roseburg Regional Airport.

Rainfall at Airport Roseburg, OR (KRBG)


Date/Time	Rainfall(Inches)	Temperature(°F)	
15 Mar 2025 01:53:00 AM	0.02	45	
15 Mar 2025 02:53:00 AM	0.00	45	
15 Mar 2025 03:53:00 AM	0.01	45	
15 Mar 2025 04:53:00 AM	0.02	43	
15 Mar 2025 05:53:00 AM	0.04	43	
15 Mar 2025 06:53:00 AM	0.00	43	
15 Mar 2025 07:53:00 AM	0.01	43	
15 Mar 2025 08:53:00 AM	0.03	43	
15 Mar 2025 09:53:00 AM	0.06	43	
15 Mar 2025 10:53:00 AM	0.02	44	
15 Mar 2025 11:53:00 AM	0.03	46	
15 Mar 2025 12:53:00 PM	0.07	46	
15 Mar 2025 01:53:00 PM	0.02	49	
15 Mar 2025 02:53:00 PM	0.03	48	
15 Mar 2025 03:53:00 PM	0.04	48	
15 Mar 2025 04:53:00 PM	0.03	48	
15 Mar 2025 05:53:00 PM	0.12	46	
15 Mar 2025 06:53:00 PM	0.11	46	
15 Mar 2025 07:53:00 PM	0.07	46	
15 Mar 2025 08:53:00 PM	0.02	48	
15 Mar 2025 09:53:00 PM	0.08	48	
15 Mar 2025 10:53:00 PM	0.02	48	
15 Mar 2025 11:53:00 PM	0.05	48	
16 Mar 2025 12:53:00 AM	0.06	49	
16 Mar 2025 01:53:00 AM	0.20	50	
16 Mar 2025 02:53:00 AM	0.18	50	
16 Mar 2025 03:53:00 AM	0.26	50	
16 Mar 2025 04:53:00 AM	0.18	49	1.75
16 Mar 2025 05:53:00 AM	0.20	48	1.93
16 Mar 2025 06:53:00 AM	0.34	48	2.23
16 Mar 2025 07:53:00 AM	0.33	46	2.56
16 Mar 2025 08:53:00 AM	0.30	46	2.85
16 Mar 2025 09:53:00 AM	0.17	45	2.99
16 Mar 2025 10:53:00 AM	0.22	44	3.15
16 Mar 2025 11:53:00 AM	0.24	41	3.37
16 Mar 2025 12:53:00 PM	0.33	36	3.67
16 Mar 2025 01:53:00 PM	0.19	34	3.79
16 Mar 2025 02:53:00 PM	0.15	34	3.92
16 Mar 2025 03:53:00 PM	0.09	37	3.98
16 Mar 2025 04:53:00 PM	0.00	39	3.94
16 Mar 2025 05:53:00 PM	0.00	39	3.91
16 Mar 2025 06:53:00 PM	0.00	39	3.79
16 Mar 2025 07:53:00 PM	0.00	40	3.68
16 Mar 2025 08:53:00 PM	0.03	39	3.64
16 Mar 2025 09:53:00 PM	0.06	39	3.68
16 Mar 2025 10:53:00 PM	0.00	42	3.60
16 Mar 2025 11:53:00 PM	0.00	43	3.58
17 Mar 2025 12:53:00 AM	0.01	43	3.54
17 Mar 2025 01:53:00 AM	0.00	42	3.48
17 Mar 2025 02:53:00 AM	0.00	43	3.28
17 Mar 2025 03:53:00 AM	0.00	43	3.10
17 Mar 2025 04:53:00 AM	0.00	42	2.84
17 Mar 2025 05:53:00 AM	0.00	43	2.66
17 Mar 2025 06:53:00 AM	0.00	41	2.46
Total	4.44		



South Umpqua River

Surcharged Manhole
D6210





STEPHENS

OAKLAND


DEE

WALNUT

GARDEN VALLEY


WILLOW


SURCHARGED MANHOLES
C10857, C10858



Surcharged Manholes
N10039, N10033

Newton Creek





STEWART PARK

2041

2021

1801

South Umpqua River

STEWART

Surcharged Manhole
G6288

1970

2108


523

524



Upstream gauge unavailable

Downstream gauge unavailable



Reliability of the Forecast:

NOTE: Forecasts are issued routinely year-round.

Flood Impacts	Gauge Info
12 - Widespread flooding of structures and farmland is occurring.	Coordinates43.2192, -123.279
11.5 - Water begins to cover Douglas Avenue west of Dawson Road.	RFCNWRC
	StateOR

