



Oregon

Tina Kotek, Governor

Department of Environmental Quality

Northwest Region

700 NE Multnomah Street, Suite 600

Portland, OR 97232

(503) 229-5696

FAX (503) 229-6124

TTY 711

January 31, 2025

Tillamook Farmers' Co-Operative, Inc.
Attn: Laurie Wicker
1920 Main Ave N
Tillamook, OR 97141-9209

RE: UST Compliance Inspection
DEQ UST# 12105 - 1920 MAIN AVE N

Dear Tillamook Farmers' Co-Operative, Inc.:

The Oregon Department of Environmental Quality (DEQ) is conducting underground storage tank (UST) inspections throughout Oregon. The purpose of this letter is to inform you that your facilities, among others, has been selected for inspection. A thorough inspection of your facilities will be conducted to determine compliance with state and federal UST requirements. **The date you receive this letter is the date that the inspection starts.** If you have work done after that date, you will need to have the previous set of records available for evaluation in addition to the most recent records.

If I do not hear from you, the inspection for these facilities is scheduled for March 6, 2025, starting at approximately 9 am at the DEQ UST #s listed below.

March 6th at 9 am:

- DEQ UST#12105 - 1920 MAIN Ave N, Tillamook, OR

Please note that the inspection will require uninterrupted participation and attendance by you or a knowledgeable assistant. For the inspection you need to provide access to tank sumps, under dispenser areas, cathodic protection rectifiers, and leak monitoring equipment. **DEQ will not touch the equipment or enter the facility, if you are unable to assist with equipment access, please have your UST Service Provider there.** This inspection may also include review of Stage I Vapor Recovery.

DEQ staff will not assist with operating tank gauges or open sump lids. Please be prepare to open and operate these system parts.

The DEQ requests the following documentation be submitted electronically via email prior to the inspection:

- Line and leak detector testing results for the past three years,
- Monthly tank leak detection records, one year
- Class A, B, and C training documentation,
- Financial responsibility mechanism,
- Annual tank gauge certification for the past three years
- Spill prevention testing records, was due by October 2020
- Monthly walkthroughs, one year
- Overfill Prevention Equipment testing, was due by October 2020
- Cathodic protection testing (if applicable).

Please submit these records to ingrid.gaffney@deq.oregon.gov for review. If these records cannot be submitted prior to the inspection, please have them available for review at the facility.

Owners must also be able to operate the tank gauge and print out applicable reports such as the tank setup and in-tank alarm reports. Owners also must be able to sound high fill over alarm from the tank gauge, if applicable.


DEQ will not touch any equipment, if you are unable to assist with equipment access, please have your UST Service Provider there. DEQ will need to observe what equipment is in the tank top sumps and under the dispensers. If ball floats are the primary overfill protection device, these will need to be verified during the inspection, please be able to locate and remove the ball floats.

If violations are found at the time of the inspection without prior notification, DEQ is required to initiate enforcement action. For UST violations, enforcement usually begins with a field citation option, which is much like paying a traffic ticket and making corrections.

Some enforcement situations including repeat violations will go through a longer and more formal process including civil penalties.

Thank you for your cooperation. I can be reached at 503-875-1246 ingrid.gaffney@deq.oregon.gov to answer any questions you may have and assist you in the preparation for your inspection.

Sincerely,



Ingrid Gaffney
UST Compliance Specialist

Oregon Department of Environmental Quality - Underground Storage Tank Program
Technical Compliance Inspection - UST Inspection Report

Inspector: Ingrid Gaffney Date: 3/6/2025

Time: 9AM

Facility: 12105

I. Site Information

Facility Name:	<u>Tillamook Farmers' Coop</u>	Permittee:	<u>Tillamook</u>	Contact:	<u>Laurie Wicker</u>
Site Address:	<u>1920 Main Ave. N</u>	Organization:	<u>FARMERS'</u>	Phone:	<u>503-842-</u>
City:	<u>Tillamook, OR 97141-9209</u>	Phone:	<u>COOP</u>		<u>4457</u>

II. Tank Information

DEQ Permit #	<u>BFFER</u>	<u>BFFEC</u>	<u>BFFED</u>		
Estimated Gallons	<u>20,000</u>	<u>12,000</u>	<u>8,000</u>		
Substance	<u>GASOLINE</u>	<u>DIESEL</u>	<u>GASOLINE</u>		
Tank Material	<u>Steel Clad</u> <u>Fiber</u>				
Tank Install Date	<u>2/20/2002</u>				
Pipe Material	<u>DW Flex plastic</u> <u>APT</u>				
Pipe Type	<u>Pressure</u>				
Pipe Install Date	<u>1/24/2024</u> <u>2/20/2002</u>				
Overfill Device	<u>Auto shut off</u>				

Notes and Comments from the UST database:

☒ Check file before conducting inspection

* New line install 2024

If tanks are manifolded, which tanks:

III. Operating Certificate			Compliance		<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<input checked="" type="checkbox"/> Current	<input checked="" type="checkbox"/> Accurate	<input checked="" type="checkbox"/> Posted for delivery drive to observe				
IV. Operator Training			Compliance		<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Class A/B Operator	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	Name:	<u>Josi Park</u>	Date:	<u>2/19/2025</u>
Class C Operator	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> Cardlock	<u>Alex Gutierrez 2</u>		<u>2/25/2025</u>
V. Financial Responsibility			Compliance		<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Type of coverage:	<u>INSURANCE</u>	Begin Date:	<u>6/30/2024</u>	End Date:	<u>6/30/2025</u>	
Coverage amount correct:	<u>\$1,000,000</u>	Number of tanks covered:	<u>3</u>			
Financial responsibility could also be in the form of self insurance, bonds, local government, trust fund, and or guarantee						
VI. Walkthrough Requirements			Compliance		<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Spill prevention and release detection equipment checked monthly?					<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Tank top sumps checked annually?					<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No

VII. Release Detection

12105

a) Annual Release Detection Operability Testing (Sometimes referred to as Tank Gauge Certification)

Compliance

☐ Yes ☒ No

Date of last testing: 2/14/2024 2/17/2023 3/30/2022

Last three tests available? ☒ Yes ☐ No

b) Piping Release Detection (Check all that apply)

☒ Pressurized Piping

☒ Mechanical Leak Detector (MLLD)

☐ Electronic Leak Detector (ELLD) - check for swiftcheck requirement

Date of last testing: 2/14/2024 2/17/2023 3/30/2022

Last three tests available? ☒ Yes ☐ No

Number of lines tested: 3

Number of LD tested: 3

Leak detector manufacturer make and model: 99LD 2000

Tank gauge manufacturer make and model: Franklin Incon

MLLD on turbine manifold?

☐ Yes ☐ No

MLLD product appropriate? (Example, diesel Red Jacket FX series on diesel system?)

☐ Yes ☐ No

If ELLD and no line testing: Annual 0.1 gph results from tank gauge?

☐ Yes ☐ No

☒ Interstitial Monitoring

[Monthly records must include, date system was checked, observations made, initials of person checking. Electronic records must include power status (on or off), alarm indication status (yes or no) and sensor malfunction notes (yes or no).]

Date of last sump testing: 2/5/2024 2/14/2024 1/9/2024

only 2024 required new lines in

Last two tests available? ☒ Yes ☐ No

Date of last sensor testing: 2/14/2024 1/9/2024

Last three tests available? ☒ Yes ☐ No

Float sensors installed correctly?

☒ Yes ☐ No

Interstitial space opened to sump?

☒ Yes ☐ No

Presence of water in sumps?

☐ Yes ☒ No

☐ Safe Suction

Check valve directly below suction pump? ☐ Yes ☐ No

c) Monthly Tank Release Detection (Check all that apply)

☐ Tank Gauge ☐ CSLD ☒ SCALD ☐ Static

Are correct tank sizes programmed at tank gauge?

☒ Yes ☐ No

Tank diameter/length seem appropriate?

☒ Yes ☐ No

Are tanks manifolded?

☐ Yes ☒ No

If so, tank gauge testing setup for manifolded tanks?

☐ Yes ☐ No

If Veeder Root tank gauge leak detection

☐ CSLD set at 99%

☐ Thermal coefficient set correctly?

(Gasoline 0.00070; Diesel 0.00045)

If Incon/Franklin tank gauge leak detection

☒ If SCALD is Vol Qual set to 14% (or 99% confidence)

☐ Is API gravity set correctly?

(Regular 63.5; Plus 62.8; Super 51.3; Diesel 32.8)

For all tank gauges doing static tests

(Static tests require tank to be 50% full for a valid test)

☐ Interstitial Monitoring [Monthly records must include, date system was checked, observations made, initials of person checking.

Electronic records must include power status (on or off), alarm indication status (yes or no) and sensor malfunction notes (yes or no).]

☐ SIR

Ensure pass or fail results within 30-day period. Inconclusive result means release detection requirement not met

Tank release detection records available during inspection

(3 tanks) missing sensor reports

T1: <input checked="" type="checkbox"/> Jan <input checked="" type="checkbox"/> Feb <input type="checkbox"/> Mar <input type="checkbox"/> Apr <input type="checkbox"/> May <input type="checkbox"/> Jun <input type="checkbox"/> Jul <input type="checkbox"/> Aug <input type="checkbox"/> Sep <input type="checkbox"/> Oct <input type="checkbox"/> Nov <input type="checkbox"/> Dec
T2: <input checked="" type="checkbox"/> Jan <input checked="" type="checkbox"/> Feb <input type="checkbox"/> Mar <input type="checkbox"/> Apr <input type="checkbox"/> May <input type="checkbox"/> Jun <input type="checkbox"/> Jul <input type="checkbox"/> Aug <input type="checkbox"/> Sep <input type="checkbox"/> Oct <input type="checkbox"/> Nov <input type="checkbox"/> Dec
T3: <input checked="" type="checkbox"/> Jan <input checked="" type="checkbox"/> Feb <input type="checkbox"/> Mar <input type="checkbox"/> Apr <input type="checkbox"/> May <input type="checkbox"/> Jun <input type="checkbox"/> Jul <input type="checkbox"/> Aug <input type="checkbox"/> Sep <input type="checkbox"/> Oct <input type="checkbox"/> Nov <input type="checkbox"/> Dec
T4: <input checked="" type="checkbox"/> Jan <input checked="" type="checkbox"/> Feb <input type="checkbox"/> Mar <input type="checkbox"/> Apr <input type="checkbox"/> May <input type="checkbox"/> Jun <input type="checkbox"/> Jul <input type="checkbox"/> Aug <input type="checkbox"/> Sep <input type="checkbox"/> Oct <input type="checkbox"/> Nov <input type="checkbox"/> Dec
T5: <input checked="" type="checkbox"/> Jan <input checked="" type="checkbox"/> Feb <input type="checkbox"/> Mar <input type="checkbox"/> Apr <input type="checkbox"/> May <input type="checkbox"/> Jun <input type="checkbox"/> Jul <input type="checkbox"/> Aug <input type="checkbox"/> Sep <input type="checkbox"/> Oct <input type="checkbox"/> Nov <input type="checkbox"/> Dec

Inspector: _____	Date: _____	Time: _____	Facility: <u>12105</u>
VIII. Spill Prevention		Compliance	
Date(s) of testing: <u>2/28/2025</u>		Number of spill buckets tested? <u>3</u>	
Did spill bucket pass most recent testing? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If no, was spill bucket replaced/repaired? <input type="checkbox"/> Yes <input type="checkbox"/> No		
During inspection, visual damage to spill bucket? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
<input checked="" type="checkbox"/> Hydrostatic testing (test takes one hour to complete) <input type="checkbox"/> Vacuum test (test takes 1 minute, ending vacuum must be 26 inches water column or greater)			
IX. Overfill Prevention		Compliance	
Date(s) of testing: <u>2/28/2025</u>		New install 2024 tested	
Overfill device pass most recent testing? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If no, overfill device replaced? <input type="checkbox"/> Yes <input type="checkbox"/> No		
Overfill method that was tested: <input type="checkbox"/> Alarm <input checked="" type="checkbox"/> Flapper <input type="checkbox"/> Ball Float			
<u>Overfill Alarm</u>			
Alarm sounds when tank is 90% full	<input type="checkbox"/> Yes	<input type="checkbox"/> No	
Driver can see or hear alarm at point of transfer?	<input type="checkbox"/> Yes	<input type="checkbox"/> No	
Sound alarm from tank gauge during inspection?	<input type="checkbox"/> Yes	<input type="checkbox"/> No	
<u>Flapper Valve</u>			
Testing verified the valve automatically restricts flow at 95%	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Visual observation of flapper on day of inspection?	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
<u>Ball Float</u>			
Testing verified the ball float automatically restricts flow at 90%	<input type="checkbox"/> Yes	<input type="checkbox"/> No	
Visual observation of ball float during inspection?	<input type="checkbox"/> Yes	<input type="checkbox"/> No	
X. Corrosion Protection		Compliance	
<input type="checkbox"/> Cathodic	<input type="checkbox"/> Galvanic	<input type="checkbox"/> Impressed Current	
Steel tank with cathodic?	<input type="checkbox"/> Yes	<input type="checkbox"/> No	
Steel pipes with cathodic?	<input type="checkbox"/> Yes	<input type="checkbox"/> No	
Steel flex-lines with cathodic?	<input type="checkbox"/> Yes	<input type="checkbox"/> No	
Date of cathodic test: _____	<input type="checkbox"/> Yes	<input type="checkbox"/> No	
Last two tests available?	<input type="checkbox"/> Yes	<input type="checkbox"/> No	
Did last test pass?	<input type="checkbox"/> Yes	<input type="checkbox"/> No	
If not:	<input type="checkbox"/> Yes	<input type="checkbox"/> No	
Was failed test reported to DEQ?	<input type="checkbox"/> Yes	<input type="checkbox"/> No	
Was system repaired?	<input type="checkbox"/> Yes	<input type="checkbox"/> No	
Date of repair? _____	<input type="checkbox"/> Yes	<input type="checkbox"/> No	
Cathodic retested within 6 mos. of repair?	<input type="checkbox"/> Yes	<input type="checkbox"/> No	
Date of retesting? _____	<input type="checkbox"/> Yes	<input type="checkbox"/> No	
If impressed current system:	<input type="checkbox"/> Yes	<input type="checkbox"/> No	
Rectifier Operational?	<input type="checkbox"/> Yes	<input type="checkbox"/> No	
Rectifier log maintained?	<input type="checkbox"/> Yes	<input type="checkbox"/> No	
Rectifier been operating continuously	<input type="checkbox"/> Yes	<input type="checkbox"/> No	
<input type="checkbox"/> Tank Lining			
Date of last test? _____	<input type="checkbox"/> Yes	<input type="checkbox"/> No	
Pressure test conducted after tank lining inspection?	<input type="checkbox"/> Yes	<input type="checkbox"/> No	

XI. General notes from inspection

Representative onsite: Laurie Wicker

email:

laurie@hillamookfarmerscoop.com

²⁰²⁵
* 2021 overfill and spill reports from Mascott ✓

• pipe install 1/2024 - ✓

Violations

• 7/8 dispense diesel lue - liquid/retro present -

+ no walkthroughs

* sensor reports not saved. LD tank reports kept/maintained.

Compliance Determination:

☐ No Violations Observed

☒ Observed violations resulting in enforcement

Inspector Signature:

Ingrid Maggner

Date:

3/6/2025



**OREGON DEPARTMENT OF ENVIRONMENTAL QUALITY
INSPECTION PHOTOLOG**

**FACILITY NAME: Tillamook Farmers' Coop #12105
INSPECTION DATE: March 6, 2025**

Page 1



1: 1920 Main Ave N, Tillamook, OR 97141



2: Tank nest looking west



**OREGON DEPARTMENT OF ENVIRONMENTAL QUALITY
INSPECTION PHOTOLOG**

**FACILITY NAME: Tillamook Farmers' Coop #12105
INSPECTION DATE: March 6, 2025**

Page 1



3: Regular fill



4: Regular sump



OREGON DEPARTMENT OF ENVIRONMENTAL QUALITY
INSPECTION PHOTOLOG

FACILITY NAME: Tillamook Farmers' Coop #12105
INSPECTION DATE: March 6, 2025

Page 1



5: Regular vapor return



6: Premium fill



**OREGON DEPARTMENT OF ENVIRONMENTAL QUALITY
INSPECTION PHOTOLOG**

**FACILITY NAME: Tillamook Farmers' Coop #12105
INSPECTION DATE: March 6, 2025**

Page 1



7: Premium sump



8: Diesel fill



**OREGON DEPARTMENT OF ENVIRONMENTAL QUALITY
INSPECTION PHOTOLOG**

**FACILITY NAME: Tillamook Farmers' Coop #12105
INSPECTION DATE: March 6, 2025**

Page 1



9: capped-off vapor return for diesel



10: Dispenser area



OREGON DEPARTMENT OF ENVIRONMENTAL QUALITY
INSPECTION PHOTOLOG

FACILITY NAME: Tillamook Farmers' Coop #12105
INSPECTION DATE: March 6, 2025

Page 1



11: Diesel sump



12: Dispenser #1/2



OREGON DEPARTMENT OF ENVIRONMENTAL QUALITY
INSPECTION PHOTOLOG

FACILITY NAME: Tillamook Farmers' Coop #12105
INSPECTION DATE: March 6, 2025

Page 1



13: UDC #2



14: Dispenser #7/8



**OREGON DEPARTMENT OF ENVIRONMENTAL QUALITY
INSPECTION PHOTOLOG**

**FACILITY NAME: Tillamook Farmers' Coop #12105
INSPECTION DATE: March 6, 2025**

Page 1



15: Potential release in UDC #7/8



16: Diesel line in UDC# 7/8 potential source of release



OREGON DEPARTMENT OF ENVIRONMENTAL QUALITY
INSPECTION PHOTOLOG

FACILITY NAME: Tillamook Farmers' Coop #12105
INSPECTION DATE: March 6, 2025

Page 1



17: DEF dispenser piped to above ground tank



18: UDC for DEF



**OREGON DEPARTMENT OF ENVIRONMENTAL QUALITY
INSPECTION PHOTOLOG**

**FACILITY NAME: Tillamook Farmers' Coop #12105
INSPECTION DATE: March 6, 2025**

Page 1



19: UDC #5/6



20: UDC #3/4



**OREGON DEPARTMENT OF ENVIRONMENTAL QUALITY
INSPECTION PHOTOLOG**

**FACILITY NAME: Tillamook Farmers' Coop #12105
INSPECTION DATE: March 6, 2025**

Page 1



21: Emergency shut-off switch



Program Enforcement No. 2025-FC-9789

This section for
DEQ use only

Department of Environmental Quality
Underground Storage Tank Program

Field Citation
For UST Violations

Page 1 of 3

DEQ Information		UST Facility Information	
Inspection Date:	03/06/2025	Facility ID#:	12105
Inspector:	Ingrid GAFFNEY	Facility Name:	TILLAMOOK FARMERS' CO-OP
DEQ Office:	700 NE Multnomah St Ste 600	Facility Address:	1920 MAIN AVE N, TILLAMOOK, Oregon 97141
Phone #:	503-229-5048	County:	Tillamook

Oregon DEQ inspected the facility listed above and identified the UST violations listed on page 3 of this Field Citation.

Field Citation Issued:	<input type="checkbox"/> In Person	<input checked="" type="checkbox"/> By Email	<input type="checkbox"/> Both	Date Issued: 03/07/2025
Facility Representative Present During Inspection:	Laurie Wicker			<input type="checkbox"/> Permittee <input type="checkbox"/> Owner <input type="checkbox"/> Other
Name of Permittee or Owner:	Tillamook Farmers' Co-Op, Inc.			
Mailing Address:	1920 Main Ave N , Tillamook Oregon 97141			
Field Citation Penalty – See Page 3 for detailed listing of each violation.				\$ 750

Check payable to: DEQ Financial Services LBX3615; P.O. Box 3615; Portland OR 97208-3615

Or pay online through your YDO account

This Field Citation is issued in accordance with the requirements for the expedited enforcement of underground storage tank (UST) violations, OAR 340-150-0250.

Owner or Permittee should select Option 1 or Option 2 below and return a signed copy of this for to DEQ by the following date:

04/07/2025

DEQ Revenue Section
700 NE Multnomah St. #600
Portland, Oregon 97232

Check one option

- ☐ **Option 1** - I acknowledge that the listed violation(s) have occurred and I am remitting the listed field citation penalty.
- ☐ **Option 2** - I do not want to participate in the expedited enforcement process and understand that my file will be referred to the Department's Office of Compliance and Enforcement for formal enforcement action.

Name:	Owner / Permittee
Signature:	Date:

Important

Read pages 2 and 3 for more information about your options and a detailed listing of violations and compliance requirements.

Field Citation Requirements

The permittee or owner should select Option 1 or Option 2 and return a signed copy of Page 1 of the Field Citation form within thirty (30) days of issuance of the Field Citation. If the permittee or owner fails to sign and send Page 1 of the Field Citation form back or pay the penalty within thirty days, Option 1 expires, the Field Citation will serve as a Pre-Enforcement Notice (PEN) and the permittee and owner will be subject to formal enforcement including the imposition of civil penalties in accordance with OAR Chapter 340, Division 12.

The permittee or owner must complete the actions required to correct the violations listed on the Field Citation by the date specified to prevent further enforcement action by DEQ.

Option 1:

By checking Option 1 the permittee or owner acknowledges that the violations listed on Page 3 of this Field Citation have occurred and agrees to pay the established penalty.

By submitting payment of the penalty amount, the responding permittee or owner agrees to accept the field citation as a final order of the Environmental Quality Commission (commission) and waives any and all rights and objections to the form, content, manner of service and timeliness of the Field Citation; to a contested case hearing and judicial review of the Field Citation [OAR 340-150-0250(6)]; and to service of a copy of this Final Order (*i.e.*, no other copy will be provided).

Upon the Department's receipt of payment of the penalty amount set forth in the Field Citation, the Field Citation becomes a Final Order of the Commission that:

1. Imposes upon the permittee or owner a civil penalty in the amount listed on Page 1 of this Field Citation; and
2. Requires the permittee or owner to satisfactorily complete the requirements and actions necessary to correct the violations documented by the dates set forth on Page 3 of this Field Citation.

Failure by the permittee or owner to complete the actions set forth on Page 3 of the Field Citation by the specified date violates the Commission Order and subjects the permittee and owner to a formal enforcement action including the imposition of additional civil penalties.

Option 2:

The permittee or owner may deny that the violations as listed on Page 3 of this Field Citation have occurred or contest the Field Citation process by checking Option 2 and submitting to the Department a signed copy of Page 1 of the Field Citation. In that event, the Field Citation will serve as a Pre-Enforcement Notice (PEN) and the permittee and owner will be subject to formal enforcement for those violations set forth in the Field Citation, including the imposition of civil penalties in accordance with OAR Chapter 340, Division 12. Civil penalties that will be imposed by the formal enforcement process will exceed the Field Citation penalties for the same violation(s).

The Department appreciates your cooperation and efforts to comply with the regulations for underground storage tank systems.

DATE ISSUED: 03/07/2025

PROGRAM ENFORCEMENT No.: 2025-FC-9789

FACILITY ID: 12105

Page 3 of 3

Violation #1:	Failure to investigate or confirm a suspected release.		
*TCR:			
Corrective Action:	Initiate investigation to confirm suspected release in UDC 7/8 within 5 days. Perform necessary repairs and submit to DEQ by April 7, 2025		
Rule Citation: OAR 340-150-0163(1)(f)	Penalty Amount: \$ 300	Correct Violation by: 04/07/2025	Date Violation Corrected:
Violation #2:	Failure to conduct monthly periodic operation and maintenance walkthrough inspection by 10/01/20 and each month thereafter.		
*TCR:			
Corrective Action:	2. Complete monthly walkthrough inspection within 30 days. Submit walkthrough inspection form to DEQ by April 7, 2025		
Rule Citation: OAR 340-150-0315(1)(a)(A)	Penalty Amount: \$ 150	Correct Violation by: 04/07/2025	Date Violation Corrected:
Violation #3:	Failure to keep the most recent 12 consecutive months of interstitial monitoring records for review and inspection.		
*TCR:			
Corrective Action:	Conduct monitoring as required by rule (print daily sensor status). Maintain records. Submit copies of recent sensor reports to DEQ by April 7, 2025.		
Rule Citation: OAR 340-150-0465(6)	Penalty Amount: \$ 300	Correct Violation by: 04/07/2025	Date Violation Corrected:
Violation #4:			
*TCR:			
Corrective Action:			
Rule Citation: OAR	Penalty Amount: \$	Correct Violation by:	Date Violation Corrected:
Violation #5:			
*TCR:			
Corrective Action:			
Rule Citation: OAR	Penalty Amount: \$	Correct Violation by:	Date Violation Corrected:
Violation #6:			
*TCR:			
Corrective Action:			
Rule Citation: OAR	Penalty Amount: \$	Correct Violation by:	Date Violation Corrected:
	<div style="background-color: yellow; padding: 5px;"> Total Penalty Amount 750 (This Page): \$ </div>		

YOU MUST CORRECT THE VIOLATIONS AS REQUIRED , SIGN THE STATEMENT BELOW AND

RETURN THIS FORM TO THE DEQ INSPECTOR LISTED ON PAGE 1 ON OR BEFORE: 04/07/2025

Retain a copy of this form and all documentation of corrective actions for your records.

I hereby certify that the UST violations noted above have been corrected: _____ / _____

Permittee/Owner Signature

Date

From: laurie@tillamookfarmerscoop.com
To: [GAFFNEY Ingrid * DEQ](#)
Subject: work order for dispenser 7/8
Date: Thursday, March 6, 2025 11:49:01 AM

Hi Ingrid,

Central Services will be here tomorrow or Monday for repair of the dispenser on pump 7/8. It was good meeting you today. Thanks for all of the information.

Thanks,

Laurie Wicker
General Manager
Tillamook Farmers Coop
503-842-4457



16823

CLIENT LOCATION:

Tillamook Farmers
Tillamook Farmers
1920 Main Street
Tillamook , OR 97141

☒ DATE: 03/11/2025

☒ BILLED TO:

Tillamook Farmers
1920 Main Street
Tillamook , OR 97141

DESCRIPTION:

☒ leak 7/8 diesel

CALL TYPE:

1 - Service

WORK PERFORMED:

Site advised DEQ found DSL in UDC and surmised a leak. Found small amount of liquid on DSL side of UDC. Placed dispenser in standalone, authorized DSL and cleaned UDC, found no drips or leaks. Pressurized each product and inspected, found no evidence of leak on any product. Site personnel in charge of overseeing compliance testing stated recent testing and filter changes could be cause of DSL. Placed dispenser back in service and monitored. 3/11/25 CJC ☒

<input checked="" type="checkbox"/> ASSIGNMENTS				
EMPLOYEE NAME	DATE	TRAVEL TIME (MINS)	DETAILS	TOTAL HOURS
<input checked="" type="checkbox"/> Cameron Carey	03/11/2025	180	9:30 AM - 3:00 PM	5.5

<input checked="" type="checkbox"/> PARTS			
QUANTITY	PART NUMBER	DESCRIPTION	EQUIPMENT
<input checked="" type="checkbox"/> 155.00	339	Mileage	--

<input checked="" type="checkbox"/> LABOR		
QUANTITY	DESCRIPTION	EQUIPMENT
<input checked="" type="checkbox"/> 5.50	Service Labor	--

IS JOB COMPLETE? ☒ YES ☐ NO

<input checked="" type="checkbox"/> Equipment Detail
--

Customer:

Type your name

Date Time

Comments (optional)

Email Address

[Clear Email Field](#)

☐ Select All

☐ (dave@tillamookfarmerscoop.com)

Other:

Employee:

Type your name

Date Time

Comments (optional)

From: [ECKERT Dylan * DEQ](#)
To: [Roger Edens](#); [DIMOCK Lauren * DEQ](#); [DROUIN Mark * DEQ](#)
Subject: RE: Tillamook Farmers CO-OP 30 Day Notice
Date: Thursday, January 25, 2024 9:51:53 AM
Attachments: [image002.png](#)
[image003.png](#)

Approved. Thank you for working with me on the modified site assessment plan.

Dylan

From: Roger Edens <edensr@fullcycleenvironmental.com>
Sent: Thursday, January 25, 2024 8:31 AM
To: DIMOCK Lauren * DEQ <Lauren.DIMOCK@deq.oregon.gov>; DROUIN Mark * DEQ <Mark.DROUIN@deq.oregon.gov>; ECKERT Dylan * DEQ <Dylan.ECKERT@deq.oregon.gov>
Subject: Re: Tillamook Farmers CO-OP 30 Day Notice

Hello,

I am asking to not sample the lines between the udcs. The soil is nearly unattainable under 2+ feet of 2" qp and the pea gravel is too large to sample. The lines are double walled and there are no indicators of impacts at the site. I have managed good samples under the udcs.

Thanks,
Roger



Roger Edens R.G.
Environmental
Geologist

M: 541-668-1141
O: 458-202-9502
E: EdensR@FullCycleEnvironmental.com
W: FullCycleEnvironmental.com

133 NE Greeley Ave. Bend, OR 97701
OR #196108 • CA # 1041982 • WA# SIPEPC825KZ

WHERE FISCAL RESPONSIBILITY AND
ENVIRONMENTAL RESPONSIBILITY WORK TOGETHER

From: DIMOCK Lauren * DEQ <Lauren.DIMOCK@deq.oregon.gov>
Sent: Thursday, December 28, 2023 8:15:24 AM
To: Roger Edens <edensr@fullcycleenvironmental.com>; PARDUE Dave * DEQ <Dave.Pardue@deq.oregon.gov>; DROUIN Mark * DEQ <Mark.DROUIN@deq.oregon.gov>
Cc: Brad Hughbanks <BradH@centralserviceinc.com>; Lee Bennett <Lee@centralserviceinc.com>; laurie@tillamookfarmerscoop.com <laurie@tillamookfarmerscoop.com>
Subject: RE: Tillamook Farmers CO-OP 30 Day Notice

Hi Roger,

Thanks for sending this, the 30-day notice has been received. We will follow up with additional info and questions as needed.

Best,

Lauren Dimock (she/her pronouns)
UST Compliance Inspector

DEQ Northwest Region
700 NE Multnomah St., Ste. 600
Portland, OR 97232
Ph: 503-229-6030
lauren.dimock@deq.state.or.us



Provide DEQ your email contact for swifter response times and notifications:

<https://forms.office.com/g/WKrybAzFgk>

Sign-up for UST Program updates here:

https://service.govdelivery.com/accounts/ORDEQ/subscriber/new?topic_id=ORDEQ_546

From: Roger Edens <edensr@fullcycleenvironmental.com>

Sent: Tuesday, December 26, 2023 2:25 PM

To: DIMOCK Lauren * DEQ <Lauren.DIMOCK@deq.oregon.gov>; PARDUE Dave * DEQ <Dave.PARDUE@deq.oregon.gov>

Cc: Brad Hughbanks <BradH@centralserviceinc.com>; Lee Bennett <Lee@centralserviceinc.com>; laurie@tillamookfarmerscoop.com

Subject: Tillamook Farmers CO-OP 30 Day Notice

Lauren,

Attached is a 30 Day Notice for upcoming work at Tillamook Farmers CO-OP Facility ID 12105.

Please let me know if you have any questions.

Please let me know you have received this.

Thanks,

Roger



Roger Edens
R.G.
Environmental
Geologist
OR&WA
ICC Certifications
U1, U2, and U3

C: 541-668-1141
O: 458-202-9502
E:
EdensR@FullCycleEnvironmental.com
W: FullCycleEnvironmental.com

133 NE Greeley Ave, Bend, OR 97701

WHERE FISCAL RESPONSIBILITY AND
ENVIRONMENTAL RESPONSIBILITY WORK TOGETHER

Tillamook Co-op
1920 main Ave N
Tillamook, OR 97141

SENSOR STATUS REPORT
Last Available

Apr 16, 2025,
6:17:39 AM

Copyright © 2004-2023
Franklin Electric. All
rights reserved.
version 3.20.4

Sensor Status

Name	Unleaded Annular
Type	Two Wire Sensor
Time	04/17/2025 12:00
Status	OK
Name	Split Annular
Type	ULS/UHS Sensor
Time	04/17/2025 12:00
Status	OK
Name	Unleaded STP
Type	ULS/UHS Sensor
Time	04/17/2025 12:00
Status	OK
Name	Supreme STP
Type	ULS/UHS Sensor
Time	04/17/2025 12:00
Status	OK
Name	Diesel STP
Type	ULS/UHS Sensor
Time	04/17/2025 12:00
Status	OK
Name	Disp 1
Type	ULS/UHS Sensor
Time	04/17/2025 12:00
Status	OK
Name	Disp 2
Type	ULS/UHS Sensor
Time	04/17/2025 12:00
Status	OK
Name	Disp 3
Type	ULS/UHS Sensor
Time	04/17/2025 12:00
Status	OK
Name	disp-4
Type	ULS/UHS Sensor
Time	04/17/2025 12:00
Status	OK



UST WALKTHROUGH INSPECTIONS CHECKLIST

TILLAMOOK FARMERS CO-OP 1920 MAIN AVE N TILLAMOOK OR 29-12105-7029-OPER
Site Name Site Address Tag #
97141

- Initial each box to indicate the equipment was inspected, as described. Use NA if the equipment inspection does not apply to the site.
- Take action for any alarms, damaged equipment and non-normal operating conditions; note actions taken on page 2
- NOTE: Petroleum found in a sump or interstice must be reported to Ecology within 24 hours.

YEAR: <u>2025</u>	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec
Date of Inspection → <u>1/25</u>												
REQUIRED MONTHLY												
Spill bucket(s) checked for damage and cracks*. Liquid and/or debris removed.	BB	BB	BB	BB								
Fill pipe(s) checked for obstructions. Removed, if found.	BB	BB	BB	BB								
Fill cap(s) securely fitted on fill pipe(s).	BB	BB	BB	BB								
Tank monitor equipment checked for alarms and normal operating condition.	BB	BB	BB	BB								
Leak detection records are reviewed for non-leaking results and kept for three years. Suspected leaks were reported.	BB	BB	BB	BB								
REQUIRED ANNUALLY												
Containment sump(s) checked for damage and presence of liquid. Liquid and/or debris removed.	BB	BB	BB	BB								
If using manual tank gauging, checked condition of tank gauge stick is good (e.g. readable at 1/8" increments throughout).												
RECOMMENDED ACTIVITIES												
Emergency spill response supplies inventoried and restocked if low. Inspected supplies for deterioration.	BB	BB	BB	BB								
Inspected loose fitting, deterioration, obvious signs of leaks and improper function of dispenser hoses, nozzles and breakaways.	BB	BB	BB	BB								

*If a tank receives deliveries at intervals greater than 30 days, the spill bucket check may instead be conducted prior to each delivery. To be eligible for this option, include a copy of each delivery receipt with this form.

Note: This checklist doesn't include the requirement to inspect hydrant pits and piping vaults at airport hydrant systems at least every 30 days.



UST WALKTHROUGH INSPECTIONS CHECKLIST

TILLAMOOK FARMERS CO-OP
Site Name

1920 MAIN AVE N TILLAMOOK OR
Site Address

29-12105-7024-OPER
Tag #

- Initial each box to indicate the equipment was inspected, as described. Use NA if the equipment inspection does not apply to the site.
- Take action for any alarms, damaged equipment and non-normal operating conditions; note actions taken on page 2
- NOTE: Petroleum found in a sump or interstice must be reported to Ecology within 24 hours.

YEAR: <u>2025</u>	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec
Date of Inspection → <u>1/25</u>												
REQUIRED MONTHLY												
Spill bucket(s) checked for damage and cracks*. Liquid and/or debris removed.	BB	BB	BB	BB								
Fill pipe(s) checked for obstructions. Removed, if found.	BB	BB	BB	BB								
Fill cap(s) securely fitted on fill pipe(s).	BB	BB	BB	BB								
Tank monitor equipment checked for alarms and normal operating condition.	BB	BB	BB	BB								
Leak detection records are reviewed for non-leaking results and kept for three years. Suspected leaks were reported.	BB	BB	BB	BB								
REQUIRED ANNUALLY												
Containment sump(s) checked for damage and presence of liquid. Liquid and/or debris removed.	BB	BB	BB	BB								
If using manual tank gauging, checked condition of tank gauge stick is good (e.g. readable at 1/8" increments throughout).												
RECOMMENDED ACTIVITIES												
Emergency spill response supplies inventoried and restocked if low. Inspected supplies for deterioration.	BB	BB	BB	BB								
Inspected loose fitting, deterioration, obvious signs of leaks and improper function of dispenser hoses, nozzles and breakaways.	BB	BB	BB	BB								

*If a tank receives deliveries at intervals greater than 30 days, the spill bucket check may instead be conducted prior to each delivery. To be eligible for this option, include a copy of each delivery receipt with this form.

Note: This checklist doesn't include the requirement to inspect hydrant pits and piping vaults at airport hydrant systems at least every 30 days.



State of Oregon
Department of
Environmental
Quality

Program Enforcement No. 2025-FC-9789

Department of Environmental Quality
Underground Storage Tank Program

Field Citation
For UST Violations

This section for
DEQ use only

Page 1 of 3

DEQ Information		UST Facility Information	
Inspection Date:	03/06/2025	Facility ID#:	12105
Inspector:	Ingrid GAFFNEY	Facility Name:	TILLAMOOK FARMERS' CO-OP
DEQ Office:	700 NE Multnomah St Ste 600	Facility Address:	1920 MAIN AVE N, TILLAMOOK, Oregon 97141
Phone #:	503-229-5048	County:	Tillamook

Oregon DEQ inspected the facility listed above and identified the UST violations listed on page 3 of this Field Citation.

Field Citation Issued:	<input type="checkbox"/> In Person <input checked="" type="checkbox"/> By Email <input type="checkbox"/> Both	Date Issued: 03/07/2025
Facility Representative Present During Inspection:	Laurie Wicker	<input type="checkbox"/> Permittee <input type="checkbox"/> Owner <input type="checkbox"/> Other
Name of Permittee or Owner:	Tillamook Farmers' Co-Op, Inc.	
Mailing Address:	1920 Main Ave N , Tillamook Oregon 97141	
Field Citation Penalty - See Page 3 for detailed listing of each violation.		\$ 750

Check payable to: DEQ Financial Services LBX3615; P.O. Box 3615; Portland OR 97208-3615

Or pay online through your YDO account

This Field Citation is issued in accordance with the requirements for the expedited enforcement of underground storage tank (UST) violations, OAR 340-150-0250.

Owner or Permittee should select Option 1 or Option 2 below and return a signed copy of this for to DEQ by the following date:

04/07/2025

DEQ Revenue Section
700 NE Multnomah St. #600
Portland, Oregon 97232

Check one option

- ☒ **Option 1** - I acknowledge that the listed violation(s) have occurred and I am remitting the listed field citation penalty.
- ☐ **Option 2** - I do not want to participate in the expedited enforcement process and understand that my file will be referred to the Department's Office of Compliance and Enforcement for formal enforcement action.

Name:	Laurie Wicker	Owner / Permittee
Signature:		Date: 4/30/25

Important

Read pages 2 and 3 for more information about your options and a detailed listing of violations and compliance requirements.

Department of Environmental Quality (DEQ) Underground Storage Tank Program				Facility Representative initials: _____	
UST FIELD CITATION					
DATE ISSUED: 03/07/2025		PROGRAM ENFORCEMENT No.: 2025-FC-9789		FACILITY ID: 12105	
Violation #1:		Page 3 of 3			
*TCR:		Failure to investigate or confirm a suspected release.			
Corrective Action:		Initiate investigation to confirm suspected release in UDC 7/8 within 5 days. Perform necessary repairs and submit to DEQ by April 7, 2025			
Rule Citation: OAR 340-150-0163(1)(f)		Penalty Amount: \$	300	Correct Violation by:	04/07/2025
				Date Violation Corrected:	3/11/25
*TCR:		Failure to conduct monthly periodic operation and maintenance walkthrough inspection by 10/01/20 and each month thereafter.			
Corrective Action:		2. Complete monthly walkthrough inspection within 30 days. Submit walkthrough inspection form to DEQ by April 7, 2025			
Rule Citation: OAR 340-150-0315(1)(a)(A)		Penalty Amount: \$	150	Correct Violation by:	04/07/2025
				Date Violation Corrected:	3/9/25
*TCR:		Failure to keep the most recent 12 consecutive months of interstitial monitoring records for review and inspection.			
Corrective Action:		Conduct monitoring as required by rule (print daily sensor status). Maintain records. Submit copies of recent sensor reports to DEQ by April 7, 2025.			
Rule Citation: OAR 340-150-0465(6)		Penalty Amount: \$	300	Correct Violation by:	04/07/2025
				Date Violation Corrected:	4/1/25
Violation #4:					
*TCR:					
Corrective Action:					
Rule Citation: OAR		Penalty Amount: \$		Correct Violation by:	
				Date Violation Corrected:	
Violation #5:					
*TCR:					
Corrective Action:					
Rule Citation: OAR		Penalty Amount: \$		Correct Violation by:	
				Date Violation Corrected:	
Violation #6:					
*TCR:					
Corrective Action:					
Rule Citation: OAR		Penalty Amount: \$		Correct Violation by:	
				Date Violation Corrected:	
		Total Penalty Amount	750		
		(This Page): \$			
<p>YOU MUST CORRECT THE VIOLATIONS AS REQUIRED , SIGN THE STATEMENT BELOW AND</p> <p>RETURN THIS FORM TO THE DEQ INSPECTOR LISTED ON PAGE 1 ON OR BEFORE: 04/07/2025</p> <p>Retain a copy of this form and all documentation of corrective actions for your records.</p> <p>I hereby certify that the UST violations noted above have been corrected: _____</p> <p style="text-align: right;">Permittee/Owner Signature _____ Date 4/30/25</p>					

From: [LITKE Emily * DEQ](#)
To: [Laurie Wicker](#)
Subject: RE: Oregon DEQ UST Inspection Determination: Tillamook Farmers" Coop #12105
Date: Wednesday, April 30, 2025 11:07:00 AM
Attachments: [image001.png](#)

Hey Laurie,

Thanks for sending this over – everything looks great.

The UST inspection for **UST facility 12105 Tillamook Farmers' Coop located at at 1920 Main Ave N Tillamook** is officially **CLOSED and COMPLETE.**

Thank you for your communication throughout this process and keeping your facility in compliance with Oregon rules and regulations.



Emily Litke (she/her)
Duty Officer, Underground Storage Tanks
DEQ Headquarters, Land Quality Division
700 NE Multnomah Street, Suite 600
Portland OR 97232-4100
503-806-9516
Emily.LITKE@deq.oregon.gov

From: Laurie Wicker <laurie@tillamookfarmerscoop.com>
Sent: Wednesday, April 30, 2025 10:49 AM
To: LITKE Emily * DEQ <Emily.LITKE@deq.oregon.gov>
Subject: RE: Oregon DEQ UST Inspection Determination: Tillamook Farmers' Coop #12105

My apologies, I thought everything was taken care of. All corrective actions have been completed. Please find attached the requested corrective actions.

Please let me know if there is anything further that I need to do. Original Payment was sent on 3/13/25

Thank You,
Laurie Wicker
Tillamook Farmers Coop
503-842-4457

From: LITKE Emily * DEQ <Emily.LITKE@deq.oregon.gov>

Sent: Tuesday, April 29, 2025 5:31 PM

To: UST Duty Officer * DEQ <UST.DutyOfficer@DEQ.oregon.gov>; Laurie Wicker <laurie@tillamookfarmerscoop.com>; Josi Park <josi@tillamookfarmerscoop.com>

Subject: RE: Oregon DEQ UST Inspection Determination: Tillamook Farmers' Coop #12105

Good afternoon,

UST facility 12105 Tillamook Farmers' Coop located at 1920 Main Ave N, Tillamook, OR 97141

Please provide an update on the status of the corrective actions from the UST inspection on 3/6/25, the deadline for these actions was 4/7/25.

Corrective Actions:

1. Initiate investigation to confirm suspected release within 5 days. Perform necessary repairs and submit to DEQ
2. Complete monthly walkthrough inspection within 30 days.
3. Conduct interstitial monitoring as required by rule (print daily sensor status). Maintain records. Submit copies of recent sensor reports to DEQ



Emily Litke (she/her)

Duty Officer, Underground Storage Tanks
DEQ Headquarters, Land Quality Division
700 NE Multnomah Street, Suite 600
Portland OR 97232-4100
503-806-9516

Emily.LITKE@deq.oregon.gov

From: UST Duty Officer * DEQ

Sent: Friday, March 7, 2025 11:37 AM

To: UST Duty Officer * DEQ <UST.DutyOfficer@DEQ.oregon.gov>; laurie@tillamookfarmerscoop.com; josi@tillamookfarmerscoop.com

Subject: RE: Oregon DEQ UST Inspection Determination: Tillamook Farmers' Coop #12105

Good morning,

Please review the attached field citation. The deadline for payment of the \$750 penalty and

completion of the corrective actions is 4/7/25.

Payment can be made either through **check** or **online** through Your DEQ Online – follow the link below to create an account.

[Department of Environmental Quality : Welcome to Your DEQ Online : Online Services : State of Oregon](#)

Questions about online payments and submittals can be directed to the Help Desk at itservicedesk@deq.oregon.gov or call 503-229-5202

[Your DEQ Online Helpdesk - Jira Service Management](#)



Emily Litke (she/her)

Duty Officer, Underground Storage Tanks

DEQ Headquarters, Land Quality Division

700 NE Multnomah Street, Suite 600

Portland OR 97232-4100

503-806-9516

Emily.LITKE@deq.oregon.gov

From: UST Duty Officer * DEQ <UST.DutyOfficer@DEQ.oregon.gov>

Sent: Friday, March 7, 2025 8:52 AM

To: laurie@tillamookfarmerscoop.com; josi@tillamookfarmerscoop.com

Cc: UST Duty Officer * DEQ <UST.DutyOfficer@DEQ.oregon.gov>

Subject: Oregon DEQ UST Inspection Determination: Tillamook Farmers' Coop #12105

Importance: High

Hello Tillamook Farmers' Coop:

Thank you for meeting with Oregon DEQ to perform the UST Inspection at 1920 Main Ave N, Tillamook, OR 97141 on March 6, 2025. It was a pleasure to meet you all.

Since DEQ observed violations DEQ must issue a filed citation per the enforcement guidelines. Attached is the email stating that Tillamook Farmers' Coop has hired CSI to come March 7 or March 10th, 2025 to investigate and/or repair the release in UDC #7/8. You will receive a field citation via a separate email from the UST Duty officer email. The payment can be made via [Your DEQ Online Website](#).

Please contact the UST Duty Officer at 503-229-5034 or ust.dutyofficer@deq.oregon.gov . Please email the UST duty officer when sending over the final documentation and testing results.

Violations:

1. L2 – Failure to investigate or confirm a suspected release in UDC #7/8. 340-150-0465(7) Class I
2. A15 - Failure to conduct monthly periodic operation and maintenance walkthrough inspection by October 1, 2020 and each month thereafter. 340-150-0315(1)(a)(A). Class II
3. J8.5c – Failure to keep the most recent 12 consecutive months of interstitial monitoring (sensors) records. 340-150-0465(6). Class I (Only one month was maintained)

Corrective Actions:

1. Initiate investigation to confirm suspected release within 5 days. **Perform necessary repairs and submit to DEQ by April 7, 2025**
2. Complete monthly walkthrough inspection within 30 days. **Submit walkthrough inspection form to DEQ by April 7, 2025**
3. Conduct monitoring as required by rule (print daily sensor status). Maintain records. **Submit copies of recent sensor reports to DEQ by April 7, 2025.**

Observations of note:

- Maintain an emergency spill kit near the dispensing area
- Maintain records of annual (tank gauge cert, lines, and leak detection devices) and tri annual testing (testing of all the sumps, UDCs and spill buckets)
- Maintain records of daily sensor reports from the EVO 600 tank gauge

Regards,

Ingrid Gaffney
UST Compliance Inspector
DEQ UST Program
700 NE Multnomah St, Ste 600
Portland, OR 97232
503-875-1246
<https://www.oregon.gov/deq/Pages/index.aspx>
she/ her

Fee

\$ 750.00

—

Paid

\$ 750.00

=

Due

\$ 0.00

Penalty

▶ 2025-FC-9789

UST - Field Citation

\$ 750.00

1 Results

Add Penalty

Send to FIMS

Payment

▼ Check by Mail 22461

3/18/2025

45280

\$ 750.00

Type

Check by Mail

Amount

750

E-Payment Confirmation#

E-Payment Settle Date

mm/dd/yyyy

Ref#

Payment Date

03/18/2025

Comments

(Remaining Length: 4000)

1 Results

Site Info

TILLAMOOK FARMERS' CO-OP

1920 MAIN AVE N, TILLAMOOK, OR 97141

9077 ✓

218783

CEM_FacilityIdentifier=7799 UST (12105)

Stationary

Contact Info

Inspection Info

7792 Completed

UST

Full Compliance Inspection (FCI) TCR only