

I. Site Information

Facility Name:	buy2	fuel@tmi-buy2stores.com	Permittee: Lutfi Thabet	Contact
Site Address:	1690	1695 W 18th	Organization:	Phone 541-344-5983
City:	Rd	Eugene	Phone: 541-447-5123	

II. Tank Information

DEQ Permit #	BDFBG	1a	BDFGH	2A	BDFBJ	3A		
Estimated Gallons	10000		10000		10000			
Substance	GAS		BIODIESEL		diesel			
Tank Material	Dw comp		DW comp		DW comp			
Tank Install Date	1995		1995		1995			
Pipe Material	dwfrp		dwFrp		dwFrp			
Pipe Type								
Pipe Install Date								
Overfill Device	shutoff		shutoff		shutoff			

Notes and Comments from the UST database: Check file before conducting inspection

1/2
3/4 VDE's need cleaning
No sensors

If tanks are manifolded, which tanks:

III. Operating Certificate**Compliance** Yes No Current Accurate Posted for delivery drive to observe**IV. Operator Training****Compliance** Yes No

Class A/B Operator

 Yes No

Name: Charles Colman

Date: 4/23/25

Class C Operator

 Yes No Cardlock**V. Financial Responsibility****Compliance** Yes No

Type of coverage: Pol. Liabil.

Begin Date: 7/6/24

End Date: 7/6/25

Coverage amount correct: 1M

Number of tanks covered: 3

Financial responsibility could also be in the form of self insurance, bonds, local government, trust fund, and or guarantee

VI. Walkthrough Requirements**Compliance** Yes No

X Pressurized Piping

Mechanical Leak Detector (MLLD)

Electronic Leak Detector (ELLD) - check for swiftcheck requirement

Date of last testing: 10/24/24

Last three tests available? Yes No

Number of lines tested: 3

Number of LD tested: 3

Leak detector manufacturer make and model: Vaporizers 99 LD 2000

Tank gauge manufacturer make and model: TLG - 350

MLLD on turbine manifold? Yes No

MLLD product appropriate? (Example, diesel Red Jacket FX series on diesel system?) Yes No

If ELLD and no line testing: Annual 0.1 gph results from tank gauge? Yes No

Interstitial Monitoring

[Monthly records must include, date system was checked, observations made, initials of person checking. Electronic records must include power status (on or off), alarm indication status (yes or no) and sensor malfunction notes (yes or no).]

Date of last sump testing: N/A

Last two tests available? Yes No

Date of last sensor testing: _____

Last three tests available? Yes No

Float sensors installed correctly? Yes No

Interstitial space opened to sump? Yes No

Presence of water in sumps? Yes No

Safe Suction

Check valve directly below suction pump? Yes No

c) Monthly Tank Release Detection (Check all that apply)

Tank Gauge CSLD SCALD Static

Are correct tank sizes programmed at tank gauge? Yes No

Tank diameter/length seem appropriate? Yes No

Are tanks manifolded? Yes No

If so, tank gauge testing setup for manifolded tanks? Yes No

If Veeder Root tank gauge leak detection

- CSLD set at 99%
- Thermal coefficient set correctly?
(Gasoline 0.00070; Diesel 0.00045)

If Incon/Franklin tank gauge leak detection

- If SCALD is Vol Qual set to 14% (or 99% confidence)
- Is API gravity set correctly?
(Regular 63.5; Plus 62.8; Super 51.3; Diesel 32.8)

For all tank gauges doing static tests
(Static tests require tank to be 50% full for a valid test)

X Interstitial Monitoring [Monthly records must include, date system was checked, observations made, initials of person checking.

Electronic records must include power status (on or off), alarm indication status (yes or no) and sensor malfunction notes (yes or no).]

SIR Ensure pass or fail results within 30-day period. Inconclusive result means release detection requirement not met

None 1695 sent instead

Tank release detection records available during inspection

T1:	<input type="checkbox"/> Jan	<input type="checkbox"/> Feb	<input type="checkbox"/> Mar	<input type="checkbox"/> Apr	<input type="checkbox"/> May	<input type="checkbox"/> Jun	<input checked="" type="checkbox"/> Jul	<input type="checkbox"/> Aug	<input type="checkbox"/> Sep	<input type="checkbox"/> Oct	<input type="checkbox"/> Nov	<input type="checkbox"/> Dec
T2:	<input type="checkbox"/> Jan	<input type="checkbox"/> Feb	<input type="checkbox"/> Mar	<input type="checkbox"/> Apr	<input type="checkbox"/> May	<input type="checkbox"/> Jun	<input checked="" type="checkbox"/> Jul	<input type="checkbox"/> Aug	<input type="checkbox"/> Sep	<input type="checkbox"/> Oct	<input type="checkbox"/> Nov	<input type="checkbox"/> Dec
T3:	<input type="checkbox"/> Jan	<input type="checkbox"/> Feb	<input type="checkbox"/> Mar	<input type="checkbox"/> Apr	<input type="checkbox"/> May	<input type="checkbox"/> Jun	<input checked="" type="checkbox"/> Jul	<input type="checkbox"/> Aug	<input type="checkbox"/> Sep	<input type="checkbox"/> Oct	<input type="checkbox"/> Nov	<input type="checkbox"/> Dec
T4:	<input type="checkbox"/> Jan	<input type="checkbox"/> Feb	<input type="checkbox"/> Mar	<input type="checkbox"/> Apr	<input type="checkbox"/> May	<input type="checkbox"/> Jun	<input type="checkbox"/> Jul	<input type="checkbox"/> Aug	<input type="checkbox"/> Sep	<input type="checkbox"/> Oct	<input type="checkbox"/> Nov	<input type="checkbox"/> Dec

Inspector: PAROUE

Date: 6/23/24

Time: 130

Facility: 5299

VIII. Spill Prevention **Compliance** Yes No

Date(s) of testing: 10-24-24 Number of spill buckets tested? 3

Did spill bucket pass most recent testing? Yes No If no, was spill bucket replaced/repaired? Yes No

During inspection, visual damage to spill bucket? Yes No

Hydrostatic testing (test takes one hour to complete)

Vacuum test (test takes 1 minute, ending vacuum must be 26 inches water column or greater)

IX. Overfill Prevention **Compliance** Yes No

Date(s) of testing: 10/27/25

Overfill device pass most recent testing? Yes No If no, overfill device replaced? Yes No

Overfill method that was tested: Alarm Flapper Ball Float

Overfill Alarm

Alarm sounds when tank is 90% full Yes No

Driver can see or hear alarm at point of transfer? Yes No

Sound alarm from tank gauge during inspection? Yes No

Flapper Valve

Testing verified the valve automatically restricts flow at 95% Yes No

Visual observation of flapper on day of inspection? Yes No

Ball Float

Testing verified the ball float automatically restricts flow at 90% Yes No

Visual observation of ball float during inspection? Yes No

X. Corrosion Protection **Compliance** Yes No

Cathodic Galvanic Impressed Current

Steel tank with cathodic? Yes No

Steel pipes with cathodic? Yes No

Steel flex-lines with cathodic? Yes No

Date of cathodic test: _____

Last two tests available? Yes No

Did last test pass? Yes No

If not:

Was failed test reported to DEQ? Yes No

Was system repaired? Yes No

Date of repair? _____

Cathodic retested within 6 mos. of repair? Yes No

Date of retesting? _____

If impressed current system:

Rectifier Operational? Yes No

Rectifier log maintained? Yes No

Rectifier been operating continuously Yes No

Tank Lining

Date of last test? _____

Pressure test conducted after tank lining inspection? Yes No

Compliance Determination:

No Violations Observed

Observed violations resulting in enforcement



View of diesel fill



1: Premium fill



2: Diesel tank top



3:



4: Dispenser 1/2



5: View below Dispenser 1/2



View of Service Island



This section for DEQ use only

State of Oregon
Department of
Environmental
Quality

Department of Environmental Quality
Underground Storage Tank Program

Field Citation
For UST Violations

DEQ Information		UST Facility Information	
Inspection Date:	06/23/2025	Facility ID#:	3299
Inspector:	Dave Pardue	Facility Name:	BUY 2
DEQ Office:	700 NE Multnomah St	Facility Address:	1690 W 18TH, EUGENE, Oregon 97402
Phone #:		County:	Lane

Oregon DEQ inspected the facility listed above and identified the UST violations listed on page 3 of this Field Citation.

Field Citation Issued:	<input type="checkbox"/> In Person	<input checked="" type="checkbox"/> By Email	<input type="checkbox"/> Both	Date Issued: 07/24/2025
Facility Representative Present During Inspection:				<input type="checkbox"/> Permittee <input type="checkbox"/> Owner <input type="checkbox"/> Other
Name of Permittee or Owner:	Thabet Management, Inc.			
Mailing Address:	1700 Valley River Dr Ste 400 , Eugene Oregon 97401			

Field Citation Penalty – See Page 3 for detailed listing of each violation. \$ 300

Check payable to: DEQ Financial Services LBX3615; P.O. Box 3615; Portland OR 97208-3615

Or pay online through your YDO account

This Field Citation is issued in accordance with the requirements for the expedited enforcement of underground storage tank (UST) violations, OAR 340-150-0250.

Owner or Permittee should select Option 1 or Option 2 below and return a signed copy of this for to DEQ by the following date:

08/24/2025

DEQ Revenue Section
700 NE Multnomah St. #600
Portland, Oregon 97232

Check one option

- Option 1** - I acknowledge that the listed violation(s) have occurred and I am remitting the listed field citation penalty.
- Option 2** - I do not want to participate in the expedited enforcement process and understand that my file will be referred to the Department's Office of Compliance and Enforcement for formal enforcement action.

Name:	Owner / Permittee
Signature:	Date:

Important

Read pages 2 and 3 for more information about your options and a detailed listing of violations and compliance requirements.

Field Citation Requirements

The permittee or owner should select Option 1 or Option 2 and return a signed copy of Page 1 of the Field Citation form within thirty (30) days of issuance of the Field Citation. If the permittee or owner fails to sign and send Page 1 of the Field Citation form back or pay the penalty within thirty days, Option 1 expires, the Field Citation will serve as a Pre-Enforcement Notice (PEN) and the permittee and owner will be subject to formal enforcement including the imposition of civil penalties in accordance with OAR Chapter 340, Division 12.

The permittee or owner must complete the actions required to correct the violations listed on the Field Citation by the date specified to prevent further enforcement action by DEQ.

Option 1:

By checking Option 1 the permittee or owner acknowledges that the violations listed on Page 3 of this Field Citation have occurred and agrees to pay the established penalty.

By submitting payment of the penalty amount, the responding permittee or owner agrees to accept the field citation as a final order of the Environmental Quality Commission (commission) and waives any and all rights and objections to the form, content, manner of service and timeliness of the Field Citation; to a contested case hearing and judicial review of the Field Citation [OAR 340-150-0250(6)]; and to service of a copy of this Final Order (*i.e.*, no other copy will be provided).

Upon the Department's receipt of payment of the penalty amount set forth in the Field Citation, the Field Citation becomes a Final Order of the Commission that:

1. Imposes upon the permittee or owner a civil penalty in the amount listed on Page 1 of this Field Citation; and
2. Requires the permittee or owner to satisfactorily complete the requirements and actions necessary to correct the violations documented by the dates set forth on Page 3 of this Field Citation.

Failure by the permittee or owner to complete the actions set forth on Page 3 of the Field Citation by the specified date violates the Commission Order and subjects the permittee and owner to a formal enforcement action including the imposition of additional civil penalties.

Option 2:

The permittee or owner may deny that the violations as listed on Page 3 of this Field Citation have occurred or contest the Field Citation process by checking Option 2 and submitting to the Department a signed copy of Page 1 of the Field Citation. In that event, the Field Citation will serve as a Pre-Enforcement Notice (PEN) and the permittee and owner will be subject to formal enforcement for those violations set forth in the Field Citation, including the imposition of civil penalties in accordance with OAR Chapter 340, Division 12. Civil penalties that will be imposed by the formal enforcement process will exceed the Field Citation penalties for the same violation(s).

The Department appreciates your cooperation and efforts to comply with the regulations for underground storage tank systems.

DATE ISSUED: 07/24/2025

PROGRAM ENFORCEMENT No.: 2025-FC-9944

FACILITY ID: 3299

Page 3 of 3

Violation #1: Failure to use interstitial monitoring equipment to monitor UST or suction piping for a release at least every 30 days and/or failure to record results on a monthly basis.
***TCR:**

Corrective Action: Submit first month of interstitial monitoring records. Keep the most recent 12 consecutive months of interstitial monitoring records (tank release detection) for review and inspection.

Rule Citation: OAR 340-150-0465(3)	Penalty Amount: \$ 300	Correct Violation by: 08/24/2025	Date Violation Corrected:
---	------------------------	----------------------------------	---------------------------

Violation #2:
***TCR:**

Corrective Action:

Rule Citation: OAR	Penalty Amount: \$	Correct Violation by:	Date Violation Corrected:
---------------------------	--------------------	-----------------------	---------------------------

Violation #3:
***TCR:**

Corrective Action:

Rule Citation: OAR	Penalty Amount: \$	Correct Violation by:	Date Violation Corrected:
---------------------------	--------------------	-----------------------	---------------------------

Violation #4:
***TCR:**

Corrective Action:

Rule Citation: OAR	Penalty Amount: \$	Correct Violation by:	Date Violation Corrected:
---------------------------	--------------------	-----------------------	---------------------------

Violation #5:
***TCR:**

Corrective Action:

Rule Citation: OAR	Penalty Amount: \$	Correct Violation by:	Date Violation Corrected:
---------------------------	--------------------	-----------------------	---------------------------

Violation #6:
***TCR:**

Corrective Action:

Rule Citation: OAR	Penalty Amount: \$	Correct Violation by:	Date Violation Corrected:
---------------------------	--------------------	-----------------------	---------------------------

	Total Penalty Amount 300		
	(This Page): \$		

YOU MUST CORRECT THE VIOLATIONS AS REQUIRED, SIGN THE STATEMENT BELOW AND

RETURN THIS FORM TO THE DEQ INSPECTOR LISTED ON PAGE 1 ON OR BEFORE: 08/24/2025

Retain a copy of this form and all documentation of corrective actions for your records.

I hereby certify that the UST violations noted above have been corrected: _____ / _____

Permittee/Owner Signature

Date

BUY2-033
1690 W 18TH AVE
EUGENE,OR 97402
541-515-6078

JAN 1, 2025 12:52 PM

LIQUID STATUS

JAN 1, 2025 12:52 PM

L 1:DIESL SUMP
SENSOR NORMAL

L 2:PREM STP
SENSOR NORMAL

L 3:UNLEADED SUMP
SENSOR NORMAL

L 4:DIESL ANNULAR SPACE
SENSOR NORMAL

L 5:B99 ANNVLAR SPACE
SENSOR NORMAL

L 6:UNL ANNULAR SPACE
SENSOR NORMAL

* * * * * END * * * * *

BUY2-033
1695 W 18TH
EUGENE OR 97402

JAN 1, 2025 12:28 PM

LIQUID STATUS

JAN 1, 2025 12:28 PM

L 1:REGULAR TANK WALL
SENSOR NORMAL

L 2:SUPER TANK WALL
SENSOR NORMAL

L 3:REGULAR TURBINE SUMP
SENSOR NORMAL

L 4:SUPER TURBINE SUMP
SENSOR NORMAL

* * * * * END * * * * *

BUY2-033
1695 W 18TH
EUGENE OR 97402

MAR 17, 2025 4:00 AM

INVENTORY REPORT

T 1:E10 NORTH
VOLUME = 5224 GALS
ULLAGE = 9752 GALS
90% ULLAGE= 8254 GALS
TC VOLUME = 5250 GALS
HEIGHT = 44.73 INCHES
WATER VOL = 0 GALS
WATER = 0.00 INCHES
TEMP = 52.9 DEG F

T 2:E10 PREMIUM
VOLUME = 1704 GALS
ULLAGE = 13272 GALS
90% ULLAGE= 11774 GALS
TC VOLUME = 1701 GALS
HEIGHT = 20.48 INCHES
WATER VOL = 0 GALS
WATER = 0.00 INCHES
TEMP = 62.5 DEG F

* * * * * END * * * * *

BUY2-033
1695 W 18TH
EUGENE OR 97402

APR 21, 2025 7:03 AM

LIQUID STATUS

APR 21, 2025 7:03 AM

L 1:REGULAR TANK WALL
SENSOR NORMAL

L 2:SUPER TANK WALL
SENSOR NORMAL

L 3:REGULAR TURBINE SUMP
SENSOR NORMAL

L 4:SUPER TURBINE SUMP
FUEL ALARM

***** END *****

BUY2-033
1695 W 18TH
EUGENE OR 97402

APR 21, 2025 7:01 AM

LIQUID STATUS

APR 21, 2025 7:01 AM

L 1:REGULAR TANK WALL
SENSOR NORMAL

L 2:SUPER TANK WALL
SENSOR NORMAL

L 3:REGULAR TURBINE SUMP
SENSOR NORMAL

L 4:SUPER TURBINE SUMP
FUEL ALARM

***** END *****

BUY2-033
1695 W 18TH
EUGENE OR 97402

MAY 1. 2025 10:10 AM

LIQUID STATUS

MAY 1. 2025 10:10 AM

L 1:REGULAR TANK WALL
SENSOR NORMAL

L 2:SUPER TANK WALL
SENSOR NORMAL

L 3:REGULAR TURBINE SUMP
SENSOR NORMAL

L 4:SUPER TURBINE SUMP
SENSOR NORMAL

* * * * * END * * * * *

BUY2-033
1023 W 18TH 97402
JUN 20. 2025 2:05 PM
LIQUID STATUS
JUN 20. 2025 2:05 PM
L 1:REGULAR TANK WALL
SENSOR NORMAL
L 2:SUPER TANK WALL
SENSOR NORMAL
L 3:REGULAR TURBINE SUMP
SENSOR NORMAL
L 4:SUPER TURBINE SUMP
SENSOR NORMAL
***** END *****

BUY2-034
1690 W 18TH AVE
EUGENE,OR 97402
541-515-6078
JUN 20. 2025 1:49 PM
LIQUID STATUS
JUN 20. 2025 1:49 PM

BUY2-033
1023 W 18TH
EUGENE OR 97402

JUN 20. 2025 2:05 PM
LIQUID STATUS
JUN 20. 2025 2:05 PM

L 1:REGULAR TANK WALL
SENSOR NORMAL

L 2:SUPER TANK WALL
SENSOR NORMAL

L 3:REGULAR TURBINE SUMP
SENSOR NORMAL

L 4:SUPER TURBINE SUMP
SENSOR NORMAL

***** END *****

L 1:DIESEL SUMP
SENSOR NORMAL

L 2:PREM STP
SENSOR NORMAL

L 3:UNLEADED SUMP
SENSOR NORMAL

L 4:DIESEL ANNULAR SPACE
SENSOR NORMAL

L 5:B99 ANNULAR SPACE
SENSOR NORMAL

L 6:UNL ANNULAR SPACE
SENSOR NORMAL

***** END *****


Re: Inspection results 1690 W 18th Fac # 3299

From TMI Fuel <TMI-Fuel@buy2stores.com>

Date Mon 9/22/2025 10:24 AM

To LITKE Emily * DEQ <Emily.LITKE@deq.oregon.gov>; UST Duty Officer * DEQ <UST.DutyOfficer@DEQ.oregon.gov>; PARDUE Dave * DEQ <Dave.PARDUE@deq.oregon.gov>

Cc Tom <GTMTS@buy2stores.com>; Kevin <GTMTS2@buy2stores.com>

 3 attachments (267 KB)

34_T1_leakhistory (1).pdf; 34_T3_Leakhistory (1).pdf; 34_T2_leakhistory (1).pdf;

Hi Emily,

I believe we sent the correct action documents a while back. Please see the attached files.

Best,

Ali Kulaib

Fuel Director

Thabet Management Inc

O: (+1) 541-565-4472

M: (+1) 541-914-1026

E: tmi-fuel@buy2stores.com

Address: 1700 Valley River Dr. 2nd Floor
Eugene, OR 97401

From: LITKE Emily * DEQ <Emily.LITKE@deq.oregon.gov>

Sent: Friday, September 19, 2025 5:35 PM

To: UST Duty Officer * DEQ <UST.DutyOfficer@DEQ.oregon.gov>; TMI Fuel <TMI-Fuel@buy2stores.com>; PARDUE Dave * DEQ <Dave.Pardue@deq.oregon.gov>

Cc: Tom <GTMTS@buy2stores.com>; Kevin <GTMTS2@buy2stores.com>

Subject: Re: Inspection results 1690 W 18th Fac # 3299

Please provide an update on the corrective actions. Payment of the penalty was processed on 9/15/25.

As soon as payment of the penalty is received, then this UST inspection can be closed.

Corrective Actions-

Submit first month of interstitial monitoring records. Keep the most recent 12 consecutive months of interstitial monitoring records (tank release detection) for review and inspection.



Emily Litke (she/her)

Duty Officer, Underground Storage Tanks

DEQ Headquarters, Land Quality Division

700 NE Multnomah Street, Suite 600

Portland OR 97232-4100

503-806-9516

Emily.LITKE@deq.oregon.gov

From: UST Duty Officer * DEQ <UST.DutyOfficer@DEQ.oregon.gov>

Sent: Thursday, July 24, 2025 9:57 AM

To: TMI Fuel <TMI-Fuel@buy2stores.com>; PARDUE Dave * DEQ <Dave.Pardue@deq.oregon.gov>

Cc: UST Duty Officer * DEQ <UST.DutyOfficer@DEQ.oregon.gov>; Tom <GTMTS@buy2stores.com>; Kevin <GTMTS2@buy2stores.com>

Subject: RE: Inspection results 1690 W 18th Fac # 3299

Good morning,

UST facility 3299 Buy 2 located at 1690 W 18th Eugene, OR 97402

Please review the attached field citation. **The deadline for payment of the \$300 penalty and completion of the corrective actions is 8/24/25.**

Payment can be made either through **check** or **online** through Your DEQ Online – follow the link below to create an account.

[Department of Environmental Quality : Welcome to Your DEQ Online : Online Services : State of Oregon](#)

[PaymentsforEEOs.pdf](#) – step by step instructions on submitting payments online

Questions about online payments and submittals can be directed to the Help Desk at

itservicedesk@deq.oregon.gov or call 503-229-5202

[Your DEQ Online Helpdesk - Jira Service Management](#) –



Emily Litke (she/her)

Duty Officer, Underground Storage Tanks

DEQ Headquarters, Land Quality Division

700 NE Multnomah Street, Suite 600

Portland OR 97232-4100

503-806-9516

Emily.LITKE@deq.oregon.gov

From: TMI Fuel <TMI-Fuel@buy2stores.com>
Sent: Wednesday, July 23, 2025 5:32 AM
To: PARDUE Dave * DEQ <Dave.PARDUE@deq.oregon.gov>
Cc: UST Duty Officer * DEQ <UST.DutyOfficer@DEQ.oregon.gov>; Tom <GTMTS@buy2stores.com>; Kevin <GTMTS2@buy2stores.com>
Subject: Re: Inspection results 1690 W 18th Fac # 3299

Thank you Dave,

The team is working to resolve all the issues.

Best,

Ali Kulaib

Fuel Director

Thabet Management Inc

O: (+1) 541-565-4472

M: (+1) 541-914-1026

E: tmi-fuel@buy2stores.com

Address: 1700 Valley River Dr. 2nd Floor
Eugene, OR 97401

From: PARDUE Dave * DEQ <Dave.PARDUE@deq.oregon.gov>
Sent: Tuesday, July 22, 2025 3:16 PM
To: TMI Fuel <TMI-Fuel@buy2stores.com>
Cc: UST Duty Officer * DEQ <UST.DutyOfficer@DEQ.oregon.gov>
Subject: Inspection results 1690 W 18th Fac # 3299

Hello Lutfi Thabet–

Thank you for facilitating my inspection of your facility on June 23, 2025. I appreciate you having Alex Goucher meet me on-site to assist with the inspection by opening the sumps/equipment for visual observation.

The facility had some compliance issues which need to be addressed as discussed below.

Equipment (at the time of inspection) appeared to be in good order except for the following:

1. The under-dispenser containment sumps beneath dispensers 1/2 and 3/4 were very dirty.

Documentation

2. No monthly tanks release detection records were provided.

This email has two intended recipients: you (permittee) and our enforcement/follow-up team. Because of this split audience, there might be some jargon used which is for DEQ internal purposes. I'll be asking for paperwork/documentation by a specific time; see below for the violation/corrective action.

Alleged Violations:

1. Failure to maintain the last 12 months of records of tank release detection records. 340-150-0465(3). J8.5a.

Corrective Action.

1. Clean and dry the UDCs beneath dispenser 1/2 and 3/4 - send photos to DEQ **by August 10, 2025.**
2. Keep the most recent 12 consecutive months of interstitial monitoring records (tank release detection) for review and inspection.

Next Steps –

Please direct your responses to ust.dutyofficer@deq.oregon.gov. This team will work with me on documents you submit or corrective actions completed to ensure the work is sufficient to close the inspection.

These violations will fit into the field citation guidance and that team will issue enforcement based off a preset calculation matrix.

Regards,

Dave

Dave Pardue
UST Program Coordinator and Inspector
503-360-4287

New UST Service Provider Rules: <https://www.oregon.gov/deq/rulemaking/pages/ust2025.aspx>

YDO is now live for the UST Program- Set up your account here:

<https://www.oregon.gov/deq/permits/Pages/UST-in-YDO.aspx>

To manage your account and link facilities see this link:

<https://www.oregon.gov/deq/permits/Documents/YDO-Account-Registration-and-Management.pdf>

Fee	-	Paid	=	Due
\$ 300.00		\$ 300.00		\$ 0.00

Penalty

▶ 2025-fc-9944 \$ 300.00

ⓘ UST - Field Citation

1 Results

➕ Add Penalty

➡ Send to FIMS

Payment

▼ Check by Mail 9914592725 \$ 300.00

📅 9/15/2025

ⓘ 54971

Type	Amount
Check by Mail	300
E-Payment Confirmation#	E-Payment Settle Date
	mm/dd/yyyy
Ref#	Payment Date
54971	09/15/2025
Comments	
2025-FC-9944	

(Remaining Length: 3988)

Site Info

BUY 2



📍 1690 W 18TH, EUGENE, OR 97402

📞 7854 ✓

📄 202508

📍 CEM_FacilityIdentifier=78449 UST (3299)

📁 Stationary

Inspection Info

8113 Completed

☰ UST

📁 Full Compliance Inspection (FCI) TCR only

📅 Start Date 6/23/2025

📅 End Date 6/23/2025

Created & Updated Info