




ASIG/PFFC
8133 Air Trans Way
Portland, Oregon 97218



Legend

-  Monitoring Well
-  Product Recovery
-  Estimated Plume



Advanced Remediation Technologies, Inc
 690 NW 1st AVENUE, SUITE 104
 CANBY, OREGON 97013 503-266-2122

FIGURE 4
FORMER SOUTH CARGO RELOAD
EMCON INVESTIGATION

Source: Esri, DigitalGlobe, GeoEye, i-cubed, USDA, USGS, AEX, Getmapping, Aerogrid, IGN, IGP, and the GIS User Community

