



Oregon

Tina Kotek, Governor

Department of Environmental Quality

Northwest Region

700 NE Multnomah Street, Suite 600

Portland, OR 97232

(503) 229-5263

FAX (503) 229-6945

TTY 711

August 8, 2025

Marc Westfall
TRMC Retail LLC
PO Box 711
Dallas, TX 75221

RE: UST Compliance Inspection
DEQ UST #12061
Speedway Express

Attention Marc Westfall,

The Oregon Department of Environmental Quality (DEQ) is conducting underground storage tank (UST) inspections throughout Oregon. The purpose of this letter is to inform you that your facility, among others, has been selected for inspection. A thorough inspection of your facility will be conducted to determine compliance with state and federal UST requirements. **The date you receive this letter is the date that the inspection starts.** If you have work done after that date, you will need to have the previous set of records available for evaluation in addition to the most recent records.

The inspection for this facility is scheduled for September 9, 2025, starting at approximately 3 PM. Please note that the inspection will require uninterrupted participation and attendance by you or a knowledgeable assistant. For the inspection you need to provide access to tank sumps, under dispenser areas, cathodic protection rectifiers, and leak monitoring equipment. DEQ will not touch the equipment or monitor, if you are unable to assist with equipment access, please have your UST Service Provider there. This inspection may also include review of Stage I Vapor Recovery.

Please read this entire notice and contact me with any questions about the upcoming inspection.

DEQ requests the following documentation be submitted electronically prior to the inspection. If this is not possible you will need to have compliance testing records available on-site on the day of the inspection. If the records are not available during the day of the inspection, you will have one (1) business day to provide the records to me electronically. After which time this facility will be subject to enforcement actions.

At a minimum the following records are required to complete this inspection:

- Line and leak detector testing results for the past three years,
- Monthly tank leak detection records (12 months),
- Class A, B, and C training documentation.
- Financial responsibility mechanism.
- Annual tank gauge / release detection equipment certification
- Spill prevention testing records
- Overfill Prevention Equipment testing
- Cathodic protection testing (if applicable)
- Tank lining records (if applicable)
- Monthly walkthroughs (last 12 months)

As stated previously, DEQ will not touch any equipment. If you are unable to assist with equipment access, please have your UST Service Provider there to remove manway or sump lids. DEQ will need to observe what equipment is in the tank top sumps and under the dispensers. If ball floats are the primary overfill protection device, these will need to be verified during the inspection, please be able to locate and remove the ball floats.

If violations are found at the time of the inspection without prior notification, DEQ is required to initiate enforcement action. For UST violations, enforcement usually begins with a field citation option, which is much like paying a traffic ticket and making corrections.

Some enforcement situations including repeat violations will go through a longer and more formal process including civil penalties.

Thank you for your cooperation. I can be reached at 503-360-4287 or dave.pardue@deq.oregon.gov to answer any questions you may have and assist you in the preparation for your inspection.

Sincerely,

Dave Pardue

Dave Pardue
UST Program Coordinator
503-360-4287



1: Regular fill



2: Regular sump



3: Premium tank-top sump



4: Premium fill



5: Below Dispenser 1/2



6: Below Dispenser 3/4



7: Dispenser 7/8



8: Below Dispenser 7/8



9: Interstitial access Premium



10: Operating Certificate



11:

12:

Oregon Department of Environmental Quality - Underground Storage Tank Program
Technical Compliance Inspection - UST Inspection Report

Inspector: Dave Pardue

Date:

9/9/25

3 PM

Facility:

12061

I. Site Information

Facility Name: Speedway Expresso

Permittee: MARC Wentfall

Contact: 214

Site Address: 4710 Royal Ave

Organization: 7-11

Phone

City: Eugene

Phone: 214 415 0146

II. Tank Information

DEQ Permit #

BFEK 2 BFEK 2

Estimated Gallons

15000 10000 prem

Substance

GAS GAS

Tank Material

PWFRP →

Tank Install Date

2001 →

Pipe Material

flex →

Pipe Type

press →

Pipe Install Date

2001 →

Overfill Device

Alarm →

Notes and Comments from the UST database:

☐ Check file before conducting inspection

Brine IM - TANK - Dry?? - Nope
ENVIRON Replaced 2017?
Line Tightness for piping

1042 - 1060

If tanks are manifolded, which tanks:

III. Operating Certificate

Compliance

☒ Yes

☐ No

☒ Current

☒ Accurate

☒ Posted for delivery drive to observe

IV. Operator Training

Compliance

☐ Yes

☒ No

Class A/B Operator

☒ Yes

☐ No

Name: Jacob Powell

Date: 5/22/23

Class C Operator

☐ Yes

☒ No

☐ Cardlock

V. Financial Responsibility

Compliance

☒ Yes

☐ No

Type of coverage:

PLI

Begin Date: 12-18-24

End Date: 12-18-25

Coverage amount correct:

1M/2M

Number of tanks covered: 2

Financial responsibility could also be in the form of self insurance, bonds, local government, trust fund, and or guarantee

VI. Walkthrough Requirements

Compliance

☐ Yes

☒ No

Spill prevention and release detection equipment checked monthly?

☐ Yes

☒ No

Tank top sumps checked annually?

☒ Yes

☐ No

6/25 8/25 7/25 4/10/25 10/24
7/25 2/25 12/24 9/24
4/25 11/24

M: 99ing May 2025

VII. Release Detection

Compliance

☒ Yes

☐ No

a) Annual Release Detection Operability Testing (Sometimes referred to as Tank Gauge Certification)

Date of last testing: 1/21/25 - Pass

Last three tests available?

☒ Yes

☐ No

b) Piping Release Detection (Check all that apply)

☒ Pressurized Piping

Line tightness testing

Mechanical Leak Detector (MLLD)

☒ Electronic Leak Detector (ELLD) - check for swiftcheck requirement

Date of last testing: 1/21/25

Last three tests available?

☒ Yes

☐ No

Number of lines tested: 4

Number of LD tested: 2

Leak detector manufacturer make and model: 99LD-2000 VR PLLD

Tank gauge manufacturer make and model: VR MAG 1, MAG 1, MAG PLUS (diesel)

MLLD on turbine manifold?

☒ Yes

☐ No

MLLD product appropriate? (Example, diesel Red Jacket FX series on diesel system?)

☒ Yes

☐ No

If ELLD and no line testing: Annual 0.1 gph results from tank gauge?

☐ Yes

☐ No

c) Interstitial Monitoring

[Monthly records must include, date system was checked, observations made, initials of person checking. Electronic records must include power status (on or off), alarm indication status (yes or no) and sensor malfunction notes (yes or no).]

Date of last sump testing:

Last two tests available?

☐ Yes

☐ No

Date of last sensor testing:

Last three tests available?

☐ Yes

☐ No

Float sensors installed correctly?

☐ Yes

☐ No

Interstitial space opened to sump?

☐ Yes

☐ No

Presence of water in sumps?

☐ Yes

☐ No

Safe Suction

Check valve directly below suction pump?

☐ Yes

☐ No

c) Monthly Tank Release Detection (Check all that apply)

☒ Tank Gauge

CSLD

☐ SCALD

☐ Static

Are correct tank sizes programmed at tank gauge?

☐ Yes

☐ No

Tank diameter/length seem appropriate?

☐ Yes

☐ No

Are tanks manifolded?

☐ Yes

☐ No

If so, tank gauge testing setup for manifolded tanks?

☐ Yes

☐ No

If Veeder Root tank gauge leak detection

☐ CSLD set at 99%

☐ Thermal coefficient set correctly?

(Gasoline 0.00070; Diesel 0.00045)

If Incon/Franklin tank gauge leak detection

☐ If SCALD is Vol Qual set to 14% (or 99% confidence)

☐ Is API gravity set correctly?

(Regular 63.5; Plus 62.8; Super 51.3; Diesel 32.8)

For all tank gauges doing static tests

(Static tests require tank to be 50% full for a valid test)

d) Interstitial Monitoring [Monthly records must include, date system was checked, observations made, initials of person checking.

Electronic records must include power status (on or off), alarm indication status (yes or no) and sensor malfunction notes (yes or no).]

☐ SIR

Ensure pass or fail results within 30-day period. Inconclusive result means release detection requirement not met

Tank release detection records available during inspection

T1:	☐ Jan	☐ Feb	☐ Mar	☐ Apr	☐ May	☐ Jun	☐ Jul	☒ Aug	☐ Sep	☐ Oct	☐ Nov	☐ Dec
T2:	☐ Jan	☐ Feb	☐ Mar	☐ Apr	☐ May	☐ Jun	☐ Jul	☐ Aug	☐ Sep	☐ Oct	☐ Nov	☐ Dec
T3:	☐ Jan	☐ Feb	☐ Mar	☐ Apr	☐ May	☐ Jun	☐ Jul	☐ Aug	☐ Sep	☐ Oct	☐ Nov	☐ Dec
T4:	☐ Jan	☐ Feb	☐ Mar	☐ Apr	☐ May	☐ Jun	☐ Jul	☐ Aug	☐ Sep	☐ Oct	☐ Nov	☐ Dec
T5:	☐ Jan	☒ Feb	☐ Mar	☐ Apr	☐ May	☐ Jun	☐ Jul	☐ Aug	☐ Sep	☐ Oct	☐ Nov	☐ Dec

Inspector: PARQUE Date: 9/9/25 Time: 3 PM Facility: 12061

VIII. Spill Prevention		Compliance		☒ Yes	☐ No
Date(s) of testing: <u>1/21/25</u>		Number of spill buckets tested? <u>2</u>			
Did spill bucket pass most recent testing?	☒ Yes	☐ No	If no, was spill bucket replaced/repaired?	☐ Yes	☐ No
During inspection, visual damage to spill bucket?	☐ Yes	☐ No			
☐ Hydrostatic testing (test takes one hour to complete)					
☐ Vacuum test (test takes 1 minute, ending vacuum must be 26 inches water column or greater)					

IX. Overfill Prevention		Compliance		☒ Yes	☐ No
Date(s) of testing: <u>2/6/25</u>					
Overfill device pass most recent testing?	☒ Yes	☐ No	If no, overfill device replaced?	☐ Yes	☐ No
Overfill method that was tested:	☒ Alarm	☒ Flapper	☐ Ball Float		
<u>Overfill Alarm</u>					
Alarm sounds when tank is 90% full	☒ Yes	☐ No			
Driver can see or hear alarm at point of transfer?	☒ Yes	☐ No			
Sound alarm from tank gauge during inspection?	☒ Yes	☐ No			
<u>Flapper Valve</u>					
Testing verified the valve automatically restricts flow at 95%	☒ Yes	☐ No			
Visual observation of flapper on day of inspection?	☒ Yes	☐ No			
<u>Ball Float</u>					
Testing verified the ball float automatically restricts flow at 90%	☒ Yes	☐ No			
Visual observation of ball float during inspection?	☐ Yes	☐ No	<u>NA</u>		

X. Corrosion Protection		Compliance		☒ Yes	☐ No
☐ Cathodic	☐ Galvanic	☐ Impressed Current			
Steel tank with cathodic?		☐ Yes	☐ No	<u>Non ferrous</u>	
Steel pipes with cathodic?		☐ Yes	☐ No		
Steel flex-lines with cathodic?		☐ Yes	☐ No		
Date of cathodic test: _____					
Last two tests available?		☐ Yes	☐ No		
Did last test pass?		☐ Yes	☐ No		
If not:					
Was failed test reported to DEQ?		☐ Yes	☐ No		
Was system repaired?		☐ Yes	☐ No		
Date of repair? _____					
Cathodic retested within 6 mos. of repair?		☐ Yes	☐ No		
Date of retesting? _____					
If impressed current system:					
Rectifier Operational?		☐ Yes	☐ No		
Rectifier log maintained?		☐ Yes	☐ No		
Rectifier been operating continuously		☐ Yes	☐ No		
☐ Tank Lining					
Date of lest test? _____					
Pressure test conducted after tank lining inspection?		☐ Yes	☐ No		

XI. General notes from inspection



Representative onsite:

TANK Testers

email:

Joe
Mariell

tank testers@gmail.com





Dual point

Dual point

10 K Mem

Reg 15K



sensor

much corrosion

Boots OK

Compliance Determination:

☐ No Violations Observed

☐ Observed violations resulting in enforcement

Inspector Signature:

[Handwritten Signature]

Date:

9/9/25



State of Oregon
Department of
Environmental
Quality

Program Enforcement No. 2025-FC-10003

This section for
DEQ use only

Department of Environmental Quality
Underground Storage Tank Program

Field Citation
For UST Violations

Page 1 of 3

DEQ Information		UST Facility Information	
Inspection Date:	09/09/2025	Facility ID#:	12061
Inspector:	Dave Pardue	Facility Name:	SPEEDWAY NO. 9484
DEQ Office:	700 NE Multnomah St	Facility Address:	4710 ROYAL AVE, EUGENE, Oregon 97402
Phone #:		County:	Lane

Oregon DEQ inspected the facility listed above and identified the UST violations listed on page 3 of this Field Citation.

Field Citation Issued:	☐ In Person	☒ By Email	☐ Both	Date Issued: 10/02/2025
Facility Representative Present During Inspection:	Marc Westfall			☐ Permittee ☐ Owner ☐ Other
Name of Permittee or Owner:	TRMC Retail LLC			
Mailing Address:	PO Box 711 , Dallas Texas 75221			
Field Citation Penalty – See Page 3 for a detailed listing of each violation.				\$ 200

Check payable to: DEQ Financial Services LBX3615; P.O. Box 3615; Portland OR 97208-3615

Or pay online through your YDO account

This Field Citation is issued in accordance with the requirements for the expedited enforcement of Underground Storage Tank (UST) violations, OAR 340-150-0250.

Owner or Permittee should select Option 1 or Option 2 below and return a signed copy of this form to DEQ by the following date: 11/02/2025

DEQ Revenue Section
700 NE Multnomah St. #600
Portland, Oregon 97232

Check one option

- ☐ **Option 1** - I acknowledge that the listed violation(s) have occurred, and I am remitting the listed field citation penalty.
- ☐ **Option 2** - I do not want to participate in the expedited enforcement process and understand that my file will be referred to the Department's Office of Compliance and Enforcement for formal enforcement action.

Name:	Owner / Permittee
Signature:	Date:

Important

Read pages 2 and 3 for more information about your options and a detailed listing of violations and compliance requirements.

Field Citation Requirements

The permittee or owner should select Option 1 or Option 2 and return a signed copy of Page 1 of the Field Citation form within thirty (30) days of issuance of the Field Citation. If the permittee or owner fails to sign and send Page 1 of the Field Citation form back or pay the penalty within thirty days, Option 1 expires, the Field Citation will serve as a Pre-Enforcement Notice (PEN) and the permittee and owner will be subject to formal enforcement, including the imposition of civil penalties in accordance with OAR Chapter 340, Division 12.

The permittee or owner must complete the actions required to correct the violations listed on the Field Citation by the date specified to prevent further enforcement action by DEQ.

Option 1:

By checking Option 1, the permittee or owner acknowledges that the violations listed on Page 3 of this Field Citation have occurred and agrees to pay the established penalty.

By submitting payment of the penalty amount, the responding permittee or owner agrees to accept the field citation as a final order of the Environmental Quality Commission (commission) and waives any and all rights and objections to the form, content, manner of service and timeliness of the Field Citation; to a contested case hearing and judicial review of the Field Citation [OAR 340-150-0250(6)]; and to service of a copy of this Final Order (*i.e.*, no other copy will be provided).

Upon the Department's receipt of payment of the penalty amount set forth in the Field Citation, the Field Citation becomes a Final Order of the Commission that:

1. Imposes upon the permittee or owner a civil penalty in the amount listed on Page 1 of this Field Citation; and
2. Requires the permittee or owner to satisfactorily complete the requirements and actions necessary to correct the violations documented by the dates set forth on Page 3 of this Field Citation.

Failure by the permittee or owner to complete the actions set forth on Page 3 of the Field Citation by the specified date violates the Commission Order and subjects the permittee and owner to a formal enforcement action, including the imposition of additional civil penalties.

Option 2:

The permittee or owner may deny that the violations as listed on Page 3 of this Field Citation have occurred or contest the Field Citation process by checking Option 2 and submitting to the Department a signed copy of Page 1 of the Field Citation. In that event, the Field Citation will serve as a Pre-Enforcement Notice (PEN) and the permittee and owner will be subject to formal enforcement for those violations set forth in the Field Citation, including the imposition of civil penalties in accordance with OAR Chapter 340, Division 12. Civil penalties that will be imposed by the formal enforcement process will exceed the Field Citation penalties for the same violation(s).

The Department appreciates your cooperation and efforts to comply with the regulations for underground storage tank systems.

UST FIELD CITATION**DATE ISSUED: 10/02/2025****PROGRAM ENFORCEMENT No.: 2025-FC-10003****FACILITY ID: 12061****Page 3 of 3**

Violation #1: *TCR:	(A17) Failure to maintain records of periodic operation and maintenance walkthrough inspections for one year.		
Corrective Action:	No corrective action required as the missing records have been provided.		
Rule Citation: OAR 340-150-0315(2)	Penalty Amount: \$ 150	Correct Violation by: n/a	Date Violation Corrected: 09/09/2025
Violation #2: *TCR:	Failure to provide documentation of compliance with operator training upon request		
Corrective Action:	No corrective action required as the missing records have been provided.		
Rule Citation: OAR 340-150-0210 (7)(b)	Penalty Amount: \$ 50	Correct Violation by: n/a	Date Violation Corrected: 09/09/2025
Violation #3: *TCR:			
Corrective Action:			
Rule Citation: OAR	Penalty Amount: \$	Correct Violation by:	Date Violation Corrected:
Violation #4: *TCR:			
Corrective Action:			
Rule Citation: OAR	Penalty Amount: \$	Correct Violation by:	Date Violation Corrected:
Violation #5: *TCR:			
Corrective Action:			
Rule Citation: OAR	Penalty Amount: \$	Correct Violation by:	Date Violation Corrected:
Violation #6: *TCR:			
Corrective Action:			
Rule Citation: OAR	Penalty Amount: \$	Correct Violation by:	Date Violation Corrected:
Total Penalty Amount: \$ 200			

YOU MUST CORRECT THE VIOLATIONS AS REQUIRED, ENTER THE DATES CORRECTED, SIGN THE STATEMENT BELOW, AND**RETURN THIS FORM TO THE DEQ INSPECTOR LISTED ON PAGE 1 ON OR BEFORE: 11/02/2025****Retain a copy of this form and all documentation of corrective actions for your records.***I hereby certify that the UST violations noted above have been corrected:* _____/_____*Permittee/Owner Signature**Date*

Re: Results of 9.9.25 Full Compliance Inspection Facility 12061 Speedway Express

From UST Duty Officer * DEQ <UST.DutyOfficer@DEQ.oregon.gov>

Date Thu 10/2/2025 10:45 AM

To PARDUE Dave * DEQ <Dave.PARDUE@deq.oregon.gov>; Westfall, Marc <Marc.Westfall@7-11.com>

Cc UST Duty Officer * DEQ <UST.DutyOfficer@DEQ.oregon.gov>; Powell, Jacob <Jacob.Powell@7-11.com>

 1 attachment (237 KB)

2025-fc-10003 issued to 12061.pdf;

Good morning,
UST facility 12061 Speedway 9484 located at 4710 Royal Ave Eugene, OR

Please review the attached field citation. The deadline for payment of the \$200 penalty is 11/2/25. The corrective actions are already complete and need no additional follow up.

Payment of Field Citation Penalty Instructions

Payment can be made either through **check** or **online** through Your DEQ Online – follow the link below to create an account.

[Department of Environmental Quality : Welcome to Your DEQ Online : Online Services : State of Oregon](#)

[PaymentsforEEOs.pdf](#) – step by step instructions for submitting payments online

Questions about online payments and submittals can be directed to the Help Desk at

itservicedesk@deq.oregon.gov or

[Your DEQ Online Helpdesk - Jira Service Management](#) –



Emily Litke (she/her)

Duty Officer, Underground Storage Tanks

DEQ Headquarters, Land Quality Division

700 NE Multnomah Street, Suite 600

Portland OR 97232-4100

503-806-9516

Emily.LITKE@deq.oregon.gov

From: PARDUE Dave * DEQ <Dave.PARDUE@deq.oregon.gov>
Sent: Wednesday, October 1, 2025 3:21 PM
To: Westfall, Marc <Marc.Westfall@7-11.com>
Cc: UST Duty Officer * DEQ <UST.DutyOfficer@DEQ.oregon.gov>; Powell, Jacob <Jacob.Powell@7-11.com>
Subject: RE: Results of 9.9.25 Full Compliance Inspection Facility 12061 Speedway Express

Hi Marc-

He did. Sorry if that was confusing. No further action or documents are needed.

Regards,
Dave

From: Westfall, Marc <Marc.Westfall@7-11.com>
Sent: Wednesday, October 1, 2025 3:05 PM
To: PARDUE Dave * DEQ <Dave.PARDUE@deq.oregon.gov>
Cc: UST Duty Officer * DEQ <UST.DutyOfficer@DEQ.oregon.gov>; Powell, Jacob <Jacob.Powell@7-11.com>
Subject: RE: Results of 9.9.25 Full Compliance Inspection Facility 12061 Speedway Express

Hi,
My understanding is Jacob provided the correction documents to you directly as indicated in your notice. Are you saying we need to send them again per the below? Please advise.
Thanks

Next Steps –

Please direct your responses to ust.dutyofficer@deq.oregon.gov. This team will work with me on documents you submit or corrective actions completed to ensure the work is sufficient to close the inspection.

These violations will fit into the field citation guidance and that team will issue enforcement based off a preset calculation matrix.

Marc Westfall

7-Eleven, Inc./SEI Fuel Services

Region Manager – Environmental/Gasoline Compliance

CO/UT/WA/OR/AZ/NM/AK/ID

Cell - 214-415-0146

Email - marc.westfall@7-11.com



From: PARDUE Dave * DEQ <Dave.PARDUE@deq.oregon.gov>
Sent: Wednesday, October 1, 2025 3:49 PM
To: Westfall, Marc <Marc.Westfall@7-11.com>; Powell, Jacob <Jacob.Powell@7-11.com>
Cc: UST Duty Officer * DEQ <UST.DutyOfficer@DEQ.oregon.gov>
Subject: Results of 9.9.25 Full Compliance Inspection Facility 12061 Speedway Express

****External - Potential security risk - Exercise caution****

Hello Marc Westfall–

Thank you for facilitating my inspection of your facility on September 09, 2025. I appreciate your assisting with the inspection by having your service provider open the sumps/equipment for visual observation.

The facility had some compliance issues which need to be addressed as discussed below.

Equipment (at the time of inspection) appeared to be clean and in good order.

Documentation

1. No Class C Operator records were available.
2. The monthly walkthrough inspection record from May 2025 was not available.

This email has two intended recipients: you (permittee) and our enforcement/follow-up team. Because of this split audience, there might be some jargon used which is for DEQ internal purposes. I'll be asking for paperwork/documentation by a specific time; see below for the violation/corrective action.

Alleged Violations:

1. Failure to maintain records of periodic Operation and Maintenance Walkthrough Inspections for one year. 340-150-0315(2). A17.
2. Failure to provide documentation of compliance with operator training 340-150-0210(10)(b). A5b.

Corrective Action- begin immediately.

1. No corrective action required as the missing records have been provided.
2. No corrective action required as the missing record has been provided.

Next Steps –

Please direct your responses to ust.dutyofficer@deq.oregon.gov. This team will work with me on documents you submit or corrective actions completed to ensure the work is sufficient to close the inspection.

These violations will fit into the field citation guidance and that team will issue enforcement based off a preset calculation matrix.

Regards,

Dave

Dave Pardue
UST Program Coordinator and Inspector
503-360-4287

New UST Service Provider Rules: <https://www.oregon.gov/deq/rulemaking/pages/ust2025.aspx>

YDO is now live for the UST Program- Set up your account here:

<https://www.oregon.gov/deq/permits/Pages/UST-in-YDO.aspx>

To manage your account and link facilities see this link:

<https://www.oregon.gov/deq/permits/Documents/YDO-Account-Registration-and-Management.pdf>

Fee	—	Paid	=	Due
\$ 200.00		\$ 200.00		\$ 0.00

Penalty

▶ 2025-fc-10003

📌 UST - Field Citation

\$ 200.00

1 Results

➕ Add Penalty

➡ Send to FIMS

Payment

▼ Check by Mail 0021176404

📅 10/16/2025

📌 56717

\$ 200.00

Type	Amount
Check by Mail	200

E-Payment Confirmation#	E-Payment Settle Date
	mm/dd/yyyy

Ref#	Payment Date
56717	10/16/2025

Comments

2025-FC-10003

(Remaining Length: 3987)

1 Results

Site Info

SPEEDWAY NO. 9484



📍 4710 ROYAL AVE, EUGENE, OR 97402

📌 85278 ✓

📌 301325

📌 CEM_FacilityIdentifier=37298 UST (12061)

📁 Stationary

Inspection Info

10564 Completed

📌 UST

📁 Full Compliance Inspection (FCI) TCR only

📅 Start Date 9/9/2025 End Date 9/9/2025

Created & Updated Info