



Oregon

Tina Kotek, Governor

Department of Environmental Quality

Headquarters Office

700 NE Multnomah Street, Suite 600

Portland, OR 97232

(503) 229-5263

TTY 711

August 12, 2025

Jim Daniels
Rosboro Company LLC
170 S 21st
Springfield, OR 97477

RE: UST Compliance Inspection
DEQ UST #2652
Rosboro Forklift Shop

Attention Mr. Daniels,

The Oregon Department of Environmental Quality (DEQ) is conducting underground storage tank (UST) inspections throughout Oregon. The purpose of this letter is to inform you that your facility, among others, has been selected for inspection. A thorough inspection of your facility will be conducted to determine compliance with state and federal UST requirements. **The date you receive this letter is the date that the inspection starts.** If you have work done after that date, you will need to have the previous set of records available for evaluation in addition to the most recent records.

If I do not hear from you, the inspection for this facility is scheduled for September 17, 2025, starting at approximately 9:00 am. Please note that the inspection will require uninterrupted participation and attendance by you or a knowledgeable assistant. For the inspection you need to provide access to tank sumps, under dispenser areas, cathodic protection rectifiers, and leak monitoring equipment. DEQ will not touch the equipment or enter the facility, if you are unable to assist with equipment access, please have your UST Service Provider there. This inspection may also include review of Stage I Vapor Recovery.

To complete this inspection, you will need to have compliance testing records available on-site on the day of the inspection or sent to me prior to the inspection at blakely.gilbert@deq.oregon.gov. If the records are not available during the day of the inspection, you will have five (5) business days to provide the records to me electronically. After which time this facility will be subject to enforcement actions.

At a minimum the following records are required to complete this inspection:

- Line and leak detector testing results for the past three years,
- Monthly tank leak detection records (12 months),
- Class A, B, and C training documentation.
- Financial responsibility mechanism.
- Annual tank gauge / release detection equipment certification
- Spill prevention testing records
- Overfill Prevention Equipment testing
- Cathodic protection testing (if applicable)
- Tank lining records (if applicable)
- Monthly walkthroughs

As stated previously, DEQ will not touch any equipment and if you are unable to assist with equipment access, please have your UST Service Provider there to remove manway or sump lids. DEQ will need to observe what equipment is in the tank top sumps and under the dispensers. If ball floats are the primary overfill protection device, these will need to be verified during the inspection, please be able to locate and remove the ball floats.

If violations are found at the time of the inspection without prior notification, DEQ is required to initiate enforcement action. For UST violations, enforcement usually begins with a field citation option, which is much like paying a traffic ticket and making corrections.

Some enforcement situations including repeat violations will go through a longer and more formal process including civil penalties.

Thank you for your cooperation. I can be reached at 503-360-4408 or blakely.gilbert@deq.oregon.gov to answer any questions you may have and assist you in the preparation for your inspection.

Sincerely,

Blake Gilbert
UST Compliance Specialist
Headquarters Office

UST Inspection Survey

Submitted by: blakely.gilbert_deq

Submitted time: Sep 30, 2025, 9:37:06 AM

Date

Sep 30, 2025

Time

08:44

UST Facility ID

2,652

Inspector


Gilbert

Type of Inspection

Full Compliance

Location

Lat: 44.045341 Lon: -122.994741



Esri, FAO, NOAA, USGS

Powered by Esri

Photograph






photos-20250930-154930.jpg




photos-20250930-161727.jpg





photos-20250930-154800.jpg





Original Department of Environmental Quality - Underground Storage Tank Program
Technical Compliance Inspection - UST Inspection Report

Inspection Date: 1/2/2024 Date: 1/2/2024 Permit: 2652

Facility Name: Resolute Truck Stop Location: 170 South 21st Street
City: Springfield, OH Zip: 45507 Phone: 513-776-2146

Owner: Resolute Truck Stop Operator: Resolute Truck Stop
Tank Information: 10000 10000 10000 10000
Tank Material: B6C7H B6C7J B6C7K Tank
Tank Capacity: 10000 10000 10000 10000
Tank Type: Diesel Diesel Gas
Tank Model: FRP FRP FRP
Tank Install Date: 1992 1992 1992

Pump Material: Sub Section Sub Section Sub Section
Pump Type: Sub Section Sub Section Sub Section
Pump Install Date: Automatic Automatic Automatic

Overfill Device: Automatic Automatic Automatic
Notes and Comments from the UST database: 6105-11 alarm, 21st and full flame? 6-11
POS - Positive Shutoff - "Flapper"
3- Sent Sensor - 21st and full flame? Verify L" Liquid Sensor Setup
3- Regular Sensor - 21st and full flame? Verify Set up before
Verify Alarm History "R"

If tanks are manifolded, which tanks:

Operating Certificate: ☒ Current ☐ Accurate ☐ Period for delivery drive to observe
Class A/B Operator: ☒ Yes ☐ No Name: Matt Nida Date: 6-9-25
Class C Operator: ☒ Yes ☐ No ☐ Cardlock

Financial Responsibility: ☒ Insurance ☐ Other
Type of coverage: Insurance Begin Date: 1/1/2024 End Date: 1/1/2026
Coverage amount correct: ☒ Yes ☐ No Number of tanks covered: 3
Financial responsibility shall also be in the form of self-insurance, bond, first government, trust fund, and/or guarantee

Multi-tank Requirements: ☒ Yes ☐ No
All prevention and release detection equipment checked monthly? ☒ Yes ☐ No
Tank top joints checked annually: ☒ Yes ☐ No
Page 1 of 4
Not done 10/2024

Math 541-554-9749

Leads H
Site vi.

Oregon Department of Environmental Quality - Underground Storage Tank Program
Technical Compliance Inspection - UST Inspection Report

Inspector: Blake Gilbert

Date: 9/30/25

Time: 9AM

Facility: 2652

I. Site Information

Facility Name: Rosboro Forklift shop	Permittee: Jim Daniel	Contact: 541-736-2146
Site Address: 170 South 21st	Organization:	Phone:
City: Springfield OR 97477	Phone:	

II. Tank Information

	1A	2A	3A		
DEQ Permit #	BCLJH	BCLJJ	BCLKK	TANK	
Estimated Gallons	10000	10000	4000		
Substance	Diesel	Diesel	Gas		
Tank Material ^{DW}	FRP	FRP	FRP		
Tank Install Date	1992	1992	1992		
Pipe Material					
Pipe Type	Safe Suction	Safe Suction	Safe Suction		
Pipe Install Date					
Overfill Device	Automatic Alarm	Automatic Alarm	Automatic Alarm		

Notes and Comments from the UST database:

overfill alarm, 2 LSV and ~~Ball floats~~? ☐ Check file before conducting inspection

POS - positive shut-off - "Flapper"

3 - Samp Sensor - Piping Samp Sensor

3 - Annular Sensors - Annular space sensors

Verify "L" Liquid Sensor setup
Verify Set up Report

* Verify Alarm History "R"

If tanks are manifolded, which tanks:

III. Operating Certificate

☒ Current	☒ Accurate	☒ Posted for delivery drive to observe	Compliance ☒ Yes ☐ No
---	--	--	--

IV. Operator Training

Class A/B Operator ☒ Yes ☐ No	Name: Matt Nida	Date: 6-9-25	Compliance ☒ Yes ☐ No
Class C Operator ☒ Yes ☐ No	☐ Cardlock		

V. Financial Responsibility

Type of coverage: Insurance	Begin Date: Aug-1st 2025	End Date: Aug-1st 2026	Compliance ☒ Yes ☐ No
Coverage amount correct: ☒ Yes ☐ No	Number of tanks covered: 3		

Financial responsibility could also be in the form of self insurance, bonds, local government, trust fund, and or guarantee

VI. Walkthrough Requirements

Spill prevention and release detection equipment checked monthly?	☒ Yes ☐ No	Compliance ☒ Yes ☐ No
Tank top sumps checked annually?	☒ Yes ☐ No	

VII. Release Detection

a) Annual Release Detection Operability Testing (Sometimes referred to as Tank Gauge Certification)

Compliance

☐ Yes ☒ No

Date of last testing: 5-27-25

Missed
↓
2024

Last three tests available?

☐ Yes ☒ No

b) Piping Release Detection (Check all that apply)

☒ Pressurized Piping

☐ Mechanical Leak Detector (MLLD)

☐ Electronic Leak Detector (ELLD) - check for swiftcheck requirement

"Safe Suction"

Date of last testing: _____

Last three tests available?

☐ Yes ☐ No

Number of lines tested: _____

Number of LD tested: _____

Leak detector manufacturer make and model: VR

Tank gauge manufacturer make and model: VR TLS-350

MLLD on turbine manifold?

☐ Yes ☐ No

MLLD product appropriate? (Example, diesel Red Jacket FX series on diesel system?)

☐ Yes ☐ No

If ELLD and no line testing: Annual 0.1 gph results from tank gauge?

☐ Yes ☐ No

☒ Interstitial Monitoring

[Monthly records must include, date system was checked, observations made, initials of person checking. Electronic records must include power status (on or off), alarm indication status (yes or no) and sensor malfunction notes (yes or no).]

Date of last sump testing: _____

Last two tests available?

☐ Yes ☐ No

Date of last sensor testing: _____

Last three tests available?

☐ Yes ☐ No

Float sensors installed correctly?

☐ Yes ☐ No

Interstitial space opened to sump?

☐ Yes ☐ No

Presence of water in sumps?

☐ Yes ☐ No

☒ Safe Suction Line tightness test ? Not needed if valve is at dispenser

Check valve directly below suction pump? ☒ Yes ☐ No

c) Monthly Tank Release Detection (Check all that apply)

☒ Tank Gauge ☐ CSLD ☐ SCALD ☐ Static

Are correct tank sizes programmed at tank gauge?

☐ Yes ☐ No

Tank diameter/length seem appropriate?

☐ Yes ☐ No

Are tanks manifolded?

☐ Yes ☐ No

If so, tank gauge testing setup for manifolded tanks?

☐ Yes ☐ No

If Veeder Root tank gauge leak detection

☒ CSLD set at 99%

☒ Thermal coefficient set correctly?

(Gasoline 0.00070; Diesel 0.00045)

If Incon/Franklin tank gauge leak detection

☐ If SCALD is Vol Qual set to 14% (or 99% confidence)

☐ Is API gravity set correctly?

(Regular 63.5; Plus 62.8; Super 51.3; Diesel 32.8)

For all tank gauges doing static tests

(Static tests require tank to be 50% full for a valid test)

☒ Interstitial Monitoring [Monthly records must include, date system was checked, observations made, initials of person checking.

Electronic records must include power status (on or off), alarm indication status (yes or no) and sensor malfunction notes (yes or no).]

☐ SIR

Ensure pass or fail results within 30-day period. Inconclusive result means release detection requirement not met

Tank release detection records available during inspection

T1: ☐ Jan ☐ Feb ☐ Mar ☐ Apr ☐ May ☐ Jun ☐ Jul ☐ Aug ☐ Sep ☐ Oct ☐ Nov ☐ Dec

T2: ☐ Jan ☐ Feb ☐ Mar ☐ Apr ☐ May ☐ Jun ☐ Jul ☐ Aug ☐ Sep ☐ Oct ☐ Nov ☐ Dec

T3: ☐ Jan ☐ Feb ☐ Mar ☐ Apr ☐ May ☐ Jun ☐ Jul ☐ Aug ☐ Sep ☐ Oct ☐ Nov ☐ Dec

T4: ☐ Jan ☐ Feb ☐ Mar ☐ Apr ☐ May ☐ Jun ☐ Jul ☐ Aug ☐ Sep ☐ Oct ☐ Nov ☐ Dec

T5: ☐ Jan ☐ Feb ☐ Mar ☐ Apr ☐ May ☐ Jun ☐ Jul ☐ Aug ☐ Sep ☐ Oct ☐ Nov ☐ Dec

IM - for tanks operating on VR TLS-350 - Test tank per month - PDF results, print out good.

Inspector: Blake Gilbert

Date: 9-17-25

Time: 9:00 AM

Facility: 2652

VIII. Spill Prevention

Compliance

☒ Yes ☐ No

Date(s) of testing:

3/21/23

4/28/2020

Number of spill buckets tested?

3

Did spill bucket pass most recent testing? ☐ Yes ☐ NoIf no, was spill bucket replaced/repaired? ☐ Yes ☐ NoDuring inspection, visual damage to spill bucket? ☐ Yes ☐ No☒ Hydrostatic testing (test takes one hour to complete)☐ Vacuum test (test takes 1 minute, ending vacuum must be 26 inches water column or greater)**IX. Overfill Prevention**

Compliance

☒ Yes ☐ No

Date(s) of testing:

5-27-25

9-11-23

Overfill device pass most recent testing? ☐ Yes ☐ No

If no, overfill device replaced?

☒ Yes ☐ No

Overfill method that was tested:

☐ Alarm☐☐ Flapper☐ Ball FloatOverfill Alarm☒

?

Alarm sounds when tank is 90% full

☒ Yes ☐ No

Driver can see or hear alarm at point of transfer?

☒ Yes ☐ No

Sound alarm from tank gauge during inspection?

☒ Yes ☐ NoFlapper Valve

Testing verified the valve automatically restricts flow at 95%

☒ Yes ☐ No

Visual observation of flapper on day of inspection?

☒ Yes ☐ NoBall Float

Testing verified the ball float automatically restricts flow at 90%

☐ Yes ☐ No

Visual observation of ball float during inspection?

☐ Yes ☐ No**X. Corrosion Protection**

Compliance

☒ Yes ☐ No☐ Cathodic☐ Galvanic☐ Impressed Current

Steel tank with cathodic?

☐ Yes ☐ No

Steel pipes with cathodic?

☐ Yes ☐ No

Steel flex-lines with cathodic?

☐ Yes ☐ No

Date of cathodic test: _____

Last two tests available?

☐ Yes ☐ No

Did last test pass?

☐ Yes ☐ No

If not:

Was failed test reported to DEQ?

☐ Yes ☐ No

Was system repaired?

☐ Yes ☐ No

Date of repair? _____

Cathodic retested within 6 mos. of repair?

☐ Yes ☐ No

Date of retesting? _____

If impressed current system:

Rectifier Operational?

☐ Yes ☐ No

Rectifier log maintained?

☐ Yes ☐ No

Rectifier been operating continuously

☐ Yes ☐ No☐ Tank Lining

Date of last test? _____

Pressure test conducted after tank lining inspection?

☐ Yes ☐ No

XI. General notes from inspection

Representative onsite: _____ email: _____

Sump and u/c sump clean and dry - Records keeping good -

Violations: No Annual Release detection operability test "Tank Bore CWT" not done in 2024 it was missed.

Cited: G-5 $\nearrow$ 340-130-0400(2) class 1 \$100.00

u/c test

LOK
PIC

LOK
PIC



Compliance Determination: ☐ No Violations Observed

☒ Observed violations resulting in enforcement - G-5

Blake Gilbert

Inspector Signature: _____

Date: _____

10/1/25

Rosboro Forklift Shop # 2652

Violation:

No Annual release detection operability testing "Tank gauge Certificate"

G-5 Failing to test for operability or running condition annually for 2024. 340-150-0400(2)

Class 1 \$100.00

Alarm -

Notes:

Sumps and UDC clean and dry – good record keeping -



State of Oregon
Department of
Environmental
Quality

Program Enforcement No. 2025-FC-10004

This section for
DEQ use only

Department of Environmental Quality
Underground Storage Tank Program

Field Citation
For UST Violations

Page 1 of 3

DEQ Information		UST Facility Information	
Inspection Date:	09/30/2025	Facility ID#:	2652
Inspector:	Blakely GILBERT	Facility Name:	ROSBORO FORKLIFT SHOP
DEQ Office:	700 NE Multnomah St Suite 600 FLR # 14	Facility Address:	170 SOUTH 21ST, SPRINGFIELD, Oregon 97477
Phone #:	503-360-4408	County:	Lane

Oregon DEQ inspected the facility listed above and identified the UST violations listed on page 3 of this Field Citation.

Field Citation Issued:	☐ In Person	☒ By Email	☐ Both	Date Issued: 10/02/2025
Facility Representative Present During Inspection:	☐ Permittee ☐ Owner ☐ Other			
Name of Permittee or Owner:	Rosboro Company LLC			
Mailing Address:	PO Box 20 , Springfield Oregon 97477			

Field Citation Penalty – See Page 3 for a detailed listing of each violation. \$ 100

Check payable to: DEQ Financial Services LBX3615; P.O. Box 3615; Portland OR 97208-3615

Or pay online through your YDO account

This Field Citation is issued in accordance with the requirements for the expedited enforcement of Underground Storage Tank (UST) violations, OAR 340-150-0250.

Owner or Permittee should select Option 1 or Option 2 below and return a signed copy of this form to DEQ by the following date: 11/02/2025

DEQ Revenue Section
700 NE Multnomah St. #600
Portland, Oregon 97232

Check one option

- ☐ **Option 1** - I acknowledge that the listed violation(s) have occurred, and I am remitting the listed field citation penalty.
- ☐ **Option 2** - I do not want to participate in the expedited enforcement process and understand that my file will be referred to the Department's Office of Compliance and Enforcement for formal enforcement action.

Name:	Owner / Permittee
Signature:	Date:

Important

Read pages 2 and 3 for more information about your options and a detailed listing of violations and compliance requirements.

Field Citation Requirements

The permittee or owner should select Option 1 or Option 2 and return a signed copy of Page 1 of the Field Citation form within thirty (30) days of issuance of the Field Citation. If the permittee or owner fails to sign and send Page 1 of the Field Citation form back or pay the penalty within thirty days, Option 1 expires, the Field Citation will serve as a Pre-Enforcement Notice (PEN) and the permittee and owner will be subject to formal enforcement, including the imposition of civil penalties in accordance with OAR Chapter 340, Division 12.

The permittee or owner must complete the actions required to correct the violations listed on the Field Citation by the date specified to prevent further enforcement action by DEQ.

Option 1:

By checking Option 1, the permittee or owner acknowledges that the violations listed on Page 3 of this Field Citation have occurred and agrees to pay the established penalty.

By submitting payment of the penalty amount, the responding permittee or owner agrees to accept the field citation as a final order of the Environmental Quality Commission (commission) and waives any and all rights and objections to the form, content, manner of service and timeliness of the Field Citation; to a contested case hearing and judicial review of the Field Citation [OAR 340-150-0250(6)]; and to service of a copy of this Final Order (*i.e.*, no other copy will be provided).

Upon the Department's receipt of payment of the penalty amount set forth in the Field Citation, the Field Citation becomes a Final Order of the Commission that:

1. Imposes upon the permittee or owner a civil penalty in the amount listed on Page 1 of this Field Citation; and
2. Requires the permittee or owner to satisfactorily complete the requirements and actions necessary to correct the violations documented by the dates set forth on Page 3 of this Field Citation.

Failure by the permittee or owner to complete the actions set forth on Page 3 of the Field Citation by the specified date violates the Commission Order and subjects the permittee and owner to a formal enforcement action, including the imposition of additional civil penalties.

Option 2:

The permittee or owner may deny that the violations as listed on Page 3 of this Field Citation have occurred or contest the Field Citation process by checking Option 2 and submitting to the Department a signed copy of Page 1 of the Field Citation. In that event, the Field Citation will serve as a Pre-Enforcement Notice (PEN) and the permittee and owner will be subject to formal enforcement for those violations set forth in the Field Citation, including the imposition of civil penalties in accordance with OAR Chapter 340, Division 12. Civil penalties that will be imposed by the formal enforcement process will exceed the Field Citation penalties for the same violation(s).

The Department appreciates your cooperation and efforts to comply with the regulations for underground storage tank systems.

UST FIELD CITATION

DATE ISSUED: 10/02/2025

PROGRAM ENFORCEMENT No.: 2025-FC-10004

FACILITY ID: 2652

Page 3 of 3

Violation #1: *TCR:	(G5) Failure to install, operate, maintain or calibrate RD equipment per manufacturer's instructions, including service checks for operability or running condition (i.e. device has been incorrectly installed, is defective, damaged, or may have been tampered with.)		
Corrective Action:	Annual release detection operability test preformed on 05/27/25, no corrective action required.		
Rule Citation: OAR 340-150-0400(1)(c)	Penalty Amount: \$ 100	Correct Violation by: n/a	Date Violation Corrected: 05/27/2025
Violation #2: *TCR:			
Corrective Action:			
Rule Citation: OAR	Penalty Amount: \$	Correct Violation by:	Date Violation Corrected:
Violation #3: *TCR:			
Corrective Action:			
Rule Citation: OAR	Penalty Amount: \$	Correct Violation by:	Date Violation Corrected:
Violation #4: *TCR:			
Corrective Action:			
Rule Citation: OAR	Penalty Amount: \$	Correct Violation by:	Date Violation Corrected:
Violation #5: *TCR:			
Corrective Action:			
Rule Citation: OAR	Penalty Amount: \$	Correct Violation by:	Date Violation Corrected:
Violation #6: *TCR:			
Corrective Action:			
Rule Citation: OAR	Penalty Amount: \$	Correct Violation by:	Date Violation Corrected:
Total Penalty Amount: \$ 100			

YOU MUST CORRECT THE VIOLATIONS AS REQUIRED, ENTER THE DATES CORRECTED, SIGN THE STATEMENT BELOW, AND**RETURN THIS FORM TO THE DEQ INSPECTOR LISTED ON PAGE 1 ON OR BEFORE: 11/02/2025****Retain a copy of this form and all documentation of corrective actions for your records.***I hereby certify that the UST violations noted above have been corrected:* _____/_____

Permittee/Owner Signature

Date

RE: DEQ UST # 2652 determination notice

From GILBERT Blakely * DEQ <blakely.gilbert@deq.oregon.gov>
Date Tue 10/7/2025 4:53 PM
To Matt Nida <mattnida@rosboro.com>
Cc UST Duty Officer * DEQ <UST.DutyOfficer@DEQ.oregon.gov>

Matt, In the email below it looks like only a Check or a card using YDO link for payments online. If you need more info or help, please contact our duty officer at UST Duty Officer * DEQ UST.DutyOfficer@DEQ.oregon.gov and they can give you the best information on how to get this done.

Thanks,
Blake

From: Matt Nida <mattnida@rosboro.com>
Sent: Tuesday, October 7, 2025 11:22 AM
To: GILBERT Blakely * DEQ <blakely.gilbert@deq.oregon.gov>
Subject: RE: DEQ UST # 2652 determination notice

Hi Blake,
I am working on getting this citation paid by our accounting department. Is this something that can be paid via invoice?

Thanks,

Matt Nida
Environmental Compliance Manager
2509 Main Street
Springfield, OR 97477
Office: 541-736-2146
Mobile: 541-554-9749
WWW.ROSBORO.COM



From: UST Duty Officer * DEQ <UST.DutyOfficer@DEQ.oregon.gov>
Sent: Thursday, October 2, 2025 3:30 PM
To: UST Duty Officer * DEQ <UST.DutyOfficer@DEQ.oregon.gov>
Cc: Matt Nida <mattnida@rosboro.com>
Subject: Re: DEQ UST # 2652 determination notice

You don't often get email from ust.dutyofficer@deq.oregon.gov. [Learn why this is important](#)

CAUTION: This email originated from outside of the organization. Do not follow guidance, click links, or open attachments unless you recognize the sender and know the content is safe.

Good afternoon,

UST facility 2652 Rosboro Forklift Shop located at 170 South 21st Springfield, OR

Please review the attached field citation. The deadline for payment of the \$100 is 11/2/25. The corrective actions are already completed.

Payment of Field Citation Penalty Instructions

Payment can be made either through **check** or **online** through Your DEQ Online – follow the link below to create an account.

[Department of Environmental Quality : Welcome to Your DEQ Online : Online Services : State of Oregon](#)

[PaymentsforEEOs.pdf](#) – step by step instructions for submitting payments online

Questions about online payments and submittals can be directed to the Help Desk at

itservicedesk@deq.oregon.gov or

[Your DEQ Online Helpdesk - Jira Service Management](#) –



Emily Litke (she/her)

Duty Officer, Underground Storage Tanks

DEQ Headquarters, Land Quality Division

700 NE Multnomah Street, Suite 600

Portland OR 97232-4100

503-806-9516

Emily.LITKE@deq.oregon.gov

From: UST Duty Officer * DEQ <UST.DutyOfficer@DEQ.oregon.gov>

Sent: Wednesday, October 1, 2025 3:54 PM

To: UST Duty Officer * DEQ <UST.DutyOfficer@DEQ.oregon.gov>

Cc: mattnida@rosboro.com <mattnida@rosboro.com>

Subject: DEQ UST # 2652 determination notice

Matt,

I want to thank you and Jim both for meeting at the Rosboro forklift shop located at 170 S 21st Springfield, Or 97477. You were both very helpful in assisting me in completing the onsite part of the DEQ Full Compliance Inspection for UST for site # 2652 on September 30th, 2025.

DEQ observed one violation, enforcement will be issued per the enforcement guidance. Below are the listed violations.

Note

You will receive the enforcement documentation via a separate email from the UST Duty officer email. The payment can be made via [Your DEQ Online Website](#).

***Please email the UST duty officer with all communications about the violation or when sending over the final testing records and any repair documentation. DO NOT SEND THEM TO ME. Contact the UST Duty Officer at [503-229-5034](tel:503-229-5034) or ust.dutyofficer@deq.oregon.gov**

Violations:

1. G-5 Failure to maintain or calibrate Release Detection equipment per manufactures instructions, including testing for operability or running condition annually 340-150-0400(2) class 1 \$ 100.00

Corrective Actions:

Annual Release Detection Operability Testing for 2024 was not done. Test performed on 05/27/25 was a passing test so no corrective action required.



Blake Gilbert (he/him)

Inspector, Underground Storage Tanks

DEQ Headquarters, Land Quality Division

700 NE Multnomah Street, Suite 600

Portland OR 97232-4100

C 503-360-4408

Fee

\$ 100.00

—

Paid

\$ 100.00

=

Due

\$ 0.00

Penalty

▶ 2025-fc-10004

UST - Field Citation

\$ 100.00

1 Results

Add Penalty

Send to FIMS

Payment

▼ Check by Mail 384943

10/15/2025

\$ 100.00

56646

Type

Check by Mail

Amount

100

E-Payment Confirmation#

E-Payment Settle Date

mm/dd/yyyy

Ref#

Payment Date

10/15/2025

Comments

(Remaining Length: 4000)

Site Info

ROSBORO FORKLIFT SHOP



Google

170 SOUTH 21ST, SPRINGFIELD, OR 97477

49328 ✓

259034

dbo.Incident.LustId=4188 UST (2652)

Stationary

Inspection Info

10569 Completed

UST

Full Compliance Inspection (FCI) TCR only

Start Date 9/30/2025

End Date 9/30/2025

Created & Updated Info