

Bethel-Danebo Closed Landfill Progress Report

For August 2018

Actions during this month:

- Regular sampling.
- Blower has run continually without issue since June the 25th 2015.
- The blower vacuum is at 7.8 The soils are completely dry and the clay soil is heavily cracked.
- I had continued conversation with an interested party of lots 15,16 and 17. I was also contacted by Jeff Demers in regards to sampling data on those lots.

Actions scheduled to be taken within the next two months:

- Continue sampling schedule.
- Schedule meeting with DEQ , Fire Marshal and City of Eugene.

Problems experienced during the month:

- Homeless camping and dumping has increased at the site to a level worse than I have ever noticed.

Readings for August 2018

Device ID	Date/Time	CH4	CO2	O2	Balance	%LEL
GEM™5000; G5 V1_14_12; LSGAM:6_0_20160627; {30105180273}						
		%	%	%	%	%
Probe001	8/30/2018 14:41	0	6.9	12.9	80.2	0
Probe002	8/30/2018 14:44	0.6	1.7	18.4	79.3	12
Probe010	8/30/2018 14:48	0	8.9	12.9	78.2	0
Probe003	8/30/2018 14:52	0	7.1	13.5	79.4	0

Probe004	8/30/2018 14:57	3.3	14.7	8.6	73.4	66
BLOWEXAU	8/30/2018 15:00	0.2	0.4	18.9	80.5	4
Probe005	8/30/2018 15:04	0	3.1	16.3	80.6	0
Probe006	8/30/2018 15:08	0.4	7.2	12.8	79.6	8
Probe007	8/30/2018 15:12	0	9.9	6.7	83.4	0
Probe007	8/30/2018 15:13	0	11.8	4.9	83.3	0
Probe008	8/30/2018 15:16	0	3.9	15.9	80.2	0
Probe009	8/30/2018 15:20	0.2	12.5	6	81.3	4
LC14-GP2	8/30/2018 15:27	8	24.6	2.1	65.3	>>>>
LC14-GP4	8/30/2018 15:33	48.5	30.8	3.4	17.3	>>>>

Don Strunk
 Supervisor/Engineering Analyst
 Lane County Waste Management Division

Device ID	Date/Time	CH4	CO2	O2	Balance	%LEL
GEM™5000; G5 V1_14_12; LSGAM:6_0_20160627; {30105180273}		%	%	%	%	%
Probe001	8/30/2018 14:41	0	6.9	12.9	80.2	0
Probe002	8/30/2018 14:44	0.6	1.7	18.4	79.3	12
Probe010	8/30/2018 14:48	0	8.9	12.9	78.2	0
Probe003	8/30/2018 14:52	0	7.1	13.5	79.4	0
Probe004	8/30/2018 14:57	3.3	14.7	8.6	73.4	66
BLOWEXAU	8/30/2018 15:00	0.2	0.4	18.9	80.5	4
Probe005	8/30/2018 15:04	0	3.1	16.3	80.6	0
Probe006	8/30/2018 15:08	0.4	7.2	12.8	79.6	8
Probe007	8/30/2018 15:12	0	9.9	6.7	83.4	0
Probe007	8/30/2018 15:13	0	11.8	4.9	83.3	0
Probe008	8/30/2018 15:16	0	3.9	15.9	80.2	0
Probe009	8/30/2018 15:20	0.2	12.5	6	81.3	4
LC14-GP2	8/30/2018 15:27	8	24.6	2.1	65.3	>>>>
LC14-GP4	8/30/2018 15:33	48.5	30.8	3.4	7 17.299999 99999999	>>>>

Adj. Power	Baro. Press.	Sys. Press.	Gas Pod Type	Gas Pod Value	CO	H2S	SO2	NO2
e3BTU/h	inches Hg	inches H2O			ppm	ppm		
N/A	29.66	N/A	N/A	N/A	1	0	N/A	N/A
N/A	29.66	N/A	N/A	N/A	0	0	N/A	N/A
N/A	29.66	N/A	N/A	N/A	1	0	N/A	N/A
N/A	29.67	N/A	N/A	N/A	1	0	N/A	N/A
N/A	29.67	N/A	N/A	N/A	2	0	N/A	N/A
N/A	29.67	N/A	N/A	N/A	0	0	N/A	N/A
N/A	29.68	N/A	N/A	N/A	0	0	N/A	N/A
N/A	29.68	N/A	N/A	N/A	0	0	N/A	N/A
N/A	29.68	N/A	N/A	N/A	1	0	N/A	N/A
N/A	29.68	N/A	N/A	N/A	0	0	N/A	N/A
N/A	29.68	N/A	N/A	N/A	0	0	N/A	N/A
N/A	29.68	N/A	N/A	N/A	1	0	N/A	N/A
N/A	29.68	N/A	N/A	N/A	3	4	N/A	N/A
N/A	29.68	N/A	N/A	N/A	3	12	N/A	N/A

