

# Bethel-Danebo Closed Landfill Progress Report

## For November 2020

### Actions during this month:

- Regular sampling.
- Blower has run continually without issue since June the 25<sup>th</sup> 2015.
- The blower vacuum was at 9.2 Soils are hydrated and the visual cracks have closed.
- Blower bearings were greased and all condensation controls refilled and emptied.
  
- **Actions scheduled to be taken within the next two months:**
- Continue sampling schedule.

### Problems experienced during the month:

No reported or observed problems at the site this month. There was more trash and a RV on the road this month.

### Monitoring Results for November 2020

Device ID	Date/Time	CH4	CO2	O2	Balanc e	%LEL
GEM™5000; G5 V1_15_12; LSGAM:6_0_20160627; {23288882303}		%	%	%	%	%
BLOWEXAU	11/24/2020 15:36	0.1	0.1	20	79.8	2
Probe004	11/24/2020 15:39	2.1	11	4.8	82.1	42
Probe003	11/24/2020 15:41	0.1	2.2	18.2	79.5	2
Probe002	11/24/2020 15:45	0.2	7.9	13.1	78.8	4
Probe001	11/24/2020 15:49	0.1	14.7	4.4	80.8	2
Probe010	11/24/2020 15:53	0.1	5.9	11.3	82.7	2
Probe005	11/24/2020 15:57	0.1	2.2	16.7	81	2
Probe006	11/24/2020 16:01	3.4	0.8	18.9	76.9	68
Probe007	11/24/2020 16:04	0.2	0.2	20.8	78.8	4
Probe008	11/24/2020 16:08	0.2	0.4	20.5	78.9	4
Probe009	11/24/2020 16:13	0.1	0.9	19.8	79.2	2

Don Strunk  
Supervisor/Engineering Analyst  
Lane County Waste Management Division

Device ID	Date/Time	CH4	CO2	O2	Balance	%LEL
GEM™5000; G5 V1_15_12; LSGAM:6_0_20160627; {23288882303}		%	%	%	%	%
BLOWEXAU	11/24/2020 15:36	0.1	0.1	20	79.8	2
Probe004	11/24/2020 15:39	2.1	11	4.8	82.1	42
Probe003	11/24/2020 15:41	0.1	2.2	18.2	79.5	2
Probe002	11/24/2020 15:45	0.2	7.9	13.1	78.8	4
Probe001	11/24/2020 15:49	0.1	14.7	4.4	80.8	2
Probe010	11/24/2020 15:53	0.1	5.9	11.3	82.7	2
Probe005	11/24/2020 15:57	0.1	2.2	16.7	81	2
Probe006	11/24/2020 16:01	3.4	0.8	18.9	76.9	68
Probe007	11/24/2020 16:04	0.2	0.2	20.8	78.8	4
Probe008	11/24/2020 16:08	0.2	0.4	20.5	78.9	4
Probe009	11/24/2020 16:13	0.1	0.9	19.8	79.2	2



Adj. Power	Baro. Press.	Sys. Press.	Gas Pod Type	Gas Pod Value	CO	H2S	SO2	NO2
e3BTU/h	inches Hg	inches H2O			ppm	ppm		
N/A	29.56	N/A	N/A	N/A	1	0	N/A	N/A
N/A	29.56	N/A	N/A	N/A	2	39	N/A	N/A
N/A	29.56	N/A	N/A	N/A	1	0	N/A	N/A
N/A	29.56	N/A	N/A	N/A	1	0	N/A	N/A
N/A	29.56	N/A	N/A	N/A	1	0	N/A	N/A
N/A	29.57	N/A	N/A	N/A	1	0	N/A	N/A
N/A	29.56	N/A	N/A	N/A	1	0	N/A	N/A
N/A	29.57	N/A	N/A	N/A	2	0	N/A	N/A
N/A	29.56	N/A	N/A	N/A	0	0	N/A	N/A
N/A	29.56	N/A	N/A	N/A	0	0	N/A	N/A
N/A	29.56	N/A	N/A	N/A	0	0	N/A	N/A







