



**OREGON DEPARTMENT OF ENVIRONMENTAL QUALITY  
INSPECTION PHOTOLOG**

**FACILITY NAME: Portland Rd Cardlock #7160**    **Page 1**  
**INSPECTION DATE: March 19, 2025**



**1: 4180 Portland Rd NE, Salem, OR 97303**




**2: Tank nest looking south**





**OREGON DEPARTMENT OF ENVIRONMENTAL QUALITY  
INSPECTION PHOTOLOG**

**FACILITY NAME: Portland Rd Cardlock #7160**    **Page 1**  
**INSPECTION DATE: March 19, 2025**



3: Premium fill



4: Premium sump





OREGON DEPARTMENT OF ENVIRONMENTAL QUALITY  
INSPECTION PHOTOLOG

FACILITY NAME: Portland Rd Cardlock #7160 Page 1  
INSPECTION DATE: March 19, 2025



5: Diesel fill



6: Diesel sump



7: Midgrade unleaded



8: Midgrade unleaded sump






OREGON DEPARTMENT OF ENVIRONMENTAL QUALITY  
INSPECTION PHOTOLOG

FACILITY NAME: Portland Rd Cardlock #7160 Page 1  
INSPECTION DATE: March 19, 2025



9: Unleaded fill




10: Unleaded sump



**OREGON DEPARTMENT OF ENVIRONMENTAL QUALITY  
INSPECTION PHOTOLOG**

**FACILITY NAME: Portland Rd Cardlock #7160**    **Page 1**  
**INSPECTION DATE: March 19, 2025**



11: Overfill alarm



12: pressure vent





OREGON DEPARTMENT OF ENVIRONMENTAL QUALITY  
INSPECTION PHOTOLOG

FACILITY NAME: Portland Rd Cardlock #7160 Page 1  
INSPECTION DATE: March 19, 2025



13: Tank 2 midgrade unleaded in alarm for high water



14: Impressed current system





**OREGON DEPARTMENT OF ENVIRONMENTAL QUALITY  
INSPECTION PHOTOLOG**

**FACILITY NAME: Portland Rd Cardlock #7160**    **Page 1**  
**INSPECTION DATE: March 19, 2025**



15: UDC #1/2



16: UDC # 3/4



**OREGON DEPARTMENT OF ENVIRONMENTAL QUALITY  
INSPECTION PHOTOLOG**

**FACILITY NAME: Portland Rd Cardlock #7160**    **Page 1**  
**INSPECTION DATE: March 19, 2025**



17: UDC #5/6



18: UDC #7/8