From:	DANA Kevin * DEQ
To:	Kyle Sattler
Cc:	DANA Kevin * DEQ; "Richard H. Allan"
Subject:	Cap Inspections at The Abigail (Block 27)
Date:	Tuesday, May 13, 2025 7:07:57 AM
Attachments:	5856 Annual Cap Inspection (2022).pdf image001.png

---

Good Morning Kyle,

I received your voicemail on Friday regarding annual cap inspections at The Abigail Apartments (ECSI 5856), on Block 27 of the former Hoyt Street Railyard. I've attached the most recent cap inspection report that DEQ has on file.

As indicated in the report, two types of annual inspections are required at The Abigail: a soil cap inspection, and inspection and maintenance of the methane monitoring system.

Let me know if you have any questions or need more information from me. Thanks!

Kevin Dana
Cleanup Project Manager
Oregon DEQ | Northwest Region Office
700 NE Multnomah Street, Suite 600
Portland, OR 97232-4100
503-229-5369
Kevin.Dana@deq.oregon.gov