



LUST - Report Release from Regulated, Unregulated, or HOT UST System

RID 32148 Submitted Date 04/22/2026

Tank Type

Regulated Underground Storage Tank

Incident Information

Date Submitted

2026-04-22

Date Discovered

2026-04-21

Name

615 Bower Ave, Nyssa, OR 97913

Site ID

317809

Physical Location

615 Bower Ave, Nyssa, OR 97913 (45.877642,-117.000867)

[Create new project](#)

Township

Range

Section

Size(acres)

0

County

Tax Lot(s)

Tax Lot(s)

Mail Contacts

Responsible Party

Ron Rembelski

Farmers Mutual Telephone Co

Manager

ron.r@fmtc.com

208-452-2000

319 SW 3rd St, Fruitland, ID 83619

Invoice Contact

☐ Same as above permittee

Ron Rembelski

 Farmers Mutual Telephone Co

 Manager

 ron.r@fmtc.com

 208-452-2000

 319 SW 3rd St, Fruitland, ID 83619

Other Contact (Optional)

Contact Type

 OR

Site Assessment

Discovery

Decommissioning

Cause

Corrosion

Source

Tank

Out Of Use

Is the Tank empty?

No

Confirmation

Contractor

Contaminants

☐ Heating Oil ☐ Diesel Motor Fuel ☐ Other Pet. Dist. ☐ Unleaded Gasoline

☐ Waste Oil ☐ Chemical ☐ Leaded Gasoline ☐ Lubricant

☐ MTBE ☐ Miscellaneous Gasoline ☐ Solvent ☒ Unknown

Impacted Media

☐ Drinking Water ☒ Groundwater ☐ Surface Water ☒ Soil

☐ Vapors ☐ Free Product

Comments

These tanks were recently discovered during site work by Farmers Mutual Telephone Co. Locals have reported this site was formerly a service station. Tanks held mostly water with a fuel skim on top. Tanks were pumped by Eastern OR Environmental Recovery prior to decommissioning. During decommissioning on April 21, 2026, heavily impacted soil was found beneath all tanks, and what appears to be either groundwater or perched stormwater was discovered.